

Andrea T-VK12, BT-VK12, Ch. VK12

These models appear on pages 2-9, 10 through 2-37 of Rider's TV Manual Volume 2. The following corrections should be made on the schematic diagram.

Part No.	Error	Correction
R14	Connected to +150 v. bus	+300 v. bus
C35A	HCE-313	HCE-318
C68	50 µf ± 10%	60 µf ± 10%
C74	5 µf ± 10%	50 µf ± 10%
C102	Connected across R109	Connected across R110
C112A	Connected to B-bus	Connect to ground
C113	ground	ground
C118	ground	ground


Belmont 7DX21, Series B

This model is the same as Model 7DX21, appearing on pages 2-71 through 2-86 of Rider's TV Manual Volume 2, except for the following. The vertical multivibrator and vertical sweep circuits were modified, as shown in the accompanying diagram, to improve the vertical linearity and to provide greater vertical capabilities.

The following components have been changed:

- Resistor R80 from 10 megohms to 4.7 megohms.
- Resistor R81 from 4.7 megohms to 10 megohms.
- Resistor R82 from 3.9 megohms to 5.6 megohms.
- Resistor R85 from 4.7 megohms to 10 megohms.
- Resistor R97 from 10 megohms to 6.8 megohms.
- Resistor R113 (10 megohms) added.
- Capacitor C101 from 0.03 µf, 600 volts, to 0.02 µf, 1000 volts.
- Capacitor C104 from 0.05 µf, 6000 volts, to 0.005 µf, 6000 volts.
- Capacitor C106 from 0.05 µf, 6000 volts, to 0.005 µf, 6000 volts.
- Capacitor C108 from 1000 to 1800 volts, to 0.02 µf, 1800 volts.
- Capacitor C108 from 220 µf to 0.0014 µf.
- Capacitor C120 (800 µf, 1600 volts) added.

formerly connected to this plate, have been connected to the plate of the other half of the tube (pin 5). Resistor R112 is used only when ballast resistor R15 is 104 ohms. When R15 is 40 ohms, the ballast resistor is marked with a yellow dot. Capacitor R108 (35,000 µf), choke coil R109, and C115 (10 µf) have all been omitted. The choke plate (pin 6) of the 19T8 tube is now connected to its cathode (pin 7) instead of to the bottom of the parallel combination of C115 and R108.



The coupling circuits associated with the first 6BA6 tube in the main chassis of the Belmont 18DX21.

Delete the following from the parts list.

Ref.	Symbol	Part No.	Description
C6	A-8C-12495-2	1.0 µf	
C17-118	A-8C-12495-7	0.5 µf	
R109	C-9B1-171	5000 ohms, 10%	
L-4-5-6	A-16A-16637	R-f choke	
C115	A-8C-11495	Electrolytic, 10 µf, 150 v.	
C116-119	C-8F-18201	100 µf, ceramic	
C44	C-8F3-109	47 µf, 10%, 500 v.	
R23	C-9B1-133	1000 ohms, 20%	
R24	C-9B1-19	10,000 ohms, 20%	
R28-34	C-9B1-82	47,000 ohms, 10%	
R87-88-89-90	C-9B1-102	2.2 megohms, 10%	
L9	A-201-16379	Choke coil	
L10-11-14-18-22-23	A-16A-16637	Filament choke	
T115	B-201-15612	Stagger tuned coil assembly	
A-200-15732		Strap assembly for front of picture tube	
B-200-16300		Strap assembly for rear of picture tube	
A-51A-16693		Iron core for stagger tuned coil assembly (part number B-201-15612)	
R61	C-9B2-66	2200 ohms, 10%, 1 watt	

Add the following to the parts list:

Ref.	Symbol	Part No.	Description
C5	A-8C-12495-7	0.5 µf	
L-4-5-6-7-8	A-201-16677	R-f choke	
C14-47	B-201-15142	Trimmer capacitor	
R23	C-9B1-171	5000 ohms, 10%, 1/2 watt	


R24	C-9B1-180	7500 ohms, 5%, 1/2 watt
R28-31	C-9B1-77	18,000 ohms, 10%, 1/2 watt
R27-38-89-90	C-9B1-31	1 megohm, 20%, 1/2 watt
L9	B-201-15611	Converter coil
L10-11-14-18-22-23	A-201-15609	Filament choke coil
A-201-15609		Retainer strap for rear of picture tube
A-49A-15616		Spring for rear tube strap
A-51A-11761		Iron core for stagger tuned coil assembly (part number B-201-15612)
R61	C-9B2-64	1500 ohms, 10%, 1 watt

DuMont RA-103

The model appears on pages 1-58 through 1-80 of Rider's TV Manual Volume 1. The manufacturer's production of the RA-103 incorporates a new type of cathode-ray tube. This new tube features a bent gun necessitates the use of magnets to deflect the electrons toward the face of the cathode-ray tube. Although these magnets are adjusted before the teletest leaves the manufacturer, they may occasionally come loose in shipment. If this occurs the illumination on the screen may be quite low. The magnet should then be adjusted for maximum brightness.

DuMont RA-105

This model appears on pages 2-59 through 2-55, 56 of Rider's TV Manual Volume 2. The following corrections should be made in the service data.
On the detailed block diagram on page 2-7, in the section for 401-A, the abbreviation Amp. should be changed to "MMK." In the voltage measurement chart on page 2-82, the measurement for pin #2 of V220 should be 135 volts instead of 13.5 volts.
In the schematic on pages 2-55, 56, in the volume control circuit, R235 is shown shorted out and the "hot" wire of the shielded lead is shown grounded. The accompanying diagram shows the correct connections.



For a short time the 47 µf, 5-kv capacitor, C414, in the flyback power supply was changed to 22 µf, 5 kv. This change was made to obtain an additional 1-kv accelerating voltage. However, it was found that the additional accelerating voltage made it difficult to obtain full horizontal size, thus necessitating a change back to the original value of 47 µf, 5 kv. In current production, R413 in the flyback power supply has been changed as follows:

The new resistor is	5.500 ohms
The old resistor was	7.500 ohms
This new resistor is described as follows	R413, 5.500 ohms, 5%, 1/2 watt, dipped.

A defective 6AT6 tube in the AGC amplifier may result in "drift" of the AGC setting which would become apparent as a change in sensitivity of the receiver as it operates. In such cases the 6AT6 tube should be replaced and the AGC readjusted as described on page 2-24. An accidental change in the AGC setting during shipment might result in low sensitivity, also necessitating readjustment of the control.


It is possible to adjust the AGC using the "meter" method without removing the main chassis from the cabinet. This can be accomplished by removing either the first or second video i. tube, V201 or V202, and inserting a sharp-pointed test prod into pin #1 of the tube socket involved. (Remember that when the tube socket is viewed from the top, the pins are counted in the counter-clockwise direction.) Once the meter connection has been made, the procedure is the same as that outlined on page 2-22, under the heading "Procedure for Adjusting in the Shop."

DuMont RA-108, RA-105, RA-106

Model RA-103 appears on pages 1-58 through 1-80 of Rider's TV Manual Volume 1. Model RA-105 appears on pages 2-5 through 2-55 of Rider's TV Manual Volume 2 and Model RA-106 is on pages 2-67 and 2-68 of the same volume. The following change has been made on all the inputters, which are the same on all these models.
The screen bypass capacitor, C110, on the 6AK5 mixer has been changed to 5000 µf, minimum. The purpose of this change is to improve the strong signal handling capabilities.
The new capacitor is described as follows:
60016760 1 CE 500 µf min, 600 v.

DuMont RA-105, RA-106

Model RA-105 appears on pages 2-6 through 2-55 of Rider's TV Manual Volume 2 and Model RA-106 on pages 2-67 and 2-68 of the same volume. The following changes have been made in the AGC circuit, as shown in the accompanying diagram.
C213 (13.5 µf, 500 v.) is changed to 26 µf, ±10%. This new capacitor is made from a piece of wax transmission line. The capacity may be varied by separating or squeezing together the two wires. In alignment, the greater the capacity, the broader will be the response of the stage.
The part number of this new capacitor is 60016890.



The AGC circuit of the DuMont RA-105 and RA-106.

Farnsworth 651-P

This model appears on pages 2-114 through 2-35 of Rider's TV Manual Volume 2. If low signal or noisy reception is encountered, it is suggested that the following be checked. Make sure that the connection at the antenna terminal lead plug has not been pulled loose. A good soldered connection is important. Make sure that the antenna terminal lead plug has not been inserted backwards into connector on side of chassis. Note: If the large prong blades in the plug are sprung this condition allows the small prong to float in the connector and may result in loss of signal energy or noise.
C231 was changed from a 0.0065 µf capacitor to a 0.1 µf, 200-volt capacitor, part number 630-3910/3-1381.
The purpose of these changes is to reduce the impedance of the grid circuit of the 6AT6 AGC stage and thus improve the stability of this circuit.

Extension cables, designed to allow the main chassis or power supply chassis of these telesets to be serviced outside the cabinet while leaving the tube or other chassis in the cabinet, are now available. These cables are 6 feet long, permitting the serviceman to work on the chassis in front of the set and view the action on the face of the CRT while making any checks. The following description of these cables should be added to the parts lists:
Part No. Where Used
34001281 Between C206's and main chassis (Z206).
34001461 Between focus assembly (PQ04) and main chassis (Z204).
50014171 Between main chassis (Z201) and power supply (Z202) on RA-106.
50014180 Between main chassis (Z202) and power supply (Z402) on RA-105.
Between main chassis (Z202) and power supply (Z701) on RA-106.
When servicing the arm tuner or in audio main, it is possible to use cable #50014171 as the extension. The use of this cable will introduce hum in the output since the signal lead of either unit should be shielded. The serviceman should take this into consideration when using this cable.
Cables #50014161 and #50014180 are exactly the same as far as external appearance is concerned. The only difference #50014180 contains the extra cable between the main chassis and the power supply. To identify this cable, it has been color-coded with a ring of red paint near the male plug.
A complete set consists of the 4 cables and will permit removal of both chassis simultaneously if necessary. However, for the high-voltage connections if the power supply is removed an improvised cable can be made up in the field. This cable consists of a suitable length of high-voltage cable with an alligator clip on each end. Obviously, the serviceman should be careful how he "dresses" this lead to prevent "arcing."
Capacitor C213 (13.5 µf, 500 v.) is changed to 26 µf, ±10%. This new capacitor is made from a piece of wax transmission line. The capacity may be varied by separating or squeezing together the two wires. In alignment, the greater the capacity, the broader will be the response of the stage.
The part number of this new capacitor is 60016890.

Farnsworth 651-P

This model appears on pages 2-11, 12 through 2-5 of Rider's TV Manual Volume 2.

A scratching or burking sound sometimes emanates from the r-f unit of Model 651-P when the 12-channel tuner is used.

This model appears on pages 1-23 through 1-30 of Rider's Television Manual Volume 1.

Refer to the waveform diagrams on Page 1-28 of Rider's TV Manual Volume 1.

Model 802 appears on pages 1-23 through 1-27 of Rider's TV Manual 1 and Model 803 appears in TV Volume 2 on pages 2-1 through 2-2.

A sharp low-frequency audio buzz which sounds similar to 60 cycle sync pulse reproduction has been noticed on the filament lead of the main tuning capacitor.

These models appear on pages 2-11, 12 through 2-5 of Rider's TV Manual Volume 2.

Model GV-260 and 651-P Model GV-260 appears in Rider's TV Manual Volume 1 on pages 1-1 through 1-25, 26.

The focus control was not listed in the service data for Model GV-260 but was on the parts list of Model 651-P.

To reduce wattage dissipation and the possibility of overheating in the focus control, apply the following:

Connect a 270-ohm, 2-watt resistor in parallel with the combination.

If leakage should develop between the heater and cathode of the 6A15 sync discriminator, hum in the picture will result and linearity will be affected.

Recent production incorporated this resistor.

Farnsworth U-12A Copeland

This model appears on pages 2-1 through 2-10 of Rider's TV Manual Volume 2.

Horizontal output transformer 750002-A is now being supplied as a replacement for transformer 94276.

The following exceptions are noted: The secondary of transformer 750002-A has only one tap, numbered 5.

This model appears on pages 1-23 through 1-30 of Rider's Television Manual Volume 1.

Model 802 appears on pages 1-23 through 1-27 of Rider's TV Manual 1 and Model 803 appears in TV Volume 2 on pages 2-1 through 2-2.

A sharp low-frequency audio buzz which sounds similar to 60 cycle sync pulse reproduction has been noticed on the filament lead of the main tuning capacitor.

These models appear on pages 2-11, 12 through 2-5 of Rider's TV Manual Volume 2.

Model GV-260 and 651-P Model GV-260 appears in Rider's TV Manual Volume 1 on pages 1-1 through 1-25, 26.

The focus control was not listed in the service data for Model GV-260 but was on the parts list of Model 651-P.

To reduce wattage dissipation and the possibility of overheating in the focus control, apply the following:

Connect a 270-ohm, 2-watt resistor in parallel with the combination.

If leakage should develop between the heater and cathode of the 6A15 sync discriminator, hum in the picture will result and linearity will be affected.

Recent production incorporated this resistor.

General Electric 802, 803

This model appears on pages 1-23 through 1-30 of Rider's Television Manual Volume 1.

Model 802 appears on pages 1-23 through 1-27 of Rider's TV Manual 1 and Model 803 appears in TV Volume 2 on pages 2-1 through 2-2.

A sharp low-frequency audio buzz which sounds similar to 60 cycle sync pulse reproduction has been noticed on the filament lead of the main tuning capacitor.

These models appear on pages 2-11, 12 through 2-5 of Rider's TV Manual Volume 2.

Model GV-260 and 651-P Model GV-260 appears in Rider's TV Manual Volume 1 on pages 1-1 through 1-25, 26.

The focus control was not listed in the service data for Model GV-260 but was on the parts list of Model 651-P.

To reduce wattage dissipation and the possibility of overheating in the focus control, apply the following:

Connect a 270-ohm, 2-watt resistor in parallel with the combination.

If leakage should develop between the heater and cathode of the 6A15 sync discriminator, hum in the picture will result and linearity will be affected.

Recent production incorporated this resistor.

Hallcrafters T-54 and 505

These models appear on pages 1-1 through 1-29 of Rider's TV Manual, Volume 1.

Remove the 100-ohm potentiometer connected into the vertical positioning circuit of the Industrial Television Model IT-11R.

Resistor R180 in the vertical sawtooth generator has been changed to 180,000 ohms, one watt from 270,000 ohms, one watt.

This change improved the range of the vertical control.

Resistor R180 (470,000 ohms, one watt) has been added between the plate and outside of V183 to stabilize the action of the noise limiter circuit.

These models appear on pages 2-1 through 2-16 of Rider's TV Manual, Volume 2.

To improve the sensitivity and remove fringe area snow, try the following.

Remove capacitors C9 and C11 from the push-button tuner.

Remove grounding leads from socket terminal #4 of V1 and #7 of V2 and ground these socket terminals directly to the chassis.

There have been some reports that the bosses on the plastic escutcheon are breaking, allowing the safety glass to drop out of position.

To prevent this, additional clips, part number 78A416, have been fastened with round head screws directly to the inside of the cabinet.

These six clips are installed around the safety glass in a manner to hold it in position independent of the boss on the plate.

It is no longer necessary to replace the entire escutcheon because of broken bosses.

Clips may be obtained from the Service Parts Department.

Hallcrafters T81-187

Reduction of noise in picture. Certain parts of the Boston area, having lower-than-normal TV signal strength, experience an accentuation of noise on the screen.

An investigation revealed that this condition is improved by shielding the leads to the contrast control.

Hallcrafters T-54 and 505

These models appear on pages 1-1 through 1-29 of Rider's TV Manual, Volume 1.

Remove the 100-ohm potentiometer connected into the vertical positioning circuit of the Industrial Television Model IT-11R.

Resistor R180 in the vertical sawtooth generator has been changed to 180,000 ohms, one watt from 270,000 ohms, one watt.

This change improved the range of the vertical control.

Resistor R180 (470,000 ohms, one watt) has been added between the plate and outside of V183 to stabilize the action of the noise limiter circuit.

These models appear on pages 2-1 through 2-16 of Rider's TV Manual, Volume 2.

To improve the sensitivity and remove fringe area snow, try the following.

Remove capacitors C9 and C11 from the push-button tuner.

Remove grounding leads from socket terminal #4 of V1 and #7 of V2 and ground these socket terminals directly to the chassis.

There have been some reports that the bosses on the plastic escutcheon are breaking, allowing the safety glass to drop out of position.

To prevent this, additional clips, part number 78A416, have been fastened with round head screws directly to the inside of the cabinet.

These six clips are installed around the safety glass in a manner to hold it in position independent of the boss on the plate.

It is no longer necessary to replace the entire escutcheon because of broken bosses.

Clips may be obtained from the Service Parts Department.

Hallcrafters T81-187

Reduction of noise in picture. Certain parts of the Boston area, having lower-than-normal TV signal strength, experience an accentuation of noise on the screen.

An investigation revealed that this condition is improved by shielding the leads to the contrast control.

Hallcrafters T-54 and 505

These models appear on pages 1-1 through 1-29 of Rider's TV Manual, Volume 1.

Remove the 100-ohm potentiometer connected into the vertical positioning circuit of the Industrial Television Model IT-11R.

Resistor R180 in the vertical sawtooth generator has been changed to 180,000 ohms, one watt from 270,000 ohms, one watt.

This change improved the range of the vertical control.

Resistor R180 (470,000 ohms, one watt) has been added between the plate and outside of V183 to stabilize the action of the noise limiter circuit.

These models appear on pages 2-1 through 2-16 of Rider's TV Manual, Volume 2.

To improve the sensitivity and remove fringe area snow, try the following.

Remove capacitors C9 and C11 from the push-button tuner.

Remove grounding leads from socket terminal #4 of V1 and #7 of V2 and ground these socket terminals directly to the chassis.

There have been some reports that the bosses on the plastic escutcheon are breaking, allowing the safety glass to drop out of position.

To prevent this, additional clips, part number 78A416, have been fastened with round head screws directly to the inside of the cabinet.

These six clips are installed around the safety glass in a manner to hold it in position independent of the boss on the plate.


It is no longer necessary to replace the entire escutcheon because of broken bosses.

Clips may be obtained from the Service Parts Department.


Hallcrafters T81-187

Reduction of noise in picture. Certain parts of the Boston area, having lower-than-normal TV signal strength, experience an accentuation of noise on the screen.


An investigation revealed that this condition is improved by shielding the leads to the contrast control.




Bias is added to the converter grid of the GE 810 and 814 in the manner shown.



The circuit will remove the vertical retrace lines in the GE810 television receiver.




The following additions should be made to the parts list:



The following additions should be made to the parts list:

Industrial Television IT-11R, IT-13R
 Model IT-11R appears on pages 2-12, 2 of *Rider's TV Manual Volume 2* and Model IT-13R appears on pages 2-12, 2 of the same volume. Due to recurrent internal shorts in the 6BG6-G horizontal sweep output tubes it has been found necessary to devise a means to protect the horizontal output transformer from being damaged by excessive current. A Mazda #47, brown bead, 65-volt, 0.150-ampere pilot bulb is inserted in the B+ feed to terminal #1 of the horizontal output transformer, T102, serving as a fuse in case of a shorted 6BG6-G tube. This change has been made in production and may readily be made in production and in the field.
 A special pilot light socket with good insulation to ground is available. The part number of this socket is 4A-235. The socket clips onto the assembly strap of transformer T102.

Magnavox CT 214 B
 This model is the same as CT 214 A, appearing on pages 2-1 through 2-27, 2 of *Rider's TV Manual Volume 2*, except for the following modifications. A green-colored peaking coil, part number 360332G10, has been inserted between the 2,000-ohm plate load resistor (183) of V14A and the +135-volt bus. This extends the hf response of this video amplifier stage.
 An iron-slug coil, part number 360346G1, has been inserted as the horizontal oscillator frequency control (25), replacing the 120- μ f capacitor (25) used previously. If it is desired to install this unit for improved stability of horizontal deflection, the following should be done:
 (1) Remove the 120- μ f capacitor (33) and replace with mica capacitor, 180- μ f $\pm 10\%$, 500-volt, part number 250159C385.
 Note: The capacitor which is removed may be used in step (3).
 (2) Remove the horizontal speed capacitor. This is the center capacitor of the three-zang trimmer (25).
 (3) Connect a 120- μ f, $\pm 10\%$, 500-volt, part number 250159C383, from the tie lug at the junction of the 100,000-ohm resistor (172) and the 180,000-ohm resistor (181) to the grounded terminal of V18 (pin 8).
 (4) Mount the horizontal speed coil, part number 360346G1, with mounting bracket part number 633750G2 directly above the zang trimmer (25). The tuning slug of the coil should be accessible through the opening marked HORIZONTAL SPEED.
 (5) The horizontal speed coil should be connected as shown in the accompanying diagram.



Horizontal speed coil in the Magnavox TV set model number CT 214 B.

- (6) Connect one side of the coil to the second lug from the end of the strip nearest horizontal linearity coil (13). Remove the 10,000-ohm resistor (155) and retain for use in step (8).
 - (7) Connect the opposite side of the coil to the center tap of Magnalok transformer (22). Dress the lead so that it will follow the contour of the wires leading to the tie lug strip mounted between the Magnalok transformer (22) and the 6Y6GT audio output stage. Connection should be made from the opposite terminal of the horizontal speed coil to the second tie lug from the end of the tie lug strip nearest the front of the chassis.
 - (8) Connect resistor 55 removed in step (6) across terminals 1 and 2 of the tie lug (across one-half of the coil).
 - (9) Connect a 0.01- μ f, 300-volt capacitor, part number 250161G53, across the coil. The connection should be made across the tie lug points 2 and 3.
- Note: Some models do not incorporate the tie lug described in step (7). For these models, steps (8) and (9) should be done as follows:
 a. Mount resistor 155 directly across the Magnalok transformer coil terminals.
 b. Mount the 0.01- μ f capacitor directly across the terminals of the horizontal speed coil.

Meissner 24TV, Serial Higher Than 1500

This receiver is the same as Model 24TV, appearing on pages 2-1 through 2-12 of *Rider's TV Manual Volume 2*, except for the following changes. The 100-ohm resistor connected between the contrast control and the 100-ohm cathode resistor of the first video i-f stage has been removed. A 0.0025- μ f capacitor in parallel with a 100-ohm resistor has been connected between the cathode (pin 5) of the 6AC7 first video amplifier and ground. The choke in the plate circuit of the second video amplifier has been changed in value from 250 μ h to 125 μ h. The new part number is 06664.

The 0.25- μ f capacitor connected between the brightness control and the choke in the plate circuit of the second video amplifier has been removed. A 6AL5 diode has been added to the circuit as the horizontal phase detector. This new tube necessitated changes in the 6SN7 sync separator circuit, as may be seen in Fig. 1.

The resistor in the arm of the brightness control has been changed in value from 220,000 ohms to 680,000 ohms, and a 0.25- μ f, 600-volt capacitor connected from the top side of this resistor to ground. The 22-ohm resistor connected to the horizontal deflection coil has been replaced by a 0.5- μ f, 400-volt capacitor. The 0.02- μ f, 600-volt capacitor connected from the junction of the horizontal linearity control and the primary of transformer 29445 to the bottom of the grid-leak combination of the

6BG6 tube has been changed to a 0.02- μ f, 1000-volt capacitor.




Fig. 1. The 6SN7 sync separator circuit for Meissner 24TV showing recent changes.

A corona ring has been added between the 1-megohm resistor and the filament (pin 7) of the 133CT high-voltage rectifier. A variable choke (05845) is used as a horizontal size control and connected from a tap to the bottom of the secondary of transformer 29445. A connection has been made from this tap to the 0.5- μ f, 400-volt capacitor mentioned formerly. The 6SN7 horizontal oscillator circuit has been changed as shown in Fig. 2.




Fig. 2. Changes in 6SN7 horizontal oscillator circuit for Meissner 24 TV.

A 0.002- μ f capacitor has replaced the 100,000-ohm resistor in the CR network in the primary of transformer 29443. A 22,000-ohm resistor has replaced the 0.005- μ f capacitor in the line leading from the sync separator. The 0.05- μ f, 600-volt capacitor connected from the bottom of transformer 29443 to ground has been changed in value to 0.25- μ f. The connections to the elements of the 6SN7 vertical oscillator tube have been reversed; that is, the connections to pins 1 and 4 have been reversed, as have those of 2 and 5, 3 and 6, and 7 and 8. No other change has been made in the circuit. The 4700-ohm resistor connected between the cathode (pin 3) of the 6SN7 vertical amplifier and the 0.05- μ f capacitor has been removed.

The voltage readings of the sync separator and the horizontal phase detector are:

Run # 1 2 3 4 5 6 7 8

6SN7 0	7	3	0	210	8.8	6.3AC	0
6AL5 0.8	4.5	6.3AC	0	0	0	0	0

The resistance readings for the sync separator and the horizontal phase discriminator are:

Pin # 1 2 3 4 5 6 7 8

6SN7 0	19K	220K	1Meg	3.3K	3.3K	2.7K	0
6AL5 0	0	0	0	27K	0	0	0

Philco 48-1001, Code 121

This model appears on pages 2-81, 82 through 2-88 of *Rider's TV Manual Volume 2*. All model 48-1001 receivers are Code 121 unless a different code number is stamped next to the model number on the rear of the chassis. To determine the run number of a set, examine the series of numbers stamped in ink on the rear of the chassis. The last digit of the series gives the run number. For example, if the number is I111374, the set is run 4.

All paper capacitors were changed to paper-molded capacitors. When replacing parts, the parts number given in TV Manual Volume 2 should be used with the following exceptions.

- Section 2**
 C210 should be Part No. 45-3502
 C211 should be Part No. 45-3502
 C217 should be Part No. 45-3502
- Section 3**
 C304 should be Part No. 45-3502
 C305 should be Part No. 45-3502
 C306 should be Part No. 45-3502
 C307 should be Part No. 45-3502
 C308 should be Part No. 45-3502
 C310 should be Part No. 45-3502
 C311 should be Part No. 45-3502
 C312 should be Part No. 45-3502
 C314 should be Part No. 45-3502
 C315 should be Part No. 45-3502
 C317 should be Part No. 45-3502
- Section 6**
 C506 should be Part No. 45-3500-3

Run 6
 Z202, the discriminator transformer, Part No. 32-4214, was replaced by Part No. 32-4214-3 to reduce frequency drift.

Run 6
 B547, Part No. 33-5247-2, was replaced by Part No. 32-5546-12. This involved a change only in rating.




Fig. 1. The 6AL5 double-diode tube has been added to give automatic frequency control.

Remington 1950
 This model is the same as Models 80 and 130, appearing on pages 1-1 through 1-10 of *Rider's Television Manual Volume 1*, except for the following changes. The B supply voltages are all supplied by one power transformer and a 5U4G rectifier. Both the centering controls are wired in series with the common supply. Only one filler choke is used in the common supply, instead of two as in Models 80 and 130.

Remington 80, 130

These models appear on pages 1-1 through 1-10 of *Rider's Television Manual Volume 1*. Since the noise levels are quite high in some localities, a/c has been added to minimize disturbances.
 A 6AL5 double-diode tube has been added to develop the oscillator control voltages. This tube receives its signal from the plate of the 6AS7 discharge tube. See Fig. 1 for connection of the 6AL5 into the circuit.

The bias arrangement has been changed on the 6AG7 video output tube. A 100-ohm resistor is connected between the cathode of the 6AG7 video output tube and ground. The grid coupling capacitor has been removed and replaced by a direct wire. See Fig. 2 for this change. When this latter change is made in a set brought in for servicing, it will help to minimize noise and is advised for locations where noise is prevalent.




Fig. 2. This change will help minimize noise in the Remington Models 80 and 130.

Philco 48-1001 Code 122
This model is similar to the Philco 48-1001 Code 121 appearing on pages 2-81, 82 through 2-86 of *Rider's TV Manual Volume 2*. It also incorporates the changes given on page 14 of the April, 1949 issue of *Successful Servicing* and page 8 of the May, 1948 issue.

The following changes have been made in Code 122:

Section 1
The ac power line has been connected directly to transformer T100 instead of to pins 4 and 10 of the ac inletlock.




Fig. 1. New discriminator transformer and associated circuit for Philco 48-1001.

Section 2
Refer to Fig. 1. Z202 has been replaced by a new discriminator transformer, part number 32-4317. Balancing choke, L204, part number 32-4143-1, has been removed. The 5- μ f capacitor, connected from the plate of the second 6A5 tube (7H) to ground, has been removed.

Capacitor C208, 0.001 μ f, part number 45-3500-5, has been added between pin 3 of the second 6A5 tube and ground. L202C, part of Z202, has been added. C202A, Balancing capacitor, C202C, part of Z202, has been removed. C202B, 10 μ f, part of Z202, has been changed to 20 μ f, and resymbolized C202A.




Fig. 2. Changes in wiring output circuit in Philco 48-1001.

C206, 0.001 μ f, part number 45-3500-5, was removed from the cathode (pin 7) of the second 6A5 tube, and connected as shown in Fig. 1. R222, 47,000 ohms, part number 66-3473340, was added. See Fig. 1.

R223, 47 ohms, part number 66-0473340, was added. See Fig. 1.

R219, 3,300 ohms, part number 66-2333340, was changed to 1,200 ohms, part number 66-2123340. R208, 27,000 ohms, part number 66-3273340, was changed to 10,000 ohms, part number 66-3273340. R210, 27,000 ohms, part number 66-3273340, was changed to 10,000 ohms, part number 66-3273340. R211, 31,03340.

Section 5
See Fig. 2. C509, coupling capacitor, 0.25 μ f, part number 61-0125, was changed to 0.1 μ f, part number 61-0113. The connection of the vertical deflection yoke, P9 and P3, were changed to 4 and 5, respectively. R349, linearity-control limiting resistor, 6,200 ohms, was changed to 33,000 ohms, part number 66-3333340. R545 and R546, horizontal linearity controls No. 2 and No. 3 were removed. The circuit was rewired as shown in Fig. 2.

R548, beam-bender control, was removed. Z502, beam-bender coil assembly (including L502A and L502B) was removed. A permanent-magnet type of beam bender (1B5500), part number 76-3913, was added.

J500, chassis receptacle (deflection-yoke-cable connector), 11 pins, part number 27-6174-4. P500, deflection-yoke-plug connector and cable, 11 pins, part number 41-3764-1, was changed to 8 pins, part number 41-3860.

Philco TV-42, TV-952
These models are the same as Model TV-40, TV-950 on pages 2-14 through 2-65, 64, of *Rider's TV Volume 2*.

Regal 1031
This model is the same as Model 1030 which appears in *Rider's TV Manual Volume 2* on pages 2-12.

Sears 8133, Ch. 101-846, 101-829-1
This model appears on pages 2-1 through 2-22, 23 of *Rider's TV Manual Volume 2*. Late production of television chassis 101-846 have incorporated a 4.5-mc trap off the plate of the first video amplifier tube 6A16, as shown in the accompanying diagram. This trap is necessary to remove the heterodyne beat caused by the 26- μ m picture if signal at the video receiver being against the very low, but still present, 21.9-mc sound i-f signal. This sound i-f signal tends to pass through the sound traps when the receiver is slightly detuned. This beat will show up on the picture tube as sound bars or a small herringbone pattern across the entire screen.

To install this 4.5-mc trap, proceed as follows:

- Place the chassis on the bench in an upside down position.
- Remove the #6 machine screw located midway between the first video amplifier 6A16 tube socket and capacitors C109 and C110.
- Install the trap coil (L30) on the chassis by placing the screw through the hole in the coil bracket and replacing the screw in the chassis. Before tightening the screw, rotate the trap coil so that the side with the soldering lugs faces the front of the chassis.
- Tighten the machine screw.
- Solder a wire from the coil lug nearest the chassis to ground.
- Connect a 4.7- μ f ceramic capacitor to the top lug on the trap coil and the plate (pin 2) of the 6A16 first video amplifier.

Due to the addition of this trap, the following information should be added after Television Alignment Procedure High Band Alignment on page 2-11.

- With the chassis completely adjusted and connected for operation, tune in a test pattern.
- Turn the contrast control to its full-on position and the brightness control to a low level (so that contrast is still noticeable).
- Detune the fine tuning control so that sound bars are just visible. A 4.5-mc beat is now readily visible on the screen.
- Rotate the 4.5-mc trap coil adjustment

The following should be added to the parts list:

Location	Part Number	Description
C24		Capacitor—1.5 μ f—ceramic
CA		Capacitor—2.2 μ f—ceramic
C135		Capacitor—4.7 μ f—ceramic
C131		Capacitor—50 μ f—ceramic
L30	R70077	Coil—4.5-mc trap
	R70090	Damper—tube
	R70067	Insulator—capacitor
R9		Resistor—2,700 ohms— $\frac{1}{2}$ w.
R207		Resistor—15 megohms— $\frac{1}{2}$ w.

The following should be added to the parts list:

Location	Part Number	Description
R9		Resistor—5,000 ohms— $\frac{1}{2}$ w
R207		Resistor—4.7 megohms— $\frac{1}{2}$ w.

screw counterclockwise to its full-out position (about 1" of screw showing).

- Turn the adjustment screw in (clockwise) until the 4.5-mc beat on the screen just disappears. Do not go beyond this point.

Radio chassis 101-829-1 used in these sets, beginning with serial number 2001, have had a phono switch bracket assembly installed for phono operation. The switch is connected between the high side of resistor R202 (2.2 megohms) and the high side of volume control R205 (500,000 ohms). The high side of R205 no longer is connected to the junction of R203 and C213.

The following deletions have been made in the parts list:

Schematic Part Number	Description
C24	Capacitor—1.0 μ f—ceramic
C131	Capacitor—1.5 μ f—ceramic
C135	Capacitor—100 μ f—ceramic
R70015	Damper—trimmer
R70017	Damper—tube
R63476	Insulator—capacitor
R63477	Insulator—capacitor
R65491	Line ass'y.—transmission—high
R65492	Line ass'y.—transmission—low
R9	Resistor—5,000 ohms— $\frac{1}{2}$ w
R207	Resistor—4.7 megohms— $\frac{1}{2}$ w.


The following should be added to the parts list:

Location	Part Number	Description
CA		Capacitor—1.5 μ f—ceramic
C135		Capacitor—2.2 μ f—ceramic
C131		Capacitor—4.7 μ f—ceramic
L30	R70077	Coil—4.5-mc trap
	R70090	Damper—tube
	R70067	Insulator—capacitor
R9		Resistor—2,700 ohms— $\frac{1}{2}$ w.
R207		Resistor—15 megohms— $\frac{1}{2}$ w.

The following should be added to the parts list:

Location	Part Number	Description
R70140		Phono switch bracket assembly (chassis serial number 2001 and up)

A limited number of these models were shipped from the factory with loose deflection yoke caps. This cap protects the high-voltage terminals of the deflection coil and it is important that it be securely fastened to the deflection yoke lousing. A



A 4.5-mc trap has been incorporated into the Sears television chassis 101-846.

good grade of paper cement can be used to fasten the cap securely. It is recommended that all deflection yoke caps be checked for proper bonding to the housing before servicing.

Mark Simpson IMB-13; MTB-13X
Second Production
These models are the same as model MTB-13X appearing on pages 2-1 through 2-3 of *Rider's TV Manual* except for the following changes:

The variable tuning capacitor used with transformer T1 has been changed in value from 28 μ f to 15 μ f. A 4,700-ohm resistor has been connected from the screen grid of the 6AK5 associated with transformer T3 to the plate of that tube, instead of the previous combination of resistors.

The 150-ohm resistor in series with the selenium rectifier may, in some cases, be 120 ohms.

Stromberg-Carlson TS-10
Because of the limited supply of twelve-inch picture tubes, it has been necessary to substitute the ten-inch 10BP4 for the 12 1/4 in some of the TV-12 table model receivers. The receiver with the ten-inch tube is known as the TS-10. Service data on pages 1-17 to 1-29 of *TV Volume 1* applies to the TS-10 when the following changes are made:

R-286 (250 ohms) has been shorted out to provide adequate focus range. C-287 (220 μ f) has been omitted to give the correct horizontal sweep for the ten-inch tube.

The following parts have been added: 111055 40 μ f, 475 v, capacitor C-294(A) to replace 111040 40 μ f, 400 v, capacitor C-294(B) 113047 10-mch tube clamp 114635 Ion trap 154053 Mask 162024 10BP4 picture tube 165009 Anode connector

In most cases when installing a Model TS-10 receiver, the ion trap will have to be adjusted. Move the ion trap back and forth on the neck of the tube, at the same time rotating it until the brightest raster is obtained on the screen of the picture tube.

Stromberg-Carlson TV-12LM, 12MSM, 12PCM, 1220T, TV12H1M, 12H2M, 12H2A

This receiver is shown in *Rider's TV Manual, Volume 1* pages 1-29 and 1-30. Terminal 5 of the horizontal-output transformer returns to plus 400 volts. Resistor R258 is 33K instead of 3.3K. Resistor R309 is 100K instead of 10K. On recent models the relay contacts of K201 break the B-plus lead instead of the B-minus lead. This is between the junction of R316 and L217, and the cathodes (pin 8) of V218 and V219.

TEST PATTERNS

Abnormalities in the patterns appearing on the scope can be classified as being caused by either:-
 1. Internal effects - i.e. misadjustment of one or more controls, incorrect voltages, deterioration of components, etc., or -
 2. External effects - i.e. interfering signals, multiple signals, too strong or too weak a signal, etc.
 Many of the internal defects, causing abnormalities in the test pattern can be corrected by the simple adjustment of the pre-set or front panel controls.

The following test patterns have been arranged firstly as to internal and then the external causes for abnormalities. It should be born in mind that whereas only one cause is given for each defect, it is possible to have more than one simultaneously, necessitating several adjustments.

These patterns are reproduced through the courtesy of the following companies: Radio Corporation of America, General Electric Company, Allen B. DuMont Laboratories, Inc., Capehart - Farnsworth Corporation, Motorola, Inc., and others




FIG. 3: CONTRAST TOO HIGH




FIG. 4: FOCUS MISADJUSTED




FIG. 5: FOCUS COIL AND ION TRAP MISADJUSTED




FIG. 6: DEFLECTION YOKE ROTATED




FIG. 2: CONTRAST TOO LOW




FIG. 1: NORMAL PICTURE




FIG. 7: PICTURE TUBE ADJUSTMENT REQUIRED



FIG. 8: VERTICAL HOLD MISADJUSTED




FIG. 16: HORIZONTAL WIDTH TOO WIDE




FIG. 18: HOR. LINEARITY MISADJUSTED - BUNCHES RIGHT OR LEFT




FIG. 20: HOR. SYNC. DISC. XFORMER FREQ. ADJUSTMENT MISADJUSTED




FIG. 15: HORIZONTAL CENTERING MISADJUSTED




FIG. 17: HORIZONTAL WIDTH TOO NARROW



FIG. 19: HOR. LINEARITY MISADJUSTED - BUNCHES TO CENTER




FIG. 10: VERTICAL LINEARITY MISADJUSTED




FIG. 12: VERTICAL HEIGHT TOO HIGH




FIG. 14: NO VERTICAL SWEEP




FIG. 9: VERTICAL LINEARITY MISADJUSTED




FIG. 11: VERTICAL CENTERING MISADJUSTED




FIG. 13: VERTICAL HEIGHT TOO LOW




FIG. 21: HOR. SYNC DISC. XFORMER PHASE ADJUSTMENT MISADJUSTED




FIG. 22: HORIZONTAL HOLD MISADJUSTED FAST MOVEMENT



FIG. 27: EXCESSIVE RIPPLE IN VIDEO AMPLIFIER



FIG. 28: EXCESSIVE RIPPLE IN VIDEO AMPLIFIER




FIG. 23: HOF. HOLD MISADJUSTED "TEAR OUT" AT TOP OR BOTTOM



FIG. 24: HORIZONTAL HOLD MISADJUSTED SYNC AFFECTED




FIG. 29: 120 CYCLE HUM IN VIDEO AND HORIZONTAL SCANNING




FIG. 30: SOUND BARS OR MICROPHONICS



FIG. 25: HORIZONTAL HOLD MISADJUSTED



FIG. 26: HUM IN VIDEO AND SYNC



FIG. 31: SOUND INTERFERENCE - INCORRECT TUNING




FIG. 32: MISALIGNMENT OR IMPROPER ANTENNA ORIENTATION




FIG. 40: IGNITION INTERFERENCE - WEAK



FIG. 42: BEAT FREQUENCY




FIG. 44: NO VIDEO SIGNAL




FIG. 39: DIATHERMY INTERFERENCE - WEAK



FIG. 41: IGNITION INTERFERENCE - HEAVY




FIG. 43: HUM IN DEFLECTION COIL



FIG. 34: TRANSIENTS




FIG. 36: DIATHERMY INTERFERENCE - HEAVY




FIG. 38: DIATHERMY INTERFERENCE - LIGHT



FIG. 33: MULTIPLE IMAGES - GHOSTS




FIG. 35: INTERFERENCE FROM ANOTHER SIGNAL



FIG. 37: DIATHERMY INTERFERENCE - MEDIUM