## PROFESSIONAL CHARGES FOR TELEVISION SERVICE

All charges are for professional services only, except where otherwise indicated. Parts should be billed at list prices as explained at the end of the schedule.

Each bill should include one of the following charges, to cover the cost of testing tubes or parts or any other tests that may be necessary to determine the nature and extent of the trouble.

This covers up to 1 hour of time including trip to and from home, if located within 2 miles of shop. Charge for extra time or mileage at rate specified in schedule. Minor repairs that can be made within time limit are included in this charge.

			11
II Check-up and test at shop, including pick-up and delivery of set This includes time and transportation expense for two round trips to a cus-	7.50	component is difficult to get at and it may be necessary to remove other parts to make replacement	5.00
tomer located up to 2 miles away from		—tubular	3.00
shop; for greater distance charge at		-can	4.00
mileage rate specified in the schedule		Dual electrolytic—tubular	3.50
of charges, and for time exceeding 1		—can	4.50
hour, charge according to the hourly		Multi-section	-
rate.		—tubular	4.50
III Charles I I I I I I I I I I I I I I I I I I I		-can	5.50
III Check-up and test at shop, when customer brings set in and takes it away This charge is for   hour time. Minor	2.50	Connections—locating and soldering loose or intermittent connectionHourly	Rate
repairs or adjustments that can be		Control:	
made within time limit should be in-		Single (brightness, contrast, volume,	
cluded.		etc.)	3.00
Charles and the second second second		Dual, concentric (Horizontal and	0.00
ALPHABETICAL SCHEDULE OF CHAI	RGES	vertical hold, etc.)	4.00
		Deflection yoke—install	5.00
Antenna-install simple outside or attic		-repair broken lead	2.00
type	30.00	Focus coil—install	5.00
(This charge includes the antenna,		—repair broken lead	2.00
lightning arrestor, lead-in, supports,		HOURT II D. CO.	
and hardware necessary to complete installation.)		HOURLY RATE	5.00
-install complex antenna for fringe		(This rate may vary considerably be-	
area. Charge list price for equip-		tween large cities and rural communi- ties. An average charge is given here.)	
ment used. Labor charge \$5.00 per		Interference—install simple power-line	
hour for man in charge of installa-		filter	1.50
tion, plus \$3.50 an hour for each		-install and adjust stub for FM inter-	7
helper.		ference	3.00
-repair, resolder lead-in	5.00	—install high-pass or low-pass filter	2.50
-install new transmission line	10.00	-install and adjust wave trap	3.00
(includes up to 100 feet of line)		-eliminate interference at source	
-orient antenna	5.00	Hourly 1	
Alignment-adjust oscillator in sets where		Minimum of	\$5.00
the oscillator can be adjusted from		Line cord, plain 2-wire—install where	1 00
the front of the set without remov-		soldering is necessary	1.00
ing the receiver from the cabinet		Loudspeaker—install	2.50
Covered in Service Ch	arge	-substitute PM for electrodynamic	4.00
-adjust oscillator where set must be	THE STATE OF	Mileage rate, per extra mile traveled	.25
removed from cabinet	2.50	Phono motor-clean and lubricate	1.50
—sound i-f alignment	2.50	-replace motor (automatic player)	4.00
-video i-f alignment, stagger tuning.	4.00	Phono pick-up-adjust, repair, or replace.	2.50
-video i-f alignment, band-pass tuning -complete alignment	6.00	DEGRAMOR 4-4-11-11	
-complete augmment	10.00	RESISTOR installation:	200
AUTOMATIC RECORD CHANGER (TV co	mbi-	Single resistor Each additional	3.00
—clean and oil	1.50	TRANSFORMER installation:	3 - 1
-adjust or replace partsHourly			3.00
Minimum of	5.00	Sound detector	4.00
		Sound i-f	3.00
COIL installation:		Horizontal output (includes adjusting	
Peaking coil	3.00		5.00
Filter choke	3.00	Vertical output (includes adjusting	TAT
Focus coil			4.00
Coil in tuner	5.00		3.00
CONDENSER installation:			4.00
Single by-pass (paper, mica, ceramic)	3.00	Trap (sound, adjacent-channel sound, adjacent-channel picture)	3.00
Each additional	.50	Power transformer (usual installa-	0.00
By-pass, coupling, etc., in tuner where	di Pari	tion, not exceeding 1 hour)	5.00

Tube socket, install—easy to get at	3.00
-difficult to get at	4.00
Tube tests-No additional charge if this	
can be carried out within the period	
allotted to general check-up. If ad-	
ditional time is required, or where	
customer simply brings tubes in, per	10
tube	.10
Tuner-install new coil strip in turret	
tuner when coll snaps in and out of	2.00
position	2.00
-install contact strip in turret tuner;	5.00
strip riveted in position  —install new detent and shaft	4.00
-dismantle and clean turret tuner	5.00
-clean contacts of turret tuner when	5.00
	3.00
not necessary to dismantle	5.00
-miscellaneous repairs Hourly	

National Radio-TV News, June-July 1952

Courtesy of Bob Dobush