

# THORDARSON

PART TO PART  
 CROSS REFERENCE  
 AMERICAN & FOREIGN BRANDS

# THORDARSON

TV  
 REPLACEMENT  
 PARTS GUIDE

- ADMIRAL
- AIRLINE
- ◊AMC
- ◊ANDREA
- ◊ARVIN
- BRADFORD
- ◊BROADMOOR
- CATALINA
- CHANNEL MASTER
- CLAIRTONE
- ◊CLOVIS
- CORONADO
- ◊DELMONICO
- DUMONT
- ELECTROHOME
- EMERSON
- FLEETWOOD
- GAMBLE SKOGMO
- GENERAL ELECTRIC
- GRUNDIG MAJESTIC
- HEATH
- HITACHI
- ◊HOFFMAN
- HOTPOINT

- ◊JVC
- MAGNAVOX
- MARCONI
- MATHES
- MATSUSHITA
- MONTGOMERY WARD
- MOTOROLA/QUASAR
- ◊NIPPON ELECTRIC CO.
- ◊NIVICO
- OLYMPIC
- PACKARD BELL
- PANASONIC
- PENNCREST
- JC PENNEY
- PHILCO

- PHILIPS
- QUASAR
- RCA
- SANYO
- SEARS ROEBUCK
- ◊SETCHELL-CARLSON
- SHARP
- SILVERTONE
- SIMPSON SEARS
- ◊SINGER
- SONY
- ◊SPARATON
- SYLVANIA
- SYMPHONIC
- TOSHIBA
- TRUETONE
- WESTERN AUTO
- WESTINGHOUSE
- WHITE STORES
- ZENITH

◊SEE MISCELLANEOUS  
 PAGE

# THORDARSON

FLYBACKS

DEFLECTION YOKES

TRANSFORMERS

VOLTAGE MULTIPLIERS

COILS

**IMPORTANT TOOLS**  
FOR YOUR SERVICE BENCH AND TRUCK

**LINE  
ISOLATION TRANSFORMER**

**23V19**

PROTECT AND ISOLATE HOT CHASSIS, TEST  
EQUIPMENT AND SENSITIVE SEMICONDUCTORS.

PRIMARY - 117 50/60 HZ  
SECONDARY - 105V, 115V, 125V  
350 VA - ELECTROSTATIC SHIELD

**DEGAUSSING COIL  
19-2000**

9 FT. LONG CORD WITH SWITCH FOR  
DEMAGNETIZING COLOR PICTURE TUBES AND  
ADJACENT METAL PARTS.

USE TO CORRECT COLOR IMPURITY IN THE  
PICTURE.

**THORDARSON ALSO HAS A COMPLETE  
LINE OF STANDARD TRANSFORMERS,  
INDUCTORS, SEMICONDUCTORS  
AND VOLTAGE MULTIPLIERS.**

**THORDARSON-MEISSNER**

**TV REPLACEMENT  
Parts Guide**

**TVPG-14**

THORDARSON MEISSNER is pleased and proud to supply you with this new pocket replacement guide. More than 600,000 copies are already in circulation. As you know, these are updated frequently with new exact replacement recommendations.

THORDARSON, established in 1895, is the oldest electronic company in existence, and has continuously served the independent electronic parts distributors and dealer/technicians since the inception of the industry. Our engineers are internationally known and respected, having pioneered yoke and flyback development since 1940's, and designed and built the first flame-retardant flybacks in the 1960's. Today we design and build thousands of original equipment flybacks and yokes as well as replacement parts for O.E.M. distribution. These contacts with low cost original equipment components enable us to improve the design and quality of the exact replacement components sold through TM distributors. All THORDARSON color flybacks are flame-retardant, as an example, even though they almost always cost you less than the inferior original equipment part.

We appreciate your use of THORDARSON MEISSNER replacement parts, and your support of your independent electronic parts distributor.

© 1981 by THORDARSON - MEISSNER, INC.

**SUGGESTED RETAIL PRICE \$2.00**







AIRLINE  
(CONTINUED)

AIRLINE  
(CONTINUED)

Table with 4 columns: MFR'S PART, REPLACEMENT, MFR'S PART, REPLACEMENT. Contains aircraft part numbers and their replacements.

Table with 4 columns: MFR'S PART, REPLACEMENT, MFR'S PART, REPLACEMENT. Contains aircraft part numbers and their replacements.

Service notes may be found at the back of this book

Printed in USA

Printed in USA

Service notes may be found at the back of this book







# CORONADO

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
L-160	19-1005	TIF373	17-5023	15-178215	19-1008	109457	Y 107
L-162	19-3180	TIF374	17-3419	15-178221	19-7047	109834	19-3060
L-163	19-4950	TIF384	20-1008	15-178222	19-7068	109840	19-3060
L-164	19-1001	T-1156	19-1006	15-178224	19-3660	112820	FLY 273
L-165	17-5003	T-L2004	19-2027	15-178225	19-3125	26586	
L-167	17-3494	T-L2005	19-3275	15-178234	17-3418	112822	26548
L-177	Y 64	T-L2006	19-3500	15-178235	17-3419	112829	26C81
L-179	17-5002	T-L7096	19-1002	15-178236	17-3414	112845	26R150
L-188	17-3495	T-L7103	19-1008	15-178237	17-3420	112866	HS 23
L-195	17-5002	TLF-140-D	19-1003	15-178238	20-1057	112869	17-6031
L-196	17-5025	TLF-302D	FLY 430	15-178244	26C81	112870	17-1083
L-197	Y 101	TLF-303DS	FLY 432	15-178248	19-1014	112871	17-3420
LC-1	19-1001	TLF-535-D	19-4073	15-178250	19-3125	112872	17-6028
LC-9	20C49	TLF-553-D	WC 18	15-178251	19-2025	112873	17-6032
LC-11	19-7047	TLF-574-D	17-1063	15-178253	19-1008	112874	17-6022
LC-9121-2	26C81	TLF-576-D	17-1063	15-178256	19-2015	112875	WC 36
LC-9133	20-1058	TLF-579-D	17-3400	15-178258	26C81	112877	17-6033
LC-9136	20-1057	TLF-580-D	HS 7	15-178277	19-2034	112879	17-3414
LC-9140	HS 23	TLF-581-D	HS 8	15-178267	19-7047	113382	FLY 277
LC-9141	17-6028	TLF-593-D	17-1062	15-178289	19-7068	113383	26R150
LC-9142	17-6022	TLF-594-D	17-3497	15-178299	19-2026	113388	19-3600
LC-9147	WC 55	TLF-6075	FLY 431	15-178300	19-3180	113390	26586
LC-9151	Y 245	TLF-611G	17-1003	15-178311	19-1014	113394	WC 44
LC-9152	WC 53	TO-9105	22534	15-178312	19-1006	113404	19-3660
LC-9153	WC 45	TO-9106	FLY 295	15-178313	19-3180	113640	FC 7
LC-9154	WC 38	TO-9109	26533	15-179022	Y 122	113999	FC 6
LC-9155	WC 41	TP-9101	26R150	15-179030	Y 109 <sup>14</sup>	200114	19-4500
LC-9156	WC 54	TR-50A/B	26508	15-179033	Y 91	200426	19-4122
LC-9157	FC 6	TR-51/A	FLY 137	15-179036	Y 123	200892	19-3125
LHO-2-E	HS 5	TR-52	26R51	15-179061	Y 120	200894	19-3125
LI-9107	20-1052	TR-77A	26508	50-688	17-5004	200896	19-3160
LI-9108	20-1050	TR-78A	26585	51-2101	19-4400 <sup>2</sup>	200902	19-2028
LI-9109	17-1083	TR-79	FLY 514	51-2102	19-3660	201114	HS 7
LI-9110	17-3418	T-S1022	17-5036	51-2167	17-4534	201136	Y 81 <sup>5</sup>
LI-9111	17-3419	T-S1055A	17-5023	51-2168	17-4522	201143	26C77
LI-9112	17-3414	T-S1822	17-3415	51-2169	HS 4	201147	17-4534
LI-9113	17-3420	T-S2011	20-1061	51-2184	19-3160 <sup>2</sup>	201148	17-4534
LI-9114	17-6031	TTR-185-1-D	26551	53-342	19-1004	201149	17-4524
LI-9115	17-6032	TTR-195-2-D	24550	53-396	Y 60 <sup>8</sup>	201150	17-5003
LI-9116	17-6033	TTR-209-D	FLY 5 <sup>1</sup>	53-398	Y 49 <sup>3</sup>	201151	17-5003
LIF-8-C	17-1031 <sup>1</sup>	TTR-224-D	Y 12 <sup>2</sup>	55-303	26575	201152	16-3445
LIF-11	16-3445	TTR-226-D	26C43	72A316-12	17-5015	201153	16-3445
LM-77J4	WC 14	T-V111	26549	72A316-18	17-3404	201154	17-1031
LM-77J4-1	WC 20	T-V120	24553	72A373-1	HS 28	201203	22586
LM-77J4-3	WC 20	T-W27	26508 <sup>1</sup>	73A55-29	19-3060	201206	26C77
LP-12A	19-3500	10-201-1	19-2028	74A31-1	26C81	201222	17-5003
LP-17	19-3160 <sup>2</sup>	10-228-5	WC 41	79A153-2	26596	299944	22561 <sup>1</sup>
LP-18	19-3160 <sup>2</sup>	10-452-1	19-7068	79A162-2	FLY 504	508341	26C93
LTO-3	17-3495	10-541	17-1062	79A169-1	FLY 461	509376	24551
LTO-13	17-3495	10-542	17-1064	80-72-6	26C81	509378	17-3402
LV-6	17-1003	10-543	17-1063	80-98-4	Y 163	509603	20-1004
LV-7	17-1063	10-544	17-3402	80-135-2	Y 171	509706	17-3493
LV-8	17-1064	10-549	FC 1	80-145-3	FLY 364	520620	19-3180
LV-9	17-1003	10-551	WC 11	80-164-9	FLY 459	520942	Y 7 <sup>3</sup>
S-38A1003	HS 7	10-552	17-1033	80-252	FLY 1	520943	HS 9
SPK-135	24553	10-555	HS 5	80-253	26549	520975	26553 <sup>7</sup>
T-116	26572	15-094012	20-1008	80-254	26R95	520980	26A03
T-116A	26572	15-094013	17-5020	80-255	26578	520984	19-3160
T-116B	26572	15-094014	17-5023	80-257	26A03	520985	19-3660
T-122B	21F12 <sup>1</sup>	15-094015	17-3419	80-284-9	24585	520986	19-3660
T-123	24551	15-094025	17-3415	83-650	Y 3	521066	FLY 24
T-124A	FLY 5	15-094026	17-5020	94-305-7	WC 62	906153-501	26R150
T-124B	FLY 5	15-094029	20-1051	94-305-8	WC 58	1104665-3	26C81
T-124D	FLY 5	15-094071	20-1008	94-305-9	Y 59	051-102101	19-4400 <sup>2</sup>
T-129	21F12 <sup>1</sup>	15-094073	17-3418	94-379-4	WC 47	051-102184	19-3160 <sup>2</sup>
T-A25	HS 16	15-094074	17-3419	94-379-9	Y 186 <sup>9</sup>	051-201996	20-1020
T-B25	26C81	15-094080	20-1051	77842	19-3075	051-202169	HS 5
T-B28A	26C79	15-094081	20-1057	100131	19-3125	053-100307	19-1005
T-B30	20C47	15-097006	Y 123	100441	19-3330	053-100342	19-1001
T-D41A	Y 81 <sup>8</sup>	15-097027	26571	101819	19-3036	053-300396	Y 16 <sup>8</sup>
T-D81C-U25	Y 122	15-097030	17-5022	103037	19-3375	055-100303	26575
T-D85A-U25	Y 122	15-097059	22561	105065	WC 41	055-300301	FLY 146
T-F58	FLY 437	15-097095	26530	105066	WC 42	055-300303	26575
T-F76A-33	FLY 390	15-178008	19-1006	105295	20-1057	201-15608	19-6022
T-F83-33	FLY 391	15-178013	19-1006	106383	20-1050	201-15612	17-1004
T-F103A	FLY 443	15-178040	26C81 <sup>1</sup>	109171	19-1008	201-19490-1	Y 5 <sup>5</sup>
T-F110A	FLY 428	15-178047	19-2026	109180	WC 43	201-19817-1	FLY 36
THLF47	19-7047	15-178061	WC 41	109248	19-2062	201-20062	17-3401
THLF68	19-7068	15-178066	19-2024	109252	17-3418	201-20186	WC 17 <sup>1</sup>
THLF100	19-2024	15-178182	19-1014	109253	17-3419	201-20265	19-1005
THLF180	19-3180	15-178187	19-2033	109255	20-1058	201-23727	20-1005
THLF470	19-3500	15-178210	19-6022	109257	19-3600	201-23729	20-1020
THLF1000	19-2023	15-178211	19-3125	109261	20-1051	201-23729-1	20-1020
THF372	17-5020	15-178212	19-1014	109264	FC 7	201-23829	17-1004

# CORONADO

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
201-23873	17-3495	201-24472-1	HS 7	201-24748	Y 5	255-100012	24548
201-23873-1	17-3495	201-24473-2	HS 8	201-25360	Y 16	256-200002	26C92
201-24056	Y 5 <sup>3</sup>	201-24473-3	HS 8	201-26019	Y 18		
201-24472	HS 7	201-27120	Y 16 <sup>5</sup>	255-100011	26585		

# CURTIS MATHES

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
1A7	16-6758	1A161-2	WC 36	1A405-366	FLY 569	10A48/-1	24504
1A8	16-6758	1A161-002	WC 40	1A411-001	17-3414	10A100-001	26C79
1A12	17-4534	1A162	20-1050	1A412-001	17-3419	10A101-001	245149
1A13	17-4534	1A162-000	20-1050	1A413-001	17-3418	10A105-001	22531
1A14	17-4536	1A163	20-1052	1A416-003	FLY 627	12A6-3	26R123
1A15	17-4535	1A163-000	20-1052	1A429-001	17-6027	12A19-1	26R121
1A16	17-4511	1A164	17-6022	1A430-001	17-6023	12A29	26R106
1A17	20-1004	1A164-000	17-6022	1A432-001/002	FLY 471	12A45	26R105
1A18	17-1026	1A165	17-6033	1A443-001	20-1005	12A46	26R105
1A19	17-3495	1A165-000	17-6033	1A449-001	17-3418	12A47	26R105
1A20	20-1005	1A166-1	WC 41	1A450-001	17-3418	12A48	26R150
1A21	HS 7	1A166-001	WC 41	1A451-001	17-3416	12A56	26R106
1A22	HS 8	1A166-2	WC 42	1A457-001	20-1057	12A95-1	21F114
1A23	19-1001	1A166-003	WC 43	1A458-002/001	FLY 465	12A102-001	23V449
1A25	FLY 150	1A166-3	WC 43	1A459-002	Y 194	14A1	19-3180
1A30-1	Y 16	1A168	Y 107	1A466-004	WC 44	14A2	19-3100
1A37	HS 6	1A169	FLY 273	1A474-001	17-3415	14A3	19-3036
1A38	20-1005	1A188	HS 16	1A489-001	Y 212	14A4	19-3180
1A39	17-4536	1A193D	Y 81	1A495-001	FLY 521	14A6	19-3250
1A40	17-4535	1A197/C	Y 81	1A512-003	19-3160	14A11	19-3600
1A41	HS 6	1A205	Y 107	1A530-001	FLY 523	14A12	19-3036
1A74	FLY 165	1A205-000	Y 107	1A531-001	Y 214	14A13	19-3180
1A75-1/-2	Y 106	1A206	FLY 277	1A533-001	Y 213	14A14	19-4073
1A76	17-5003	1A210	Y 81	1A534-001	Y 212	14A014-001	19-3075
1A77	17-5002	1A242	FLY 277	1A541-001	FLY 571	14A15	19-1004
1A78	17-4523	1A243-000	Y 245	1A547-001	Y 212	14A19	19-3125
1A79	17-4538	1A244-000	FLY 656	1A548-001	Y 213	14A22	19-4060
1A80	17-4538	1A245-000	WC 53	1A551-001	FLY 571	14A23	19-1055
1A81	17-1031	1A246-000	HS 23	1A552-1	FLY 648	14A24	19-3660
1A93	FLY 165	1A246-001	WC 55	9A2648	Y 165	14A025-000	19-3036
1A93-1	FLY 165	1A247-001	WC 41	10A3-5/D/6/6D	24542	14A052-021	19-3500
1A96	17-3495	1A247-002	WC 38	10A3-7/-8/-A	26542	14B348-003	VMT-08
1A124	19-4060	1A247-003	WC 54	10A9	26507	14B348-1	VMT-08
1A133/-1	FC 7	1A247-004	WC 45	10A10	24592	14B348-2	VMT-08
1A133-							

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
1564-1	24553	734223	24561	R113404	19-3660	20008570	17-4523
77842	19-4073	737014	26C77	R113547	17-3419	20008711	26553
180281	24553	737046	26C93	R113640	FC 7	20008712	26514
180313	24553	737047	26C77	18002761	26549	20008731	17-4522
180330	24553	737048	26C77	18002771	22551	20008745	17-4502
180332	24553	737049	26C81	18002791	22596	20008761	17-3497
705021	19-1005	737053	26C77	18002792	22558	20008771	26R92
708351	19-4400	737056	26C77	18002793	22553	20008801	FLY 16
708370	19-4201	737057	26C81	18002801	22559	20008901	26R93
708379A	Y 53	738163	FLY 229	18003001	26549	20008991	17-4524
708382	Y 79	738168	FLY 245	18003041	26549	20008993	17-4524
708394	WC 18	738171	26572	18003061	26549	20008995	17-4522
708401	19-3180	738176	26572	18003131	26549	20008997	17-4522
708402	Y 62	738186	FLY 258	18003141	26549	20008998	17-4524
708403	Y 62	738188	FLY 258	18003212	26549	20009016	26R09
708405	19-3275	738189	26572	18003321	22562	20009018	26R88
708406	19-3093	738190	FLY 292	18003322	22558	20009019	26R88
708407	Y 79	738191	FLY 292	18003331	26549	20009041	17-3497
708415	Y 105	738192	FLY 293	18003361/21	22558	20009043	17-3497
708416	WC 18	738193	26585	18003471	26549	20009091	FLY 16
708424	FC 7	738194	26572	18003481	26549	20009261	15-1082
708432	20-1057	738195/A	FLY 277	18003501	26549	20009262	15-1082
708434	HS 23	738196	26586	18003511	26546	20009321	26554
708436	WC 41	738202	FLY 295	18003521	26546	20009332	26554
708444	WC 36	738203	26533	18003611	22533	20009391	FLY 75
708448	Y 107	738213	FLY 277	20003901	17-1043	20009701	24560
708452	Y 105	738214	FLY 277	20003921	HS 11	20009761	26A03
708461	FC 6	AT2941	24553	20003923	HS 11	20009781	FLY 16
708463	Y 245	R100037	26548	20003931	26A01	20009791	22589
708481	Y 105	R100131	19-3125	20003941/42	24586	20009792	24560
713046	20-1049	R101819	19-3036	20003944	24586	20009795	22533
713047	17-4534	R102134	26C81	20003951	FLY 4	20009797/98	24551
713050	20-1005	R102201	19-4060	20004044	16-6758	20010141	26R11
716136A	HS 11	R103037	19-3375	20004061	FLY 4	20010142	26R120
716148	HS 25	R105065	WC 41	20004071	21F10	20010161	22525
716149	HS 26	R105066	WC 42	20004081	HS 1	20010185	26R12
716151	HS 27	R105195	26C81	20004142	26A01	20010331/-1	26552
720075	16-6758	R105196	WC 35	20004261	FLY 1	20010332	26522
720315	20-1079	R105213	17-6018	20004331	26F60	20010451/52	26514
720316	17-3418	R105214	17-6019	20004441	17-3457	20010453/54	26553
720318	17-3418	R105216	17-6011	20004511	20-1049	20010524	20-1049
720336	20-1054	R105294	17-3417	20004611	HS 3	20010531/32	17-5004
720337	17-1052	R105295	26A04	20004721	26A04	20010561	17-3495
720364/A	17-3489	R106383	20-1050	20004722	26A04	20010571	22561
720404	20-1054	R107290	17-3402	20004723	26A04	20010572/73	24583
720419	17-3418	R107837	17-6012	20004726	26A04	20010601	26R77
720421	17-4522	R109180	WC 43	20004728	26A04	20010611/12	FLY 245
720433	17-3495	R109221	FLY 281	20004731	26553	20010613	FLY 245
720434	20-1005	R109237	HS 8	20004732	26553	20010791	26R121
720452	20-1054	R109252	17-3418	20004771	26R95	20010871	FLY 16
720453	20-1054	R109253	17-3419	20005011	26F60	20010873	FLY 16
720454	17-3418	R109254	17-3414	20005012	26F60	20011182	26R47
720455	17-3418	R109257	19-3600	20005013	26F60	20012681	26R116
720462	20-1049	R109261	20-1052	20005014	26F60	20012691/92	FLY 148
720465	16-6786	R109262	17-1083	20005015	26F60	20013881	22525
720466	16-6787	R109263	26586	20005021	FLY 6	20013891	17-4536
720469	20-1052	R109264	FC 7	20005031	26553	20013901	17-4535
720471	17-1083	R109286	26R150	20005032	26553	20013911	17-4514
720472	20-1050	R109295	20-1057	20005037	24586	20013931	26508
720474	17-3418	R109457	Y 107	20005211	17-1011	20013941	26A03
720475	17-3414	R109826	17-1035	20005271	17-1035	20013951	FLY 201
720477	17-3420	R109840	19-3060	20005491	26553	21003971	17-1004
720478	17-6031	R109845	Y 107	20005492	26553	21004121	17-3402
720479	17-6032	R109850	26586	20005497	24586	21004135/36	17-1003
720481	17-6033	R112820	FLY 273	20005571	HS 3	21004137/38	17-1004
720486	17-1052	R112821	26586	20005581	17-1011	21004141	19-1001
720513	17-1052	R112822	26548	20005662	26553	21004171	WC 11
720514	17-3419	R112829	26C81	20005781	17-1004	21004241	Y 5
720518	17-3420	R112845	26R150	20005851/52	HS 3	21004243	Y 3
720540	17-3418	R112866	HS 23	20005891	24R05	21004350	WC 14
730094	26R116	R112869	17-6031	20006141	17-3497	21004382	26C90
730109	26R120	R112870	17-1073	20006731	FLY 115	21004421	19-1001
730111	26R116	R112871	17-3420	20006883/84	26R93	21004451	19-1001
730113	26R47	R112872	17-6028	20007611	HS 3	21004711	WC 11
730114	26R116	R112873	17-6032	20008021	26554	21004721	26C41
730120	26R150	R112874	17-6022	20008031	26R71	21004722	20C64
730126	26R106	R112875	WC 36	20008041	17-1062	21004741	WC 10
730129	26R150	R112877	17-6033	20008061	FLY 12	21004751	WC 14
734185/6	24551	R112879	17-3414	20008182	26R91	21004762/63	WC 14
734195	24553	R113382	FLY 277	20008241	19-1052	21004771	WC 11
734214	24551	R113383	26R150	20008251	17-4504	21004801/02	17-1004
734215	24553	R113388	19-3600	20008261	17-5004	21004831	20-1004
734221	24553	R113390	26586	20008303	17-5004	21004971	Y 5
734222	22586	R113394	WC 44	20008481/82	26554	21005212	26C95

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
21005213	26C91	21010962	20-1004	21014851	20-1005	89013321	Y 41
21005218	26C91	21010964	20-1004	21014871/72	26C44	89013333	Y 14
21005221	WC 17	21010991	HS 5	21014874	26C93	89013572	Y 18
21005341/42	FC 4	21010992	HS 5	21014876	26C78	89013574	Y 18
21005343	FC 4	21011001	WC 23	21014877	26C78	89013801	Y 16
21005421	19-1001	21011011	WC 22	2101489/92	20-1020	89014092	Y 16 <sup>12</sup>
21005431	26C77	21011013	WC 22	21014911	HS 5	89014491	Y 77
21005432/33	26C77	21011021	17-3400	21014914	HS 5	89014641	Y 78
21005491	WC 17	21011032	17-1003	21014931	17-4538	89015781	Y 72
21005501	Y 3	21011061	Y 41	21014932	17-4538	902492-2	22545
21005541	Y 5	21011062	Y 41	21014939	20-1049	20-375	FLY 1
21005601	19-1001	21011081	19-3036	21014942	20-1044	20-380	24586
21005711	Y 6	21011082	19-1006	21014952	17-4538	21-338	Y 3
210057118	Y 6	21011180	17-1004	21014954	20-1044	9A2365	20-1049
21005821	WC 22	21011301	19-2864	21014961/62	20-1049	9A2366	20-1004
21006091	Y 6	21011383	20-1005	21014971	20-1049	9A2367	20-1005
21006191	Y 6	21001601	WC 18	21014971	20-1049	9A2372	HS 8
21006230	19-3001	21011742	Y 41	21014972	17-4534	9A24158	Y 72
21006280	19-1002	21011762	19-1001	21015531	Y 75	9A2416	HS 7
21006370	19-1004	21012011	19-1004	21015532-1	Y 75	20C-12477	17-1043
21006520	19-1003	21012151	26C91	21015562	19-4400	20C-12478	17-1011
21006550	19-1005	21012191	19-1994	21015563	19-3300	20C-12572-1	HS 1
21006621	19-3036	21012192	19-1002	21015563	19-3180	20C-12922-1	16-6758
21006622	19-3100	21012201	20-1047	21016051	Y 78	20C-12922-2	16-6758
21006623	19-3160	21012211	17-3400	21016171	HS 5	20D-12926	24R02
21006624	19-3160	21012212	20-1004	21016181/82	20-1049	20D-4901-2	26A01
21006627	19-4400	21012251	Y 14	21016691	Y 77	21A-13087-101	17-1004
21006628	19-3180	21012421	17-4538	21017691	WC 19	21A-13087-102	19-1021
21006629	19-3500	21012431	26C41	21017692	WC 19	21A-13088-101	17-1004
21006641	Y 6	21012451	19-6022	21018491	17-1026	21A-13089-101	17-1004
21006781	17-1004	21012452	19-6022	21018501	20-1005	21A-13089-102	17-1004
21006926	Y 6	21012851	20-1005	21018511	20-1045	21A-13089-103	17-1004
21007281	19-1001	21013261	Y 18	21018521	20-1049	21A-13090-101	19-1021
21007791	WC 17	21013781/82	20-1004	21018541	19-3160	21A-13090-102	19-1021
21008871	Y 5	21013783	20-1044	21018551	19-3100	21A-13090-103	19-1021
21008972	19-1002	21013791/92	20-1005	21018561	20-1005	21A-13090-104	17-1004
21009171	20-1049	21013793	20-1004	21018571	19-3160	21A-13098-101	17-3401
21009961	Y 4	21013861	19-3160	21018581	19-3160	21A-13230-101	WC 11
21009962	Y 4	21013864	19-3250	21018591	26C79	21A-13307	WC 14
21							

# ELECTROHOME

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
21-344-01	17-3495	21-1045-01	17-6027	24-100005-04	26578	50-94358-1	WC 22
21-347-01/-02	20-1005	21-1055-01	WC 23	24-100005-05	26507	51-88332-1/-2	Y 46
21-350-01	17-5004	21-1084-01	20-1054	24-100006-01	26578	56-94273-1	26585
21-335-02/-03	17-1026	21-1091-01	WC 38	24-100008-01/-02	26578	76-14198-1	Y 150
21-360-01	20-1005	21-1099-01	WC 16	24-100010-02/-04	26586	103383	26R150
21-382-01	17-4523	24-632-01	WC 23	24-100011-01	26533	105065	WC 41
21-383-01	17-1031	24-100101-01	26586	24-100011-01	26533	105295	20-1057
21-389-09	17-3495	24-10109-02	26R152	24-100013-01	26578	106383	20-1050
21-391-01	17-4535	24-10109-03	26R152	24-100013-02	26508	109252	WC 43
21-392-01	17-4523	24-10109-04	26R152	24-100013-03	26508	109252	17-3418
21-392-02	17-3423	24-10109-01	26R152	24-100013-04	26508	109261	20-1052
21-393-01	17-4523	24-10109-02	26R152	24-100013-05	26508	109457	Y 107
21-395-01	20-1044	24-80008-08	26551	24-100014-01	26533	112822	24506
21-397-01	17-4534	24-80008-11	24552	24-100015-01	26538	112829	26C81
21-432-02	16-6758	24-80008-12	24551	24-100016-01/-02	26533	112866	HS 23
21-631-01	FLY 277	24-80008-13	24551	24-110002-01	26C77	112870	17-1083
21-632-01	WC 23	24-80014-07	26549	24-110002-03	26C77	112871	17-3420
21-1004-01	FC 6	24-80035-05	26549	24-110002-02	26C81	112873	17-6032
21-1012-01	17-6028	24-80042-02	24506	24-110024-02	26C81	112875	WC 36
21-1018-01	17-6032	24-80063-01	24564	24-110024-07	26C81	112877	17-6033
21-1019-01	17-6033	24-80080-02	24506	24-110024-08	26C81	112879	17-3414
21-1020-01/-03	17-6028	24-80080-03	24549	24-110024-10	26C81	113382	FLY 277
21-1024-02	WC 55	24-100001-01/-02	24552	24-110026-02	26C81	113383	26R150
21-1024-03	WC 23	24-100002-01	26578	25-105-01	Y 48	113390	26586
21-1026-1	WC 38	24-100003-01	24552	28-32-0X	VMT-03	113394	WC 44
21-1028-02	WC 45	24-100004-01/-02	26578	28-35-01	VMT-05-02	113547	17-8419
21-1036-01	Y 5016	24-100005-01/-02/-03	26507	32-10008-9	FLY 302	906186-501	Y 245
21-1038-01	FC 6			32-10012-11	26597	502	Y 245
				50-94292-1	FLY 148	ELH-47	Y 245

# EMERSON

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
72A185-5	17-1072	73A90-2	19-2033	79D142-3	24551	94A405-1/-2	Y 148
72A216-5	20-1057	73A125-1	19-1001	79A142-5	24560	135C14	26C81
72A251-2	17-3422	73A125-3	19-1008	79D142-5	24560	135P37	21F09
72A251-8	17-3419	73A125-4	19-2017	79A146-2	FLY 444	135A61	24506
72A287-3	20-1051	73A126-1/-2	19-7047	79A146-3/C	FLY 444	150A17	24553
72A287-4	20-1051	73A360-1	17-3409	79D146-3/G	FLY 444	700A814-8	Y 229
72A296-7	17-3404	74A18-45	26C78	79A153-1/-2	26596	700C814-3/-5	Y 229
72A301-2	17-1073	74C18-45	26C78	79D153-2/-5	26596	700C1089-6	Y 229
72A308-1	17-5015	74A18-60	26C77	79A154-1	FLY 385	750C305-24/-26/-29	Y 229
72A308-2	17-3414	74D18-60	26C77	94D255-1/2/3	Y 229	750C1089-2	Y 88
72A314-2	17-1048	74A18-62	26C77	94A/B268-4	HS 7	750C1089-3/-6/-12/-13	Y 229
72A316-8	20-1079	74C18-62	26C77	94A277-2	HS 48	750C1089-3/-6/-12/-13	Y 229
72A325-3	17-6038	74A18-63	26C77	94C277-2	WC 53	750C1089-3/-6/-12/-13	Y 229
72A327-1	17-6039	74D18-63	26C77	94D302-6/5	Y 229	750C1089-3/-6/-12/-13	Y 229
72A357-1	17-6050	74A27-4	26C80	94D302-16	Y 229	750C1089-3/-6/-12/-13	Y 229
72A359-1	17-3405	74B27-4	26C80	94A304-1/-2	Y 138	750C1089-3/-6/-12/-13	Y 229
72A361-1	20-1077	74A30-1	26C80	94A304-5	Y 117	750C1089-3/-6/-12/-13	Y 229
72A362-1	20-6051	74C30-1/D	26C80	94D034-7/-9/-11	Y 131	750C1089-3/-6/-12/-13	Y 229
72A362-1	17-6051	47A30-5	26C77	94A304-8/-10	Y 117	750C1089-3/-6/-12/-13	Y 229
72A363-1	17-6052	74C30-5-H	26C77	94A305-7	WC 62	750C1089-3/-6/-12/-13	Y 229
72A364-1	17-6071	74A31-1	26C78	74B31-1	WC 62	750C1089-3/-6/-12/-13	Y 229
72A373-1	HS 28	79D33-112	22586	94A/D305-8	WC 58	750C1089-3/-6/-12/-13	Y 229
73A5-40	19-4201	79A106-5	26586	94A305-9	WC 59	750C1089-3/-6/-12/-13	Y 229
73A5-62	19-3125	79D106-5	26586	94D305-9	WC 59	750C1089-3/-6/-12/-13	Y 229
73A31-11	19-1001	79A124-5	24583	94A/D377-1	Y 131	750C1089-3/-6/-12/-13	Y 229
73A46-21	29-3060	79D131-2F	26586	94A/D377-2	Y 131	750C1089-3/-6/-12/-13	Y 229
73A55-10	19-6022	79D134-2G	26586	94A/D377-3	Y 109	750C1089-3/-6/-12/-13	Y 229
73A55-12	19-3125	79A134-3	26591	94A/D377-4	Y 216 <sup>14</sup>	750C1089-3/-6/-12/-13	Y 229
73A55-17	19-2027	79D134-3H	26591	94A/D377-5	Y 117	750C1089-3/-6/-12/-13	Y 229
73A55-18	19-3660	79A138-4	FLY 421	94A/D377-6	Y 117	750C1089-3/-6/-12/-13	Y 229
73A55-26	19-2013	79D138-6	FLY 422	94A/D377-7	Y 109 <sup>1</sup>	750C1089-3/-6/-12/-13	Y 229
73A55-27	19-1008	79D138-14	FLY 421	94A/D377-8	Y 216 <sup>14</sup>	750C1089-3/-6/-12/-13	Y 229
73A55-29	19-3060	79A140-1	FLY 386	94A/D377-9	Y 109 <sup>1</sup>	750C1089-3/-6/-12/-13	Y 229
73A55-31	19-2005	79D140-1D	FLY 386	94A/D377-10	Y 210	750C1089-3/-6/-12/-13	Y 229
73A55-37	19-1000	79A141-1	FLY 386	94A/D377-11	Y 210	750C1089-3/-6/-12/-13	Y 229
73C55-38	19-7068	79D141-1	24589	94D379-1/2/3	Y 193 <sup>14</sup>	750C1089-3/-6/-12/-13	Y 229
73A55-40	19-2022	79B141-1	24589	94A/D379-4	Y 147	750C1089-3/-6/-12/-13	Y 229
73A55-41	19-6033	79A142-1	24551	94A/D379-5/6	Y 193 <sup>9</sup>	750C1089-3/-6/-12/-13	Y 229
73C55-46	19-6033			94D379-8/-9	Y 186 <sup>9</sup>	750C1089-3/-6/-12/-13	Y 229
				94D379-12	Y 239	750C1089-3/-6/-12/-13	Y 229
				94D379-13	Y 193 <sup>9</sup>	750C1089-3/-6/-12/-13	Y 229

# EMERSON

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
705041	19-1001	708209	19-1003	708468	WC 54	720141	17-3495
705047	19-1008	708210	17-3496	708475	19-1008	720142	17-5001
705049	19-1001	708211	Y 18 <sup>9</sup>	708476	Y 116	720146	17-3495
705050	19-1008	708212	Y 18 <sup>9</sup>	708479	Y 116	720147	17-5001
705058	19-1009	708213	20-1049	708481	Y 105 <sup>8</sup>	720148	17-4523
505065	19-1005	708214	Y 10 <sup>5</sup>	708493	19-3125	720149	20-1049
705067	19-4214	708226	WC 23	708496	Y 116	720151	19-1020
705079	19-3036	708228	WC 18	708506	Y 116	720154	20-1049
705120	17-3400 <sup>1</sup>	708232	Y 61 <sup>9</sup>	708512	19-3125	720155	17-5004
707214	Y 10	708241	17-6013	708514	Y 147	720156	17-5001
708002	17-1013	708243	19-3500	708516	Y 147	720157	17-3495
708003/04	WC 14	708247	19-4950	708517	19-2023	720166	20-1049
708008	17-1013	708248	19-3036	708518	19-3060	720175	17-4523
708014	19-6022	708249	WC 23	708521	19-7047	720178	17-3495
708017	17-3496	708255	HS 5	708522	19-7068	720181	17-4523
708018	17-3496	708265	17-6013	708523	19-1003	720182	17-3495
708019	WC 15	708269	Y 61 <sup>9</sup>	708524	19-2026	720185	17-3495
708021	WC 16	708270	Y 10 <sup>5</sup>	708526	19-7047	720187	17-6758
708023	FC 3	708271	19-1003	708529	WC 44	720198	17-4522
708027	FC 1	708272/A	19-3300	708531	19-3300	720199	17-4522
708030	Y 3	708273	19-4400	708532/A	Y 105 <sup>8</sup>	720201	17-5004
708031	17-3496	708274	19-3660	708534	Y 144	720204	17-4522
708031B	17-3496	708275	HS 21	708538	19-4216	720213	17-4522
708032	20-1004	708276	20-1053	708539	Y 147	720215	17-5038
708032-1	17-3495	708279/A	19-3500	708549	Y 147	720216	17-4523
708036	Y 3	708288	Y 49	716037	HS 3 <sup>3</sup>	720221	17-1024
708037	WC 14	708312	19-1005	716052	HS 7	720226	17-4522
708039	FLY 5 <sup>8</sup>	708313	Y 61	716052-A	HS 7	720229	19-6012
708041	FC 1	708321	Y 10 <sup>5</sup>	716073	HS 7	720231	17-4523
708043	Y 13	708322	Y 61	716074	HS 5	720238	17-4523
708051	WC 11	708330	Y 62	716083	HS 7	720241	17-4522
708052	WC 14	708332	Y 61	716084	HS 8	720243	17-1027
708053	WC 27	708334	Y 53 <sup>8</sup>	716102	HS 20	720246	17-3495
708054	WC 17	708336	19-4950	716103	HS 29	720247	17-4523
708055	WC 14	708432	WC 14	716117	HS 7	720259-2/-3	16-6780

# EMERSON

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
720563	17-6054	734212	24564	738068	FLY 13	738223	FLY 656
720566	17-5027	734215	26553	738069	FLY 13 <sup>3</sup>	738233	FLY 656
720570	17-6061	734221	22586 <sup>1</sup>	738070	26573	738415	Y 105 <sup>8</sup>
720575	17-6062	734223	24561	738071	HS 8	739000	FLY 1
720579	17-6065	734225	24553	738073	FLY 13	750033	16-6758
720580	17-6063	734226	24553	738075	FLY 13	906186-501/-502	Y 245
720582	17-6062	734228	24553	738076	26524	-503/-504/-507	Y 245
720583	17-6064	734248	24506	738078	FLY 202	962159	15-1082
720589	20-1079	735151	FLY 5017	738079	FLY 160	970013	20-1051
730002	22R05 <sup>1</sup>	737002	26C42	738080	26551	970014	19-1008
730005	26R00 <sup>1</sup>	737003	20C49 <sup>1</sup>	738081	26551	970015	17-3414
730018	24R94	737011	20C49 <sup>1</sup>	738082	FLY 13	970016	Y 229
730022	26R21	737012	20C64	738083	FLY 13	970116	Y 229
730023	26R95	737015	20C49 <sup>1</sup>	738084	FLY 160	970241	19-1005
730024	26R65	737016	26C44	738085	FLY 13	970243	19-1001
730026	26R95	737017	26C41	738086	FLY 13	970244	19-1004
730029	26R95	737018	26C93	738087	FLY 202	970383	20-1051
730031	26R95	737019/23	26C80	738090	26A04	970485	22586
730032	26R88	737027	26C77	738091	FLY 89	970706	19-2012
730037	26R88	737028	26C78	738094	FLY 160	970800	Y 229
730039	26R88	737031	26C80	738095	FLY 160	970842	19-3275
730041	26R79	737033	26C77	738096	FLY 89	970844	19-2032
730043	26R88	737036	26C77	738097	26551	970845	19-1008
730044	26R88	737036	26C78	738098	26551	970998	FLY 422
730046	26R79	737038	Y 109	738099	FLY 89	971423	Y 109
730051	21F09	737039	26C77	738100	FLY 89	972026	Y 210
730052	26R88 <sup>1</sup>	737043	26C77	738102	26572	972133	Y 210
730054	21F09	737044	26C77	738103	FLY 141	981289	26C81
730060	26R113	737047	26C77	738105	26572	981292	WC 53
730061	26R113	737048	26C79	738106	FLY 142	981294	19-1008
730062	26R113	737049	26C81	738107	FLY 142	981295	19-7068
730064/65	26R113	737056	26C77	738108	26572	981296	19-2028
730074	26R47	737057	26C81	738109	FLY 141	981297	19-2024
730078	26R116	737058	26C79	738110	26572	981300	26564
730079	26R47	737059	26C81	738111	FLY 142	981328	Y 245 <sup>14</sup>
730094	26R116	738000	FLY 1	738119	FLY 143	981368	WC 41
730108/111	26R116	738003	WC 14	738121	26572	981369	WC 45
730109	26R120	738004	24A88	738122	FLY 143	981387	19-1008
730113	26R113	738005	24A90	738124	26572	981388	19-1008
730114	26R116	738008	24A89	738126	26585	981389	19-7047
730118	26R150	738009	FLY 1	738127	26571 <sup>1</sup>	981398	19-2014
730120	26R150	738010	24586	738128/29	FLY 143	981400	19-3330
730126	26R106	738010-1	24586	738134	26512	981401	20-1058
730129	26R150	738011	26553 <sup>1</sup>	738137	26585	981404	17-3418
730149	26R152	738012	FLY 1	738138/A	FLY 230 <sup>8</sup>	981891	Y 122
730152	21F09	738013	FLY 1	738139	26572 <sup>1</sup>	981920	26C81
734004	22556	738014	FLY 4	738140	FLY 143	981921	20C47
734018	26549	738015	FLY 1	738142/145	FLY 228	981924	FLY 443
734028	24560	738016	24586	738147	26572	981927	19-2016
734044	24550	738017	24586	738150	26572	981938	26549
734051	26549	738019	HVO 50	738152	26585	981981	17-3419
734052	24550	738020	24A89	738153	26572	981985	20-1057
734058	24550	738022	24A89	738154	FLY 229	981989	19-7068
734058-1	24550	738023	24A89	738155	FLY 231	981991	19-2024
734063	24550A <sup>1</sup>	738024	FLY 4	738156	26572	981992	19-3180
734064	24550A	738026	26551 <sup>1</sup>	738158	HS 8	981993	19-3500
734074	26549	738026A	26551 <sup>1</sup>	738159	26572	981996	19-2014
734082	24550 <sup>1</sup>	738027	26551 <sup>1</sup>	738160	FLY 230	981997	19-1006
734084	26548	738028	FLY 1	738161	26585	981998	19-2001
734088	24548	738029	26552	738162	FLY 231	982023	19-2034
734099	24551 <sup>1</sup>	738029-2	26552	738163	FLY 229 <sup>3</sup>	982024	19-7068
734103	24548	738030	24A88	738168	FLY 150	982046	19-2033
734104	24553	738031	24A89	738169	FLY 232	983746	17-3405
734107	24553	738032	26553	738170	26570	983754	19-6033
734122	26558	738032-A	26553	738171	26572	983755	19-2027
734123	24551	738033	26553	738177	FLY 231	983756	19-3640
734126	24564	738034	FLY 46	738180	26575	983757	19-2026
734130	24548 <sup>1</sup>	738035	HS 3	738182	26572	983758	20-1055
734134	24564	738037	HS 8	738186/88	FLY 258	983760	Y 123 <sup>9</sup>
734139	24553	738039	FLY 5	738189	26572	983762	22561
734144	24553 <sup>1</sup>	738042	24A89	738190	FLY 292	983764	26C79
734146	24548	738044	26557	738191	FLY 292	983952	19-1008
734161	24553 <sup>1</sup>	738047	FLY 2	738192	FLY 293	983955	Y 122
734162	24551 <sup>2</sup>	738048	FLY 2	738193	26585	983957	FLY 443
734163	24564 <sup>2</sup>	738048A	FLY 2	738195/A	FLY 277	983972	14-9004
734168	24548	738050	26522	738196	26584	983976	20-1057
734172	24548	738052	26557	738197	FLY 294	983979	19-1006
734176	24548	738053/51	FLY 2	738202A	FLY 295	983981	19-7047
734178	24553	738054	26522	738203	26533	983982	19-2023
734181	24564 <sup>1</sup>	738059	26557 <sup>1</sup>	738206	FLY 293	983992	19-1002
734188	26558 <sup>1</sup>	738060	FLY 8	738210	FLY 293 <sup>3</sup>	986388	16-9035
734195	26543	738065	HS 8	738213	FLY 295	986590	14-9021
734202	26559	738066	26524	738214	FLY 277	986591	16-9033
734205	24548	738067/74	FLY 13	738222A/M	FLY 324	986592	16-9034

# EMERSON

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
986696	16-9030	F 122	FLY 443	R109237	HS 8	R112870	17-1083
986697	16-9031	R77842	19-4073	R109251	HS 32	R112871	17-3420
986698	16-9032	R100037	26548	R109252	17-3418	R112872	17-6028
986701	16-9028	R100131	19-3125	R109253	17-3419	R112873	17-6032
986704	16-9026	R101819	19-3036	R109254	17-3414	R112874	17-6022
986705	16-9027	R102134	26C81	R109257	19-3600	R112875	WC 36
027-033200	Y 148	R102201	19-3060	R109261	20-1052	R112877	17-6033
032-003000	26C78	R103037	19-3375	R109262	17-1083	R112879	17-3414
033-014300	26596	R103137	19-3355	R109263	26586	R113382	FLY 277
033-016200/D	FLY 385	R105065	WC 41	R109264	FC 7	R113383	26R150
750C1089-4	Y 229	R105066	WC 42	R109286	26R150	R113388	19-3600
950C1089-12	Y 229	R105195	26C81	R109457	Y 107	R113390	26586
AT2916	24553	R105196	WC 35	R109826	19-3060	R113394	WC 44
8515-215	FLY 5017	R105213	17-6018	R109838	19-3093	R113547	17-3419
BH-2401	17-5023	R105214	17-6019	R109840	19-3060	R113640	FC 7
BH-2402	17-3423	R105216	17-6011	R109845	Y 107	T79C124-5-1	24583
BH-2404	20-1062	R105294	17-3417	R109850	26586	T 125-020039	22522
BH 2429	19-1002	R105295	20-1057	R112820	FLY 273	T-825	26C81
BH 3012	20-1055	R104383	20-1050	R112821	26586	T-830	20C47
BH 5003	26C79	R107290	17-3402	R112822	26548	T-D81A-JC-25	Y 122
BH 8000	26530	R107837	17-6012	R112829	26C81	T-D81C-JC-25	Y 122
BH 9002	HS 12	R109171	19-1008	R112845	26R150	T-V111	26549
BH 9040	Y 123 <sup>9</sup>	R109180	WC 43	R112866	HS 23		
F 103	FLY 443	R109221	FLY 281	R112869	17-6031		

# FLEETWOOD

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AT92	24596	E7115	24561	TR788	26585	71F044	FLY 173
C2302	26572	E7116	24596	TR98	FLY 291	71F069/-1/-2	24561
CL26215	Y 65	E7213	24552	TR101	FLY 291	71F080	26533
E917	WC 34	E7214	26507	TV111	26548	71F083	FLY 257
E920	WC 11	E7225	Y 47	TW127	24551	71F085-1	26585
E931	24550	E7228	Y 47	TV127	26586	71F118	24506
E932	26578	E7232	FLY 202	TW40	26573	71F119	26586
E947	Y 122	E7267	FLY 16	VZ13054	Y 245	71F122	24506
E983/A	FLY 172	E7339	FLY 202	XL537A	WC 22	85F101	24550
E1759	Y 39	E7342	24551	XL665/A	WC 34	80-48-3	FLY 5059
E1852	WC 22	E7348	Y 65	66F054-3	VMT-03-01	215R1	WC 18
E1947	Y 27	E7357	26507	66F054-4	VMT-03-01	219D1	Y 14
E1948	Y 39	E7482	FLY 5051	66F112-2	VMT-05	520L301	26C91
E1978	26519	E7483	24506	66F112-1	VMT-05	660T301	26R21
E1998	26519	E7484	24551	66F159-1	VMT-08	740T601	FLY 16
E2003	Y 39	E7674/A	Y 68	66F159-2	VMT-08	857	26548
E2548	24561	E8735	FLY 202	66F159-3	VMT-08	994	HS 5
E2644	Y 27	E9271	24551	66F181-1	VMT-05	1044B	26C41
E2661	FLY 202	E9530	Y 6				

# GAMBLE SKOGMO

(SEE CORONADO)

# GENERAL ELECTRIC

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
EA61X11	16-6780	ES36X18	19-2027	ET36X12	19-1001	ET36X177	20-1004
EP36X1	19-1002	ES36X19	19-3660	ET36X15	WC 19	ET36X178	19-3160 <sup>2</sup>
EP36X4	19-2016	ES36X20	17-6066	ET36X16	WC 19	ET36X179	20-1049
EP36X7	19-3036	ES36X21	17-6067	ET36X17	WC 21	ET36X180	HS 5
EP36X8	19-1006	ES36X26	19-2028	ET36X18	WC 18	ET36X184	20-1051
EP36X11	19-7047	ES36X41	19-2026	ET36X19	WC 14 <sup>1</sup>	ET36X191	19-7068
EP36X17	19-2026	ES36X42	19-3000	ET36X20	WC 18 <sup>1</sup>	ET36X194	19-3160
EP36X19	19-3660	ES36X44	19-3114	ET36X21	17-6067 <sup>1</sup>	ET36X200	17-4522
EP36X20	17-6066	ES36X45	19-1002	ET36X22	WC 18	ET36X206	17-3401
EP36X21	17-6067	ES36X48	19-2018	ET36X25	WC 21	ET36X207	17-4534
EP36X24	WC 37	ES36X49	20-1051	ET36X26	WC 22 <sup>1</sup>	ET36X208	20-1049
EP36X25	19-2026	ES36X51	17-3410	ET36X30	19-3036	ET36X215	17-3404
EP36X26	19-3275	ES36X54	19-2028	ET36X47	19-4160	ET36X216	20-1045
EP36X29	19-3660	ES36X55	19-2026	ET36X59	19-3250	ET36X217	20-1044
EP36X30	20-1051	ES36X58	19-1001	ET36X66	19-1002	ET36X218	20-1044
EP36X31	19-1008	ES36X64	19-2018	ET36X69	19-1002	ET36X219	19-7068
EP36X32	19-1050	ES36X67	19-3275	ET36X70	17-4534	ET36X220	19-1005
EP36X33	19-3060	ES36X75	19-2026	ET36X72	17-4502	ET36X224	19-3180 <sup>2</sup>
EP36X43	19-2027	ES36X79	19-7047	ET36X76	19-1920	ET36X233	19-3180 <sup>2</sup>
EP36X45	19-6033	ES36X80	19-3330	ET36X77	19-1921	ET36X234	19-3180 <sup>2</sup>
EP36X46	19-2024	ES36X81	19-2010	ET36X78	17-4502	ET36X235	20-1020
EP36X48	19-4201	ES36X84	19-3036	ET36X79	20-1004	ET36X237	19-3300
EP36X49	19-2028	ES36X89	19-3125	ET36X87	17-4500	ET36X239	19-3100
EP36X83	20-1051	ES36X91	19-2026	ET36X88	20-1049	ET36X240	17-4502
EP36X84	19-3036	ES36X92	19-3330	ET36X89	17-4503	ET36X241	20-1020
EP36X811	17-6068	ES36X93	19-3060	ET36X90	17-4504	ET36X242	HS 5
EP36X812	19-3060	ES36X94	19-1008	ET36X91	19-3250	ET36X243	19-7068 <sup>2</sup>
EP36X813	17-1051	ES36X118	19-3275	ET36X92	17-4538	ET36X244	17-4534
EP36X814	20-1051	ES36X665	20-1051	ET36X94	17-3402	ET36X245	20-1004 <sup>1</sup>
EP61X13	20-1057	ES36X772	19-1001	ET36X95	17-3401	ET36X246	20-1044
EP61X170	17-5036	ES36X772	19-1001	ET36X96	19-4201	ET36X247	20-1049
EP61X173	17-6027	ES36X786	20-1084	ET36X97	19-4201	ET36X248	19-3300 <sup>2</sup>
EP61X174	17-6051	ES36X812	19-2021	ET36X98	17-4523	ET36X251	19-3250
EP61X175	17-6050	ES36X813	17-1051	ET36X101	19-3180	ET36X252	19-4538
EP61X177	17-6069	ES61X1	17-1034	ET36X103	20-1004	ET36X258	17-1038
EP62X37	19-6022	ES61X7	17-3487	ET36X105	19-1005	ET36X259	HS 10
EP63X2	26C80 <sup>1</sup>	ES61X8	17-1072	ET36X106	19-4500	ET36X260	19-1008
EP63X4	26C77	ES61X174	17-6051	ET36X107	19-5100	ET36X261	19-3660
EP63X8	26C81	ES63X1	26C81	ET36X108	19-3250	ET36X262	20-1020
EP63X9	20C137	ES64X100	26558	ET36X109	17-1023	ET36X263	HS 8
EP63X10	20C14 <sup>1</sup>	ES64X102	26586	ET36X110	19-3160 <sup>2</sup>	ET36X264	19-3375
EP63X67	26C77	ES64X111	26538	ET36X111	19-3160	ET36X269	19-1001
EP64X14	26557	ES64X112	26540	ET36X116	17-4534	ET36X271	19-3050
EP64X25	21F08	ES64X113	26557 <sup>1</sup>	ET36X118	19-4121	ET36X272	19-1001
EP64X113	26557 <sup>1</sup>	ES76X2	Y 125	ET36X119	19-3180 <sup>2</sup>	ET36X273	17-4534
EP76X2	Y 233	ES76X4	Y 149	ET36X120	19-3036	ET36X274	20-1049
EP76X6	Y 114	ES76X5	Y 125	ET36X121	17-4538	ET36X275	19-3300
EP76X7	Y 233	ES76X6/-10	Y 253	ET36X122	20-1004	ET36X276	HS 8
EP76X10	Y 232	ES76X17	Y 254	ET36X123	20-1004	ET36X279	19-1001
EP76X11	Y 234	ES76X36	Y 81	ET36X124	19-3180	ET36X281	20-1049
EP76X12	Y 233	ES76X38	Y 81	ET36X125	19-3250	ET36X282	HS 11
EP77X1	FLY 612	ES76X45/49	Y 255	ET36X132	20-1049	ET36X283	19-4400
EP77X2	FLY 642	ES76X48	Y 115	ET36X133	19-3160	ET36X284	19-4950
EP77X4	FLY 641	ES77X2	FLY 642	ET36X134	19-3300	ET36X291	17-1039
EP77X9	FLY 613	ES77X9	FLY 380	ET36X135	19-3036	ET36X292	HS 12
EP77X10	FLY 641	ES77X12	FLY 623	ET36X136	19-3125 <sup>2</sup>	ET36X294	19-3100
EP77X13	FLY 565	ES77X16	FLY 622	ET36X137	19-3250	ET36X295	19-4201
EP77X14	FLY 639	ES77X19	FLY 623	ET36X139	20-1045	ET36X296	19-1001
ER77X15	FLY-641	ES77X89	FLY 642	ET36X140	20-1049	ET36X297	19-1041
EP77X18	FLY 639	ES77X90	FLY 310	ET36X141	17-3401	ET36X300	17-5039
EP77X20	FLY 558	ES77X92	FLY 310	ET36X142	20-1004	ET36X315	17-1098
EP77X21	FLY 606	ET35X18	HS 7	ET36X143	19-3125	ET36X324	HS 14
EP77X22	FLY 607	ET35X24	HS 2	ET36X144	19-3125	ET36X325	17-1040
EP77X23	FLY 640	ET35X25	26A04	ET36X145	20-1049	ET36X326	20-1083
EP77X24	FLY 566	ET35X29	26A02	ET36X146	19-3100	ET36X327	19-1005
EP77X27	FLY 615	ET35X34	HS 5	ET36X147	19-3300 <sup>2</sup>	ET36X328	19-1005
EP77X28	FLY 567	ET35X37	HS 5	ET36X148	19-3250	ET36X329	19-3500
EP77X29	FLY 614	ET36X2	WC 22	ET36X149	19-3125 <sup>2</sup>	ET36X330	HS 13
EP77X31	FLY 638	ET36X3	WC 14	ET36X150	20-1045	ET36X334	HS 15
EP77X32	FLY 638	ET36X4	WC 18	ET36X151	19-3036	ET36X335	17-10099
EP77X89	FLY 642	ET36X5	WC 20	ET36X152	20-1004	ET36X339	19-3250
ES36X5	19-3330	ET36X6	WC 14	ET36X154	20-1049	ET36X344	19-1009
ES36X8	17-1073	ET36X7	WC 14	ET36X157	19-3180	ET36X345	19-4500
ES36X12	19-1001	ET36X8	WC 22	ET36X163	17-3401	ET36X349	HS 13
ES36X16	19-6033	ET36X10	WC 18	ET36X176	20-1004	ET36X352	17-1003

# GENERAL ELECTRIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
ET36X354	17-4536	ET36X695	17-1073	ET61X36	17-5001	ET63X41	26C93
ET36X356	17-4500	ET36X717	19-3375	ET61X37	17-4536	ET63X42	26C44
ET36X358	17-4502	ET36X718	19-3300	ET61X38	17-4536	ET63X44	26C77
ET36X359	17-4500	ET36X722	19-1001	ET61X39	17-4536	ET63X45	26C41
ET36X373	17-4500	ET36X727	HS 30	ET61X43	17-4522	ET63X47	26C41
ET36X375	19-3075	ET36X731	17-1049	ET61X44	17-4523	ET63X48	26C77
ET36X374	19-3300	ET36X732	20-1051	ET61X46	17-4502	ET63X50	26C44
ET36X375	19-3300	ET36X752	19-3300	ET61X47	17-4522	ET63X51	26C79
ET36X376	19-3660	ET36X758	19-2027	ET61X48	17-4522	ET63X52	26C79
ET36X379	17-5040	ET36X778	17-1037	ET61X62	17-4522	ET63X53	20C64
ET36X381	19-1000	ET36X786	20-1084	ET61X65	17-4522	ET63X54	26C64
ET36X382	17-5041	ET36X787	WC 41	ET61X66	16-3445	ET63X55	26C79
ET36X383	17-1007	ET36X789	WC 68	ET61X68	17-4523	ET63X56	26C79
ET36X386	19-2003	ET36X792	HS 14	ET61X71	17-4536	ET63X57	26C79
ET36X387	19-1015	ET36X793	20-1066	ET61X72	17-5014	ET63X58	26C79
ET36X88	WC 74	ET36X795	17-6070	ET61X73	17-5014	ET63X59	26C81
ET36X400	19-3036	ET36X796	19-1003	ET61X74	17-5034	ET63X60	26C41
ET36X401	19-1005	ET36X804	19-1002	ET61X75	17-5042	ET63X61	26C79
ET36X402	HS 16	ET36X811	17-6068	ET61X80	17-5014	ET63X62	26C81
ET36X405	17-1008	ET36X812	19-3020	ET61X81	17-5014	ET63X63	26C79
ET36X409	WC 74	ET36X813	17-1051	ET61X82	17-5014	ET63X64	26C80
ET36X410	19-3125	ET36X814	20-1051	ET61X83	17-5043	ET63X65	26C78
ET36X411	19-4201	ET36X818	17-1101	ET61X86	17-5042	ET63X67	26C79
ET36X413	19-2001	ET36X820	WC 38	ET61X87	17-5044	ET64X1	21F08 <sup>1</sup>
ET36X415	HS 16	ET36X836	WC 53	ET61X93	17-5045	ET64X2	26563
ET36X420	19-1005	ET36X854	17-1049	ET61X95	17-5046	ET64X3	21F08 <sup>1</sup>
ET36X424	19-3250	ET36X861	19-2019	ET61X96	17-3419	ET64X5	26A03
ET36X425	19-3250	ET36X875	19-3300	ET61X99	17-5047	ET64X7	24586 <sup>1</sup>
ET36X427	19-1004	ET37X4	15-1083	ET61X100	17-5035	ET64X8	26549
ET36X433	19-3100	ET37X5	15-1083	ET61X101	17-5048	ET64X9	26509
ET36X435	17-1042	ET37X6	15-1083	ET61X104	17-5049	ET64X12	26548
ET36X436	HS 13	ET37X7	15-1083	ET61X105	17-5035	ET64X13	24586 <sup>1</sup>
ET36X447	HS 13	ET37X8	15-1084	ET61X106	17-5050	ET64X14	26553
ET36X448	20-1051	ET37X9	15-1089	ET61X107	17-5035	ET64X15	24550 <sup>1</sup>
ET36X536	19-1008	ET37X11	15-1089	ET61X110	16-6758	ET64X16	26553
ET36X537	WC 35	ET37X12	15-1091	ET61X111	16-6758	ET64X17	26549
ET36X538	HS 8 <sup>1</sup>	ET37X13	15-1090	ET61X115	17-1102	ET64X18	24586 <sup>1</sup>
ET36X539	19-3060	ET37X14	15-1092	ET61X118	17-1014	ET64X19	24550 <sup>1</sup>
ET36X540	20-1058	ET37X16	15-1093	ET61X120	17-3402	ET64X20	24553
ET36X541	19-1001	ET37X23	15-1093	ET61X121	20-1057	ET64X21	26550
ET36X543	20-1052	ET37X25	15-1093	ET61X124	17-1083	ET64X22	26549
ET36X544	19-3060	ET37X28	15-1093	ET61X125	17-3418	ET64X23	26550
ET36X547	19-1010	ET51X5	HS 2 <sup>1</sup>	ET61X126	17-3419	ET64X24	26C41
ET36X548	19-3060	ET51X7	24A88 <sup>1</sup>	ET61X127	17-3418	ET64X25	26553 <sup>1</sup>
ET36X548	19-3125	ET51X8	16-3445	ET61X128	17-3417	ET64X27	26A04
ET36X549	HS 32	ET51X24	WC 45	ET61X129	17-6018	ET64X28	26550
ET36X550	17-6011	ET56X14	17-4532	ET61X130	17-6019	ET64X30	26552 <sup>1</sup>
ET36X553	WC 41	ET56X22	17-3493	ET61X131			

# GENERAL ELECTRIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
ET64X73	26F68	ET77X23	FLY 90	ET105X41	17-3494	EU77X10	FLY 617
ET64X75	26S49	ET77X24	FLY 102	ET105X44	16-6758	EU77X11	FLY 356
ET64X76	24S96	ET77X26	FLY 112	ET105X45	16-3487	EU77X12	FLY 558
ET64X77	26S03	ET77X27	FLY 104	EU36X2	19-2018	EU77X13	FLY 356
ET64X80	26S50	ET77X28	FLY 105	EU36X3	20-1055	EU77X14	FLY 356
ET64X81	26S48	ET77X29	FLY 105	EU36X4	19-2026	EU77X15	FLY 624
ET64X84	26S06	ET77X30	FLY 94	EU36X6	17-6070	EU77X20	FLY 558
ET64X85	26S53	ET77X31	FLY 107	EU36X7	17-6022	EU77X88	FLY 624
ET64X87	26S86	ET77X32	FLY 108	EU36X8	17-5051	EU77X99	FLY 356
ET64X90	24S49	ET77X33	FLY 94	EU36X10	WC 78	EU77X102	FLY 356
ET64X92	24S53	ET77X35	FLY 107	EU36X261	19-3660	EU77X106	FLY 356
ET64X93	26S55 <sup>1</sup>	ET77X37	FLY 144	EU36X376	19-3660	EU77X110/111	FLY 558
ET64X94	24S115	ET77X38	FLY 166	EU36X433	19-3100	EU77X112	FLY 356
ET64X95	22S21	ET77X39	FLY 145	EU36X536	19-1008	EU77X115	FLY 616
ET64X97	26S48	ET77X40	FLY 167	EU36X537	WC 35	EU77X116	FLY 617
ET64X98	26S34	ET77X41	FLY 233	EU36X538	WC 18	G185462K	FLY 86
ET64X99	26S35	ET77X42	FLY 177	EU36X540	10-1058	K63J132-1	26R92
ET64X100	26S58	ET77X43	FLY 178	EU36X543	20-1052	K63J134-1	22S93
ET64X102	26S86	ET77X44	FLY 178	EU36X547	19-3060	K63J135-1	20C54 <sup>1</sup>
ET64X103	24S53	ET77X45	FLY 234	EU36X549	HS 32	K65J435	24S86 <sup>1</sup>
ET64X104	24S36	ET77X46	FLY 235	EU36X550	17-6017	K65J436	20C65 <sup>1</sup>
ET64X106	26S34	ET77X47	FLY 178 <sup>3</sup>	EU36X552	19-3660	K65J437	20C64 <sup>1</sup>
ET64X109	26S58	ET77X48	FLY 178	EU36X553	WC 41	K65J438	26S49
ET64X111	26S38	ET77X64	FLY 178	EU36X555	WC 43	K66J301	26C45 <sup>1</sup>
ET64X112	26S40	ET77X66	FLY 281	EU36X558	FC 7	K66J691	26S49
ET64X113	26S57	ET77X67	FLY 296	EU36X583	19-3036	K67J23	26S49
ET64X114	26S39	ET77X68	FLY 178	EU36X635	19-3075	K67J460-1	24S51
ET64X116	26S41	ET77X69	FLY 297	EU36X637	HS 23	K68J13	26S48
ET76X5	Y 125	ET77X71	FLY 298	EU36X639	17-6022	K68J41-1	26S49
ET76X6	Y 27	ET77X72	FLY 299	EU36X640	WC 40	K68J294	20C64
ET76X7	Y 233	ET77X73	FLY 273	EU36X655	20-1050	K68J295	20C64
ET76X10	Y 28	ET77X74	FLY 298	EU36X691	WC 44	K68J297	24S86 <sup>1</sup>
ET76X11	Y 29	ET77X76	FLY 299	EU36X694	19-3600	K68J420	26R18
ET76X12	Y 30	ET77X77	FLY 5048	EU36X727	HS 30	K68J420-2	26R18
ET76X13	Y 30	ET77X78	FLY 277	EU36X787	WC 41	K68J436	24S86 <sup>1</sup>
ET76X14	Y 31	ET77X79	FLY 277	EU36X789	WC 68	K68K489	26S53
ET76X16	Y 32	ET77X80	FLY 301	EU36X793	17-1030	K68K489-1	26S53
ET76X17	Y 34	ET77X81	FLY 302	EU36X794	19-3075	K68J490-1	24S50 <sup>1</sup>
ET76X19	Y 32	ET77X82	FLY 302	EU36X795	17-6070	K68J640	26R71
ET76X20	Y 33	ET77X83	FLY 303	EU36X804	19-1002	K68J842	26S53
ET76X21	Y 21	ET77X86	FLY 300	EU36X820	WC 38	K69J88	26C41
ET76X22	Y 33	ET77X88	FLY 624	EU36X836	WC 53	K69J91-1	26S50
ET76X23	Y 33	ET77X89	FLY 642	EU51X24	WC 45	K69J91-2	26S50
ET76X24	Y 14 <sup>3</sup>	ET77X90	FLY 310	EU56X1	20-1055	K69J91-3	26S50
ET76X26	Y 51	ET77X91	FLY 324	EU56X57	20-1050	K69J91-4	26S50
ET76X28/29	Y 80	ET77X92	FLY 310	EU56X58	20-1050	K69J91-5/-6	26S50
ET76X31	Y 80	ET77X93	FLY 324	EU56X61	20-1061	K69J367-1	26C92 <sup>1</sup>
ET76X32	Y 107	ET77X94	FLY 335	EU61X1	20-1057	K69J449	26R18
ET76X33	Y 81	ET77X95	FLY 300	EU61X2	17-3419	K69J620	24S50 <sup>1</sup>
ET76X35	Y 81	ET77X96	FLY 335	EU61X3	17-3419	K69J673	24A88 <sup>1</sup>
ET76X36/37	Y 81	ET77X98	FLY 310	EU61X7	17-6031	K69J681	26C44 <sup>1</sup>
ET76X38	Y 81	ET77X99	FLY 356	EU61X120	17-3402	K69J682	26C43 <sup>1</sup>
ET76X39	Y 81	ET77X102	FLY 356	EU61X121	20-1057	K71J87-1	26S49
ET76X39/-2	Y 81	ET77X108	FLY 335	EU61X124	WC 45	K71J129	24S53
ET76X39/-3/-4	Y 81 <sup>8</sup>	ET77X110	FLY 558	EU61X125	17-3418	K71J129-1	24S53
ET76X41	Y 115	ET77X111	FLY 558	EU61X126	17-3419	K71J363	FLY 3
ET76X42	Y 114 <sup>11</sup>	ET77X112	FLY 356	EU61X127	17-3414	K71J417	24S51
ET76X44/46	Y 114 <sup>11</sup>	ET77X114	FLY 335	EU61X128	17-3417	K71J631	20C53
ET76X45/49	Y 255	ET77X115	FLY 616	EU61X129	17-6018	K71J631-1	20C53
ET76X47	FLY 178 <sup>3</sup>	ET77X116	FLY 617	EU61X140	17-6031	K71J811-1	26C41
ET76X48	Y 115	ET88X5	26R18	EU61X142	17-3420	K71J844-1	26A04
ET76X51	Y 81	ET88X6	26R18	EU61X143	17-6028	K71J844-2	26A04
ET76X52	Y 81	ET88X7	26R18	EU61X144	17-6032	K71J844-3	26S53 <sup>1</sup>
ET76X56	Y 81	ET88X8	26R18	EU61X145	17-6033	K82J1154-1	FLY 3
ET77X2	FLY 3	ET88X9	26R18	EU61X146	17-3414	K82J1154-2	FLY 3
ET77X3	FLY 3	ET88X16	26R88	EU61X153	17-1083	K82J182-1	20C49
ET77X4	FLY 3	ET88X17	26R71	EU61X155	17-3414	K82J363	21F08 <sup>1</sup>
ET77X5	FLY 3	ET88X20	26R92	EU61X179	17-3419	K83J374-1	26S52 <sup>1</sup>
ET77X6	FLY 3	ET88X23	26R91	EU61X180	17-3414	K83J542-1	26C44 <sup>1</sup>
ET77X7	FLY 3	ET88X24	26R39	EU63X1	26C78	K83J999-4	26S49
ET77X9	FLY 49	ET88X25	26R40	EU64X1	26S86	K109J2-4	24S51
ET77X10	FLY 49	ET88X27	26R41	EU64X97	22S25	K109J2-4-7	24S51
ET77X11	FLY 49	ET88X36	26R47	EU76X1 THRU -8	Y 114	K109J2-6	24S51
ET77X12	FLY 49	ET88X46	26R122	EU76X9/-10	Y 114	K115J217-1	26S19
ET77X13	FLY 49	ET88X52	26R122 <sup>1</sup>	EU76X11	Y 114	K115J630-11	26C41
ET77X15	FLY 5	ET88X61	26R150	EU76X32	Y 107	K115J857-2	26A02
ET77X16	FLY 86	ET88X66	26R10 <sup>3</sup>	EU76X42/-44	Y 114	K118J224-2	FLY 145
ET77X17	FLY 86	ET88X67	26R122 <sup>3</sup>	EU76X46/-47	Y 114	K119J15	26R88
ET77X18	FLY 87	ET88X74	26R105	EU77X3	FLY 624	K119J17	26C91
ET77X19	FLY 87	ET88X76	26R150	EU77X5	FLY 356	K119J18-1	26C44
ET77X20	FLY 88	ET88X77	26R150	EU77X6	FLY 558	K121J900	26S58
ET77X21	FLY 19	ET88X79	26R106 <sup>1</sup>	EU77X7	FLY 356	K128J68-3/-4	26C41
ET77X22	FLY 90	ET88X85	26R150	EU77X8	FLY 356	K129J26	26R92
		ET105X24	19-1001	EU77X9	FLY 616	K129J27	26R72

# GENERAL ELECTRIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
K129J91	26S54	M8530738	FLY 148	R6765	FLY 5044	RLD-074	Y 14 <sup>3</sup>
K132J30-1	26A03	M8530739	Y 25	R6831	FLY 5048	RLD-075	Y 33
K138J72-1	26S73 <sup>1</sup>	M8530772-1/		R6854	Y 81	RLD-076	Y 14 <sup>3</sup>
K138J73-1	24S60 <sup>1</sup>	2/-3	Y 25	R6931	Y 65	RLD-080	Y 51
K142J98	26R40	M8531387	FLY 104	R7050	Y 81	RLD-091	HS 7
K144J26	26R39	M8531395	Y 33	R7085	FLY 5044	RLF-005	20C65 <sup>1</sup>
K148J27-1	22S48	M8531396-1	Y 33	R7092	FLY 5044	RLF-006	20C64 <sup>1</sup>
K148J27-2	22S48	M8531430	Y 10	R7118	Y 81	RLF-010	20C54 <sup>1</sup>
K148J53-4	26C41	M8533282	FLY 107	R7294	Y 81	RLF-011	26C45 <sup>1</sup>
K149J79-1	26A02	M8533330	Y 27	R7434	Y 81	RLF-018	20C64
K149J80-1	26R41	M8533332-1	FLY 105	R7575	FLY 5044	RLF-019	20C64
K188J46-1	26R71	M8533372-1	Y 68	R7652	FLY 145	RLF-024	19-3036
K853205-1	FLY 3	M8533373-1/2	FLY 148	R7722	Y 115	RLF-031	26C43 <sup>1</sup>
M76J102	19-1001	M8533380-1/2	FLY 148	R7870	FLY 310	RLF-032	26C44 <sup>1</sup>
M76J505-2	19-3036	M8533382	FLY 107	R8369	Y 114	RLF-040	20C53
M76J581-1	HS 2 <sup>1</sup>	M8533386-1	Y 65	R8389	FLY 5055	RLF-042	FC 3
M76J582-3	WC 14	M8533489-1/3	Y 65	R8511	FLY 356	RLF-045	26C91
M76J595-3	Y 27	M8533493-1	Y 65	R8512	FLY 356	RLF-047	FC 3
M77J1	FLY 3	P74J18-2	26C41	R8624	Y 115	RLF-048	26C44
M77J1-1	FLY 3	P74J590-1	FLY 3	R8639	Y 114	RLF-051	26C78
M77J1-2	FLY 3	P74J615	FLY 3	R8787	FLY 310	RLF-056	26C78
M77J1-4	FLY 3	P74J615-2	FLY 3	R9438	Y 114	RLF-061	26C91
M77J1-7	FLY 3	P74J615-6	FLY 3	R9506	Y 115	RLF-062	26C44
M77J1-13	FLY 3	P74J616-6	FLY 3	R9724	FLY 310	RLF-068	26C41
M77J1-15	FLY 3	P79J893-1	Y 34	RLA-036	15-1083	RLF-069	26C93
M77J1-16	FLY 5	P126J302-2	26R10 <sup>3</sup>	RLA-037	15-1083	RLF-070	26C78
M77J2-8	Y 27	P126J486-1	26R105	RLA-040	15-1083	RLF-072	26C77
M77J4-1	WC 14	P126J580-1	26R106 <sup>1</sup>	RLA-041	15-1083	RLF-073	26C41
M77J4-2	WC 14	P126J717-4	Y 107	RLA-042	15-1083	RLF-074	26C77
M77J4-3	WC 14	R1057	FLY 86	RLA-043	15-1089	RLF-075	26C41
M77J4-4	WC 18	R1303	Y 27	RLA-045	15-1089	RLF-076	26C77
M77J4-5	WC 22	R1344	FLY 3	RLA-046	15-1091	RLF-078	26C41
M77J4-13	WC 18	R1372	FLY 86	RLA-047	15-1090	RLF-079	26C79
M77J5-1	HS 7	R1859	Y 33	RLA-050	15-1092	RLF-080	26C79
M77J11-8	Y 27	R1920	FLY 104	RLA-053	15-1093	RLI-005	19-1001
M77J11-17	Y 29	R2101	Y 33	RLC-091	HS 7	RLI-008	19-4160
M77J11-20	Y 30	R2102	Y 33	RLC-102	HS 2	RLI-042	19-1002
M77J11-22	Y 27	R2139	FLY 104	RLC-103	26A04	RLI-055	HS 5
M77J11-23	Y 30	R2217	FLY 107	RLC-107	HS 2	RLI-059/60	20C64
M77J11-25	Y 30	R2503	Y 25	RLC-108	26A04	RLI-063	19-1002
M77J13-2	FLY 49	R2581	FLY 107	RLC-125	HS 7	RLI-068	19-3250
M77J13-3	FLY 49	R2601	Y 25	RLC-137	26A02	RLI-069	19-1002
M77J14-1	FC 3	R2622	Y 33	RLD-005	WC 22	RLI-085	19-3160
M77J14-2							

# GENERAL ELECTRIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
RLI-183	19-3180	RLI-379	17-1039	RTL-195	17-5014	RTO-159	26529
RLI-184	19-3250	RLI-380	HS 12	RTL-198	17-5034	RTO-161	FLY 112
RLI-192	20-1049	RLI-382	19-3100	RTL-208	17-5014	RTO-162	26573 <sup>1</sup>
RLI-193	19-3160	RLI-383	19-4201	RTL-209	17-5014	RTO-163	24560 <sup>1</sup>
RLI-194	19-3300	RLI-384	19-1001	RTL-214	17-5014	RTO-165-1	FLY 105
RLI-195	19-3036	RLI-386	19-1041	RTL-215	17-5043	RTO-166	FLY 104
RLI-196	19-3125 <sup>2</sup>	RLI-413	17-1098	RTL-220	17-5044	RTO-166-5	FLY 104
RLI-197	19-3250	RLI-424	HS 14	RTM-003	HS 21	RTO-167	26552
RLI-200	20-1045	RLI-425	17-1040	RTM-007	24A88 <sup>1</sup>	RTO-168	24548
RLI-201	29-1049	RLI-426	20-1083	RTM-008	16-3445	RTO-169	24561
RLI-202	17-3401	RLI-428	19-1005	RTO-016	24586 <sup>1</sup>	RTO-170	24561
RLI-203	20-1004	RLI-429	19-1005	RTO-017	26549	RTO-173	FLY 105
RLI-204	19-3125	RLI-430	19-3500	RTO-020	FLY 3	RTO-174	FLY 104
RLI-205	19-3125	RLI-431	HS 13	RTO-026	22593	RTO-175/-33	FLY 94
RLI-206	20-1049	RLI-439	HS 15	RTO-027	26549	RTO-178	22598
RLI-207	19-3100	RLI-440	17-1099	RTO-029	FLY 3	RTO-179/-4	FLY 107
RLI-208	19-3300 <sup>2</sup>	RLI-445	19-3250	RTO-035	26549	RTO-180	26552
RLI-209	19-3250	RLI-456	HS 13	RTO-051	24551	RTO-181	24551
RLI-210	HS 5	RLP-010	17-1003	RTO-052	26548	RTO-183	FLY 108
RLI-212	19-3125 <sup>2</sup>	RLP-011	17-1003	RTO-053	24586 <sup>1</sup>	RTO-184	26525
RLI-213	20-1045	RLP-012	17-1003	RTO-054	FLY 3	RTO-187	FLY 94
RLI-214	19-3036	RLP-013	17-1003	RTO-058	FLY 3	RTO-189	26506
RLI-215	20-1004	RLP-014	17-1003	RTO-059	FLY 3	RTO-190	FLY 108
RLI-217	20-1049	RLP-016	17-4536	RTO-060	FLY 3	RTO-192	26A02 <sup>1</sup>
RLI-220	19-3180	RLP-018	17-4502	RTO-061	26553	RTO-193	26506
RLI-226	17-3401	RLP-019	17-4500	RTO-062	24550 <sup>1</sup>	RTO-194	26549
RLI-228	16-3445	RLP-020	17-4502	RTO-064	26553	RTO-196	FLY 144
RLI-241	19-7068	RLP-021	17-4500	RTO-066	26550	RTO-197	26549
RLI-243	20-1004	RLP-022	17-4500	RTO-067	FLY 3	RTO-198	26552 <sup>1</sup>
RLI-244	20-1004	RLT-001	FLY 3	RTO-068	FLY 3	RTO-207	FLY 166
RLI-245	19-3160 <sup>2</sup>	RLT-002	FLY 3	RTO-071	FLY 3	RTO-208	FLY 145
RLI-246	20-1049	RLT-003	FLY 3	RTO-072	24550	RTO-209	26530
RLI-247	HS 5	RLT-004	FLY 3	RTO-073	26549	RTO-210	24548
RLI-260	19-7068	RLT-005	FLY 3	RTO-074	24586 <sup>1</sup>	RTO-212	26506
RLI-263	19-3160	RLX-024	19-3036	RTO-076	FLY 3	RTO-213	24553
RLI-269	17-4522	RLX-042	17-4523	RTO-077	24550 <sup>1</sup>	RTO-214	FLY 167
RLI-270	19-3300	RTD-006	17-3494	RTO-080	FLY 3	RTO-215	26A02
RLI-277	17-3401	RTD-008	17-3493	RTO-081	24553	RTO-216	26506
RLI-278	17-4534	RTD-011	17-1033	RTO-082	26550	RTO-217	26549
RLI-279	20-1049	RTD-012	17-1033 <sup>2</sup>	RTO-084	26549	RTO-2141-11	FLY 167
RLI-280	16-3445	RTD-013	17-1033 <sup>2</sup>	RTO-085	FLY 3	RTP-014	17-1033 <sup>2</sup>
RLI-291	20-1004	RTD-014	17-1033 <sup>2</sup>	RTO-086	26550	RTP-035	26R92
RLI-292	20-1045	RTD-015	17-1033 <sup>2</sup>	RTO-088	FLY 3	RTP-062	26R18
RLI-293	20-1044	RTD-018	17-1033 <sup>2</sup>	RTO-089	24551	RTP-066	26R18
RLI-294	20-1044	RTD-020	17-3474	RTO-090	FLY 3	RTP-300	26R18
RLI-295	19-7068	RTD-021	17-3497	RTO-092	FLY 3	RTP-301	26R18
RLI-296	19-1005	RTD-023	17-3497 <sup>2</sup>	RTO-096	26C41	RTP-315	26R88
RLI-300	19-3180 <sup>2</sup>	RTD-024	17-3474	RTO-097	26553 <sup>1</sup>	RTP-318	26R71
RLI-301	19-1001	RTD-025	17-3475	RTO-101	FLY 49	RTP-321	26R92
RLI-310	19-3180 <sup>2</sup>	RTD-026	17-3476	RTO-103	26A04	RTP-322	26R72 <sup>1</sup>
RLI-311	19-3180 <sup>2</sup>	RTD-027	17-3459	RTO-104	FLY 49	RTP-325	26R71 <sup>1</sup>
RLI-312	20-1020	RTD-030	17-3458	RTO-105	26550	RTP-326	26R39
RLI-315	19-3300	RTD-032	17-3476	RTO-109	FLY 49	RTP-327	26R40
RLI-317	19-3100	RTF-002	21F09	RTO-114	FLY 49	RTP-331	26R41
RLI-319	17-4502	RTF-003	26563	RTO-116	FLY 5	T-D78	Y 149
RLI-320	20-1020	RTF-004	21F08 <sup>1</sup>	RTO-117	26552 <sup>1</sup>	WT76X27	Y 80
RLI-321	HS 5	RTL-043	16-6767	RTO-120	24551	WT76X28	Y 80
RLI-322	19-7068 <sup>2</sup>	RTL-054	16-6758	RTO-121	26529	WT76X31	Y 80
RLI-323	17-4534	RTL-066	26C79	RTO-123	24551	WT76X33	Y 80
RLI-324	20-1004 <sup>1</sup>	RTL-078	16-6758	RTO-124	24551	23B210061-1	26S71
RLI-325	20-1044	RTL-080	16-3487	RTO-125	FLY 86	23B210061-3	26S57 <sup>1</sup>
RLI-326	17-4538	RTL-085	17-1012	RTO-126	FLY 86	23B210136-1	26S39
RLI-327	19-3660	RTL-090	17-1011	RTO-127	FLY 86	23B210540-1	Y 114
RLI-328	19-3300 <sup>2</sup>	RTL-096	26C79	RTO-129	FLY 87	23B215010-1	26C78
RLI-331	19-3250	RTL-118	17-4535	RTO-130	FLY 87	23C220058-1	26S40
RLI-331	19-3250	RTL-119	17-4500	RTO-131/-132	FLY 88	23C220310-1	26S41
RLI-332	17-4538	RTL-120	16-3445	RTO-134	24551	23C220534-1	Y 81
RLI-338	17-1038	RTL-125	17-5003	RTO-135	26549	23C220722-2	26S86
RLI-339	HS 12	RTL-126	17-5001	RTO-136	26529	23C220771-1	Y 114
RLI-340	19-1004	RTL-127	17-4536	RTO-139	24551	23C220771-9	Y 114
RLI-342	19-3660	RTL-137	17-4536	RTO-140	24551	23D230065-5	FLY 324
RLI-343	20-1020	RTL-138	17-4536	RTO-141	FLY 88	73B140414-2	26C80 <sup>1</sup>
RLI-344	HS 8	RTL-144	17-4522	RTO-142	26529	73C182902-2	20C141
RLI-345	19-4400	RTL-145	17-4523	RTO-146	FLY 19	73D220359-2	Y 232
RLI-350	19-1001	RTL-147	17-4502	RTO-146-3	FLY 19	73D220466-1	Y 234
RLI-352	19-3500	RTL-153	17-4522	RTO-148	FLY 19	73D220500-1	Y 233
RLI-353	19-1001	RTL-155	17-4522	RTO-149	FLY 90	73C482163-2	26C81
RLI-354	17-4534	RTA-035	26A03	RTO-149-1	FLY 90	83J270	26S63
RLI-360	19-1001	RTL-175	17-4522	RTO-150	FLY 90	83J284/-2	26S70 <sup>1</sup>
RLI-363	17-1098	RTL-178	17-4522	RTO-151-3	FLY 102	83J284-4	26S70 <sup>1</sup>
RLI-364	20-1049	RTL-180	16-3445	RTO-153	24560 <sup>1</sup>	83J374-2	26S71 <sup>1</sup>
RLI-365	HS 11	RTL-186	17-4523	RTO-154	26554	83J374-2	24S51
RLI-365	19-4400	RTL-192	17-4536	RTO-155	26524	109J2-3	24S51
RLI-368	19-4950	RTL-194	17-5014	RTO-156	26549	113C6708	FLY 5044

# GENERAL ELECTRIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
113C6711/-1	FLY 5044	126J302-2	26S19	134J74-2	26S73	947C386	FLY 178
113C6714	Y 81	126J377-3/-4	26S86	143J53-1	26S52	947C388	FLY 178
113C6800-1	Y 81	127C8004-1	Y 115	144C583-1	FLY 145	947C404-1/-2/-3	Y 81
113C6809	FLY 5044	127C8061	Y 115	144J45-1	24561		
113C6818	FLY 145	127J387-1	26R150	152B568	Y 65	947C414	FLY 178
113C6851	FLY 310	128J68-1	26C41 <sup>1</sup>	152B868	Y 65	947C423-1	FLY 178
113C6866	Y 115	128J68-1/-2/-3	26C41	152B899	Y 65	947C445	Y 81
113C6916	FLY 5055	-3	26C41	783B700	FLY 148	947C504	FLY 5044
113C6997-4	FLY 310	128J127-2	26S34	783B720	Y 65	947C463-1	FLY 5048
115J217-2	26S10	128J180-1	26S35	783B738-1	FLY 148	1084	VMT-05
115J857-1	26A02 <sup>1</sup>	128J232-2	24549	783B771-1/-2	Y 80	1086	VMT-05
117J972	FLY 145	128J532-3/-4	26S34	783B777	Y 80	906152-501	FLY 277
123J827-1	26C44 <sup>1</sup>	128J630-1	24S36	783B791-1/-2	Y 80	906153-501	26R150
123J829-1	24553	132J21-1	26S49	783B794-1/-2	Y 80		
124J866-4	26C81	134J74-1	26S73	947C303-1/-2	FLY 178		

# GRUNDIG MAJESTIC

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
A-1486-10	WC 11	C-1.522-2	19-4400	C-9.225A	20C48	C-9.254-3J	Y 7
A-1651-13	26C94	C-1.522-3	19-3180	C-9.226	24S180	C-9.254-3L	Y 7
A-1652-13	26S51	C-1.522-4	19-3125	C-9.228-3	26S51	C-9.255	20C48
A-1654-13	26S49	C-1.522-5	19-3125	C-9.228-3	26S51	C-9.255A	26C42
A-6661-13	26A03	C-1.528-1	17-3497	C-9.228-4	26S51	C-9.259	FLY 49
B-1.458	WC 11	C-1.529	17-3402	C-9.228-5	26S51	C-9.259-1	FLY 49
B-1.459	WC 14	C-1.529-1	20-1005	C-9.228-6	26S51	C-9.271	FLY 16
B-1.519	HS 5	C-1.529-2	17-3402	C-9.230-2	26A03	C-9.381-1	26C44
B-1.530	HS 6	C-1.542-1	17-3488	C-9.230-3	26A03	C-9.384	21F12
B-1.531	WC 22	C-1.549	HS 3	C-9.230-4	26A03	C-9.385-2	24S30
B-1.533/-1/2	WC 14	C-1.552	17-3497	C-9.230-5	26A03	C-30.320	FLY 50
B-1.549	HS 3	C-1.552-1	17-3497	C-9.234-1	FC 2	D-9.228-5	26S51
B-1.553	WC 14	C-1.553	17-1063	C-9.234-2	FC 1	D-9.228-6	26S51
B-1553-1	WC 14	C-1.554	17-3402	C-9.234-4	FC 2	D-9.235	26R19
B-1450-9	Y 5	C-1.555	20-1004	C-9.237	26C93	D-9.246	Y 5
B-1452-9	Y 5	C-1.707	17-3495	C-9.237-2	26C93	D-9.248/-1	22R06
B-1651-10	26C94	C-1.709	17-3495	C-9.237-3	26C93	D-9.248A	22R05U
B-1653-13	245177	C-1.710	17-1031	C-9.240-1	FLY 1	D-9.252	26R92
C-1.445-2	16-6758	C-1.746	17-1066	C-9.241	26549	D-9.252A	26R92
C-1.445-3	16-6758	C-9.201	24R40	C-9.241-2	26550	D-9.253	Y 7
C-1.445-6	16-6758	C-9.209	Y 1	C-9.242	Y 5	D-9.255	20C48
C-1.458	WC 11	C-9.213	24A88	C-9.243	FC 5	D-9.260/-D	26R136
C-1.459	WC 14	C-9.221	26S51	C-9.244	FLY 5	D-9.270	Y 14
C-1.476	17-1066	C-9.223	26C89	C-9.251	FLY 49	D-9.382-1	Y 18
C-1.509-1	16-3445	C-9.224	20C184	C-9.253/-1	FLY 49	D-9.383-1	FLY 160
C-1.520	WC 14	C-9.22					

# HITACHI

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
2073A3-1	Y 125	353017	Y 245 <sup>14</sup>	453111	24504	2160242	WC 44
321403	20-1005	358054	WC 22	453114	26549	2160343	WC 45
321909	17-4524	358068	HS 7	453117	24564	2160352	WC 41
321911	17-4524	358090	HS 7	453118	24508	2220021	26C81
321922	17-4534	358123	WC 45	455035	26S11	2440011	Y 121
323906	20-1049	423016	26C77	0358123	WC 45	2440062NLA	Y 109
325024	17-3477	423020	26C77	0358134	WC 41	2440151	Y 125
352028	Y 81	453123	22586	0423020	26C77	2440152	Y 125
352039	Y 86	424027	26C81	0453111	24504	2440164	Y 245 <sup>14</sup>
352041	Y 86	424028	26C81	0453118	24508	2440651	Y 157
352058	Y 81	453074	24504	0453123	24504		

# HOTPOINT

(SEE GENERAL ELECTRIC)

# MAGNAVOX

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
32A007-1	26530	300077-1	26R51	320058-2	26C80	320130-5/5P/	
32A022-1	26571	300077G-1	26R51	320058-2B	26C80	-16	24561
32B009-1	22532	300078-1/2	22R04	320058X-2	26C80	320135-1	26571
32B010-1	26573 <sup>1</sup>	300079G-1	26R137	320058-3	26C80	320141-1	24553
32B011-1	26549	300091-1	26R121	320058-4	26C80	320142-1	26508 <sup>1</sup>
36A001-9	19-1050	300093-1	26R51	320059-2	26R85	320143-1	26C77
36A001-10	19-1052	300099-1	26R121	320060-1	26S51	320144-1	24560 <sup>1</sup>
36A001-14	Y 125	300170-1	26R51	320060-3	26A04	320144-2	22561 <sup>1</sup>
36A023-5	20-1055	300171	26R127 <sup>1</sup>	320061-1/3	FLY 246	320147-1	26572
36A023-6	17-1085	300173-1	26R33	320063-1	26549	320147-2	26571
36A023-8	20-1051	300178-1	22R05U	320064-1	26C78	320148-2	26C31 <sup>1</sup>
36A023-13	19-2028	300179-01/1	26R127	320065-2	26C79	320232-3	26C81
36A023-14	19-6022	300179-10	26R127	320065-2B	26C79	320232-4	20C137
36A023-16	19-1030	300186-1	26R106 <sup>1</sup>	320066-1	26S53	320232-6	20C137
36A023-18	20-1051	300187-1	26R106 <sup>1</sup>	320067-1	26S54	320232-12	20C137
36A023-19	19-1001	300192-1	26R31 <sup>1</sup>	320067-2	26S54	320251-1/2	24553
36A036-1	19-1008	300208-1	26R150	320068-1	26S50	320254-1/3	26554
36A036-10	19-3275	300218-1	26R150	320068-2	26S50	320255-1/2	26581
36A037-1	Y 86 <sup>9</sup>	300226-1	26R150	320068-2B	26S50	320255-3/4	26581
36A040-29	19-2026	300251-1/5	26R152	320068G-1	26S50	320260-4	26A04
36A040-30	19-1000	300251-6	26R152	320074-1	26C79	320262-1/2/2B	26A05
36A041-2	19-3330	320024-1	24586 <sup>1</sup>	320075-1	26S04 <sup>1</sup>	320262-3	26A03
36A041-27	Y 120	320024-2	24586	320076-1	26F63 <sup>1</sup>	320262-4/5	26A03
36B001-9	19-2025	320025-1	24A88	320077-1	22558	320262-4/5	26A03
36B029-1	FLY 380	320026-1	FLY 1	320078-1	26C80	320363-1/2	26506
36B030-1	17-1073	320027-1	26S48	320079-1-3-4	26S04	320266-1/2	26C78
36B031-1	20-1051	320027-2	26S48	320082-1	24551A <sup>1</sup>	320269-1	26S29
36B033-1	17-3410	320027-3	24561	320082-2-3-7	26S49	320277-1	26F63 <sup>1</sup>
36B035-1	17-3487	320027-4	24561	320083-1	26S48	320278-2	26S05
36B039-1	HS 5	320030-1/2	26A04	320084-3	24551	320279-1/3	26S50
36B041-1	Y 149	320032-1	26A03 <sup>1</sup>	320084-3	24551	320279-4/7	26S50
36B043-1	17-3419	320033-1	24586 <sup>1</sup>	320085-2	22556	320280-1	26S50
36B043-5	20-1057	320034-1	FLY 1	320089-2	26C77	320290-2/1	26C80
36B044-3	19-1001	320035-1	FLY 4	320111-2/3	26S86	320297-5	26S49
36B047-2	Y 121	320040-1	26S51	320111-4/6	26S86	320308-2	26S30
36C011-8	20-1008	320041-1	26C44	320119-1-2-4	26S30	320309-1/2	24550
36C012-2	Y 120 <sup>4</sup>	320041-2	26C76	320120-1	24550	320309-3	24550
300037G-1	26R15	320041-2A	26C76	320120-2	24553	320312-1	26S49
300045-1	26R18	320041-3/4	26C76	320124-1/2	26C81	320314-1/2	26S30
300054-1	24R94	320041-5	26C76	320124-4/6/	26C81	320317-1	26S86
300055-1/2	26R17 <sup>14</sup>	320042	FLY 1	-8/-11	26C81	320317-2/3	26S86
300057-1	26R19	320042-1	FLY 1	320124-17	26C79	320317-4/5/6	26S86
300058-1	26R95	320048	FLY 1	320124-18	26C81	320317-7/8/	-10
300059-1	26R20	320050-1	FLY 9 <sup>1</sup>	320124-19	20C137	-10	26S86
300060-1	26R19	320055-1	FLY 246	320124-22	26C81	320327-2	22S45
300062-1	24R08	320056-2	26S51	320125-1	26C81	320328-1/C	26S30
300064-1	26R24	320056-3	26S51	320125-4	26C81 <sup>1</sup>	320330-1	22S32
300068-1	26R94	320056-3B	26S51	320130-1	26C48	320333-1/2	24550
300071-1	26R92	320056-4/5	26S51	320130-3	24561	320342-2	26C81
300072-1	26R137	320058-1	26C80	320130-4	24506	320342-3	24S07

# MAGNAVOX

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
320345-1	26S100	360461-2	17-1066	360622-6	19-3125 <sup>3</sup>	360852-11	19-1000
320346-1	24S98	360461G-1	17-1063	360622-7	19-4400	360853-1	19-3275
320348-1	26C41	360462-1/4	Y 6	360622-8	19-3160	360853-2	19-4400
320355-1/2	26C79	360462-5/6	Y 6	360622-9	19-3250	360853-3/4	19-3125
320362-5	21F106 <sup>1</sup>	360462G-1	Y 6	360622-10	19-3660	360853-5	19-2026
320369-1	26S101	360464	Y 6	360622-12	19-3500	360853-7	19-4400
320369-3	26S85	360468-1	19-1023	360622-13	19-3100 <sup>2</sup>	360853-8/-9/	-10
320374-4	26S86	360479-1	HS 3	360622-14	19-3075 <sup>2</sup>	360853-11	19-3600
320376-2	26S86	360481-1	17-3400	360622-15	19-3250	360853-13	19-3500
320377-6/7	26S86	360481-2	20-1004	360622-16	19-3300	360853-13	HS 16
320381-1	24561	360481G-1	17-3400	360623	FLY 248	360854-1	Y 76
350390-1	26S101	360482-1	17-1033	360623-1	FLY 248	360861A	WC 14
320462-11	Y 6	360483-1	17-3401	360625-1	16-6770	360862-1	HS 16
320802-2	22S45	360484-1	19-1029	360632-1	FLY 28 <sup>1</sup>	360865-1	Y 84
320803-2	26C79 <sup>9</sup>	360490-2	15-1083	360636-1	17-4522	360867-1	Y 84
320810-1	26S52	360496-1	Y 6	360637-1	17-5003	360881-1	FLY 255
320811-1	FLY 180	360497-3	15-1082	360638-1	17-4514	360898-1/2	FLY 267
320819-1	22S58	360499-1	HS 9	360640-1	20-1049	360900-1	Y 85
330035-1	26S71	360499-3/4	HS 3	360642-1	17-3496	360912-1	FLY 179 <sup>9</sup>
330038-1	22S58	360511-1	17-1062	360643-1	17-4511	360940-1	FLY 273
330039-1	24561	360512-2	17-3496	360644-1	17-4536	360946-1	Y 107
350046-1	26C44 <sup>1</sup>	360515-1/2	Y 6	360645-1	17-4500	360947-1	19-3125
357015	FLY 308	360516-1	Y 6	360650-1	20-1020	360950-1	17-3418
360153-1	HS 16	360517-1	WC 17	360651-1	17-1031 <sup>1</sup>	360951-1	19-3125
360266-13	19-3100	360519-1	16-3495	360652-1	WC 14 <sup>1</sup>	360951-2	17-3420
360330-1/5	Y 3	360521-1	WC 27	360654-1	17-4503	360951-4	20-1058
360330-7	Y 5	360522-9	19-2009	360657-1	20-1020	360951-5	17-3414
360330-9	Y 3	360524-8	19-1001	360659-1	FLY 14	360951-6/7	17-3419
360331-1/2	WC 11	360526-1	Y 6	360660-1	Y 16	360952-2/3	17-3420
360332-03	17-1001	360532	FLY 26	360667-1	19-4201	360953-2	20-1057
360336-5	17-1002	360533-1	WC 22	360667-2	19-3250	360954-2	17-6031
360332-6	17-1003	360534-1	WC 20	360667-3	19-4400	360955-2	17-6032
360332-11	19-3001	360535-1	17-3402	360669-1/2	WC 14	360957-1/3/4	FC 7
360332-12	17-1012	360540-1	17-4524	360672-14	19-3036	360959-2/3	17-6028
360332-13	17-1013	360545-1	17-4504	360673-11	19-3075	360959-4/5	17-6028
360332G-3	17-1001	360546-1	17-4531	360673-14	19-3036	360959-6	17-1085
360332G-4/5	17-1002	360548-1	17-4521	360674-6	19-3600	360962-1	WC 41
360332G-6	17-1003	360549-1	17-4511	360676-1	19-1006	360962-2	WC 42
360332G-7	19-4122	360552-1	FLY 26	360676-5	19-1008	360962-3	WC 43
360332G-8	19-3093	360552-2	FLY 26	360676-7	19-1008	360963-2/3/	-4/5/7
360332G-9	19-4180	360552-2A	FLY 26	360676-8	19-1008	360963-2/3/	17-6022
360332G-10	19-3250	360554-1	20-1004	360676-11	19-1001	360998-1/2	FLY 291 <sup>3</sup>
360332G-11	19-3001	360556-1/2	Y 99	360699	WC 14	360999-4/5	19-3060
360332G-12	17-1012	360556-3/4	Y 99	360700-1/2	FLY 156	361018-3	19-3125
360332G-13	17-1013	360556-					



# MAGNAVOX

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
361066-1	19-3275	361304-4/-5/		361475-220	19-6022	M105216	17-6011
361077-3	Y 150	-6/-7	Y 126	361484-1	FLY 457	M105294	17-3417
361084-(B)/		361308-1/C	FLY 360	361488-1	FLY 508	M105295	20-1057
-2/-3/-4/-5	FLY 305	361323-569	19-1008	361488-2	FLY 509	M106305	Y 107
361091-1	19-3060	361323-689	19-2014	361499-1/B	FLY 462	M106358	26R150 <sup>1</sup>
361091-2	19-1014	361324-101	19-1016	361502-1	Y 168	M106359	FLY 284
361091-3	19-2026	361324-102	19-3032	361502-2	Y 240	M106360	26S95
361091-4	19-3300	361324-121	19-3125	361510-1/-3/		M106381	17-1077
361091-5	19-1016	361342-151	19-2026	-5/-6	FLY 596	M106382	17-1076
361091-11	19-1022	361324-181	19-3180	361510-2/-4/-7	FLY 597	M106383	20-1050
361091-13	19-3180	361324-330	19-6033	361520-2/-3/		M106385	17-3411
361091-16	19-2023	361324-331	19-3300	-4/-5	FLY 574	M106386	17-3413
361091-17	19-3100	361324-470	19-7047	361521-1	FLY 463	M106387	17-3414
361091-18	19-3180	361324-680	19-7068	361524-1	Y 235	M107290	17-3402
361092-1	WC 41	361328-1/B	FLY 353	361525-2/-3/-4	FLY 575	M107837	17-6012
361092-2	WC 43	361329-1	FLY 329	361538-1	FLY 576	M109180	WC 43
361092-4	WC 62	361329-2	FLY 448	361538-2	FLY 576	M109221	FLY 281
361092-5	WC 65	361339-1	17-6041	361538-3	FLY 577	M109237	HS 8
361092-6	WC 63	361340-1/2	Y 133	361547-1/2	FLY 578	M109252	17-3418
361092-8	WC 64	361340-3	Y 169	530153-1	VMT-05-01	M109253	17-3419
361092-13	WC 65	361340-4	Y 133	530165-1	VMT-05-01	M109254	17-3414
361093-1/2	17-6027	361340-5	Y 143	530165-2	VMT-05-01	M109257	19-3600
361094-1/2	17-6023	361340-6	Y 133	530165-3	VMT-05-01	M109261	20-1052
361095-1	17-6020	361340-101	Y 133	530165-4	VMT-05-01	M109263	26S86
361096-1/-2/		361341-1	17-6040	530165-6	VMT-09	M109264	FC 7
-3	Y 87 <sup>3</sup>	361343-1	17-6042	530165-8	VMT-11	M109286	26R150
361113-1	FLY 291 <sup>3</sup>	361348-1/-3/		530165-10	VMT-11	M109457	Y 107
361121-1	Y 81	-6/-8	Y 110	530165-11	VMT-09	M109826	19-4060
361129-1/2	HS 16	361348-5/-10	Y 134	530165-12 <sup>17</sup>	VMT-14	M109838	19-4180
361130-1/-2/		361350-2	Y 145	530165-13	VMT-09	M109840	19-3060
-3	Y 110	361350-3	Y 157	530165-14	VMT-09	M109850	26S86
602/-702	Y 110	361352-1	FLY 362	530165-15	VMT-11	M112820	FLY 273
361135-1	WC 23	361353-1/B	FLY 355	530165-16	VMT-11	M112821	26S86
361138-1/-2/		361373-1	FLY 372	530165-17	VMT-09	M112822	26S48
-3/-4/-5	FLY 304	361375-1/2	FLY 355	530165-18	VMT-09	M112829	26C81
361149-1	17-1084	361376-1/2	FLY 513	620032	22S58	M112845	26R150
361159-1	19-2012	361376-3/4	FLY 507	623278-1	24S61 <sup>1</sup>	M112866	HS 23
361162-1/-2/		361377-1/-2/-3	Y 139	700703-1	Y 83	M112869	17-6031
-3/-4/-5	Y 136	361378-1	FLY 373	700703-5	Y 84	M112870	17-1083
361171-1/-4/2	HS 5	361379-1/2	Y 160	700747-1/-2/-4/		M112871	17-3420
361172-1	FLY 354	361380-1	Y 110	-5/-6/-7	Y 82	M112872	17-6028
361188-1	WC 41	361380-2	Y 134	700894/-1	Y 161	M112873	17-6032
361192-1	17-6027	361380-4/7	Y 155	700895-1/-2/-3	Y 85	M112874	17-6022
361193-2	17-6027	361380-5/6	Y 153	700895-991	Y 85	M112875	WC 36
361197-1/A-2	FLY 329	361383-1/-2/-3	FLY 362	703025-1/2	Y 85	M112877	17-6033
361198-1/2	17-6020	361385-1/A/-2	FLY 472	703046-1/2/-5	Y 87	M112879	17-3414
361202-1	17-4536	361387-2/4	WC 23	703046-3/4	Y 102	T-013-3	26S72
361209-1	HS 5	361394-1/2	FLY 360	703046-6	Y 102	T-104-3-3	26S71
361210-1	19-1005	361395-1/2	Y 135	703046-7/-8	Y 102	T-A46	HS 5
361211-1	19-1004	361395-3	Y 133	903562-502	Y 107	T-D40A	Y 121
361218-1	20-1020	361395-4	Y 158	903562-507	Y 107	T-D41	Y 81
361221-1	17-4535	361398-1	17-3404	906152-501	FLY 277	T-D78	Y 149
361222-1	Y 16 <sup>3</sup>	361398-2	17-3404	962636-501	FLY 281	TLF-3705-2D	FLY 342
361224-2	19-3500	361400-1	19-1002	F 104	FLY 380	TLF-468D/5	Y 5008
361224-3	19-3250 <sup>2</sup>	361411-1	FLY 355	L10-02-5	HS 16	TLY-3359-4D	Y 120
361224-4/-5	19-3250	361411-2	FLY 394	M77842	19-3075	TLY-3361-1D	Y 120
361241-1/B-2	FLY 353	361411-3	FLY 355	M100037	26S48	TLY-3364DS	Y 120
361267-2/3	FLY 378	361411-4	FLY 394	M100131	19-3125	T-V127	22S32
361271-4/-6/		361412-1	FLY 362	M101819	19-3036	T-W40	26S73 <sup>1</sup>
361274-1/2	Y 120	361423-1	Y 189	M102134	26C81	YSG-356318	26S71
361275-1	FLY 342	361424-2	FLY 458	M102195	HS 17	YSG-35821	Y 91
361277-1	19-2025	361429-1	Y 133	M102201	19-3060	YSG-35821A	Y 91
361290-102/		361429-3	Y 156	M105065	WC 41	YSG-361008	FLY 5065
-202/-302	Y 134	361444-2219	19-6022	M105066	WC 42	YSG-361295	HS 16
361290-402	Y 134	361444-3319	19-6033	M105195	26C81	YSG-T88-3-2	FLY 538
361292	HS 16	361457-1/2	FLY 450	M105196	WC 35	YSG-T88-5-1	FLY 595
361294-1/-1C	FLY 361	361458-1	19-3125	M105197	HS 7	YSG-T115-1-12	Y 105
361296-1/2	17-6020	361459-1	19-2032	M105212	17-6016	YSG-T115-1-17	Y 105
361298-1	20-1057	361461-1/2	FLY 451	M105213	17-6018		
361304-1/-2/3	Y 126	361469-1/2	FLY 453	M105214	17-6019		

# MARCONI

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
100-186	24S51	512-518	24S51	516-485	FLY 172	523-717	Y 65
130-080	24S51	513-004	26S29	516-486	Y 68	524-009	24S51
303-014	Y 10	513-009	FLY 16	517-147	Y 65	524-010	FLY 231
303-015	Y 10	513-017	22S45	517-416	Y 68	524-011	24S53
303-073	26C79	513-083	Y 10	517-417	24S51	524-042	Y 65
303-414	Y 10	513-515	FLY 5004	517-473	26C79	525-316	Y 65
303-608	26S78	513-517	24S51	517-637	24S51	525-615	FLY 5003
303-609/A	FLY 10	513-556	Y 10	518-414	FLY 5005	525-617	Y 65
303-614	Y 10	513-574	24S52	518-415-4/-5	FLY 5003	525-747	Y 65
303-616	24S51	513-808	FLY 202	518-446	Y 65	525-916	Y 150
303-617	24S51	513-817	24S51	518-447	Y 65	525-975	Y 150
303-641	WC 16	513-846	Y 68	518-450	FLY 5003	526-217	26S48
303-642	WC 11	513-847	Y 10	518-473	26C79	526-418	24S53
307-817	24S51	513-873	26C79	518-474	26S19	526-917	26C79
307-948	24S51	513-874	24S52	518-743	26C79	526-974	FLY 5003
309-704	26S29	514-017	24S53	520-136	26C79	526-975	Y 150
309-708	26S29	514-047	26S29	520-166	26C79	526-976	26S29
309-709	FLY 172	514-073	26C81	520-316	24S51	527-044	26S48
309-717	24S53	514-074	24S52	520-615	FLY 5003	527-065	FLY 5003
309-751	WC 11	514-109	FLY 16	520-616	Y 61	527-068	24S86
309-752	WC 15	514-156	Y 10	521-114	26S29	527-083	WC 34
309-783	Y 10	514-158	Y 13	521-115	FLY 5003	527-134	Y 5010
510-017	24S51	514-183	Y 10	521-116	Y 61	527-165	FLY 5003
510-266	WC 16	515-136	26C79	521-214	26S29	527-218	Y 150
510-267	WC 15	515-215	FLY 5017	521-215	FLY 5004	527-226	FLY 5005
511-107	FLY 172	515-217	24S51	521-216	Y 150	527-245	26S29
511-712	FLY 129	515-247	Y 68	522-226	FLY 5005	527-420	26S29
511-804	24S52	515-272	26C79	522-315	FLY 5004	527-438	26S29
511-809A	FLY 5004	515-273	26C79	522-447	FLY 5004	527-439	FLY 5005
511-817	24S53	515-274	24S52	522-477	FLY 5004	527-440	Y 150
511-873	26C81	515-279	26C79	522-876	Y 81	527-474	FLY 5005
511-875	26C79	515-517	24S51	522-878	24S06	527-481	Y 150
511-893	Y 10	515-573	26C79	523-015	FLY 5003	540-136	26C79
512-312	26S29	515-574	26C79	523-615	FLY 5003	8515-215	FLY 5017
512-343	Y 68	515-740	26C79	523-715	FLY 5003	735151	FLY 5017
512-346	Y 68	516-214	Y 68	523-716	Y 65		

# MATHES

(SEE CURTIS MATHES)

# MATSUSHITA/PANASONIC

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
IC-91Q	24S51	ETA-57A2A/B/C	22S35	LP-5102	26C81	TLF-418-T	FLY 398
40E56W	24S51	ETD-57A16A	26C92	LQ-131-999	19-3125	TLF-505D	WC 11
40E56WA	24S51	ETK-132A	24S150	LQ-301-153	19-3300	TLF-506DA	WC 18
41E05MA	24S64	ETK-41E	24S64	LQ-301-822	19-3300	TLF-553D	WC 34
48E27MA	24S150	ETP-57A40A	26F67	LQ-750-272	17-4073	TLF-607S/-1S	FLY 431
48E27MAL53	24S150	ETP-57A40C	26F67	LS-1001-2	20-1005	TLF-619D	WC 18
48E27WA	24S150	ETP-57A40D	26F67	LV-226	26S11	TO 5D	FLY 342
956M	24S50	ETQ-48A1A	26C77	LY-3359/-D1	Y 120	TLF-3706-2D/	
ETA-28A14A	24S58	ETQ-48B2A	26C77	LY-3359-4D	Y 120	TLF-3715-2D/	
ETA-28A36A	24S64	ETQ-57A4A	26C81	OT-956	24S50	TLF-5002/-U	FLY 620
ETA-28F3A	24S04	ETQ-57A16A	26C92	RU-2C257-M	16-9026	TLF-5004-1/-3	FLY 643
ETA-28F19A	24S04	ETQ-57B1A	26C81	TC-91Q	24S51	TLF-5004-8S	FLY 646
ETA-35A4A	24S64	ETV-48A1A/2A	26S99	TC-941	24S89	TLF-5005	FLY 621
ETA-40E27MA	24S51	ETV-57A2A	26S11	TLA-OT-956	24S51	TLF-5007-1S/F	FLY 682
ETA-40E56M/W	24S51	ETV-57A3A	24S52	TLB-101-153	19-3100	TLF-5013	FLY 644</

# MATSUSHITA/PANASONIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
TLH-3201D	Y 120	TLP-3231-3	26F67	-2/-3	17-3495	TLY-469D5PS	Y 265
TLH-3703	19-6819	TLP-3238	26F72	TL5-51203-2	17-1031	TLH-3201D	Y 120
TLH-5301	HS 7	TLP-5102	26C81	TLT-470-999	19-7047	TLY-3359-4D	Y 120
TLH-6953	WC 125	TLP-5105	26C92	TLV-101	26A02	TLY-3361-2D/1D	Y 120
TLH-80701	WC 11	TLP-5106	26C79	TLV-102	26A02		
TLI-51251	17-5014	TLP-5106-1	26C79	TLV-226	26S23	TLY-3364A5	Y 120
TLI-51252	17-5014	TLP-5151/-5152	26C81	TLV-227	26S99	TLV-5310	Y 263
TLI-51253	17-5014	TLP-80293K	26F73	TLV-228	24S52	TLV-5310S	Y 263
TLI-53052	17-4538	TLQ-121-999	19-3125	TLV-230	26S72	TLV-5311	Y 263
TLI-53052-1	17-4538	TLQ-251-223	19-3250	TLV-231	26S99	TLV-5320F	Y 263
TLK-5102	26C81	TLQ-301-822	19-3300	TLV-233	26S78	TLV-80315TS	Y 266
TLP-108	26C77	TLQ-351-999	19-3375	TLV-3359-4D	Y 120	TLV-80402GP	Y 81
TLP-110	26C77	TLQ-700-999	19-3075	TLV-3361D	Y 120	TP-110	26C77
TLP-113	26C77	TLQ-850-223	19-3093	TLV-5204-2	26S33	TTA-28A36A	24S64
TLP-113Z	26C77	TL5-1002	17-3402	TLV-5205	26S83	TTA-28A36AZ	24S64
TLP-408	26C81	TL5-34202-7	19-2026	TLV-465	Y 105	TVL-226	26S23
TLP-3231	26F67	TL5-51003	20-1004	TLV-468T/S/			
TLP-3231-1	26F67	TL5-51201/-1	17-1026	D/T5	Y 5008		
TLP-3231-2	26F67	TL5-51202/-		TLV-469D/S	Y 105 <sup>13</sup>		

# MONTGOMERY WARD

(SEE AIRLINE)

# MOTOROLA/QUASAR

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
The first letter in the Motorola part number has no significance and is replaced with a -.							
N2A	VMT-09	1-66523A36	20-1088	24-25261A02	Y 196	24-65131A79	20-1086
N2A-1	VMT-09	1-66523A39	17-6073	24-25261A11	Y 195	24-65131A80	20-1087
N2A-2	VMT-09	1-66523A40	17-6163	A04, A12	Y 198	24-65131A89	WC 47
1-25681	VMT-09	1-66523A43	17-6075	24-60419A01	16-6758	24-65132A03	20-1087
1-40802A01	19-6022	1-66523A44	17-6076	24-60419A02	16-6770	24-65132A04	20-1085
1-65206A83	16-3445	1-66523A47	17-5052	24-60419A03	16-6758	24-65132A06	17-5055
1-65816A97	17-5052	1-66539A39	17-5052	24-60419A05	16-6770	24-65132A10	17-5052
1-66099A99	20-1085	1-66539A42	20-1090	24-60419A06	16-6758	24-65132A38	17-5052
1-66206A83	17-3495	1-66539A68	17-5055	24-60419A07	16-6758	24-65132A40	20-1086
1-66241A47	16-3445	1-68609A47	WC 81	24-60419A08	16-6780	24-65132A54	20-1088
1-66241A48	17-3495	1-703335	17-1063	24-60419A09	16-6780	24-65132A55	FC 8
1-66244A26	17-5052	1-712105	17-1063	24-64390A01/02	16-6780	24-65132A80	FC 9
1-66244A27	20-1085	1-712106	17-1063	24-64616A038	Y 62	24-65133A23	17-5056
1-66245A98	20-1085	1-730808	20-1004	24-64666A13	20-1044	24-65133A25	20-1092
1-66501A74	17-5052	1-732555	HS 5	24-65127A84	WC 83	24-65133A26	20-1093
1-66501A75	20-1087	1-732556	HS 5	24-65127A85	WC 77	24-65133A28	17-6082
1-66501A76	20-1085	1-732558	17-6016	24-65127A86	WC 79	24-65133A30	17-6075
1-66501A77	20-1086	1-732564	20-1004	24-65127A89	17-5054	24-65133A31	17-6083
1-66504A14	20-1089	1-736152	HS 5	24-65127A91	20-1088	24-65133A32	17-6084
1-66504A15	20-1087	1-737757	HS 5	24-65127A92	20-1087	24-65133A39	17-6163
1-66504A16	20-1085	1-739709	HS 5	24-65127A93	FC 7	24-65133A73	17-6072
1-66507A10	20-1087	1-741308	HS 7	24-65127A94	17-6078	24-65133A74	20-1088
1-66507A11	20-1085	1-741397	WC 19	24-65127A95	17-6079	24-65133A78	20-1086
1-66507A58	17-4538	1-741946	HS 5	24-65127A96	17-6080	24-65133A80	20-1087
1-66507A59	17-4538	1-742677	WC 30	24-65127A97	17-4538	24-65143A34	17-6163
1-66507A61	17-5054	1-747585	17-4523	24-65127A98	17-4538	24-65143A38	20-1094
1-66507A63	20-1004	1-747587	17-4522	24-65127A99	20-1004	24-65143A66	FLY 629
1-66507A64	20-1087	1-790341	17-3461	24-65127A01	WC 49	24-65145A24	WC 22
1-66507A65	20-1088	1-792591	17-1062	24-65131A01	WC 49	24-65145A27	17-6084
1-66507A67	17-1035	1-792736	20-1004	24-65131A02	WC 46	24-65190A01	16-3445
1-66508A70	17-6072	15-742818	Y 61	24-65131A03	20-1085	24-65171A75	WC 17
1-66508A52	WC 49	23-751487	19-3500	24-65131A04	HS 7	24-65172A32	17-6075
1-66508A53	WC 50	24-10250A02	Y 242	24-65131A06	WC 22	24-65173A31	FLY 467
1-66508A54	WC 48	24-10250A04	Y 193	24-65131A07	20-1091	24-65174A14	FLY 601
1-66512A68	20-1087	24-10250A07	Y 241 <sup>11</sup>	24-65131A08	17-6075	24-65175A18	FLY 636
1-66520A82	20-1087	24-10250A08	Y 105 <sup>11</sup>	24-65131A09	17-5053	24-65192A53	FLY 628
1-66520A84	FC 9	24-10250A09	Y 241	24-65131A12	17-6073	24-65209A50	Y 150
1-66522A06	20-1087	24-10250H09	Y 105 <sup>11</sup>	24-65131A14	20-1087	24-66258A101	17-5057
1-66522A45	20-1087	24-10250A11	Y 221	24-65131A15	17-6163	24-65362A01	19-6819
1-66523A31	17-5033	24-10282A03	17-6077	24-65131A16	17-6081	24-66258A05/C	FC 256
1-66523A35	20-1087	24-10435A01	FLY 618	24-65131A17	17-6076	24-65364A02	WC 88
				24-65131A78	17-5055	24-65410A01	FLY 236

# MOTOROLA/QUASAR

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
24-65410A02/B	FLY 241	24-66491A02	17-5060	24-67324A49	19-3100	24-68002A24	19-3125
24-65410A04	FLY 237	24-66492A01	17-5059	24-67324A50	19-3125	24-68002A25	19-3100
24-65410A05	FLY 238	24-66492A02	17-5060	24-67324A51	19-3300	24-68002A26	19-2032
24-65616A02/B	Y 65	24-66516A05	Y 65	24-67362A03	17-4523	24-68002A27	19-3300
24-65616A03B	Y 70	24-66544A80	17-6074	24-67362A04	17-4523	24-68002A28	19-3100
24-65616A06/5F	Y 65	24-66545A29	20-1095	24-67461A01	Y 242	24-68002A29	19-2011
24-65616A07	Y 66	24-66545A71	20-1092	24-67461A03/E	Y 242	24-68002A38	19-3950
24-65616A09	Y 65	24-66546A11	20-1094	24-67461A04	Y 242	24-68002A40	19-5581
24-65616A10	Y 66	24-66546A12	17-5056	24-67534A19	19-1001	24-68002A42	19-4201
24-65616A14	Y 65	24-66547A04	17-5022	24-67534A23	19-2020	24-68002A43	19-1011
24-65616A17	Y 150	24-66548A11	Y 88 <sup>8</sup>	24-67534A24	19-3100	24-68002A48	19-5102
24-65666A01	17-4538	24-66548A53	20-1092	24-67534A25	19-4400	24-68002A91	19-4201
24-65666A07	17-4500	24-66548A57	20-1095	24-67554A05	26C79	24-68002A94	19-2026
24-65666A14	17-4538	24-66548A59	17-6078	24-67564A01	FLY 629 <sup>3</sup>	24-68002A96	19-5581
24-65666A18	17-4538	24-66548A01	17-6084	24-67564A03/B	FLY 280	24-68002A98	19-1008
24-65666A15	17-4500	24-66549A19	17-5052	24-67564A04	FLY 280	24-68002A99	19-2023
24-65698A04	WC 86	24-66549A89	17-6083	24-67564A06/M	FLY 399	24-68523A01/	
24-65698A07	WC 14	24-66549A91	17-6084	24-67564B01	FLY 629	9/10/12	Y 195
24-65707A01	Y 62	24-66550A78	17-5061	24-67564B03	FLY 629 <sup>3</sup>	24-68523A02/	
24-65775A01	19-4217	24-66550A79	20-1096	24-67564B04	FLY 629 <sup>3</sup>	3/4	Y 196
24-65828A01/02	19-1009	24-66550A80	20-1097	24-67564B06	FLY 399	24-68523A07/	
24-65828A06	19-1041	24-66550A85	20-1098	24-67564A07	FLY 399	8/11/14	Y 197
24-65828A07	19-3500	24-66552A61	17-5052	24-67564A09	FLY 636	24-68523A13/15	Y 198
24-65828A08	19-1009	24-66552A63	20-1090	24-6758A01	FLY 629	24-68523A16	Y 199
24-65828A09	19-1005	24-66552A64	20-1087	24-67602A04	FLY 5063	24-68531A01	Y 120
24-65828A11	19-4950	24-66553A22	20-1090	24-67602A10/B10FLY	601	24-68592A01	Y 191
24-65828A12	19-4201	24-66621A01/B	Y 67	24-67602A11/B11FLY	601	24-68592B01	Y 191
24-65828A13	19-3275	24-66772A01	19-1000	24-67602A14/B14FLY	601	24-68607A31	17-5019
24-65828A14	19-3250	24-66772A02	19-1003	24-67602A15/B15FLY	601	24-68609A47	WC 81
24-65828A15	19-3100	24-66772A03	19-1004	24-67602A17/B17FLY	601	24-68614A76	20-1099
24-65828A17	19-1004	24-66772A05	19-1004	24-67602A18	FLY 601	24-68615A95	17-6075
24-65828A19	19-4160	24-66772A06	19-1004	24-67602B18	FLY 601	24-68801A01	19-2018
24-65828A21	19-3275	24-66772A07	19-1001	24-67602A20	FLY 601	24-68801A02	19-3500
24-65828A23	19-3125	24-66772A08	19-6033	24-67602A22	FLY 601	24-68801A03	19-2024
24-65828A24	19-3125	24-66772A09	19-6033	24-67602A26	FLY 601	24-68801A13	19-6022
24-65828A25	19-1002	24-66772A11	19-1009	24-67621A01(C)	Y 243	24-68801A15	19-2027
24-65828A28	19-3125	24-66772A12	19-2015	24-67621A03	Y 241 <sup>15</sup>	24-68801A16	19-5012
24-65828A33	19-1008						

# MOTOROLA/QUASAR

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
24-90070A01	19-3419	24-701016	17-1063	24-721831	Y 35	24-736006	19-3180
24-90073A01	17-5023	24-701069	26A05	24-721912	19-3500	24-736007	19-3375
24-90074A01	17-5020	24-701099	FLY 33	24-721951	17-5002	24-736008	19-3275
24-90092A01	WC 41	24-701134	FLY 33	24-721953	17-5003	24-736012	19-3250
24-90118	Y 3	24-701136	Y 18	24-722126	FLY 63	24-736084	FLY 64
24-90119	WC 11	24-701138	Y 18	24-730103	17-1033 <sup>1</sup>	24-736204	FLY 162
24-90155A01	19-2026	24-701139	Y 18	24-730140	26550	24-736226	20-1004
24-90163A01	20-1008	24-701141	Y 18	24-730311	19-1001	24-736228	17-3402
24-90197	17-1003	24-701142	Y 18	24-730391	19-1001	24-736229	20-1004
24-90243A02	19-2013	24-701343	17-1006	24-730392	17-4524	24-736267	17-4522
24-90243A03	19-1005	24-701344	17-1006	24-730393	17-1006	24-736268	17-4523
24-90243A05	19-3125	24-701349	WC 22 <sup>1</sup>	24-730614	17-5003	24-736270	17-4522
24-90243A06	19-2027	24-701552	FLY 29	24-730615	17-5002	24-736445	Y 45
24-90243A07	19-3660	24-701558	HS 5	24-730618	19-1001	24-736446	Y 68
24-90243A10	20-1079	24-701559	HS 5	24-730632	Y 36	24-736449	Y 68
24-90243A12	17-5015	24-701564	17-1063	24-730633	Y 36	24-736487	FLY 162
24-90243A19	19-1001	24-701566	WC 22	24-730634	Y 36	24-736488	FLY 121
24-90243A22	19-3060	24-701588	HS 5	24-730677	15-1082	24-736496	19-4950
24-90243A23	19-1000	24-701600	Y 6	24-730678	19-1013	24-736673	17-3497
24-90243A24	19-7068	24-701601	Y 6	24-730692	FLY 63	24-736696	20-1044
24-90243A26	WC 62	24-701609	Y 6	24-730695	FLY 63	24-736961	19-3125
24-90243A27	WC 58	24-701610	Y 6	24-730902	FLY 20	24-736963	19-4400
24-90243A28	WC 59	24-701611	Y 6	24-730903	FLY 20	24-736966	20-1049
24-90243A29	Y 131	24-701612	Y 6	24-730904	FLY 20	24-736977	Y 68
24-90257A03	FLY 386	24-701636	FLY 29	24-731008	FC 4	24-736978	Y 45
24-92173	Y 10	24-701751	19-1050	24-731090	WC 24	24-767213	19-3660
24-119838	19-3075	24-702039	Y 18	24-731610	FLY 74	24-737218	FLY 135
24-119847	19-3125	24-702040	Y 6	24-731831	Y 13	24-737340	17-5004
24-119850	19-3180	24-702496	17-1006	24-731883	20-1004	24-737402	20-1004
24-119854	19-3250	24-702543	17-1033	24-731893	20-1049	24-737615	20-1004
24-119855/56	19-3300	24-702655/57	Y 35	24-731937	FLY 190	24-737733	19-1005
24-119869	19-3250	24-702661/63	Y 35	24-732110	Y 13	24-737734	20-1004
24-119889	19-1005	24-702772	Y 27	24-732111	Y 37	24-737829	19-1005
24-120588	19-4200	24-702773	Y 27	24-732201	17-5002	24-737848	20-1049
24-120887	19-3125	24-702958	Y 35	24-732205	17-6015	24-737850	20-1049
24-120984	19-3250	24-702959	Y 35	24-732584	FLY 74	24-737851	20-1044
24-121278	19-1005	24-702975	FLY 62	24-732632	19-4950	24-738122	17-3402
24-121805	19-4200	24-702983	17-1001	24-732652	19-1001	24-738699	FLY 162
24-132059	19-1008	24-702984	17-1069	24-732672	19-4950	24-738803	19-3250
24-132921	19-1009	24-703239	Y 6	24-732676	FLY 162	24-738942	20-1004
24-135059	19-1004	24-703240	Y 6	24-732710	Y 37	24-738943	17-3495
24-135220	19-1004	24-703260/B	Y 35	24-732711	Y 37	24-739220	20-1004
24-470159	17-3401	24-703262	Y 35	24-732746	FLY 20	24-739257	Y 68
24-470316	17-1033	24-703263	Y 35	24-732747	FLY 20	24-739275	Y 54
24-470794	HS 1	24-703265	Y 35	24-732806	19-3180	24-739276	Y 54
24-470796	WC 14	24-703312	20-1004	24-732807	19-4200	24-739283	FLY 190
24-471340	17-1013	24-703319	19-4500 <sup>2</sup>	24-732808	19-3250	24-739284	FLY 123
24-471520	16-6758	24-710140	19-4201	24-732809	19-3250	24-739290	20-1004
24-471670	17-3465	24-710236	Y 13	24-732811	Y 37	24-739304	17-3402
24-471672	17-3495	24-710636	FLY 33	24-732820	20-1049	24-739447	20-1020
24-471718	16-3758	24-711217	Y 35	24-733106	FLY 64	24-739448	20-1020
24-471720	17-3495	24-711236	Y 35	24-733107	FLY 63	24-739630	17-3402
24-471722	17-3497	24-711265/A	FLY 63	24-733200	19-5101	24-0739631	20-1004
24-472535	19-4217	24-711266	FLY 63	24-733225	19-1005	24-739909	15-1083
24-480209	24A90	24-711268	Y 35	24-733239	Y 38	24-740117	19-3300
24-481874	16-6758	24-711413	19-6033	24-733407	FLY 74	24-740135	FLY 194
24-482863	16-6758	24-711581	Y 35	24-733411	Y 37	24-740136	FLY 195
24-482865	16-6758	24-711583	Y 35	24-733436	Y 37	24-740282	17-1104
24-484077	20-1004	24-711584	Y 35	24-733484	17-5002	24-740283	17-3499
24-484078	HS 6	24-711585	Y 35	24-733485	17-5003	24-740285	17-5012
24-484078	HS 6	24-711587	Y 35	24-733510	WC 24	24-740286	15-1083
24-484082	17-1004	24-711587	Y 35	24-733510	WC 24	24-740289	17-5013
24-484084	17-1043	24-711652	FLY 29	24-733646	FLY 64	24-740290	19-1005
24-485474	Y 3	24-711937	FLY 62	24-733734	WC 18	24-740291	17-5013
24-485475	Y 3	24-712101	19-3250 <sup>2</sup>	24-733751	WC 24	24-740512	19-4840
24-485476	Y 3	24-712102	19-3500 <sup>2</sup>	24-740513	20-1004	24-740513	19-3250
24-485553	16-6758	24-712193	FLY 62	24-733873	20-1004	24-740546	19-3060
24-485555	16-6770	24-720154	Y 35	24-733874	17-3402	24-740546	20-1004
24-485933	16-6758	24-720155	Y 35	24-733875	20-1049	24-740553	17-3402
24-489036	17-1011	24-720622	Y 35	24-733962	Y 37	24-740587	Y 16 <sup>1</sup>
24-489071	17-1064	24-720623	Y 35	24-734187	19-5100	24-740596	20-1004
24-638488	17-3498	24-720624	Y 35	24-734459	17-3497	24-740597	19-3180
24-690540/41	16-3487	24-720747	Y 35	24-734483	17-6012	24-740642	FLY 193
24-690542	17-3488	24-720936	15-1082	24-735172	19-4400	24-740696	Y 54
24-700050	Y 18	24-720937	17-1067	24-735179	17-4535	24-740980	17-5003
24-700069	Y 10	24-720977	17-1070	24-735180	17-4536	24-740982	17-5002
24-700088	WC 22	24-721064	HS 5	24-735522	19-3330	24-740984	17-5004
24-700089	WC 22	24-721065	HS 5	24-735532	19-3330	24-741341	17-5001
24-700588	FLY 33	24-721271	19-3500 <sup>2</sup>	24-735697	17-3497	24-741645	17-1031
24-700694	Y 18	24-721273	17-1063	24-735703	Y 36	24-741646	17-3495
24-700714	Y 18	24-721274	19-1000	24-735844	FLY 57	24-741937	FLY 190
24-700774	Y 18	24-721290/C	FLY 63	24-735868	FLY 74 <sup>1</sup>	24-741938	FLY 123
24-700776	Y 18	24-721301/C	FLY 63	24-735869	Y 16 <sup>1</sup>	24-742047	FLY 193
24-700778	Y 18	24-721829	Y 35	24-735873	Y 38	24-742247	17-3497
24-700882	26R24	24-721830	Y 35	24-735962	Y 13	24-742634	19-3180

# MOTOROLA/QUASAR

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
24-742676	FLY 191	24-751948	Y 65	24-791592	19-1021	25-65984A12	22S64
24-742767/68	17-3402	24-751951	17-4536	24-791723/25	Y 10	25-65984A13	24S64
24-742781	19-1001	24-751955	20-1044	24-791793	26F64	25-65984A14	24S64
24-742789	17-4522	24-751989/AB	22S61	24-791974	FLY 32	25-65984A15/Y	24S61
24-742790	17-4523	24-752065	HS 7	24-792171/73	Y 18	25-65984A18	24S64
24-742835/D	Y 52	24-752132	Y 65	24-792489	Y 10	25-65984A19	24S06
24-743210	24551	24-752138	20-1085	24-792506	Y 18	25-65984A20	24S83
24-743212	26C44	24-752139	20-1100	24-792508	Y 18	25-65984A21/	-AG
24-743272	17-3402	24-752140	20-1101	24-792577	19-1003	-AG	22S73 <sup>1</sup>
24-743287	19-1001	24-752324	19-3180	24-792578	17-1063	25-66001A04	21F21 <sup>1</sup>
24-743363	20-1044	24-752328	FLY 259	24-792585	17-1063	25-66001A06	21F08
24-743425	17-1031	24-752351	19-3275 <sup>2</sup>	24-792586	17-1003	25-66761A01	26S92
24-743426	HS 5	24-752352	19-1050 <sup>2</sup>	24-792587	17-1006	25-66761A02/D	26S96
24-743456	Y 61	24-752839	17-1031	24-792590	FLY 33	25-66761A03/E	26S91
24-743463	17-1030	24-752840	17-1079	24-792691	FLY 40	25-66761A07/N	26S86
24-743536	FLY 135	24-752963	19-3250	24-792699	Y 6	25-66761A09	26S86
24-743552	19-1001	24-753093	20-1005	24-792714	Y 6	25-66841A11	26R150
24-743675	Y 54	24-753234	19-3495	24-792715	Y 27	25-66841A12	26R150
24-743727	19-1009	24-753305	19-4840 <sup>2</sup>	24-792722	WC 19	25-66841A13/S	26R154
24-743765/...	Y 54	24-753397	17-3495	24-792735	20-1004	25-66841A15/V	26R150
24-743768	17-5004	24-753439/79	19-3250	24-792753/D	FLY 33	25-66841A16	26R150 <sup>1</sup>
24-743769	17-5004	24-753509	19-1009	24-792756	Y 18	25-67448A01	26R105 <sup>1</sup>
24-744042	17-4534	24-753543	19-1010	24-792758/59	Y 10	25-67448A03	26R105 <sup>1</sup>
24-744043	FLY 188	24-753544	19-1001	24-792772	19-1002	25-67448B05	26R105 <sup>1</sup>
24-744084	FLY 186	24-753804	19-2026	24-792820	WC 18	25-67552A02/G	24S06
24-744084	Y 61	24-754004	19-3100	25-21175	24551	25-67552A05	22S86
24-744200	15-1082	24-754006	17-5055	25-60329A01/			

# MOTOROLA/QUASAR

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
25-701619	26S72	25-731015	26S17	25-740915	24S48	25-7515796/AU	26C78
25-701632	24S51	25-731027	26S17	25-741322/A	26S30	25-751797/AZ	26C78
25-701659	26R20	25-731058	26S17	25-742649	24S53	25-751989/AB	24S05
25-702429/A	26A05	25-731268	21F12 <sup>1</sup>	25-742828	26S08	25-752106	26R112 <sup>1</sup>
25-702429/B	26A05	25-731568	26A05	25-743041	26C44	25-752869/N	26R118 <sup>1</sup>
25-702429K	26A05	25-732800	26A05	25-743210	24S51	25-753388	26S23
25-702445	26S17	25-733190F	21F08	25-743211	26S49	25-754067	26S24
25-702800	26A03	25-733199	21F12 <sup>1</sup>	25-743212Y	26C44	25-754329AB	26S29
25-703068	24S51	25-733208	24S52	25-743311	26R51 <sup>1</sup>	25-754420AK	22S86 <sup>1</sup>
25-710060	24S50	25-733443	26S50	25-743545	24S51	25-790015	26S77
25-710657	26R24 <sup>1</sup>	25-734495A	26C92	25-743634/B	26C92	25-790140	26F60 <sup>1</sup>
25-710658	26R24 <sup>1</sup>	25-7345388	21F25 <sup>1</sup>	25-744697	26S23	25-790141	21F24
25-710659	26R24 <sup>1</sup>	25-734746	26A05	25-744974/AT	26S22	25-790151	26S51
25-710730	26A05	25-734747	26A05	25-745051	26S30	25-790686	24S51
25-710731	26A03	25-734908	26C92	25-745052	26C78	25-790698	22S58
25-710925/C	24S53	25-734976	26S75	25-745059/J	26S22	25-790863	26R42
25-710925/D	24S53	25-735740	26S52	25-745778	26R118 <sup>1</sup>	25-790864	26R42
25-711592	21F08	25-736254	26A05	25-745919	26C78	25-790914	26A02
25-720048	21F08	25-736255	26S52	25-746165	26S48	25-790923	26S57 <sup>1,7</sup>
25-720050	21F08	25-736256	26S50	25-746756/AK	26S24	25-790952	26C92 <sup>1</sup>
25-720168	24S50	25-736256C/D	26S50	25-746803	26C92	25-791793	26F64
25-720749	21F12 <sup>1</sup>	25-736967	21F24 <sup>1</sup>	25-747167	26C78	25-791804	26S51
25-721027/G	26S17	25-737472	26C44	25-747597	26S22	25-792168/D	26S72
25-721779	21F12	25-737476	26R56	25-747849	26C78	25-792564	26R92 <sup>1</sup>
25-721871	26A05	25-738716	26S23	25-748245	24S48	25-792710	26S72
25-721872	24S52	25-738763	26C44	25-748820	21F41 <sup>1</sup>	25-798545A	26S77
25-721878	26S49	25-738847	26S49	25-749146/D	24S07	64-736204	FLY 162
25-730138	26S17	25-738848	24S51	25-749230/D	24S07	401-2311	FLY 162
25-730139	21F12 <sup>1</sup>	25-739569	26R56	25-749593	26C78	401-2595	FLY 162
25-730140	24S50	25-739866	26A05 <sup>1</sup>	25-749665	26S46	424-620	Y 13
25-730179/C	26A05	25-739898	26S52	25-749732	21F08	424-625	Y 68
25-730204	26S41	25-740238	22S45	25-751215	26C92		
25-730923	26S16	25-740426	26C76	25-751216	24S53		
		25-740674	26C44	25-751752/AY	26C79		

# OLYMPIC

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
B-28A	26C80	CL-2753	Y 7	CL-5827	19-3300	CLJ-31369	17-4522
CK-1346	26C44	CL-2760	HS 8	CL-5837	20-1049	CLJ-31370	17-4523
CK-4047	26C80	CL-2766-1	24S53	CL-25491	19-3660	CLJ-31371	17-4538
CK-4225	19-1001	CL-2767	HS 7	CL-25518	17-1026 <sup>1</sup>	CLJ-31373	20-1004
CK-4415	19-1004	CL-2972	20-1021	CL-25545	20-1049 <sup>9</sup>	CLJ-31375	HS 5
CK-25465	26C80	CL-2973	20-1006	CL-25786	19-4160	CLJ-31521	17-3419
CK-26651/-2	26C80	CL-2990	HS 3	CL-25787	19-3125	CLJ-31522	17-3419
CK-32072/-3	26C81	CL-3386-1	17-3495 <sup>5</sup>	CL-26189	17-4504	CLJ-33010	Y 91
CK-32072R	26C81	CL-3398	19-3250	CL-26215	Y 90	CLJ-33012	17-3419
CK-33749	26C81 <sup>1</sup>	CL-3401	19-3075 <sup>2</sup>	CL-26425	19-3100	CLJ-33206	Y 91
CK-34653/-1	26C81	CL-3403/-1	19-3300	CL-26426	19-4160	CLJ-33264	Y 123
CKJ-33014	26C77	CL-3497	17-5001 <sup>8</sup>	CL-26946	17-4534	CLJ-33266	WC 22
CKJ-33264	Y 123	CL-3498	17-5002	CL-27854	Y 90	CLJ-33338	17-3415
CKJ-33385	26C81	CL-3499	17-5003	CL-28083	17-4524	CLJ-33389	Y 86
CKJ-60841	26C80	CL-3500	17-5001	CL-28212	17-5003	CLJ-33390	HS 16
CKL-33014	26C77	CL-3598	Y 9 <sup>8</sup>	CL-28518	HS 5 <sup>1</sup>	CLJ-60129	Y 123
CL-1356	Y 3	CL-3603/-1/C	-4/-6/-7	CL-28650	20-1049	CLJ-71097	Y 132
CL-1357	19-4180	CL-3606-1	17-1031	CL-28785	HS 5 <sup>1</sup>	CLJ-71202	Y 132
CL-1358	19-3180	CL-3614	17-1031	CL-31052	17-1031	CLP-31683	19-3036
CL-1471	17-1003	CL-3659	17-3495 <sup>8</sup>	CL-31686-2	19-3160	CLP-31686	19-3180
CL-1472	20-1021	CL-3668	17-1063	CL-32071-5	FC 7	DC-167	Y 123
CL-1502	WC 11	CL-3715	17-1063	CL-32138-507	Y 107	F-83/A	FLY 391
CL-1503	WC 14	CL-3831	17-4524	CL-32138R	Y 107	R-0060	Y 16
CL-1535	19-3180	CL-3833-1	17-4503 <sup>1</sup>	CL-32320-2	WC 35	R-1405	HS 8
CL-1536	19-4122	CL-3847	Y 10 <sup>8</sup>	CL-32417-1	WC 41	R-1406	HS 7
CL-1543	FC 2	CL-4021	17-3412	CL-32417-3	WC 43	R-1431	19-6002 <sup>2</sup>
CL-1842	Y 1	CL-4413	17-1063	CL-32417-4	WC 44	R-1470	19-3093
CL-2073	19-3250	CL-4511	17-4524	CL-32418-2	17-6022	R-1635	17-3400
CL-2087/-2	Y 6	CL-4711	17-4523	CL-32420-3	17-6028	R-1949	19-5100 <sup>2</sup>
CL-2300/-1	FC 2	CL-4753/-1	20-1049	CL-32422-4	20-1057	R-2054	17-4522
CL-2309	17-1062	CL-4791	17-4523	CL-32442-15	19-3125	R-2055	17-4522
CL-2331	20-1004	CL-4806	17-4503	CL-32634P	19-3100	R-2056	26C78
CL-2427	19-3001	CL-4806-1	17-4504 <sup>8</sup>	CL-32888-2	19-2025	R-2057/-1	FLY 154
CL-2614	19-3500	CL-5402	WC 22	CL-34090-2	WC 53	R-2058	26S25
CL-2678	WC 14	CL-5464/-1	HS 5 <sup>1</sup>	CL-34517	WC 43	R-2059	24S54
CL-2709	14-1073	CL-5706	20-1020	CLJ-31367	Y 91	R-2060	Y 54
CL-2752	WC 18			CLJ-31368	17-4534	R-2062	17-4534

# OLYMPIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
R-2065	19-1001	TR-2615	FLY 59	TR-31659-1/2	26S72 <sup>1</sup>	100037	26S48
R-2159	20-1005	TR-2630	17-3497	TR-31752	26R116	100131	19-3125
SA-29096	Y 89	TR-2686	26S48	TR-31898P	16-6780	101817	19-3036
SA-29097	Y 89	TR-2690-1	24S50A1	TR-32060K/R/		101819	19-3036
SA-29099/A	Y 89	TR-2706-1	24S50	-501/-502	26R150	102134	26C81
SA-33752	Y 105 <sup>14</sup>	TR-2765	26S75 <sup>7</sup>	TR-32061R	FLY 277	105065	WC 41
SA-34214	Y 109	TR-2766/-1/1B	24S53	TR-32061-501	FLY 277	105066	WC 42
SA-34503	Y 109	TR-2766-1C	24S53	TR-32062-3	24S86	105195	26C81
SA-34548	Y 105 <sup>14</sup>	TR-2770	24S78 <sup>1</sup>	TR-32062R	26S86	105196	WC 35
T-D41H	Y 81 <sup>8</sup>	TR-2771	24S78 <sup>1</sup>	TR-32411-3	17-6033	105213	17-6018
T-D111-UC25	Y 109 <sup>12</sup>	TR-2771-1/2	FLY 12	TR-32413-2	20-1050	105214	17-6019
T-D115-UC25	Y 109 <sup>12</sup>	TR-2781-1	17-1023	TR-32413-3	20-1052	105216	17-6011
TDT-330/-7	26S85	TR-2977	17-3495	TR-32419-2	17-6032	105294	17-3417
TDT-332E/-1	Y 91	TR-2978	26R91	TR-32421-2	17-3420	105295	20-1057
TDT-335E-1	Y 91	TR-2990/-1	HS 9	TR-32423-4	17-1083	106383	20-1050
TDT-395E-1	Y 86	TR-3159	24S61	TR-32424-2	17-6031	107290	17-3402
TDT-396	HS 16	TR-3385	26S51	TR-32444-7	17-3414	107837	17-6012
TDT-405H	26S90	TR-3386-1	17-3495 <sup>5</sup>	TR-32444-8	17-3419	109180	WC 43
TDT-442-1	Y 123	TR-3388-9	26S54	TR-332062R	26S86	109221	FLY 281
TDT-483-1	Y 109 <sup>9</sup>	TR-3397/-1/2	FLY 75	TR-33549/-1	26S72	109223	HS 8
TF-83A-33	FLY 109 <sup>9</sup>	TR-3599/-2	FLY 207 <sup>8</sup>	TR-33747	22S32	109253	17-3419
TFT-276	HS 5	TR-3599-3/4/		TR-33747	22S32	109254	17-3414
TL-23	HS 16	-4A/-5/-5A/	FLY 207	TR-34650	FLY 593	109254	19-3600
TL-260	19-1014	-5D/-6	26F12 <sup>1</sup>	TR-34652	26S86	109257	20-1052
TL-262	19-1027	TR-3642	26S48	TR-100037	26S48	109261	26S87
TL-275	19-3125	TR-3659	26S26	TR-105195	26C81	109263	FC 7
TL-276	19-2028	TR-3661	24S98	TR-109237	HS 8	109264	FC 7
TL-983	WC 22	TR-3667	26R47	TR-131364	26S75 <sup>8</sup>	109286	26R150
TLT-122	26C77	TR-3689/-1/		TR-131365	17-4522	109286	Y 107
TLT-122-07	26C79	-C/-D	26S26	TR-131369	17-4511	109475	19-4060
TLT-122-41	26C77	TR-3689-3	26S75	TR-131372	17-3419	109840	26S88
TLT-123	24S51	TR-3821-1/2	26R71	TR-131522	26S01 <sup>1</sup>	109850	16-6758
TLT-123H41	24S51	TR-3855	FLY 207 <sup>3</sup>	TR-131527	24S05	110463	16-6758
TLT-128H41	22S33	TR-4007/-2/		TR-131529	22S33	110464	16-6758
TLT-158	24S53	2R2/-28	26R116	TR-133025	22S33	111295	16-6758
TLT-158-21	22S61	TR-5598	FLY 208	TR-133267	22S61 <sup>1</sup>	111296	16-6758
TLT-174H-21	26C81	TR-5620/A/		TR-133268	26S30	112820	FLY 273
TP-33549	26S48	-1/-2	24S53	TR-133269	FLY 339	112821	26S86
TR-1342	FLY 1	TR-5657	26S26	TR-133287	24S53	112822	26S48
TR-1343	24S68	TR-25367	22S87 <sup>1</sup>	TR-60178	26S90	112829	26C81
TR-1469	17-1013	TR-25743	24S06	TR-60182	22S61	112845	26R150
TR-1470	17-1011	TR-25791/-1/		TR-60445	19-3275	112866	HS 23
TR-1471	17-1004	-2/-C	26S27	TR-60843	FLY 391	112869	17-6031
TR-1472	20-1021	TR-25992/-1	24S06	TR-60848	24S53	112870	17-1083
TR-1473	26A03	TR-26192	26R21 <sup>8</sup>	TR-60849	26S34	112871	17-3420
TR-1474	26R98	TR-26192-1	26R40	TR-71100	FLY 443	112872	17-6028
TR-1475	HS 2	TR-26205/-1	FLY 209	TRP-31707	26S49	112873	17-6032
TR-1475-1	HS 3	TR-26214	26R106 <sup>1</sup>	TRP-31715	26S49	112874	

# PACKARD BELL

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
TLL-52251-1	17-3420	29078	16-6758	29644/A	17-4523	29882	19-1003
TLM-053-999	19-1008	29080/C	16-3445	29645/C	Y 52	29892	Y 245
TLM-070-999	19-1004	29080/B	17-3495	29646	19-1005	29894	HS 5
TLM-080-999	19-2015	29081	20-1005	29650	19-4060	29895/A	WC 53
TLP-108	26C77	29091/A	17-1031	29659/D	HS 5	29896	FC 6
TLP-113	26C79	29267	16-6780	29661	HS 17	29897	WC 23
TLP-408	26C79	29271/A	16-3490	29669/A	HS 5	29898	17-6033
TLP-3231	26F67	29276	16-6780	29694	17-3477	29914A	17-1077
TLP-5106	26C79	29469E	17-4524	29695/A	HS 5	29915A	17-1077
TLP-5151	26C81	29501	19-3250	29658/D	HS 5	29916B	20-1050
TLQ-700-999	19-7068	29502	17-1002	29696	Y 52	29917	FC 6
TL-1153	20-1051	29503	WC 11	29697	17-4593	29918	19-3036
TL-1160	20-1051	29504	WC 14	29699/A	HS 5	29928/-B	Y 109
TL-1165	20-1055	29505	FC 1	29703/A/-B	HS 5	29939	19-3100
TL-1176	20-1008	29506	19-4122	29713/A	19-3600	29948	19-2026
TL-51003	20-1004	29507	19-3093	29713D	19-3600	29951	WC 41
TL-51201-1	17-1026	29508	19-4180	29714/C	20-1005	29952	WC 44
TL-512020-2	17-3495	29509	19-3250	29715/A	HS 5	29953	WC 48
TL-51203-1	17-1031	29509A	19-3250	29716/A	Y 92	29954A/B	Y 109
TLT-033-999K	19-1003	29509C	19-3250	29717	Y 52	29962	17-1048
TLT-039-109	19-1003	29510	24A88	29718/A	WC 34	29968	19-7068
TLT-121-999	19-3125	29511	FLY 1	29718/B/C	WC 34	29992	19-7068
TLT-221-999	19-4201	29515	19-4060	29727	17-3411	29994	WC 10
TLT-301-999	19-3300	29516	20-1021	29728	17-3413	29995	19-3275
TLT-351-999	19-3330	29517	WC 16	29729	17-3414	72162-1	VMT-05-01
TLT-470-999	19-7047	29519	FC 3	29730	17-3417	72162-2	VMT-03
TLT-500-999K	19-7047	29520	19-3036	29731/32	19-3180	72180	VMT-08
TLT-700-999K	19-3075	29521	FC 2	29734	WC 41	89027/A	26R26U <sup>1</sup>
TLT-01017	19-1000	29527	HS 5	29735	WC 42	89031	26A03
TLT-010999	19-1003	29529	20-1004	29737	Y 107	89032	26R27U <sup>1</sup>
TLT-040107	19-1003	29530	Y 6	29740	WC 35	89035	26R21
TLV-101	26A02	29531,B,C	WC 17	29741	HS 7	89036/B/-C	26R35 <sup>3</sup>
TLV-102	26A02	29532	WC 23	29744/B	17-6016	89041	26R35
TLV-233	26S97	29533	Y 13	29745	17-6018	89042	26R21 <sup>3</sup>
TLV-468-S/-D/-TS	Y 5008	29536	Y 13	29746	17-6019	89043/-B	26R21 <sup>3</sup>
TLV 469DS/PS	Y 105 <sup>13</sup>	29537	Y 7 <sup>2</sup>	29748/A/B	17-6821	89045	26R92
TLV 3359/-4D	Y 120	29539	Y 7 <sup>2</sup>	29752	19-3180	89046	26A03
TLV-5310	Y 122	29540	WC 22	29753/A	HS 5	8047	26R00
TLV-5311	Y 122	29541	16-3445	29755	17-4534	89050	26R88
25545	17-3401	29542	Y 9 <sup>2</sup>	29757	20-1049	89051	26R33 <sup>3</sup>
27005	26C93	29545/-A	20-1005	29758/A	Y 93	89056/-A	26R122
27006/A/-B	26C79	29547	17-3402	29759	20-1049	89058	26R88
27006C	26C79	29548/A/C	20-1004	29760/64A	20-1049	89060.A	23V52
27006D/E	26C79	29549	17-1070	29766/A	20-1049	89066	26R130
27012	26C79	29551	19-3001	29771	19-2026	89067	FLY 201
27013/A	26C79	29552	19-3093	29773	19-3250	89076/A/B	26R100
27016	26C80	29553	17-1069	29778	20-1005	89084	26R120 <sup>1</sup>
27017/-A	26C77	29554	17-1070	29779	17-4511	89090/A	26R122
27018	26C80	29555B	WC 18	29781	19-3250	89113A/D	26R150 <sup>1</sup>
27020/C	26C81	29556	Y 11 <sup>2</sup>	29782/A	19-1006	89229	26S01
29018	17-3487	29557	19-3250	29787	19-1008	89405	22558
29021	16-3487	29558	19-4400	29788/B	FC 7	89422	26553
29022A	16-6758	29559/A	20-1049	29797/-1B	Y 93	89423	24586
29023	16-6758	29560	17-4536	29802/A	17-3402	89424	FLY 4
29025	17-1011	29561/A	17-4523	29803B	17-3417	89425	22558
29026	17-1001	29563	16-3445	29803C	17-3417	89426	22558
29027	17-1002	29564/A	20-1049	29807/-A	WC 49	89426/A	22558
29028	17-1003	29565/A	17-4538	29807/-B	WC 49	89427	24552
29029	19-1013	29566	19-1005	29808/-A	WC 50	89427/A	24551
29030	HS 1	29567	Y 14 <sup>2</sup>	29808/-B	WC 50	89430	26552
29031	17-1043	29568	WC 18	29814/A	WC 35	89431/B	26556 <sup>4</sup>
29036	19-3036	29569	WC 22	29815/A	17-6012	89432A/-C	FLY 2
29038	16-3487	29570A	17-4535	29815B	17-6019	89434	26554
29041	16-4445	29572A	17-4522	29816A	17-4335	89434/A/B/C	26554
29047	17-1002	29574	17-4501	29818/A	17-4535	89434/D	26554
29048	HS 3	29575	Y 14 <sup>2</sup>	29821B	17-6018	89435	FLY 12
29050	16-6678	29576	17-3400	29822B	17-6018	89436	24551
29051	16-6678	29576A	20-1005	29824	17-3477	D/E	24551
29052	16-6678	29577	19-4400	29825F	20-1005	89437	FLY 12
29053/B	20-1004	29579	17-4522	29826/B	Y 92	89438/B	FLY 12
29053C	20-1005	29581	WC 18	29828	17-4522	89439	22556
29054	17-3493	29582/A	HS 5	29829/30	20-1045	89440	FLY 24
29055	17-1063	29584/A	17-4534	29838	20-1005	89440/A	FLY 24
29056	17-1063	29585	17-4523	29839	17-4534	89441	26557 <sup>1</sup>
29057	16-3472	29586/A	17-4522	29840	Y 107	89442	26553 <sup>2</sup>
29058	17-3487	29587	17-4522	29842/B	Y 92	89442/B	FLY 16
29059	17-3487	29587/A	17-4523	29843/A	WC 48	89443/B	26573
29063	16-6758	29587B	17-4523	29843/B	WC 48	89448/B	FLY 16
29064	16-6758	29589/A	HS 5	29843/-1B	WC 48	89451	26552
29066	16-6758	29590A/B	Y 60	29844/B	WC 56	89456/A	26556 <sup>4</sup>
29067	16-6758	29590/C	Y 60	29845	FC 7	89456/B	26556
29068	17-3493	29606	19-4122	29861	HS 5	89457	FLY 24
29077	16-6758	29629	HS 5	29864	19-3180	89458/B	FLY 76
				29866A	17-4538	89460/A	22588

# PACKARD BELL

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
89461/B	FLY 212	89508	26S95	89557A/-C	26C81	89622-1	FLY 446
89465	FLY 202	89510	26C81	89561	26R111 <sup>1</sup>	290520/C	Y 109
89465A	FLY 202	89515/A/B	22533	89562/-A	26R150	290545-2/E	Y 159
89466/A	26S48	89522/B	26S08	89563	FLY 277	903562-507	Y 107
89479B/D	FLY 100	89529	26S08	89573A/B	24551	906186-501	Y 245
89479D	FLY 100	89532/B	26S01	89579	24551	10-220-5	WC 23
89480	26S14	89543/A/B/C	26S07	89580	26S07 <sup>1</sup>	10-228-5	WC 41
89480A/B	26S08	89545/A	22533	89583/B	FLY 336	80-72-6/A	26C81
89483/B	26S08	89545/B	22533	89585/D	26R152	80-98-4/B	Y 163
89488/A	FLY 166	89547	26R150	89592-B/C	FLY 336	80-145-3/D/C/G	FLY 364
89500/B	24S52	89548/B/E	FLY 273	89594/B	FLY 503	80-28-1/C	24S85
89500/C	24S52	89549/-C	26S86	89604/A/C	24S96 <sup>8</sup>	80-284-9	24S85
89501/B	26S08	89551	22586	89605/B	FLY 336		
89506	26R150	89552/A/B	24551	89606/B/C	24S50		
89507	FLY 284	89554	26R150	89616/A	FLY 395		

# PANASONIC

(SEE MATSUSHITA/PANASONIC)

# PENNCREST

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AZ-396A	WC 14	TLL-52251/-1	17-3420	TLT-331-999	19-3330	9A2477-001H	Y 72
AZ-9037	HS 7	TLL-50352	17-4528	TLT-390-999	19-2020	9A2477-002/A	Y 72
AZ-9052A	WC 14	TLM-053-999	19-1008	TLT-470-999	19-7047	9A2477-002/B/D	Y 72
AZ-9099A	HS 17	TLM-070-999	19-1004	TLT-500-999	19-7047	9A2481/-A/-B	HS 7
AZ-9107	WC 35	TLM-080-999	19-2015	TLT-700-152	19-7068 <sup>2</sup>	9A2485/-1/-1E	Y 73
AZ-999B	WC 10	TLP-113(Z)	26C79	TLT-700-999	19-3075	9A2485-2	Y 73
ELQ-3A9	19-2006	TLP-3231-1	26F67	TLU-500-392	19-7047 <sup>2</sup>	9A2485-2D	Y 73
EP77X21	FLY 606	TLP-3238	26F67	TLU-700-999	19-7068	9A2487	HS 5
EP77X22	FLY 607	TLP-5106-1	26C79	TLV-102	26A02	9A2491	16-6758
EP77X31	FLY 638	TLP-5151	26C81	TLV-468TS/S/D	Y 5008	9A2504	20-1004
EP77X32	FLY 638	TLP-5152	26C81	TLV-469D/S/PS	Y 105 <sup>13</sup>	9A2508	16-6758
ETA-28A36A	22S61 <sup>1</sup>	TLP-5222	23V456 <sup>1</sup>	TLV-3359-4D	Y 120	9A2514-1	Y 74
ETA-28F3A	24S60	TLP-8508	19-4201	TLV-3361-D	Y 120	9A2514-2	Y 74
ETA-41D2A	24S60	TLQ-120-106	19-1005	TLV-3361-3D	Y 120	9A2515/-B/-001	HS 16
ETA-41D2A	24S06	TLQ-120-139	19-1010	TLV-3361-D	Y 120	9A2522/-1/-1B	Y 104
ETA-48E27B	24S06	TLQ-700-999	19-7068	TLV-5310/11/11S	Y 122 <sup>4</sup>	9A2525	17-5021
ETA-48E27WA	24S06	TLV-1160	20-1051	TLV-5320/F	Y 132	9A2526	20-1069
ETA-48E65C	24S06	TLV-1165	20-1055	TPW-104	26C81 <sup>1</sup>	9A2526	20-1069
ETA-48E65WA	24S06	TLV-1176	20-1008	TPW-951	26C77	9A2526-001	10-1069
ETP-57A40A	26F67	TLV-2151	17-1008	TPW-971	26C80 <sup>1</sup>	9A2527	17-1075
ETQ-57B1A	26C81	TLV-5120-1	20-1054	TPW-988	26C80 <sup>1</sup>	9A2527-001	17-1075
TLD-02501-5	19-6022	TLV-51003	20-1004	TSB-205	22S61 <sup>1</sup>	9A2528	17-5020
TLD-02891-2	19-2011	TLV-51003-1	20-1004	TSB-324	24S52	9A2529	20-1070
TLD-05001-5	19-3060	TLV-51201-1	20-1054	TSP-1001	22S31	9A2529-001	20-1070

# PENNCREST

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
9A2558-001	WC 36	32-4902-14	19-2028	52X0112-003	26C78	235V144801	17-6093
9A2558-002	WC 55	32-9801-1/2	Y 105	52X0112-004	26C78	235V145801	20-1057
9A2559-000	20-1050	32-10152-1	FLY 557	52X0112-005	26C78	430V039C11	26S75
9A2559-001	20-1050	32-10177-2	FLY 306	52X0112-006	26C78	430V039H11	26S75
9A2560-000	20-1052	32-10834	Y 17	52X0114-000	26C81	430V067H01/	
9A2560-001	20-1052	36A2	19-3180	52X0114-001/		801	26S48
9A2561-000	17-1083	36A12	19-4160	002/F	26C81	430V121C05/	
9A2561-001	17-1083	36A19	19-3125	53X98F	FLY 146	02	26C77
9A2562-001	17-3418	36A22	19-3300	53X207/-1A	26S22	430V121H02	26C77
9A2562-002	17-3414	36A27	19-3330	53X307/B	26R121 <sup>9</sup>	430V150H02	22S61 <sup>1</sup>
9A2562-003	17-3419	36A28	19-4400	53X395	26R106	430V161801/02	26C81
9A2562-004	17-3419	36A45	19-3275	53X397	FLY 244	490V017C01	Y 105 <sup>8</sup>
9A2563-000	20-1058	36A51/-52	19-3375	53X397-2	FLY 244	490V028D03	Y 108 <sup>8</sup>
9A2563-001	20-1058	36A9A-1	19-4201	53X397-002	FLY 244	490V031D02	Y 108 <sup>8</sup>
9A2564-001	17-6022	36A9A-2	19-3660	53X398/-F/C	FLY 146	493V015H01	FLY 561
9A2565-000	20-1057	36A9A-3	19-3330	53X404	24R47 <sup>8</sup>	493V018H01	FLY 560
9A2565-001	20-1057	36A9A-9	19-3300	53X404-B	26R47 <sup>8</sup>	493V019H01	FLY 561
9A2566-001	17-6028	36A9A-10	19-4201	53X404-C	26R47 <sup>8</sup>	493V020H01/	
9A2566-002	17-6028	36A0094-001	19-4201	53X408/-A	FLY 225	H02/H03/C01/	
9A2567-001	17-6032	36A0094-005	19-3500	53X0397-002	FLY 244	C03	FLY 562
9A2568-001	17-6037	36A0094-006	19-3500	53X0407-001	26R126	493V023D01	FLY 445
9A2569-001	17-3420	36A0094-009	19-3300	53X0408-000A	FLY 225	493V023D03/E	FLY 445
9A2570-001	17-6031	36A0094-010	19-4201	53X0414-001A	26R150	493V023D03/F/	
9A2572-001	FC 6	36A0094-015	19-3060	53X0416-001	FLY 277	G	FLY 445
9A2572-002	FC 6	36A0095-001	19-7068	53X0425-001/		600X0060-009	26C79
9A2572-003	FC 6	36A0095-002	19-1005	53X0431-001	FLY 336	600X0062-053	FLY 557
9A2576-001	Y 107	36A0095-005	19-1037	53X0437-001	FLY 397	600X0111-009	Y 105
9A2577-001	16-6765	36A0095-006	19-2025	53X0438-001/		601X0003-009	Y 245
9A2578-001	16-6770	36A0095-007	19-1037	B/C	FLY 277	601X0203-009	17-3418
9A2595-001	20-1054	36A0095-009	19-3330	53X0440-001	FLY 333	601X0204-009	17-3419
9A2597-001	17-1019	36A0095-010	19-3060	53X0441-001C	26R152	601X0219-036	19-2026
9A2599-001	17-1049	36A0096-001	19-3036	53X0444-001C	FLY 333	690V101H47	FLY 445
9A2602-001A	Y 104	36A0096-003	19-3125 <sup>2</sup>	53X0446-001C/		0333085	19-1008
9A2602-002A	Y 104	36A0096-005	19-2028	B/A	FLY 337	0333096	19-2026
9A2604-001/A	Y 104	36A0096-007	19-1008	53X0447-001	FLY 392	0352041	Y 91 <sup>5</sup>
9A2605-001/B/D	Y 104	51X192-2	24S48	53X0452-002	23V452 <sup>1</sup>	0423200	26C77
9A2605-001C	Y 104	51X192-3	24S48	53X0453-001/C	FLY 384	0453111	22S61
9A2606-001	17-5024	51X192-4	24S48	53X0456-002	23V452 <sup>1</sup>	0455035	26C30
9A2611-001	17-1083	51X192-5	24S48	53X0456-001/G	23V453 <sup>1</sup>	105065	WC 41
9A2622-001	17-3415	51X193-2	26S85	53X0459-001/A/		105295	20-1057
9A2623-001	17-5030	51X193-3/B	26S85	F/G	FLY 502	106383	20-1050
9A2624-001	17-5019	51X206	22S25	53X0464-001/		109180	WC 43
9A2625-001	Y 52 <sup>8</sup>	51X207-2/A	26S22	F/G	FLY 476	109252	17-3418
9A2625-001A	Y 52 <sup>8</sup>	51X220-4	24S92	53X0465-001F/		109255	20-1058
9A2629-002/B	HS 48	51X220-5	24S96	H/J/L	FLY 501	109261	20-1052
9A2630-001	WC 54	51X223-3	26S08	53X0470-001B	FLY 651	109457	Y 107
9A2632-001	Y 245	51X224	26S07 <sup>5</sup>	54X24	21F21	112822	26S48
9A2634-001(A)	WC 38	51X229-1/-1A	26S30	54X0024-001	21F21 <sup>5</sup>	112829	26C81
9A2634-002	WC 38	51X233-1	26S23	54X0024-002	21F21 <sup>5</sup>	112866	HS 23
9A2637-001	Y 245	51X0192-004	24S48	54X0024-003	21F21 <sup>5</sup>	112869	17-6031
9A2648-001/E/B	Y 245	51X0192-005	24S48	230V019H24	19-7068	112870	17-1083
9A2654-001/B	Y 109	51X0223-003	26S08	230V031H01	20-1055	112871	17-3420
9A2654-001/D/E	Y 109	51X0223-004	26S08	230V031C06	20-1055	112872	17-6028
9A2656-001	17-6022	51X0229-001A	26S30	230V031H06	20-1055	112873	17-6032
9A2658-001	17-6028	51X0229-003	26S30	230V130H01	19-1008	112874	17-6022
9A2658-002	17-6028	51X0229-005	26S30	230V130H02	19-1006	112875	WC 36
9A2660-001	17-6053	51X0235-001	24S53	230V130H03	19-2009	112877	17-6033
9A2661-001	17-6027	51X0235-001A	24S53	230V130H09	19-2011	112879	17-3414
9A2661-002	17-6027	51X0235-005	24S53	230V130H10	19-2013	113382	FLY 277
9A2662-001	WC 23	51X0236-000	24S61	230V141H02	19-3600	113383	26R150
9A2667-001	17-3420	51X0236-001	24S61	230V141H03	19-3125	113390	26S86
9A2667-002	17-6022	51X0236-002	24S61	230V141H04	19-3500	113394	WC 44
9A2679-001	17-6023	51X0236-003A/		230V141H06	19-3300	113404	19-3660
9A2680-003	19-1003	004	24S06	230V141H12	19-7068	113547	17-3419
9A2680-004	19-1004	51X0237-001	26S86	230V141H13	19-3660	113640	FC 7
9A2681-001	20-1079	51X0238-001	24S64	230V141H14	19-1005	113641	Y 150
9A2681-002	20-1079	51X0239-001	26S07	230V141H15	19-2013	113642	26S109
9A2682-001	HS 6	51X0239-002	26S07	230V144H01	HS 16	113543	WC 41
9A2683-001	17-5020	51X0240-001	24S48	230V144H01	HS 16	113669	Y 188
9A2685-001	17-6060	51X0240-002	24S48	230V183B01	HS 46	113742	Y 224
9A2707-001-B/-A	Y 137 <sup>14</sup>	51X0241-001	26S103	230V184B01	WC 38	113816	FLY 518
G/M	Y 181	51X0242-001	26S105	230V185B01	WC 45	113846	26C81
9A2745-001/C/F	Y 172	/D	26S102	230V186B01	WC 54	113851	FLY 517
9A2746-001	Y 172	51X0246-001	26S104	230V187B02	WC 41	114146	FLY 592
9A2757-001/A	Y 259	(B)	26S107	230V188B01	17-6091	142130	Y 246
9A2758-001/B	Y 172	51X0249-001/D	24S05	230V192B01	17-6022	200426	19-3036
32-4112-63	19-4217	52X95-11	26C90	235V046H01	17-1090	200892	19-3125
32-4645-7	19-1002	52X95-12	26C79	235V048H01	17-3419	200894	19-3126
32-4686-34	17-5036	52X95-13	26C79	235V048H04	17-3419	200902	19-4400
32-4686-13	17-3489	52X102-2	26C81 <sup>1</sup>	235V049H02	17-5017	201114	HS 7
32-4745-12	17-3489	52X102-2/-4	26C81	235V076H04	20-1192	201142	Y 150
32-4754-3	HS 16	52X112-1	26C78	235V141B01	20-1102	201148	20-1044
32-4876-1	20-1050	52X0102-003	26C81 <sup>1</sup>	235V143B01	17-6023	201166	19-2019
32-4902-10	19-3180	52X0102-006	26C81 <sup>1</sup>	235V143C02	17-6023	201167	19-7047

# PENNCREST

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
201168	19-1014	299860	19-1010	23222011	WC 35	23252313	19-2021
201171	19-2026	1435649	FLY 518	23222012	WC 10	23252314	19-2023
201173	19-3180	1435684-502	FLY 592	23222540	HS 7	23252321	19-1051
201176	19-3275	1456605-503	Y 150	23225120	HS 7	23252365	19-7047
201183	19-2033	1463747-501	Y 246	23242106	19-2026	23252436	19-1001
201279	WC 14	22252298	19-1014	23252026	19-2047	23261014	19-1008
201290	19-1030	23211018	26C80 <sup>1</sup>	23252109	19-7033	23261015	19-1009
201349	19-5101	23211019	26C80 <sup>1</sup>	23252286	19-2019	23261018	19-1008
201433	HS 7	23211023	19-1030	23252289	19-3180	23261019	19-1010
201453	WC 35	23211025	26C81 <sup>1</sup>	23252291	19-3275	23272013	19-1008
201457	19-1001	23214008	24S52	23252292	19-3330	48004014	Y 109 <sup>14</sup>
299766	26C80 <sup>1</sup>	23216058	22S31	23252299	19-3160		
299773	FC 6	23221009	19-4201	23252311	19-2020		

J. C. PENNEY

(SEE PENNCREST)

PHILCO

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AZ-599A	19-6821	18-2010-1/2	Y 68	32-4234-8	19-1023	32-4467-3	19-3100
AZ-634A	17-6019	18-2327-1	Y 65	32-4234-12	19-1023	32-4467-7	19-1921
AZ-749H	HS 7	18-2654-1	Y 68	32-4234-13	17-1003	32-4467-11	19-1923
AZ-854G	19-6022	18-2810-2	Y 68	32-4234-17	19-1021	32-4467-13	19-1923
AZ-9052	WC 14	18-2880-2/		32-4234-19	19-1021	32-4467-18	19-1921
AZ-9107	WC 35	-5/-6	Y 150	32-4236	17-1011 <sup>1</sup>	32-4467-19	19-1921
EP36X20	32-4112-2		19-3001	32-4240-3A	16-6758	32-4467-20	19-1921
EP36X813	32-4112-3		19-3001	32-4256	19-3247	32-4467-22	19-3125
EP61X173	32-4112-11		19-3001	32-4257	16-3487	32-4468	WC 23
EP61X174	32-4112-15		19-1002	32-4257-1	16-3487	32-4468-1	WC 23
EP61X175	32-4112-24		19-1005	32-4258	16-6758	32-4468-4	WC 23
EP61X177	32-4112-25		19-1005	32-4261	17-3488	32-4468-5/-6	WC 23
EP63X67	26C77	32-412-31	19-1001	32-4263	14-1073	32-4470-1/	
EP64X113	26S57	32-4112-43	19-1007	32-4302	19-1021	-3	HS 3 <sup>1</sup>
ET36X814	20-1051	32-4112-49	19-1002	32-4303	19-1020	32-4480-1	19-3036
EUA61X121	20-1057	32-4112-50	19-1006	32-4303-2	19-1021	32-4480-2/3	19-3100
ETA-							

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
32-4548	17-4523	32-4753-3	HS 16	32-4912-2	19-1000	32-8515	26S71
32-4548-12	19-3001	32-4754-2	HS 16	32-4924-1	HS 7	32-8525-1	24S51
32-4548-15	19-1002	32-4754-3	HS 16	32-4929-1	17-6113	32-8533	FLY 55
32-4548-24/-25	17-4524	32-4762-1	19-3375	32-4930-1	17-6114	32-8534	FLY 55
32-4548-26	17-4524	32-4762-3	19-3075	32-4931-1	17-6115	32-8537-1	26C44 <sup>1</sup>
32-4548-27	17-4523	32-4762-4	19-3100	32-4932-1	17-6116	32-8538	21F43
32-4557-3/-4	HS 5	32-4762-5	19-3125	32-4936-1	20-1109	32-8539	26S30
32-4583-23	16-6780	32-4762-6	19-4160	32-4936-2	20-1110	32-8539-1	26S30
32-4597-2	19-1001	32-4762-7	19-3180	32-4942-1	19-2015	32-8555	FLY 11
32-4597-3	19-3001	32-4762-8	19-3250	32-4959-12	20-1111	32-8565	FLY 27
32-4597-11	19-1003	32-4762-9	19-3275	32-4959-15	20-1111	32-8568	FLY 5021
32-4597-12	19-1001	32-4762-10/-20	19-3330	32-5877	17-6022	32-8572	FLY 119
32-4597-15	19-1001	32-4762-11	19-4400	32-8206-1	24S86 <sup>1</sup>	32-8573-1/-2	26C23
32-4598-3	17-4523	32-4762-12	19-3600	32-8242/-7	26S49	32-8574	21F12 <sup>1</sup>
32-4630	19-6022	32-4762-13	19-3600	32-8242-9	26S49	32-8577/-	TO -5
32-4631A	17-3497	32-4762-14	19-3660	32-8242-11/-12	26S49	32-8244/-1	FLY 5021
32-4631-1A	17-3497	32-4762-20	19-3330	32-8244-1	26S48	32-8244/-1	22S35
32-4644-3	20-1008	32-4762-27	19-2023	32-8244-2	26S48	32-8244-1	26S15
32-4644-4	20-1061	32-4762-28	19-2011	32-8303	26S61	32-8690	26R47
32-4644-13	20-1061	32-4762-30	19-1003	32-8304	26R94	32-8691	FLY 16 <sup>3</sup>
32-4644-14/18/19	20-1061	32-4766-1	17-1079	32-8304-3/4	26A06	32-8693	26C76
32-4644-15	20-1061	32-4769-2	19-4500	32-8305	26A06	32-8695-1	FLY 131
32-4644-20/25	20-1061	32-4769-4	19-3330	32-8305	FLY 1	32-8701-1	FLY 27 <sup>3</sup>
32-4645	19-1003	32-4769-6	19-3180	32-8306/-1	24S86 <sup>1</sup>	32-8704	26S14
32-4645-2	19-1001	32-4769-7	19-3375	32-8307/-2/-3	24A89 <sup>1</sup>	32-8705-1	FLY 16 <sup>3</sup>
32-4645-3/-19	19-1002	32-4769-8	19-4201	32-8308	20C69 <sup>1</sup>	32-8708	26R43
32-4645-4	19-1000	32-4770-3	HS 3	32-8312	26C42	32-8709	FLY 130
32-4645-6	19-1002	32-4805-1	20-1061	32-8331	FLY 1 <sup>1</sup>	32-8709-1	FLY 5021
32-4645-7	19-1002	32-4824-1	19-1002	32-8335-1	26C64 <sup>1</sup>	32-8710-2	26C44
32-4645-8	19-1002	32-4834-1	16-6787	32-8335-1	26S49	32-8710-3/-4	26C44
32-4645-9	19-1002	32-4834-2/-3	16-6780	32-8335-1	24S51	32-8710-7/-8	26C78
32-4645-18	19-1002	32-4837-1	19-6022	32-8338	FLY 4 <sup>1</sup>	32-8710	26C78
32-4645-19	19-1002	32-4837-3	19-2008	32-8362-5	26S50	32-8711	26R47
32-4645-20/22	19-1000	32-4838-2	19-3125	32-8366	20C55	32-8712	26S13
32-4645-32	19-1001	32-4838-4	19-3093	32-8367-1/-2	26S50	32-8719	26R48
32-4645-33	19-3001	32-4840-2	FC 7	32-8367-3/-4	26S50 <sup>1</sup>	32-8730	26R49
32-4645-34	19-1002	32-4847-5	17-3419	32-8367-5	26S50	32-8731	26S29
32-4645-35	19-1002	32-4849-2	HS 23	32-8384-2	26S50A	32-8732	26R43
32-4645-36	19-1002	32-4849-6	WC 44	32-8387-1	20C55 <sup>1</sup>	32-8745	26C44
32-4645-37	19-1002	32-4849-7	WC 36	32-8391	24R64	32-8747-1/-4/	26C79
32-4645-38	19-1004	32-4851-9	19-3660	32-8398/-1	FLY 4 <sup>1</sup>	32-8747-5/6-7	24S48
32-4645-45	19-1001	32-4853-4	19-3610	32-8399	20C55	32-8748	22S50
32-4645-48/32-4652-78/32-4653-1	19-3180	32-4854-1	19-3375	32-8405	26S71 <sup>1</sup>	32-8750	26A01 <sup>1</sup>
32-4653-2	19-3100	32-4867-2	17-3418	32-8405-1	26S53	32-8752	26R124
32-4653-3	19-3100	32-4867-5	17-3419	32-8409	FLY 1	32-8753-1	FLY 197
32-4653-4	19-3100	32-4869-1/-2	17-3420	32-8411-1	26R15 <sup>1</sup>	32-8753-2	FLY 5021
32-4653-5	19-3160	32-4869-1	20-1057	32-8417	26R19 <sup>1</sup>	32-8755	26C44
32-4653-6	19-3250	32-4869-2	20-1057	32-8419-2	26R124 <sup>1</sup>	32-8756	26R124 <sup>1</sup>
32-4662-27	19-2023	32-4869-3	20-1057	32-8421	FLY 1 <sup>1</sup>	32-8757	FLY 197
32-4672-1	HS 5	32-4871-1	20-1052	32-8422-1	26S77	32-8761	26R88
32-4674	19-1006	32-4872-1	17-1083	32-8423-2	26R95	32-8795-1	FLY 197
32-4674-1	19-6022	32-4873-1	HS 23	32-8425	26S72	32-8799-1	FLY 265
32-4684-1	17-4523	32-4873-3	HS 23	32-8425-1	26S71 <sup>1</sup>	32-8802-1	26S71
32-4686-1/-2/3	17-5036	32-4874-1	WC 56	32-8428-1/-2	FLY 47	32-8805-1	26R128
32-4686-11/-25/27-28/30/31-32/34	17-5036	32-4875-1	17-6031	32-8431-2/3	26A06	32-8806-1/-2	FLY 266
32-4688-1/2	17-1078	32-4876-1	20-1050	32-8431-4/-7	26A06	32-8807-1/2	26R116
32-4688-5	17-1078	32-4876-3	20-1061	32-8431-8/9-10	26A06	32-8807-3	26R47
32-4688-6/-7/8-9/10	17-1078	32-4877-1	17-6022	32-8432	26S70	32-8814-1	26S52
32-4688-11/-13/-14	17-3489	32-4878-1	17-6028	32-8432	26S70	32-8825-2	24S52
32-4689-1/-2	17-1078	32-4878-2	17-6055	32-8435	26C43	32-8829-1	26S72
32-4689-3	19-4400	32-4878-3	17-6109	32-8437	FLY 1 <sup>1</sup>	32-8829-2	26S72
32-4690-3	19-3100	32-4879-1	17-6033	32-8438	26C44	32-8829-4	26S72
32-4690-4	19-1921	32-4880-1	17-6032	32-8442	26A02	32-8829-5	26S72
32-4690-5	19-3160	32-4881-1/8	WD 41	32-8442	26A02	32-8830-1	FLY 196
32-4690-7	19-3250	32-4881-2	WC 43	32-8452	26R92	32-8830-2	FLY 196
32-4690-8	19-3250	32-4881-3	WC 44	32-8453/-3	FLY 48	32-8830-3	FLY 196
32-4690-12	19-4400	32-4881-4	WC 68	32-8454-1/-5	26S51	32-8830-4	FLY 196
32-4690-14	19-3250	32-4881-5/-7	WC 63	32-8455	26C43 <sup>1</sup>	32-8840-1/2	FLY 264
32-4690-18	19-3250	32-4884-2/-4/	WC 63	32-8456	26C76	32-8845-1/4	26R126 <sup>1</sup>
32-4691-1/-13/-14	17-3489	32-4885-4/	17-6110	32-8468	26R63	32-8849-1	24S17 <sup>1</sup>
32-4691-2	17-3454	32-4888-1	17-6110	32-8469	26R92	32-8850-1	26R12U <sup>1</sup>
32-4691-3	19-3100	32-4889-1	17-6111	32-8478-2	26C91 <sup>1</sup>	32-8852-1/2	26S72
32-4691-4	19-3250	32-4890-1	17-6103	32-8479-1/-2	26C41	32-8853-1	FLY 196
32-4691-11	19-4400	32-4891-1	WC 98	32-8480	24S50A	32-8855-1/2/	26S72
32-4691-12	19-3500	32-4894-1	HS 48	32-8481	26R94	32-8855-7/-8/9	FLY 196
32-4691-14	19-3250	32-4894-2	WC 99	32-8483	26S50	32-8862-1/2	24S51
32-4691-18	19-3250	32-4902-6	19-7068	32-8484-2	FLY 31	32-8872-3	FLY 30
32-4691-19	17-3454	32-4902-7	19-2025	32-8488	26R94	32-8876-1	24S52
32-4691-21	17-3454	32-4902-10	19-3180	32-8492	26S73	32-8877-1	FLY 196
32-4725-4/-8/32-4735-1/-2	17-3453	32-4902-15	19-2028	32-8500	26C44	32-8881-1/2	FLY 5021
32-4745-2/-5/-6/-8/-12/-13	17-3489	32-4902-19	19-2025	32-8509	FLY 30	32-8899-1	FLY 221
		32-4902-39	19-1015	32-8509-9	26C91	32-8902-1/2/	

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
32-8902-4	26R106 <sup>1</sup>	32-10010-10	26C79	76-9173-8/		76-14327-6	VMT-03
32-8903-1	FLY 5033	32-10010-11	26C81	-6/-10	Y 43	76-14327-7	VMT-03
32-8904-1	26S75	32-10012-5/-6/		76-9173-9	Y 40	76-14327-8	VMT-03
32-8940-1	26S72	32-10013-1	22S32	76-9173-12	Y 43	76-14328-1	Y 190
32-8940-2/		32-10013-2/-6	24S53	76-9173-13	Y 57	76-14328-2	Y 190
-4/-5	26S72	32-10013-4/-3	22S61	76-9173-14	Y 57	76-14328-3	Y 218
-2/-4	FLY 222	32-10013-5	22S32	76-10119/-2	Y 16 <sup>8</sup>	76-14357-1	Y 219
32-8953-1	22S33	32-10014-1/		76-10119-4	Y 68	76-129429-9/	
32-8953-3	24S51	-2	FLY 5042	76-10119-5	Y 57 <sup>8</sup>	-T1	Y 105
32-8958-2	24S07	32-10016-1	26S48	76-10119-6/		79-12942-9	Y 94
32-8961-2/-3	22S61	32-10016-2	24S06	-8/-12	Y 68	229-1214-37	FLY 343
32-8980-2	26C78	32-10017-2/-3	26S86	-2/-3	Y 58	229-1301-11	FLY 546
32-8980-3	26C78	32-10018-1/2	26C81	76-10282-4/-5	Y 58	229-5100-168	19-7068
32-8980-4	26C81	32-10019-2/-3	26R150	76-10304-1	Y 65	229-5100-169	19-1008
32-8980-5	26C81	32-10023-1	FLY 277	76-10508-3	Y 59	229-5100-170	19-1010
32-8980-6	26C81	32-10025-1	21F21	76-10508-4	Y 59 <sup>3</sup>	229-5100-171	19-3275
32-8982-1	26S72	32-10037-1	FLY 556	76-10508-5	Y 59	229-5100-172	19-1001
32-8982-2	26S72	32-10042-1	FLY 313	76-10508-6	Y 59	229-5100-173	19-3330
32-8982-3	26S72	32-10043-1	24S83	76-10508-8	Y 59	229-5100-174	19-2027
32-8982-4	26S72	32-10044-1	26C81	76-10508-9	Y 59	229-5100-175	19-2028
32-8985-1	24S84	32-10057-1/2	24S48	76-10508-10	Y 59	229-5100-176	19-2027
32-8985-2	22S25	32-10058-1	22S61	76-10508-14	Y 59	229-5100-178	19-4201
32-8985-3	24S83	32-10062-1	FLY 387	76-10508-16	Y 59	229-5100-179	Y 108 <sup>8</sup>
32-8985-4	24S60	32-10065-1/2	FLY 556	76-10508-22	Y 59	229-5100-180	WC 14
32-8985-5	24S83	32-10075-1	26C79	76-10508-23/-24	Y 59	229-5100-181	19-2012
32-8986-1	26C79 <sup>1</sup>	32-10079-1/2	FLY 388	76-10513-2/-8	Y 65	229-5100-182	WC 35
32-8987-1	26R106 <sup>1</sup>	32-10092-2	FLY 579	76-11070	Y 8 <sup>5</sup>	229-5100-183	19-1016
32-8988-1	26R51	32-10092-4	FLY 579	76-11489-1	15-1082	229-5100-184	17-3402
32-8989-2	24S06	32-10095-1/2	26C79	76-12097-1/		229-5100-185	19-6022
32-8989-3	24S60	32-10095-3	26C79	-4/-5	Y 5		

# PHILCO

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
322-0162	26548	322-0189	17-6033	962636-501	FLY 281	1107858-1	17-3417
322-0163	26C86	322-5306	Y 27	962712-502	26R150	1107859-4	20-1057
322-0164	26R150	322-8002	Y 59	972128-8	26548	1107861-2	17-3462
322-0179	17-1083	322-8010	FLY 497	972569-1	HS 8	1107864-1	17-6019
322-0180	19-3036	322-10017-2	26586	972569-2	HS 23	1107865-1	17-6011
322-0181	17-3420	322-10023-1	FLY 277	973941-3	17-3418	1107872-1	WC 41
322-0183	17-6028	903562-504/-507	Y 107	973941-4	17-3419	1107872-2	WC 42
322-0184	17-6022	906152-501	FLY 277	973941-5	17-3414	1107872-3	WC 43
322-0186	WC 36	961415-1	26586	1104665-2	26C81	1470005-2	20-1050
322-0187	17-6031	961416-1	26R150	1105981-1	WC 35	1470045-2	17-6012
322-0188	17-6032			1107853-1	17-6018	1470045-3	17-6012

# PHILIPS

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AT1055/04	Y 138	050-262	24552	050-453	24550	060-244	Y 68
AT2082-03	FLY 5097	050-270	FLY 5003	050-457	24552	060-248	24552
050-110	24551	050-270-4	FLY 5003	050-459-01	24550	060-276	WC 16
050-142	24551	050-275	24552	050-471-00	26S09	060-281-6	Y 25
050-175	FLY 104	050-276	24553	050-487-00	26S85	060-287	WC 16
050-176	26S19	050-277	26C43	050-495-00	26C77	060-296	Y 25
050-177	24551	050-283	20C68	050-497-00/01	24552	060-309-02	Y 25
050-194	26S19	050-286/-4/-5	FLY 5003	050-513-00	26S85	060-311	WC 34
050-195	FLY 104	050-300	24556	050-516-00	24556	060-334	WC 19
050-196	24551	050-303	26S48	050-535-00	24553	060-340	Y 25
050-200	FLY 172	050-314	26S19	060-153	WC 22	060-343	Y 62
050-201	24553	050-313	26S29	060-156	Y 27	060-361-3/-4	Y 62
050-209	24553	050-328	26C43	060-167	Y 27	060-361-6/-7	Y 62
050-210	26S19	050-340	FLY 5003	060-168	WC 34	B	Y 62
050-217	24553	050-357-4	FLY 5003	060-169	WC 22	060-398	Y 62
050-219	26S19	050-358	26S29	060-172	WC 15	060-404	Y 62
050-222	FLY 172	050-360	26C43	060-173	WC 15	060-407-01	Y 62
050-224	26S29	050-367	26S29	060-177	Y 10	02/-03	Y 62
050-226	24553	050-368-5	FLY 5003	060-185	Y 10	060-419-01	Y 174
050-227	26A04	050-369	26C43	060-196	WC 15	060-479	Y 62
050-228	20C68	050-379	24553	060-197	WC 15	070-383	WC 34
050-230	24506	050-395	24553	060-205	Y 10	070-389	WC 34
050-232	24553	050-404	FLY 5003	060-210	Y 10	121-306	Y 10
050-233	24553	050-420	24551	060-211	WC 34	121-426	Y 68
050-246	20C68	050-422-01/1	FLY 5004	060-215	WC 34	121-469	Y 68
050-247/-245	26A04	02/03	FLY 5004	060-216	WC 22	121-488	24553
050-254	24552	050-423	24550	060-221	Y 68	121-706	24553
050-255	FLY 5003	050-424	26C43	060-224	Y 10	3107-108-40401	VMT-15
050-256	24553	050-429	26S29	060-228	WC 34	3107-108-40404	VMT-15
050-258	20C68	050-446	26S29	060-233-2	Y 10	3107-108-40501	VMT-08

# QUASAR

(SEE MOTOROLA/QUASAR)

# RCA

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
201R1	WC 11	203R1	HS 2	208T9	26A04	231T1	FLY 15
201R3	WC 14	204T2	24586	211T1	FLY 1	With AGC Wdg.	FLY 44
201R4	WC 15	204T9	26S78	211T3	FLY 1	232T1	FLY 38
201T6	26R61 <sup>1</sup>	205R1	HS 3	211T5	FLY 4	235T1	FLY 16
201T7	26R67 <sup>1</sup>	207R1	WC 17	217T1	FLY 147	31301	26S48
201T8	26R17 <sup>1</sup>	208T2	24A88	225T1	FLY 12	37048	24R06
202D1	FC 1	208T8	HS 1	230T1	FLY 14	37899	24S61

# RCA

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
42888	16-3487	74170	19-3036 <sup>2</sup>	76484	WC 30	78598	19-1004
70127	24R11	74194	26R17	76494	26S57 <sup>1</sup>	78805	26R58
71415	26R73	74212	19-3180	76495	26R57	78809	26S73
71416	FLY 1	74214	19-3180	76498	26C44	78810	FLY 60
71417	24586	74262	Y 3	76501	FLY 43	78842	19-3075
71418	24A88	74358	24551	76509	19-3500 <sup>2</sup>	78869	Y 14 <sup>5</sup>
71419	24581	74581	26R35	76510	19-1003	78886	17-6012
71420	Y 3	74586	26R21 <sup>1</sup>	76563	19-3001	78887	17-6010
71421	FC 1	74587	26S52 <sup>1</sup>	76616	Y 42	78888	17-6011
71422	17-1002	74589	17-4507	76640	19-1001	78889	17-6013
71423	17-1001	74590	17-1001	76641	WC 18	78891	17-6015
71424	17-1011	74591	17-1020	76642	WC 18	78892	17-6016
71425	17-1002	74592	17-1001	76646	19-3075 <sup>2</sup>	78895	17-6014
71426	19-1021	74600	26S48	76647	19-3180 <sup>2</sup>	78897	17-3402
71427	17-1013	74633	17-4523	76650	26A03 <sup>2a</sup>	78902	19-5102
71428	HS 1	74874	26R70 <sup>1</sup>	76653	Y 24	78903	17-5101
71429	WC 11	74892	26R35	76702	17-3497 <sup>1</sup>	78961	26C81
71430	Y 3	74902	26S48 <sup>1</sup>	76703	17-3402 <sup>2</sup>	78987	17-4519
71449	WC 14	74918	16-6758	76704	20-1004	78988	17-4519
71505	19-3001	74930	16-2864	76753	19-3001	78989	17-4520
71526	19-3250	74949	26R17	76763	19-3001	78990	17-4523
71527	19-3093	74950	26S57	76780	17-1062	78991/92	17-4522
71528	19-4180	74951	FLY 2	76795	FLY 24 <sup>2</sup>	78993	17-4504
71529	19-4122	74952	Y 17	76977	15-1082	78995	17-6014
71625	16-6658	75034	24552	76978	26S73 <sup>1</sup>	78996	17-1021 <sup>1</sup>
71631	16-6660	75036	24561	76979	17-4512	78998	17-1033
71661	24556	75084	26R57	76980	17-1063	79010	WC 19
71772	26R68	75154	FLY 45	76981	17-1071	79057	14-1074 <sup>1</sup>
71773	24A89	75181	17-1063	76982	24552	79067	19-3001
71774	24586	75202	19-3001	76983	20-1004	79140	17-1034
71775	24A88	75204	Y 13	76984	26R50	79143	26S79
71776	24S61	75207	26R13 <sup>1</sup>	76997	26S48	79144	WC 34
71777	Y 3	75208	26S56 <sup>1</sup>	77112	17-1033	79145	FLY 60
71793	19-3036	75209	17-1020	77122	24S60	79157	17-3402
71845	16-3487 <sup>1</sup>	75210	17-4508	77124	19-5100	79159	26S49
71846	16-6666	75211	19-1021	77153	19-1007	79160	HS 7
71847	16-3487 <sup>1</sup>	75212	17-1035	77194	19-4950	79161	HS 8
71848	16-6667	75213	HS 9	77195	19-3125 <sup>2</sup>	79162	26R61
71849	16-3487	75240	FLY 45	77197	17-4532	79164	HS 8
71942	19-3001	75251	20-1004	77198	17-4531	79185	19-4550
71970	26C93	75252	19-3500	77208	19-3001	79321	19-3250 <sup>2</sup>
71975	24R04 <sup>1</sup>	75253	19-3125	77225	20-1004 <sup>1</sup>	79379	26A03
72167	26C43	75255	19-3500	77323	22S56 <sup>1</sup>	79382	26S73
72168	19-6022	75290	19-3060	77416	16-6758	79383	17-3402
72179	26R65	75299	19-4036	77513	16-3487	79386	17-1034
72180	26C44	75486	16-6758	77625	Y 42	79387	26R58
72187	WC 11	75487	16-6770	77626	15-1082	79388	17-4531
72333	14-1060	75508	26R46	77631	19-3001	79390	17-4523
72574	19-1007	75519	FLY 45	77632	19-3001	79394	26S73
72618	19-6022	75520	26S48	77635	26R72	79476	26S49
72619	19-3093 <sup>2</sup>	75559	16-3487 <sup>1</sup>	77636	26S18	79490	Y 14 <sup>8</sup>
72770	HS 2	75560	16-3487	77637	17-4521	79510	Y 7 <sup>8</sup>
72887	16-3487 <sup>1</sup>	75566	24R17	77648	17-4522	79527	16-6758
72888	16-3487	75585	FLY 45	77649	26R94	79534	HS 7
72889	17-3488	75645	26R95	77650	26A03 <sup>2</sup>	79565	19-3001
72952	24586	76011	19-3036	77674	19-3250 <sup>2</sup>	79630	26S71
73017	16-6770	76132	19-3500 <sup>2</sup>	77676	26C78	79676	26C44
73037	16-6770	76136	Y 13	77695	Y 7	79706	26R61
73154	26C93	76139	26S56 <sup>1</sup>	77697	Y 42	79720	19-3001
73233	FC 1	76140	26C93	77821	24S61	79733	15-1082
73376	16-6675	76154	FLY 45	77823	26S18	79736	FLY 60
73477	19-3001	76156	24552	77824	26C92 <sup>1</sup>	79808	Y 42 <sup>5</sup>
73566	FC 2	76264	17-1020	77833	FLY 66	79869	26R61
73567	26R67	76271	24S61	77840	19-316		



MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
100422	17-4538	103267	Y 68	106063	FLY 150	109263	26S86
100430	17-6014	103525	15-1082	106142	Y 48	109264	FC 7
100431	17-6012	103570	HS 7	106144	FLY 100	109286	26R150
100442	19-3300	103809	26C44	106145	26R51	109297	26R123 <sup>1</sup>
100454	15-1082	103810	19-1001	106169	FLY 100	109298	19-3250 <sup>2</sup>
100586	Y 25	103829	26S24	106170	26R122	109299	26S48
100827	26548	103830	Y 46	106211	25253	109318	HS 33
100828	FLY 124	103834	26R62	106219	FLY 201	109321	17-3418
100834	26573	103839	FLY 148	106305	Y 107	109322	20-1116
100853	WC 24	103858	17-3489	106358	26R150 <sup>1</sup>	109323	17-5074
100855	26R51	103859	19-3300	106359	FLY 284	109385	26S08
100856	26R48	103860	19-3160	106360	26S95	109457	Y 107
100857	24561	103861	HS 38	106377	19-3060	109463	19-1002
100860	FLY 60	103903	19-1005	106378	19-3036	109532	Y 103
100867	26574	103904	24S48	106381	17-1077	109532A	Y 103
101147	Y 25	104078	Y 47	106382	17-1076	109685	26S07
101252	26R51	104085	26S01	106383	20-1050	109695	Y 48
101287	19-3250	104086	WC 22	106385	17-3411	109696	FLY 150
101288	19-3180 <sup>2</sup>	104087	HS 7	106386	17-3413	109758	19-3036
101289	19-3300 <sup>2</sup>	104101	26S02	106387	17-3414	109771	Y 95
101290	19-4122	104130	26R51	106434	17-3402	109782	19-3300
101819	19-3036	104136	17-1080	106532	26R51	109783	26S29
102046	26S12	104137	17-3489	106533	FLY 200	109828	19-3060
102047	26R55	104138	20-1051	106757	19-3125	109834	19-3330
102048	24549	104139	17-5073	106858	17-1026	109838	19-3093
102049	17-1031	104141	20-1079	107022A	Y 47	109840	19-3060
102050	17-3477	104192	17-3418	107071	26S19	109845	Y 107
102051	17-4511	104193	24S52	107165	19-3060	109850	26S86
102054	WC 18	104228	19-4400	107166	19-3250 <sup>2</sup>	109942	WC 22
102062	Y 88	104229	19-3125	107167	19-3300 <sup>2</sup>	109943	19-3075
102083	19-1001	104230	19-3300	107182	FLY 270	109944	19-3250
102087	19-3300 <sup>2</sup>	104233	17-3418	107201	17-1009	109945	19-3300
102131	26R62	104234	20-1056	107202	17-3418	109946	19-3180
102132	FLY 5082	104236	FLY 201	107203	17-3418	109947	HS 31
102133	Y 107	104302	26R51	107204	17-3418	109948	HS 31
102134	26C81	104309	FLY 200	107222	26S02	109949	17-1113
102135	20-1044	104369	Y 50	107233	26R51	109950	24S82
102136	17-4538	104408	Y 47	107284	HS 19	109951	17-1081
102137	WC 16	104481	FLY 100	107289	17-6012	109954	FLY 240
102138	WC 23	104482	Y 48	107290	17-3402	109961	FLY 240
102195	HS 17	104876	FLY 150	107296	19-1000	109962	Y 103
102196	19-3180	104877	26S01	107327	26S02	109986	WC 72
102198	19-3180	104903	20-1055	107337	WC 110	109991	26S48
102199	19-3125	104904	19-3180	107338	26S24	109992	FLY 272
102200	19-3300	104921	26R51	107377	26R51 <sup>1</sup>	109993	26R115 <sup>1</sup>
102201	19-3060	105020	Y 107	107382	26R127	110027	22S56
102242	17-6016	105053	Y 47	107385	19-1009	110133	24S89
102244	19-1051	105065	WC 42	107408	Y 61 <sup>1</sup>	110330	26R122
102245	19-1052	105066	FLY 42	107421	FLY 150 <sup>1</sup>	110463	16-6758
102247	19-3180	105192	WC 283	107422	FLY 150 <sup>1</sup>	110464	16-6758
102248	19-3660	105193	26S90	107463	19-1002	110498	24S96
102351	19-3180	105195	26C81	107466	19-1002	110655-1	FLY 3
102396	19-3180	105196	WC 35	107628	WC 41	110889	17-3498
102406	26R115	105197	HS 7	107668	Y 47	111295/96	17-3498
102407	26524	105212	17-6016	107698	FLY 239	111383	16-6780
102431	19-4160	105213	17-6018	107837	17-6012	111384	16-3490
102518	19-6821	105214	17-6019	107933	Y 47	111385	16-6780
102569	17-4538	105216	17-6011	108421	24S42	111386	16-3490
102576	15-1082	105250	19-2864	108472	22S88	111517	26S59 <sup>1</sup>
102637	24S52	105255	19-3250	108489	22R05U <sup>1</sup>	112135	21F40
102638	26C79	105286	17-1075	108687	24S53	112250	26R106
102639	19-1006	105287	17-1074	108974	24S53	112252	16-6758
102696	19-3180 <sup>2</sup>	105288	20-1052	109066	26S07	112253	16-6758
102698	19-3125 <sup>2</sup>	105292	17-3415	109067	26S82	112256	20C126
102699	19-3300 <sup>2</sup>	105293	17-3416	109068	FLY 150 <sup>1</sup>	112509	26C79
102834	26R62	105294	17-3417	109069	26R105	112511	WC 72
103037	19-3375	105295	20-1057	109070	Y 48	112540	Y 88
103038	19-3125 <sup>2</sup>	105306	20-1115	109071	109071	112541	26R105 <sup>1</sup>
103039	19-3300 <sup>2</sup>	105308	19-1005	109076	17-3418	112553	26S82
103087	19-4400	105311	19-3250 <sup>2</sup>	109158	17-3418	112577	26R105
103092	FLY 100	105456	19-3125	109171	19-1008	112646	21F40
103093	26S19	105516	19-3500	109180	WC 43	112655	24S82
103094	24S52	105522	WC 22	109221	FLY 281	112712	Y 88
103096	17-1031	105632	Y 47	109237	HS 8	112820	FLY 273
103097	17-4522	105648	FLY 199	109240	19-1001	112821	26S86
103098	17-4523	105649	26S02	109248	19-1001	112822	26S48
103099	17-4534	105667	HS 18	109251	HS 32	112829	26C81
103100	20-1049	105668	19-3250	109252	17-3418	112845	26R150
103101	20-1005	105687	26R127 <sup>1</sup>	109253	17-3419	112866	HS 23
103102	HS 8	105771	24R12U	109254	17-3414	112867	19-1005
103103	HS 7	105795	20-1056	109255	20-1058	112869	17-6031
103104	WC 34	105924	15-1082	109257	19-3600	112870	17-1083
103114	Y 50	106056	19-3036	109261	20-1052	112871	17-3420
103266	26S20	106062	26R115	109262	17-1083	112872	17-6028

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
112873	17-6032	116464	FLY 240	121558	17-6149	129453	WC 71
112874	17-6022	116465	26C77	121559	17-6150	129703	19-1002
112875	WC 36	116466	26S83	121561	19-2034	129704	19-3500
112877	17-6033	116467	24S83	121562	19-1008	129710	19-3500
112879	17-3414	116499	19-3125	121563	17-6151	129712	19-3500
112947	WC 22	116506	HS 50	121591	17-6152	129713	19-3036
112966	HS 23	116507	19-1003	121779	17-3418	129715	22S22
113045	Y 95	116510	19-2012	121780	FLY 410	129956	Y 5027
113095	FLY 240	116511	19-6033	121783	26S108	130022	19-7047
113096	26S83	116537	26S33	121939	26S108	130023	19-6033
113097	17-1073	116539	17-6028	121945	FLY 411	130026	VMT-10
113099	17-3418	116540	17-6057	121946	Y 150 <sup>9</sup>	130093	FLY 439
113100	24S82	116541	17-6058	122118	26S42	130100	17-6160
113216	26R105 <sup>1</sup>	116542	17-6059	122121	19-3330 <sup>2</sup>	130101	17-6161
113256	Y 103	116543	20-1074	122205	19-6033	130104	17-6162
113280	19-3330	116553	26R152	122394	FLY 150 <sup>9</sup>	130106	17-6151
113293	26S83	116554	FLY 307	122866	HS 23	130121	20-1051
113382	FLY 277	116560	17-5027	122918	WC 55	130131	19-3093
113383	26R150	116580	WC 45	123279	16-9028	130491	WC 41
113388	19-3600 <sup>2</sup>	116643	19-1008	123280	16-9026	130492	WC 41
113390	26S86	116648	26C818	124245	Y 150	130558	Y 204
113394	WC 44	116651	26C79	124256	Y 150	130584	17-3418
113422	26S83	116655-1	FLY 3	124271	19-3500	130620	24S61
113428	24S53	116894	19-3060 <sup>2</sup>	124274	26S109	130635	FLY 416
113436	FLY 368	117173	FLY 369	124275	24S48	130694	FLY 413
113468	Y 103	117176	19-7068	124276	17-3418	130719	WC 115
113546	24S61	117337	Y 103	124277	FLY 412	130739	FLY 583
113547	17-3419	117380	19-2025	124337	Y 150	130829	19-1012
113570	WC 22	117382	20-1052 <sup>1</sup>	124461	26C79	130970	19-1002
113599	FLY 240	117383	20-1052	124462	FLY 413	131008	19-1009
113640	FC 7	117384	17-1083	124463	FLY 414	131009	19-2014
113991	26R152	117426	FLY 352	124708	17-3418	131032	26S109
113992	FLY 278	117428	26S86	124709	20-1055	131044	FLY 438
113997	24S06	117535	19-3075	124710	20-1061	131105	FLY 417
113999	FC 6	118359	19-2023	124711	17-3418	131158	WC 41
114000	19-7047	118403	26S108	124758	19-1010	131229	19-2015
114003	17-6027	118409	19-3125	124759	19-3125	131326	FLY 526
114004	17-6023	118410	20-1055	124760	17-6153	131327	FLY 584
114006	WC 37	118498	FLY 609	124761	17-6154	131370	24S64
114012	17-6020	118526	Y 150	124764	17-6155	131567	FLY 312
114047	26S86	118533	22S25	124767	17-5075	131633	26S109
114152	WC 40	118696	20-1080	124803	20-1073	131786	Y 204
114164	WC 1						

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
135704	FLY 586	TO -506	Y 27	906223-502	Y 120	961416-1	26R150
135705	21F09	344943-1/2/	24589	906224-501	FLY 312	961417-8	24589
135755	Y 204	-3/-4	Y 61	906226-501	FLY 609	961419-501/2	Y 48
135772	FLY 608	345212-1	FLY 240	906228-501	Y 150	961419-503	Y 103
135852	Y 204	TO -5	FLY 240	906228-504	Y 150	961421-1	HS 31
135974	26C81	345259-12	26R106	906241-501	FLY 352	961421-4	HS 50
136010	FLY 602	345286-1	FLY 240	906243-501	FLY 410	961422-1	26S07
136011	FLY 603	345288-1	FLY 150	906245-501/		961422-2	26S07
136012	FLY 604	345300-2/-3/		906245-503	Y 123 <sup>9</sup>	961422-4	26S29
136359	245149	-4	FLY 5031	906250-502	Y 150 <sup>9</sup>	961422-5	26S83
136387	FLY 527	345312-2/-3	FLY 5031	906250-503	Y 150 <sup>9</sup>	961422-6/-7	26S83
136425	Y 204	345318-2/-3/	FLY 5031	906250-504	Y 150 <sup>9</sup>	961422-8	26S83
136442	Y 202	-4	FLY 240	906253-501	FLY 411	961423-1	FLY 150
136609	Y 202	345362-9/-10	22S35	906261-501	26C79	961426-1	26S48
136612	Y 204	345812-3/-4	FLY 150	906242-501	FLY 413	961429-3	26S48
136640	FLY 516	349013-1/2	Y 68	906263-501	FLY 412	961429-9	24S06
136669	Y 188	349044-1 TO 7	Y 68	906265-501/		961429-11/X	24S06
136672	FLY 526	731391-3	26S18	502	Y 150	961737-1-3	26R127 <sup>1</sup>
136692	19-1000	902462-1	26S48	906265-504	Y 150	961795-3	26R122 <sup>1</sup>
137031	VMT-01	902470-1	24S52	906265-506/		961809-2-5	26R53
137077	Y 204	902473-1	24S48	508	Y 150	961809-5-1	26R57
137112	Y 204	902621-501/504/		906266-501	FLY 414	962628-5	22S46
137140	FLY 587	506/507	Y 13	906270-501/504	Y 5027	962636-501	FLY 281
137342	Y 224	902679-507	Y 27	906270-507	Y 203	962675-504	Y 88
137345	FLY 588	903502-507	Y 107	906270-510	Y 188	962675-503	Y 88
137555	FLY 588	903519-501	FLY 5082	906270-511	Y 202	962792-4/-3	26S33
137598	FLY 605	903562-502	Y 107	906280-501	FLY 492	962792-6/-7	26S42
137646	VMT-01	903562-504	Y 107	906282-501	FLY 415	962792-8/-9	26S42
137674	FLY 529	903562-507	Y 107	906282-504	Y 245	962792	26S42
137693	VMT-01	903562-509	Y 107	906285-501	FLY 416	970122-8/	
137815	Y 150 <sup>9</sup>	903562-510	Y 107	906366-501	26C81	-9/-10	Y 27
137816	FLY 611	906102-504	Y 95	906376-501	Y 224	970445-5	17-3488 <sup>1</sup>
137858	Y 150	906118-501	Y 47	906387-501	Y 120	970445-22-23	22R05U <sup>1</sup>
138019	VMT-01	906121-501	FLY 150	906387-502	Y 223	970507-5	17-3488 <sup>1</sup>
138164	FLY 518	906122-501	Y 48	907251-1	FLY 150	970608-7	24S52
138321	FLY 589	906122-504	Y 103	907251-2	FLY 239	970669-1	Y 17
138421	VMT-01	906122-506	Y 103	907252-1	FLY 150	970683-16	26R13 <sup>3</sup>
138422	FLY 586	906125-501	FLY 240	907265-504	Y 150	970690-1	Y 13
138746	26C81	906125-502	FLY 240	926636-501	FLY 281	970694-1	Y 45
138751	FLY 517	906125-503	FLY 240	938314-4	19-1009	970721-1-2	26R95
138752	VMT-02	906127-501	FLY 272	938314-9	19-2009	970727-1-3	26R21 <sup>1</sup>
138907	VMT-01	906128-501	26R115	940394-1	24S56	970727-6/-7	26S48
139001	VMT-02	906129-501	26R115	940777-1	26R65	970777-2	24S61
139029	FLY 582	906130-501	26R105 <sup>1</sup>	940873-3	26C93	970727-10/-14	26S48
139628	FLY 527	906133-501	26R105	940877-1	26C44	970727-15	26S49
139755	Y 223	906141-501	FLY 273	940877-2	26C43	970727-20/	
140106	24S149	906147-501	FLY 240	941129-4	26A04	-23	26S48
140107	24S89	906152-501	FLY 277	941129-5	26A04	970727-25/	25S61
140393	FLY 590	906153-501	26R150	941520-231	19-2010	970727-26/	
140438	Y 150	906156-501	FLY 368	941520-235	19-1002	-27	26S48
140716	Y 256	906158-501	26R152	941520-237	19-6033	970925	24R94
141252	FLY 591	906159-501	FLY 240	941520-243	19-1008	970950	26R19
141254	VMT-07	906160-501	FLY 278	941520-251	19-1010	970972-1-3	26R21 <sup>1</sup>
141464	VMT-07	906160-502	FLY 278	941521-231	19-1001	970979-1	FLY 2
141465	FLY 592	906161-501	FLY 368	941521-241	19-1008	971165-2	25S61 <sup>1</sup>
141485	FLY 518	906167-501	FLY 240	941521-363	19-1012	971234-1	Y 13
142130	Y 246	906170-501	FLY 308	941688	26C93	971237-1-4	26R61 <sup>1</sup>
142270	FLY 594	906170-502	FLY 308	941988-3	26C93	971237-1-6	26R61 <sup>1</sup>
142728	VMT-06	906170-504	FLY 308	942126-1	26C93	971237-3	26R61
143988	Y 267	906171-501	Y 150	942176-1	26C44	971239-1	FLY 60
145718	VMT-07	906171-502	Y 150	942176-5/-7/		971239-2	FLY 60
145719	VMT-06	906171-503	Y 150 <sup>9</sup>	-12	26C78	971316-1-4	26R46
154428	22S25	906176-501	26R105 <sup>1</sup>	942476-1	26A03	971317-1/2	FLY 45
335731-501	Y 27	906182	26C79	942476-3	26A03	971321-1	FLY 45
337119-1/2	FLY 104	906186-501	Y 245	942889-2	24S60	971331-1	16-3445
337160-1/2/	-3	906186-502	Y 245	943431-2	26C79	971337-1-4	26R13
337161-1/2	Y 68	906186-503	Y 245	943431-3	26C79	971350	HS 31
337178-1	FLY 202	906186-504	Y 245	943431-8	26C93	971351-1	26S57 <sup>1</sup>
337180-1/2	Y 27	906186-507	Y 245	943431-12/		971352-1-4	26R57
337180-1/2	FLY 202	906192-502/		-13	26C79	971363-2	17-4532
337178-1	Y 27	503	Y 47	943431-15/		971364-1	17-4533
337180-1/2	FLY 202	906193-502	Y 103	-16	26C79	971365-1/2	17-4511
TO -4	FLY 202	906193-503	Y 103	943431-18/		971366-1	17-1033
337196-2/-3/	TO 5	906195-501	FLY 5046	-20	26C79	971376-1	17-4505
337548-18	20C126	906197-501	Y 150	943431-21/		971376-4	17-4505
337550	FLY 5031	906198-501/		-22	26C79	971377-1	17-4531
337558-1	FLY 240	906200-501	FLY 409	943431-23	26C77	971385-1/2	Y 42
337567-1	FLY 240	906201-501	26R152	943431-24	20C137	971385-3	Y 42
337583-1	FLY 240	906201-503	26R152	943431-25	26C77	971385-5	Y 42
337583-2	FLY 240	906205-501	26R152	961199-2-5	26R51	971387-3	Y 24
337591-1	FLY 240	906206-501	FLY 307	961405-1-1	26R122	971390-1	FLY 43
339015-5	Y 27	906208-501	FLY 240	961409-1	26R51	971390-2	FLY 66
		906218-501	FLY 369	961413-2Y	26R105	971391-1	26S18
		906220-501	FLY 5089	961415-2/		971391-2	26S18
				-3/-5	26S86	971391-6	26S18

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
971454-2	16-6770	972958-7	Y 48	1107856-3/-4	17-1083	1462346-3	17-6161
971602-1	FLY 24 <sup>5</sup>	972958-8/-9/		1107858-1	17-3417	1462347-1	17-6152
971608-1	24S52	10	Y 47	1107858-2	17-3420	1462347-6	20-1051
971625-1	17-1033	973432-1	FLY 100	1107859-4	20-1052	1463641-1	VMT-10
971628-1	26S18 <sup>1</sup>	973432-2	FLY 100	1107861-2	17-3407	1463678-1	17-6162
971628-2	26S73	973463-1	FLY 199	1107864-1	17-6019	1463679-2	19-1002
971628-4	26S73	973577-6/-12	22S88	1107872-1	WC 41	1463679-4	19-2015
971628-5-9	26S73	973872-1	FLY 270	1107872-2	WC 42	1463679-7	19-1000
971628-6/		973907-1	FLY 201	1107872-3	WC 43	1463680-1	17-6151
-7/-9	26S75	973908-1	FLY 200	1107872-6	WC 41	1463682-7/-8/	
971633-1-5	24R50	973924-1	Y 61 <sup>8</sup>	1107893-1	26S90	1463705-2	Y 150
971674-1/		973932-1	26S02	1435416-1	WC 123	1463707-1	FLY 413
-3/-4/-5	Y 39	973932-2	26S24	1435602-501	FLY 585	1463725-501/505Y	202
971677-1-4	26R72	973932-3	26S02	1435604-504	FLY 585	1463733-502	Y 256
971690-1-4	26R94	973932-5	26S07	1435604-504	FLY 585	1463747-501	Y 246
971699-1	Y 14 <sup>5</sup>	973932-7	26S08	1435605-501	FLY 524	1463760-503	Y 267
971703-1	26C92 <sup>1</sup>	973932-9	26S82	1435606-501	FLY 608	1464223-1/2/	
971715-1	FLY 60	973932-10	26S08	1435608-501	FLY 526	1464236-1	19-1010
971715-2/3	FLY 60	973944-1	HS 7	1435609-501	FLY 440	1464573-1	WC 41
971718-1/2	26R58	973944-4	FC 6	1435609-502	FLY 440	1464573-2	WC 41
971736-1/2	Y 42 <sup>5</sup>	973944-5	FC 6	1435615-501	FLY 608	1464573-3	WC 45
971736-4	Y 42 <sup>5</sup>	973961-1/2	17-1081	1435618-503	21F21	1464573-4	WC 119
971744-1	Y 24	973966-1	19-3300	1435621-501	FLY 525	1464575-2	WC 44
971764-1/3	Y 14 <sup>5</sup>	973966-15	19-3500	1435624-501	FLY 602	1464573-6	WC 38
971778-1	26R58	973966-17	19-3330	1435625-501	FLY 604	1464573-7	WC 41
971792-1-3	26R51	973966-21	19-6033	1435626-501	FLY 603	1464607-1	VMT-01
971798-1	26S79	973966-22	19-3275	1435627-501	FLY 586	1464607-2	VMT-01
972101-1	17-1034	973966-28	19-3330	1435627-502	FLY 586	1464607-3	VMT-01
972102-1-1	26R58	973966-31	19-3250	1435631-501	FLY 587	1464607-4	VMT-01
972103-1	17-4531	973966-34	19-2010	1435635-501	FLY 605	1464607-5	VMT-01
972125-13	19-3036	973966-35	19-1008	1435636-501	FLY 516	1464607-6	VMT-01
972125-46	193036	973966-40	19-3180	1435637-502/501	FLY 588	1464607-7	VMT-02
972125-47	1903036	973966-43	19-1010	1435637-503	FLY 589	1464607-8	VMT-02
972128-3/-6	26S48	973966-45	19-3093	1435644-501	FLY 529		

# RCA

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
1476153-2	17-5078	S-9395	FLY 3	S-11496	Y 68	S-16844	FLY 5046
1476153-3	17-5077	S-9466	Y 27	S-11532	Y 5010	S-16890	FLY 240
1476153-5	20-1073	S-9499	Y 27	S-11538	Y 68	S-16894	Y 47
1476162-2	24564	S-9526	FLY 104	S-11558	Y 68	S-17258	FLY 5046
1476162-3	24561	S-9561	Y 27	S-11610	FLY 240	S-17260	Y 5012
1476162-5	24564	S-9620	Y 27	S-11611	FLY 240	S-17262	FLY 240
1476400-1	WC 122	S-9623	Y 27	S-11736	FLY 150	S-17265	FLY 308
1478607-1	245149	S-9628	FLY 104	S-11756	Y 47	S-17348	Y 107
1585273-1/2	Y 47	S-9647	Y 27	S-12035	Y 50	S-17368	Y 245
1599095-1/2/3	FLY 5068	S-9653	FLY 104	S-12121	Y 68	S-17411	FLY 308
1599221-1/2	FLY 5068	S-9731	Y 27	S-12154	FLY 240	S-17481	FLY 240
1627129-1/2	FLY 5046	S-9869	Y 39	S-12224	Y 47	S-17629	FLY 5046
1627129-3/4	FLY 5068	S-9876	FLY 202	S-12279	FLY 150	S-18214	FLY 308
1817640-1	Y 150	S-9931	Y 27	S-12352	FLY 150	S-18323	Y 123
1817961-1	FLY 438	S-9936	FLY 104	S-12458	Y 47	S-18339	FLY 341
1820655-1	FLY 5090	S-10237	FLY 202	S-12618	Y 50	S-18392	Y 125
1820665-1	VMT-01	S-10293	Y 68	S-12796	Y 61	S-18407	FLY 340
1820665-2	VMT-01	S-10294	Y 68	S-12800	FLY 5031	S-19109	Y 150
1820665-3	VMT-02	S-10326	Y 27	S-12858	Y 5010	S-19113	FLY 351
1820665-4	FLY 440	S-10335	FLY 202	S-12888	FLY 240	S-19157	Y 245
2519502-1	FLY 5046	S-10388	Y 68	S-12897	Y 47	S-19486	FLY 5046
8946289-2	WC 57	S-10389	FLY 202	S-12902	Y 47	S-19601	FLY 5046
50-94292-1	FLY 148	S-10453	Y 68	S-13263	Y 5010	S-19624	Y 61
51-88332-1	Y 46	S-10456	FLY 202	S-13319	Y 10	S-19703	Y 123
51-94416-1	Y 46	S-10463	Y 68	S-13320	Y 68	S-19705	FLY 341
56-94273-1	26575	S-10515	FLY 202	S-13474	Y 47	S-20587	FLY 5090
62-12800	FLY 5031	S-10555	FLY 202	S-13528	FLY 5031	S-20638	Y 245
62-13412	FLY 5031	S-10557	Y 68	S-13601	FLY 240	S-20671	FLY 5046
62-13528	FLY 5031	S-10568	FLY 202	S-13774	Y 61	S-20750	FLY 5046
62-14052	FLY 5031	S-10626	Y 68	S-13833	Y 5010	S-20764	Y 5012
62-14414	FLY 5031	S-10683	Y 68	S-13843	FLY 240	S-20788	FLY 5068
62-15015	FLY 5031	S-10706	Y 68	S-13862	Y 5010	S-20907	Y 150
62-16397	FLY 5046	S-10786	FLY 202	S-13976	FLY 5046	S-20922	FLY 492
62-16844	FLY 5046	S-10899	Y 68	S-14009	FLY 240	S-20986	Y 123
62-17258	FLY 5046	S-10914	Y 68	S-14052	FLY 5031	S-20995	FLY 429
62-17629	FLY 5046	S-10922	Y 68	S-14267	FLY 240	S-21051	FLY 5046
62-19486	FLY 5068	S-10957	Y 68	S-14267	FLY 240	S-21051	FLY 5046
62-19601	FLY 5046	S-10993	Y 68	S-14414	FLY 5031	S-21105	FLY 341
62-20587	FLY 5090	S-11003	Y 68	S-14474	FLY 240	S-21120	FLY 5068
62-20671	FLY 5046	S-11006	Y 68	S-14610/A	Y 5010	S-21277	FLY 5068
62-20750	FLY 5090	S-11007	Y 68	S-15015	FLY 5031	S-21277	FLY 5068
62-20788	FLY 5068	S-11008	Y 68	S-15300	FLY 240	S-21475	FLY 5068
62-21270	FLY 5068	S-11008	Y 68	S-15438	FLY 240	S-21671	FLY 39
62-21277	FLY 5068	S-11034	FLY 202	S-15465	FLY 240	S-21759	FLY 308
62-21283	FLY 5068	S-11080	Y 68	S-15807	FLY 240	S-22253	FLY 308
62-21475	FLY 5068	S-11156	FLY 202	S-15868	FLY 240	S-22391	Y 5027
62-22472	FLY 5068	S-11185	FLY 240	S-16196	FLY 240	S-22472	FLY 5068
62-102132	FLY 5082	S-11234	FLY 202	S-16375	Y 150	S-22546	Y 245
S-9187	FLY 45	S-11262	FLY 202	S-16397	FLY 5046	S-22583	FLY 438
S-9239	Y 13	S-11270	Y 68	S-16544	FLY 240	S-23064	Y 5027
S-9289	Y 13	S-11393	Y 68	S-16668	Y 123	S-23556	FLY 440
		S-11424	Y 68	S-16715	FLY 339	S-24342	FLY 5068

# SANYO

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
4-2261-30770	19-3330	4-2760-03671	Y 81	F-83	FLY 391	T-D74C	Y 122
4-2520-03500	26C77	4-2760-03700	Y 149	F-83A	FLY 391	T-D78	Y 149
4-2520-03800	20C59	4-2760-22101	Y 159	F-99	FLY 390	T-D81/C/A	Y 122
4-2530-03200	26549	4-2760-22800	Y 109 <sup>12</sup>	F-103	FLY 443	T-D82	Y 121
4-2531-06270	19-3125	4-2760-43202	Y 121	F-122	FLY 443	T-D85C	Y 122
4-2540-03200	26549	4-2761-04180	Y 5021	F-122-P-ISO	FLY 443	T-D104A-UC-25	Y 122
4-2540-03400	24553	4-2761-04470	Y 69	T-A05	WC 34	T-D110A-UC-25	Y 159 <sup>12</sup>
4-2711-94470	19-2026	4-2761-04270	26599	T-A133	WC 34	T-D111-UC-25	Y 132
4-2720-12800	19-3125	46-80425-3	Y 245	T-825	26C81	T-D115-UC-25	Y 132 <sup>13</sup>
4-2720-12900	19-3180	46-80437-3	Y 132	T-825A	26C81	T-D122-326E-1	Y 150
4-2720-16800	19-6033	40256	24551	T-828A	26C77	TDT-330	26529
4-2721-01500	19-2026	42761	Y 69	T-830	20C59	TDT-330-07	26529
4-2721-02700	19-3275	981924	FLY 443	T-D37A	Y 5021	TDT-332E	Y 150
4-2721-03300	19-3330	983957	FLY 443	T-D39	FLY 443	TDT-332E-1	Y 150
4-2721-03900	19-2028	CKJ-71095	26C81	T-D40A,6	Y 121	TDT-335J-1	Y 5012
4-2721-10000	19-2032	CKJ-71096	20C59	T-D41A/B/C	Y 81	TDT-400H-2	Y 81
4-2721-10001	19-2033	CLJ-71097	Y 132	T-D41E/F/H	Y 81	TDT-403-21	26511
4-2751-04316	FLY 380	CLJ-71202	Y 245	T-D66	Y 5009	TDT-403-41	26511
4-2751-05900	FLY 437	D-4470	Y 69	T-D67	Y 122	TDT-403J-21	26511
4-2751-44200	FLY 428	F-75	FLY 390	T-D73	Y 81	TDT-422-1	Y 123

# SANYO

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
TDT-433	WC 22	T-F98AC	FLY 5088	TLT-123	24596	T-V111	26549
TDT-483-1	Y 245	T-F99AE	FLY 390	TLT-123H-41	24596	T-V120	24551
TDT-508	26586	T-F99AC	FLY 390	TLT-128	24596	T-V123	24553
T-F58/G	FLY 437	T-F99A-17	FLY 390	TLT-128H	24596	T-V127	24551
T-F75	FLY 390	T-F103-1	FLY 443	TLT-128H-41	24596	T-V127	24552
T-F76A	FLY 390	T-F104	FLY 380	TLT-158	24551	T-W32	26586
T-F76A-33	FLY 390	T-F107	FLY 443	TLT-158-21	24551	T-W40	26573
T-F83A-33	FLY 391	T-F110A	FLY 428	TLT-158-41	24551	T-W42	26585
T-F86A	FLY 5088	T-F116	FLY 443	TRJ-60843	FLY 391	T-W48	26585
T-F88A	FLY 5088	T-F122	FLY 443	TRJ-71100	FLY 443		
T-F89A-33	FLY 390	T-F128	FLY 5101	TRJ-71106	26549		
T-F91A	FLY 5060	T-HLF1000	19-2033	T-V108	26548		

# SEARS/SILVERTONE

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
A-80-15-6	26C79	A14D1479	HS 5	M5181232	WC 14	N23094	17-3497
A1095	FLY 1	A17B1031	26C43 <sup>1</sup>	M5181242	HS 3	N23095	19-3001
A1098	24R96	A2396A	WC 14	M5181277	WC 17	N23098-1	26C41
A1099	26A03	A2634A	17-6019	M5181290	17-1063	N23397	26R91
A1201/02	17-3497	A2749H	HS 7	M5181335	WD 18	N23449	HS 5
A1350-2	26553	A29052A	WC 14	M52C185	26R64	N23490	24550 <sup>1</sup>
A1352	26551	A29099A	HS 7	M52C196	26R27U	N23490-1	24560
A1354	26551	A29107	WC 35	M52C199	26R66 <sup>1</sup>	N23502-1	19-1004
A1404	20C49 <sup>1</sup>	B10106	24A87	M52C204	26R24	N23541	26R33
A1406	26C44	B12C1122	24552	M52C205	26R22	N23542	21F03 <sup>1</sup>
A2304	HS 8	B13H1369	20-1021	M53A180	Y 3	N23614	17-4501 <sup>1</sup>
A3392	17-1003	B13K1047	17-1043	M53B009	19-3100	N23657	26557
A3393	17-3497 <sup>1</sup>	B80-1	26A03	M53C194	Y 3	N23672	17-4502
A3395	16-3487	BH9000	Y 123	M53C195	Y 7	N23802-1	FLY 49 <sup>1</sup>
A3396	16-6758	C23087-1	26C41	M53C197-B	Y 7 <sup>8</sup>	N23817	Y 9
A3397	17-3487	C24776-1	26549	M53C201-D	Y 7 <sup>8</sup>	N23840	21F12 <sup>1</sup>
A3399	16-6758	D80-36-35	FLY 441	M53C202	Y 5	N23842	21F03
A10100	FLY 1	D80-67-3C/E	FLY 396	M53C203	Y 12	N23894	WC 22
A10104	FLY 59	DC-40	Y 72	M53C217	Y 12	N23931-1	24550
A10105	26R20	EB4-15990	FLY 5048	M55A128	26552	N24283	26549
A10108	FLY 59	E25696	26R17	M55A166	26552	N24807	Y 10 <sup>8</sup>
A10109	FLY 59	ES76X10	Y 253	M55B115	24A87	N24989	FLY 12
A10114-4	26551	ES77X12/-19	FLY 623	M55B128	26552	N24990-1	26554
A10115-5	26553	F83/A	FLY 391	M55B150	24551 <sup>1</sup>	N25322	17-1033
A10126	FLY 51	F103	FLY 443	M55B151-B	26554	N25410	17-4500
A10134	26A04	F104	FLY 380	M55C115	24A87	N25411	17-4501
A10135	FLY 59	F122	FLY 443	M55C132	24552	N25412	17-4502
A10136	FLY 58	F128	FLY 5101	M55C133	FLY 5	N25413	17-4503
A10137	FLY 58	LC-13	19-1006	M55C134	24552	N25414	17-4504
A10152	26527	LC-15	19-3001	M55C144	FLY 5	N25433	26R17
A28253	19-3036	LF-30	16-3487	M55C149	FLY 12	N25468-1	19-3100
A28254	20-1020	LF-32	16-6758	M55C152-B	FLY 12	N25468-5	19-3100
A28255-1	19-3125	LF-33	17-3498	M55C201-A	FLY 5	N25468-6	19-3036
A28255-2	19-4201	LF-34	16-3487	M55C156	FLY 8	N25468-8	19-3250
A28258-1	WC 11	LF-35	16-6758	M55C171	FLY 8	N25474	17-4504
A28258-2	WC 11	LG-10017	HS 5	M56B117	FLY 8	N25543	17-1031
A28259	WC 14	LGA-10017A	HS 5	M56C116	26C41 <sup>1</sup>	N25609	20-1004
A28261	Y 3	LGA-10017B	HS 5	N22446-1-2	26A04	N25728-1	19-5712 <sup>1</sup>
A28263	HS 5	LGA-10021A	26C43	N22446-3	26A04	N25729-1	16-5714 <sup>1</sup>
A28264	19-3001	M50A431	17-1063	N22446-4	26A04	N25729-1	19-1000
A28276	19-1005	M50A432	20-1020	N22500-3	19-3250	N40028	WC 17
A28278-2	Y 5	M50A474/-G	20-1004	N2			

# SEARS/SILVERTONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
N41879	16-3445	R65432	26A31U	TLF135-D	19-4160	TTH-253-D	FLY 5 <sup>1</sup>
N41884	WC 18 <sup>1</sup>	R65441	FLY 1	TLF137-D	HVO 50	TTR-105	26R17
N41887	WC 22 <sup>1</sup>	R65451	24586	TLF142-D	17-3497 <sup>1</sup>	TLF-106-D	26C79
N41984-1	26572	R65452	WC 11	TLF144-D	19-3001	TTR-106-1D/	
N42135	17-4522	R65453	HS 8	TLF146-D	19-3001	2D	26C79
N42144/-1	22552	R65454	FC 1	TLF302D	FLY 430	TTR-106-2A	26C44
N42504	Y 14 <sup>8</sup>	R65461	Y 3	TLF303DS	FLY 432	TTR-152	24A88
N51018	26548	R65463	26R94	TLF607S	FLY 431	TTR-152-/2	24A87
NA23334-1	19-3001	R65479	17-1013	TLF502-/D	19-4125	TTR-153	24586
NA23502-1	19-1004	R65480	17-1011	TLF503	19-3036	TTR-153-2D	26578
P810125	26A03	R65513	16-6758 <sup>1</sup>	TLF504	19-4180	TLF504	26551
P823802-1/E	Y 5	R65745	19-3001	TLF505-/D	WC 11	TTR-154	FLY 1
PC5866	24548	R66180	19-3001	TLF506-/DA	WC 14	TTR-156	24552
PC10107	FLY 59	R66188	19-1004	TLF507	FC 1	TTR-157-/D	HS 2
PC10138	FLY 51	R66189	19-1004	TLF514-D	19-3660	TTR-159-D	Y 3
PC28278	Y 5	R66190	26R31U <sup>1</sup>	TLF519-D	19-3100	TTR-161-D/3	24A87
PC28330	Y 5	R66192	24551A	TLF520-D	19-3001	TTR-161-1D	24A87
PMA51022	24548	R67133	26C77	TLF522-D	FC 3	TTR-161-2D	24A87
PMA52020	19-1020	R67183	HS 7	TLF522-/1D	FC 3	TTR-165-D	24551
PMA52021	17-1003	R67304	26R94	TLF525-D	20-1004	TTR-165-1D	26551
PMA52023	19-3100	R67316	24552 <sup>1</sup>	TLF526-D	19-4201	TTR-170-D	26R95
PMA52024	19-3500	R67800	16-6758	TLF531-D	17-3497 <sup>1</sup>	TTR-178-1D	26C41
PMA52025	19-4201 <sup>2</sup>	R67801	16-6758	TLF532-D	17-3497 <sup>1</sup>	TTR-179-D	24551
PMA52027	17-3497	R67802	16-3487	TLF533-D	WC 18	TTR-181-D	FLY 1
PMA52028-1/		R67803	16-3487	TLF535-D	17-1031 <sup>1</sup>	TTR-182-D	26R95
-2	17-3400	R67885	24552 <sup>1</sup>	TLF562-D	19-3300	TTR-185-1D/D	26551
PMA52029	17-1062	R70077	17-3402 <sup>1</sup>	TLF566-D	HS 3	TTR-186-D/1D	FLY 1
PMA52029-2	17-1063	R70155	FLY 1	TLF570-D	20-1004	TTR-188-D	26R15
PMA52104	17-1064	R70158	24552 <sup>1</sup>	TLF574-D	17-1063	TTR-195-2D	24550
PMA52105	20-1020	R70181	17-1031	TLF576-D	17-1063	TTR-201-D	Y 5
PMA56000	Y 7 <sup>8</sup>	R70189	26R00	TLF579-D	20-1004	TTR-208-D	FLY 2
PMA56001	WC 17	R70190	26R00	TLF580-D	HS 7	TTR-209-D	FLY 5 <sup>1</sup>
PMA56003	WC 22	R70656	17-1004	TLF581-D	HS 8	TTR-210/212	FLY 5
PMA56004	26554	R70834	16-3445 <sup>1</sup>	TLF593-D	17-1062	TTR-217-D	Y 18
PMA56005	26A03	R70930	FLY 1	TLF594-D	17-3497	TTR-219-D	FLY 59 <sup>1</sup>
PMA56019	WC 13 <sup>1</sup>	T33-226	19-1006	TLF607S	FLY 431	TTR-220-D	Y 5
PMB51005	24552	T33-236	19-3001	TLF619-D	FLY 431	TTR-223-D	Y 5
PMB51005-2	24A87	T33-237	19-6022	TO10023	WC 11	TTR-224-D	Y 12 <sup>8</sup>
PMB51018	24548	T33-238	26C41	TOA/10023/-C	WC 11	TTR-226-D	26C78
PMB51020	26549 <sup>1</sup>	TA100	19-1001	TO10024	WC 14	TTR-227-D	Y 12
PMB52019	HS 3	TA105	19-3500	TOA10024	WC 14	TTR-242-D	Y 5
PMB52033	16-6758	T-825	26C81	TOC10034C	24548	TTR-254-D	Y 5
PMB52049	17-5003 <sup>2</sup>	T-825A	26C81	TO10045	26551	TTV-252-D	26551
PMB52050	17-5002 <sup>2</sup>	T-828A	26C79	TOB10045D	26551	TV111	26549
PMB52051	17-4503 <sup>2</sup>	T-830	20C47	TOB10045/-D/		TVC-100-D	HVO 50
PMB52052	17-5001	T-D40A	Y 121	-E	26552	TW40	26573 <sup>1</sup>
PMB52053	19-3001	T-D41/B	Y 81	TO10051	26A03	W115228	Y 6
PMB52104	17-1063	T-D78	Y 149	TOA10051A	26503	W162190	WC 17
PMB52105	20-1020	T-DB1A-UC-25	Y 122 <sup>8</sup>	TOA10053	WC 14	W505867	16-6758
PMB52106	17-1033 <sup>1</sup>	T-DB1C-UC-25	Y 122 <sup>8</sup>	TPC10005-A	26R95	W505905	16-3487
PMB52107	17-4503 <sup>1</sup>	T-D111-UC-25	Y 132 <sup>1,2</sup>	TPC10011	26R95	W505912	26549
PMB52108	17-5003	T-D115-UC-25	Y 132	TPC10018	26R95	W506080	16-3487
PMB52110	17-5004	TDV-1016	Y 235	TPW104	26C81 <sup>1</sup>	W507321	17-3493
PMB52111	17-5004	TF58	FLY 437	TPW107	26C81	W507343	17-1003
PMB52121	17-5001	TF63A-33	FLY 391	TPW125	26C80 <sup>1</sup>	W507367	19-7100
PMB52122	HS 3	TF103/A-U	FLY 443	TPW971	26C80 <sup>1</sup>	W507373	19-2400
PMB56016	26553	TF104	FLY 380	TPW984	26C80	W507374	19-4400
PMB56018	26C44 <sup>1</sup>	TF110A	FLY 428	TPW988	26C80 <sup>1</sup>	W507567	17-1004
PMB56037	26A03 <sup>1</sup>	TF122	FLY 443	TS1052	17-3487	W507586	19-1000
PMB56040	26525	TF128	FLY 510 <sup>1</sup>	TS1532	17-3414	W507587	19-1007
PMB56048	26525	TFD-336	26572 <sup>1</sup>	TS1820	17-3410	W507590	19-3001
PMB97213	FLY 7 <sup>8</sup>	TH10000	FLY 68 <sup>1</sup>	TS1822A	17-3415	W507591	49-1021
PMCS6002	FLY 12	THC1000A	FLY 68 <sup>1</sup>	TS2022	20-1051	W507791	Y 3
PMCS6007	FLY 16 <sup>2</sup>	THC10002	WC 14	TS2023	17-1072	W507935	19-2400
PMCS6038	FLY 125	THC10003/E	FLY 68 <sup>1</sup>	TS3819	17-6022	W507970	19-3001
PMCS6039	Y 10 <sup>8</sup>	T-HLF47	19-7047	TS7010	19-2024	W507971	19-3001
PMCS6044	Y 10 <sup>8</sup>	T-HLF68	19-7068	TSA10030B	17-1003	W508058	FLY 1
PMCS6049	FLY 127	T-HLF82	19-2023	TSA10050/-A/		W508059	26551
PMCS6050	Y 16 <sup>8</sup>	T-HLF100	19-2024	-B	20-1004	W508060	26R82
PMCS97281	Y 14 <sup>8</sup>	T-HLF150	19-2026	TSA10050C	20-1004	W508061	17-3495
PMD52033-1	16-6758	T-HLF180	19-3180	TSA10054	17-1063	W508069	19-4201
PMD52033-2	16-6758	T-HLF470	19-3500	TSB-200/A	Y 207 <sup>1,2</sup>	W508070	19-4201
R60518	16-6758 <sup>1</sup>	T-HLF1000	19-2033	TSB-200B/D/S	Y 207	W508076	26A03
R61107	14-1060	TL 156	19-1006	TSB-200U	Y 207 <sup>5</sup>	W508077	HS 5
R62149	22R06 <sup>1</sup>	TL 162	19-3180	TSB238B	Y 123	W508179	17-3498
R62174	22556	TL 163	19-3500	TSB242	24505	W508195	14-1074
R62175	20C53	TL 265	19-4060	TSB286	24548	W508218	WC 27
R63929	2455A <sup>1</sup>	TL 266	19-3180	TSB302	Y 109 <sup>5,14</sup>	W508341	26C93
R63936	19-3001	TL 267	19-3250	TSB303B	Y 121	W508555	19-1023
R63937	19-3001	TL 983	WC 22	TSB324	24552	W508667	WC 20
R63946	19-3001	TL 7081	19-2014	TSB328	Y 123	W508674	26552
R63947	19-3001	TL 7096	19-1002	TSB10051	17-1033	W508675	Y 6
R65426	17-1006	TL 7103	19-1008	TSB10051/A	17-1033	W508679	FLY 5 <sup>1</sup>
R65428	24A87	TLF114-D	17-1031 <sup>1</sup>	TSP-41-8	24553	W508883	FLY 5 <sup>1</sup>

# SEARS/SILVERTONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
W508956	26552	10-50-5	WC 41	10-124-1	19-1004	10-275-1	19-2026
W508967	HS 5	10-51-0	17-6033	10-125-5	WC 53	10-276-1	19-3180
W508971	FLY 5 <sup>1</sup>	10-51-5	WC 42	10-126-1	19-3250	10-279-1	19-3250
W509361	WC 23	10-52-0	17-6031	10-126-5	WC 38	10-293-1	19-3032
W509375	26553	10-52-5	WC 43	10-127-1	19-3300	10-296-1	19-1008
W509376	245551	10-53-3	17-1016	10-128-1	19-4200	10-303-1	19-1006
W509380	26R21	10-54-0	20-1020	10-134-3	17-6101	10-315-1	19-3060
W509384	FLY 5 <sup>1</sup>	10-55-3	17-5019	10-135-2	16-3490	10-317-1	19-1001
W509704	Y 6	10-57-3	20-1081	10-136-1	17-1002	10-320-1	19-1002
W522519	HS 3	10-57-5	20-1081	10-136-3	17-6022	10-321-1	19-6022
YD-10001	Y 6	10-59-5	WC 36	10-142-5	WC 97	10-328-5	20-1107
YDB-10000A	Y 6	10-60-2	17-5014	10-143-1	HS 23	10-332-1	19-2014
7T-145	24505 <sup>1</sup>	10-60-3	17-3419	10-143-5	HS 23	10-333-1	19-6022
BT-157	26504 <sup>1</sup>	10-60-5	HS 23	10-147-1	19-3275	10-334-1	19-3125
BFT-564	FLY 350	10-61-1	20-1020	10-148-1	19-3060	10-335-1	19-3300
BFT-598	FLY 435	10-62-3	17-5023	10-148-5	20-1069	10-337-1	19-3100
BFT-650	FLY 436	10-64-1	19-3060	10-149-1	19-3036	10-338-1	19-6033
BFT-656	FLY 429	10-65-1	19-1010	10-149-2/C	16-6780	10-341-1	19-3060
8-34-1	24564	10-66-1	19-3250	10-150-1	19-3275	10-342-1	19-7047
10-3-0	17-3497	10-66-3	20-1103	10-150-2/C	16-6780	10-347-1	17-1015
10-3-1	17-3497	10-66-5	20-1005	10-152-1	17-1015	10-368-1	17-6106
10-3-5	HS 34	10-67-5	HS 35	10-155-1	19-1002	10-385-1	17-6107
10-5-0	17-4538	10-68-3	20-1057	10-156-1	19-1000	10-400-1	17-6108
10-7-2	17-5004	10-71-1	19-3036	10-163-2	17-3418	10-402-1	19-2009
10-8-2	17-5014	10-71-3	17-5064	10-164-2	17-3419	10-404-1	19-4201
10-9-2	17-5002	10-71-5	WC 44	10-165-1	19-1010	10-405-1	19-7047
10-11-0	17-3495	10-72-1	19-3180	10-166-1	19-3275	10-449-1	19-6033
10-11-1	17-3495	10-72-2	16-6780	10-166-2	20-1052	10-452-1	19-7068
10-11-5	HS 22	10-72-3	17-5020	10-167-1	HS 36	10-461-1	19-3093
10-12-1	19-3125	10-72-5	WC 40	10-169-1	19-1002	10-541	17-1062
10-12-5	20-1081	10-73-1	19-3330	10-170-1	19-3275	10-542	17-1063
10-13-5	HS 22	10-73-2	16-6780	10-172-1	19-1002	10-543	17-1062
10-17-2	17-5004	10-73-3	17-3419	10-172-2	17-3420	10-551	WC 11
10-17-5	20-1081	10-74-2	16-6780	10-173-2	17-1083	10-552	17-1033
10-18-1	HS 3	10-74-5	20-1082	10-174-2	17-3414	10-555	HS 5
10-18-2	17-5004	10-75-5	HS 35	10-175-2	17-1108	10-556	17-3400
10-19-4	HS 7	10-76-2	17-5003	10-178-1	24553	10-557	19-3093
10-20-5	HS 22	10-76-3	17-6094	10-183-1	19-3180	10-558	19-4400
10-21-0	17-3428	10-77-2	17-5037	10-188-			

# SEARS/SILVERTONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
10-697	19-3001	46-10753-3	26C81	55-303	26S85	80-23-6	26C81
10-698A-D	Y 16 <sup>8,5</sup>	46-10754-3	19-2034	55A303	26S85	80-24-4	Y 97
10-699	Y 10	46-10793-3	19-1010	55B248	24553	80-24-6/B/C	26C81
10-781	17-3495	46-10805-3	19-1001	55B250	26A05	80-25-3	FLY 273
10-785	20-1049	46-10810-3	19-1047	55B251	FLY 25	80-25-4/A/B	Y 97
10-786	17-4524	46-10812-3	19-1045	55B253	FLY 25	80-26-2/A	26S29
10-787	17-5001	46-10820-3	19-1014	55B260	26S76	80-26-3/K	
10-788	19-3075	46-80107-3	Y 123	55B266	FLY 25	F/D	FLY 511
10-789	19-1006	46-80167-3	Y 121	55B270	FLY 25 <sup>1</sup>	80-27-2/A	26S30
10-790	19-3250 <sup>2</sup>	46-80185-3	26S49	55B274	FLY 25	80-27-4/A	Y 96
10-791	HS 34	46-80187-3	FLY 443	55B283	FLY 25	80-27-5/B	21F140
10-792	Y 18 <sup>8</sup>	46-80189-3	20C47	55C249	26S17	80-28-3/A	FLY 257
10-815/B	Y 16 <sup>8</sup>	46-80205-3	Y 149	55C260	26S76	80-29-4/F	Y 96
33-244	26C77	46-80209-3	26C80 <sup>1</sup>	55C284	26S77	80-30-2/A/B	26S29
33-245	26C92	46-80211-3	FLY 647	55C301	FLY 146	80-30-3/A	FLY 257
33-246	19-3001	46-80212-3	24552	55C302	24548	80-31-2/B	26S23
33-248	19-1004	46-80215-3	Y 122 <sup>8</sup>	55D270	FLY 25	80-31-4	Y 107
46-433	Y 121	46-80220-3	26C81 <sup>1</sup>	55D274	FLY 25 <sup>3</sup>	80-31-6/B/C	26C81
46-802-3	Y 121	46-80223-3	HS 7	55D285	FLY 109	80-32-3	FLY 257
46-1024-3	19-1006	46-80232-3	Y 207	56A250	26C77	80-33-2/A	26S86
46-1039-3	19-2019	46-80244-3	FLY 443	56B187	26C41	80-33-3	FLY 277
46-1041-3	19-3125	46-80261-3	Y 5021	56B224	26C77	80-34-1	24564
46-1044-3	19-1016	46-80272-3	FLY 428	80-1-1	FLY 168	80-34-3	FLY 5037
46-104-3	19-3180	46-80274-3	Y 81 <sup>8</sup>	80-1-2/G/CF	26S06	80-34-4	Y 150
46-1048-3	19-1010	46-80301-3	FLY 5101	80-1-3/3Q	FLY 168	80-35-2	26S29
46-1049-3	19-3330	46-80307-3	Y 252	80-1-3B/H/R/S	FLY 168	80-35-4/F	Y 244
46-1054-3	19-3100	46-80323-3	Y 149	80-1-4/L	Y 97	80-36-3/A	FLY 441
46-1055-3	19-3180	46-80324-3	19-2024	80-1-7	26A03	80-36-4P	Y 96
46-1056-3	19-3500	46-80326-3	HS 7	80-2-2	26S25	80-36-6/B	HS 7
46-1065-3	19-7047	46-80354-3	26C81 <sup>1</sup>	80-2-3/A	FLY 127	80-37-6/C	26C81
46-1077-3	26C79	46-80357-3	19-2023	80-2-4/H/J	Y 97	80-38-3/D	FLY 5037
46-1081-3	19-1014	46-80371-3	19-4216	80-3-2/C	26S24	80-38-4/A	Y 96
46-8015-3	24505	46-80374-3	FLY 437	80-3-3	FLY 168	80-39-3	FLY 381
46-10127-3	26C81	46-80425-3	Y 132 <sup>5,12</sup>	80-3-3F	FLY 168	80-39-4B	Y 53
46-10138-3	19-2026	46-80430-3	Y 207 <sup>5</sup>	80-3-7/B	26A05	80-40-4/D	Y 244
46-10143-3	19-2033	46-80432-3	24553	80-4-2/C	26S24	80-41-3	FLY 5048
46-10165-3	19-1014	46-80437-3	Y 132 <sup>5,12</sup>	80-4-3F	FLY 168	80-42-3/A	FLY 5037
46-10168-3	19-1001	46-80480-3	Y 88	80-5-4/A/C/F/G	Y 97	80-42-4/C	Y 96
46-10170-3	WC 14	46-80497-3	26S84	80-6-1	24549	80-42-6	26C77
46-10171-3	WC 35	46-80579-3	Y 235	80-6-3	FLY 168	80-43-3/C	FLY 511
46-10176-3	26C80 <sup>1</sup>	46-80643	FLY 391	80-7-2	26S24	80-44-3	FLY 396
46-10186-3	19-2028	46-86261-3	Y 5021	80-7-4/A	Y 96	80-44-4	Y 53
46-10187-3	19-2032	50A-688	17-5000 <sup>1</sup>	80-8-2/A	26S29	80-44-6	26C81
46-10210-3	19-2024	50A-341	17-1063	80-8-3	FLY 211	80-45-0	24R20U <sup>1</sup>
46-10213-3	19-3500	50A-431	17-1063	80-9-3/D	FLY 211	80-45-2/A	26S86
46-10214-3	19-2024	50A-432	20-1020	80-9-4/A	Y 96	80-45-4/B	Y 244
46-10215-3	19-3125	50A-654	17-5004 <sup>1</sup>	80-10-2/2A	26S29	80-45-4/E	Y 244
46-10216-3	19-3180	50B-58	17-1064	80-10-2/E/F	26S29	80-45-6/B	26C81
46-10217-3	19-7068	50B-406	17-1033	80-10-3/B	FLY 212	80-46-4	Y 53
46-10222-3	26C80	50B-458	17-1064	80-10-4	Y 96	80-47-4/C	Y 96
46-10280-3	19-2021	50B622	HS 3	80-11-2/A/B	26S30	80-47-6/A	26C77
46-10301-3	19-4216	50C648	HS 9	80-11-4	Y 96	80-48-3	FLY 5059
46-10316-3	19-1008	51-2100	19-3180	80-12-3/C	FLY 212	80-48-4/E	Y 140
46-10318-3	19-2023	51-2101	19-4400 <sup>2</sup>	80-12-4	Y 96	80-49-4/D	Y 140
46-10363-3	19-2023	51-2102	19-3100	80-13-2/E	24S24	80-51-4/D/H	Y 53
46-10406-3	17-3415	51-2103	20-1020	80-13-3/G	FLY 257	80-52-4/D	Y 244
46-10410-3	19-1057	51-2104	20-1049	80-13-4	Y 96	80-53-3	FLY 396
46-10418-3	19-7047	51-2105	17-4522	80-13-6	26C80	80-53-4/B	Y 107 <sup>8</sup>
46-10423-3	19-1002	51-2167	17-4534	80-14-2	26S86	80-53-6/B	26C79
46-10425-3	19-1008	51-2169	HS 5	80-14-3/C/H/J	FLY 257	80-54-4	Y 150
46-10427-3	19-2020	51A1854	17-1062	80-15-2/A/F	26S23	80-56-1/P	26C81
46-10430-3	19-4216	51A1857	20-1005	80-15-3	FLY 212	80-57-6	26C79
46-10440-3	19-3330	51A1858/59	20-1020	80-15-6	26C79	80-59-4	Y 109
46-10453-3	19-1008	51A1861	17-1003	80-16-2	26S86	80-59-6/C	26C81
46-10462-3	19-2026	51A1925	20-1049	80-16-4	Y 96	80-60-4	Y 150
46-10494-3	19-4201	51A1927	17-4501	80-16-5/C	21F140	80-61-4	Y 140
46-10503-3	19-3330	51A1947	19-3500 <sup>2</sup>	80-17-3	FLY 257	80-61-6	26C81
46-10520-3	19-1008	51A1952	19-3075	80-17-3R/B	FLY 257	80-63-0/-1	24S51
46-10542-3	19-6033	51A1996	20-1020	80-17-4	Y 97	80-64-6/B	26C77
46-10570-3	19-1002	51A1997	19-5100	80-18-3/H/A	FLY 257	80-65-3	FLY 407
46-10587 <sup>3</sup>	19-7068	51B1948	17-4501	80-19-3/3B	FLY 510	80-65-4/E	Y 245
46-10623-3	19-2014	51B1996	20-1020	80-19-4	Y 65	80-65-6/B	26C81 <sup>1</sup>
46-10641-3	19-3180	51B2109	HS 5	80-19-5	21F140	80-66-3	FLY 5048
46-10655-3	26C80 <sup>1</sup>	51C1875	19-4950 <sup>2</sup>	80-19-6/C	26C80	80-67-3/C/E	FLY 396
46-10658-3	19-7047	51C1876	19-3500 <sup>2</sup>	80-20-2/C/D/		80-67-6B	26C81
46-10660-3	19-2024	52C322	26F64	E	26S23	80-67-9	FLY 441
46-10661-3	19-3330	53-396	Y 60	80-20-4/L/B	Y 96	80-68-6/A	26C77
46-10662-3	19-6033	53A282	19-3001	80-20-6/B/E	26C81	80-69-3	FLY 511
46-10663-3	19-5101	53A307	19-1006	80-21-1	24S48	80-69-4	Y 245
46-10664-3	19-6022	53A342	19-1004	80-21-2(B)	26S30	80-71-4	Y 245
46-10665-3	19-2018	53C396	Y 60 <sup>8</sup>	80-21-4	Y 96	80-71-6/A	26C81
46-10666-3	19-1004	53D324	Y 11 <sup>8</sup>	80-21-5	21F140	80-72-D	26R150
46-10736-3	19-2015	53D325	Y 16 <sup>8</sup>	80-22-4	Y 96	80-72-C	26R150
46-10737-3	19-6022	55-301	FLY 146	80-23-2/A	26S86	80-72-1	24S48

# SEARS/SILVERTONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
80-72-6	26C81	80-135-4A	Y 171	80-353	26S49	102201	19-3060
80-73-3/A/D	FLY 407	80-136-1	24S48	80-361	FLY 127	105196	WC 35
80-73-4/C	Y 140	80-138-3	26C81	80-363	FLY 127	105213	17-6018
80-73-6	26C81	80-141-3	FLY 425	80-368	FLY 126	105214	17-6019
80-74-4	Y 140	80-145-3/C/D	FLY 364	80-370	FLY 24	105216	17-6011
80-75-4	Y 53 <sup>3</sup>	80-145-9	FLY 364	80-371	26A04	105294	17-3417
80-75-6/A	26C77	80-146-3	FLY 377	80-375	FLY 127	105295	20-1057
80-76-4	Y 109	80-147-3/F	FLY 348	80-376	FLY 127	106383	20-1050
80-76-6/A	26C77	80-148-3	FLY 365	80-377	26S25	107290	17-3402
80-77-3	FLY 619	80-149-1/B	24S83	80-378	24S48	107837	17-6012
80-77-4/A	Y 170 <sup>3</sup>	80-153-3	FLY 442	80-380	26A03	109171	19-1008
80-77-4/D	Y 268	80-159-3	FLY 464	80-386	21F24 <sup>1</sup>	109180	WC 43
80-77-6	26C77	80-160-3	FLY 454	80-389	24S61	109221	FLY 281
80-78-1	22S86	80-161-3	FLY 455	80-390	FLY 126	109237	HS 8 <sup>1</sup>
80-78-4/H	Y 165	80-161-9	FLY 455	80-411	FLY 126	109248	19-1001
80-79-4	Y 109	80-164-3	FLY 459	80-415	FLY 127	109251	HS 32
80-80-1/B	24S48	80-164-9	FLY 459	80-486-0/A	26R152	109252	17-3418
80-80-3	FLY 406	80-167-3/-9	FLY 655	80-495-0	23V455 <sup>1</sup>	109253	17-3419
80-80-4	Y 109 <sup>8,14</sup>	80-168-3	FLY 676	80-19090	FLY 419	109254	17-3414
80-80-6	26C40	80-169-1	26S48	81-56-6/D	26C81	109255	20-1058
80-81-0	26R150	80-170-1/C	22S35	82-694	Y 5	109257	19-3600
80-81-1/E	24S51	80-172-1/A/D	26S49	83-669	Y 5	109261	20-1052
80-82-3/B/C	FLY 346	80-172-3	FLY 600	83-694	Y 5	109262	17-1083
80-82-4/D/F	FLY 346	80-179-1/C	26S46	83-743	Y 7 <sup>8</sup>	109264	FC 7
80-83-3	FLY 357	80-192-1/G/E	24S53	83-776	Y 7 <sup>8</sup>	109286	26R150
80-85-3/D	FLY 559	80-192-116	24S53	84-15084	Y 107	109457	Y 107
80-85-4	Y 170	80-196-1C	24S61	84-15990	FLY 376	109825	19-1001
80-86-3	FLY 449	80-198-1A	22S34	84-15992	FLY 381	109826	19-3060
80-86-4/F	Y 177	80-198-1/B	24S53	84-17550	FLY 374	109838	19-3093
80-87-1/A	24S96	80-202-1/B	24S26	84-17576	FLY 374	109840	19-3060
80-87-4/B	Y 179	80-204-1	24S53	84-17601	FLY 375	109845	Y 107
80-88-0/C	26R150	80-217-1/B	24S149	84-17922/E	FLY 375	109850	26S86
80-88-4/C	Y 180	80-225-1	26S119	84-17923	FLY 375	200145	19-2012
80-89-4/C	Y 180	80-226-1	24S53	84-19058	FLY 419	200426	19-6033
80-90-4/A/C	Y 109	80-227-1/B	24S53	85C186	24S50	200529	17-6019</

# SEARS/SILVERTONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
509603	17-3401	520734	19-1021	522020	19-1004	23226229	FLY 647
509613	17-1003	520942	Y 7 <sup>B</sup>	53377	Y 10 <sup>B</sup>	23227034	Y 120
509706	17-3493	520943	HS 9	55248	24550	23227035	Y 109 <sup>5,14</sup>
520487	26R21	520975	26S53 <sup>7</sup>	903562-507	Y 107	23227040	Y 123
520489	FLY 5 <sup>1</sup>	520977	17-1063	906152-501	FLY 277	23227057	Y 207
520518	19-3001	520979	17-1062	906153-501	26R150	23227704	Y 235
520520	19-3001	520980	26A03	962636-501	FLY 28 <sup>1</sup>	23252104	19-1016
520620	19-3180	520984	19-3160 <sup>2</sup>	23211019	26C80 <sup>1</sup>	4251134872	23V448 <sup>1</sup>
520689	19-3180	520985	19-3660	23211025	26C81 <sup>1</sup>	4276104180	Y 5021
520714	19-3001	520986	19-3660	23214008	24552	4276104473	Y 81
520715	17-1004 <sup>1</sup>	521066	FLY 24 <sup>1,3</sup>	23226165	FLY 647		

# SHARP

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
DC-011T	Y 178 <sup>5</sup>	TV-6185	Y 86	8FT-617	FLY 341	302012	24S60
DC-117	Y 125	TV-11144	26S49	8FT-620	FLY 5099	302013	26S29
DC-125	Y 125	TV-11146	FLY 349	8FT-623	FLY 351	302101	FLY 351
DC-134	Y 72	TV-11162	26C81	8FT-640	FLY 341	302113	19-2027
DC-136	Y 124	TV-11172	FLY 341	8FT-644	FLY 5098	302114	FLY 341
DC-140/42	Y 47	TV-11224	FLY 341	8FT-650	FLY 436	302115	FLY 341
DC-143	Y 93 <sup>14</sup>	TV-11239	24S04	8FT-656	FLY 429	303010	26S07
DC-144	Y 150	TV-11338	Y 123	8T-118	26S29	303012	26S19
DC-158	Y 121	TV-61254	Y 123	8T-153	24S60	303011	24S96
DC-159	Y 150	TV-61306	Y 122	8T-157	26S07 <sup>1</sup>	303111	26S30
DC-161	Y 91 <sup>14</sup>	TV-61339	Y 86	8T-166	26S19	303112	19-3300
DC-167	Y 123	TV-61477	Y 123	8T-169	26S07 <sup>1</sup>	303114	22S61
DC-169	Y 91 <sup>14</sup>	TV-61617	Y 91 <sup>9</sup>	8T-173	26S116	303131	HS 7
DC-173	Y 123	TV-61873	Y 125	8T-178	26S30	304012	FLY 350
DC-179	Y 125	TV-61985	26C81	8T-179	26S29	304111	FLY 339
DC-180	Y 122	X3DC-115	Y 122	8T-187	26S30	304112	19-2025
DC-184	Y 123	X3DC-115U	Y 122	8T-188	26S117	304114	26S30
2T1F-443	17-4538	K9T-177	26C81	8T-191	26S117	304115	26S30
DC-188	Y 91 <sup>9</sup>	X0C-180A	Y 122	8T-192	26S30	304131	FLY 5099
DC-191	Y 121	2DC-105	Y 125	8T-196	26S85	305112	19-2026
F 1009CE	FLY 5098	2DC-117	Y 125	8T-204	26S30	305115	24S51
G 13211	26C77	2DC-144	Y 91 <sup>9</sup>	9L-202	19-3125	306110	WC 22
RC1F2170TAZZ	Y 123	2DC-170	Y 123	9L-203	19-3300	306113	FLY 340
RTRNC007CEZZ	26C81	2DC-180	Y 86	9L-204	19-3500	307113	FLY 340
RTRNF1009CEZZ	FLY 5098	2T1F-431	17-4538	9L-207	19-3300	310010	19-2027
RTRNV0011TAZZ	26S30	2T1F-443	17-4538	9L-208	19-3500	310030	Y 124
TL-9	HS 7	2T1F-468	17-3415	9T-154	26C77	310050	Y 124
TL-23	HS 16	7T-145	24S05 <sup>1</sup>	9T-177	26C81 <sup>1</sup>	311010	19-3250
TL-28	WC 22	7T-154	26S48	15-097059	24S173	311030	FLY 426
TL-223	19-3250	7T-161	24S60	15-097142	24S04	312110	24S60
TL-248	19-3060	7T-167	22S61 <sup>1</sup>	15-178365	26C81	313110	26S24
TL-260	19-1014	7T-169	22S86	15-179033	Y 86	313111	19-1005
TL-262	19-2027	7T-171	22S61	216311	Y 93 <sup>14</sup>	314012	HS 16
TL-265	19-3060	7T-173	26S49	226307	FLY 426	315101	19-3180
TL-266	19-3180	7T-174	24S49	246812	Y 93 <sup>14</sup>	315111	19-1014
TL-267	19-2027	7T-179	24S173	301010	Y 72	316100	19-1014
TL-275	19-3125	7T-182	24S173	301012	Y 93 <sup>14</sup>	317100	WC 22
TL-276	19-2028	7T-184/193C	24S04	301013	24S04	317111	19-3125
TL-289	19-3180	7T-194	24S173	301020	Y 124	318100	HS 7
TL-602	WC 22	8F-612	FLY 340	301031	319100	319100	26S48
TL-616	19-3036	8FT-564	FLY 350	301100	Y 93 <sup>14</sup>	320010	19-3060
TL-902	WC 22	8FT-568	FLY 426	301101	26S29	320100	FLY 427
TL-980	WC 22	8FT-572	FLY 350	301110	Y 105	320132	FLY 5098
TL-983	WC 22	8FT-573	FLY 427	301111	Y 105	321010	WC 22
TLF-430	17-3402	8FT-592	FLY 339	301112	Y 125	323130	19-2025
TLF-505D	WC 11	8FT-598	FLY 435	301114	Y 123	328130	26S49
TLF-506D	WC 18	8FT-610	FLY 349	301115	Y 123	340130	FLY 349
TLF-553D	WC 34	8FT-612	FLY 340	301130	Y 122	342130	26C81 <sup>1</sup>
TLF-581D	WC 34	8FT-613	FLY 339	301131	Y 121		
TLF-619D	WC 18	8FT-614	FLY 351	302010	24S05 <sup>1</sup>		

# SILVERTONE

(SEE SEARS/SILVERTONE)

# SIMPSON SEARS

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
BH9000	Y 123	46-8045-3	26S48	46-80187-3	FLY 443	46-80261-3	Y 5021
17Y7Z	26S99	46-8064-3	FLY 391	46-80209-3	26C80	46-80272-3	FLY 428
24WBZ	26S85	46-10170-3	WC 34	46-80212-3	24S51	46-80274-3	Y 81
46-433	Y 121	46-10655-3	26C80	46-80215-3	Y 122	46-80374-3	FLY 437
46-802-3	Y 121	46-80167-3	Y 121	46-80221-3	26S99	46-86261-3	Y 5021
46-1077-3	26C77	46-80185-3	26S50	46-80257-3	26S99		

# SONY

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
A51-0416	19-2011	A52-3190	26S115	1-407-105	19-1008	1-407-187	19-1008
A51-0442	WC 22	A52-3190-M	26S115	1-407-159	19-3100	1-407-363	19-5102
A51-0485	20-1054	A52-3194	24S51	1-407-165/-00	19-7047	1-421-013/-11	19-1011
A51-0489	17-5014	TS-154	Y 52	1-407-169	19-2024	1-427-087-11	24S04
A51-0491	17-3489	1-407-58-00	19-3100	1-407-172	19-3180	1-441-876-00/-11	23V443 <sup>1</sup>
A51-0492	19-3275	1-407-048	19-4201	1-407-175	19-3330	1-442-324-00/-11	23V448 <sup>1</sup>
A51-0943	19-4400	1-407-049	19-1060	1-407-177/-00	19-3500	1-451-003-00	Y 121
A51-3195	26C77	1-407-050/11	19-3330	1-407-178/-00	19-1001	1-451-004-00	Y 121
A52-3151	Y 52	1-407-068	19-1003	1-407-184	19-1003		

# SYLVANIA

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
32-33057-3	VMT-03-01	50-15318-2	19-6033	50-16192-3	17-6033	50-17719-2	FLY 487
32-33057-4	VMT-03-01	50-15318-4	19-7047	50-16206-2	20-1050	50-17730-1	HS 23
32-33057-5	VMT-03	50-15318-5	19-3060	50-16206-3	20-1050	50-17850-1	WC 94
32-33094-2	VMT-05-01	50-15318-4	19-7068	50-16206-5	17-1017	50-17913-1	FLY 493
32-33094-5	VMT-05-01	50-15318-7	19-1015	50-16207-4	17-1083	50-17956-3	FLY 500
32-33094-6	VMT-05-01	50-15318-8	19-3100	50-16207-5	17-1083	50-17985-7	19-1030
32-35894-1	VMT-03-01	50-15318-9	19-3125	50-16221-2	HS 23	50-23094-1	17-5015
32-35894-2	VMT-05-01	50-15318-10	19-2026	50-16234-2	17-3420	50-23213-1	20-1055
32-35894-3	VMT-05	50-15318-11	19-3180	50-16236-6	20-1058	50-23213-2	20-1055
32-35894-4	VMT-05	50-15318-12	19-4201	50-16236-7	20-1058	50-23505-1	WC 53
32-35894-5	VMT-03-01	50-15318-13	19-3275	50-16238-4	20-1057	50-23506-1	FLY 326
32-35894-6	VMT-05	50-15318-14	19-3330	50-16238-5	20-1057	50-23507-1	WC 23
32-35894-7	VMT-05	50-15318-16	19-3500	50-16248-1	WC 41	50-23827-2/	
32-39091-1	VMT-08	50-15319-9	19-3125	50-16248-2	WC 42	50-23842-1/	
32-39091-2	VMT-08	50-15353-1	WC 90	50-16248-3	WC 43	-2	FLY 389
32-39091-3	VMT-08	50-15476-1	26S08	50-16248-4	WC 44	50-23921-8	19-3100
32-39091-4	VMT-08	50-15904-2	19-1008	50-16248-5	WC 41	50-23921-10	19-2026
32-39091-5	VMT-08	50-15904-4	19-1008	50-16248-6	WC 44	50-27405-1	17-6089
32-39091-6	VMT-08	50-16016-1	FLY 277	50-16248-7	WC 91	50-27406-1	17-6090
32-39091-7	VMT-08	50-16016-2	FLY 277	50-16248-8	WC 92	50-27415-1/	
32-39091-8	VMT-08	50-16103-13	19-3036	50-16248-9	WC 92	-3	FLY 328
32-39091-9	VMT-08	50-16103-45	19-3075	50-17062-2	WC 93	50-27549-1	17-6033
32-39704-1	VMT-05	50-16103-46	19-1036	50-17069-1/		50-27550-1	17-6031
32-39704-2	VMT-05	50-16109-2	19-3125	-2/-3	FLY 332	50-27551-1	17-6032
32-43737-1	VMT-09	50-16184-3	17-6028	50-17102-1	HS 23	50-27760-1/D	FLY 494
50-11378-1	19-2011	50-16184-4	17-6088	50-17314-1/		50-27819-1/	
50-11378-8	19-1002	50-16185-2	17-6022	-3	FLY 553	-2/-3	FLY 484
50-11603-2	HS 37	50-16185-3	17-6022	50-17314-2/		50-27845-1	FC 6
50-11634-1	19-3036	50-16189-2	WC 36	-4	FLY 5		

# SYLVANIA

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
50-31050-12	20-1069	-2/-3	Y 128	55-77335-2	22R43	57-23827-2	20-1065
50-31050-16	FLY 380	51-15800-1	Y 129 <sup>14</sup>	55-77482-1	26R20	57-23827-3	20-1062
50-31050-19	20-1051	51-15942-2	Y 245	55-78674-1	26R28U <sup>1</sup>	57-23827-4	20-1065
50-31050-20	17-3410	51-15949-1/2/		55-86853-3	24R40	57-23827-5	20-1079
50-31050-22	17-3487	-3/-4	Y 225	55-99164-1	26R110	57-23827-6	20-1062
50-31050-26	19-1001	51-16083-1	Y 107	56-10099-5	26S49	57-23831-1	17-5065
50-31050-27	19-2026	51-17570-1/		56-10388-1	22S79	57-23832-1	17-3409
50-31050-28	19-2028	-2	Y 166	56-11607-1	26S24	57-31057-1	17-1015
50-31050-31	FLY 512	51-17817-1	Y 249	56-11651-1/2	26C79	57-31657-3	17-1073
50-33085-2	FLY 499	51-17908-1	Y 129	56-11651-5	26C92	57-55045-1	17-5015
50-33195-1	20-1008	51-23503-1	Y 225 <sup>15</sup>	56-11651-6/	-7	57-85966-1	17-5067
50-33628-1/		51-27822-1/3	Y 141	56-11997-1	26C78	57-85975-1	17-5068
-2	FLY 551	51-29071-1	Y 111	56-11998-1	26C80	76-13910-1/2/	
50-33636-1	FLY 547	51-29123-2	Y 225	56-11999-1	26S07	-3/-4/-5/-6	Y 225
50-33902-1	FLY 543	51-29369-1	Y 205	56-15476-1	26S08	76-14236-1	Y 225
50-33927-1	FLY 549	51-29369-2	Y 205	56-15476-2	26S08	-7/-8	Y 225
50-33955-1/		51-29847-1	Y 131	56-15476-4	26S80	80-82-4F	Y 178
50-35021-1/		51-29847-2	Y 215	56-16017-1	26S86	80-119-4B	FLY 512
-2	FLY 484	51-29978-1/		56-16017-4	26S86	80-123-3B	
50-35345-1	FLY 549	-2	Y 226	56-16018-3	24S61	89-84287-1/	
50-35498-2	WC 92	51-29986-1	Y 225	56-16018-4/		100-0001	Y 12
50-35542-1	FLY 544	51-29986-2	Y 225	-5	26S06	100-0002	Y 12
50-35601-1	FLY 545	51-29995-1/		56-16018-8/	24S07	100-0003	Y 19
50-39010-1	FLY 546	-2/-3/-4	Y 205	56-16018-8/	-9	100-0004	Y 22
50-39082-1/		51-31051-1	Y 178	56-16018-11	24S60	100-0005	Y 19
50-39234-1	FLY 548	51-31052-2	Y 149	56-16024-3	26C81	100-0006	Y 19
50-39287-1/3	FLY 550	51-31057-2	17-1072	56-17558-5	26S86	100-0007	Y 23
50-39372-1	FLY 683	51-33308-1	Y 225	56-17559-3/	26S86	100-0011	Y 14
50-39373-1	FLY 675	51-33657-1/2	Y 151	56-17559-4/	-5/-6	100-0013	Y 14
50-41339-2	FLY 650	51-33657-3	Y 151	56-17568-1/		100-0017	Y 27
50-41422-1	FLY 550	51-33724-2/3	Y 151	-8/-2/-3/-4/		100-0018	Y 27
50-41703-1	FLY 550	51-35809-1/	Y 141	-5/-6/-7/-8	26C81	100-0019	Y 11
50-41704-1	FLY-649	51-35809-1/	Y 141	56-27823-1/3	26S34	100-0022	Y 11 <sup>3</sup>
50-41705-1/2	FLY 658	51-37769-1	Y 236	56-27823-4	26S34	100-0023	Y 16 <sup>3</sup>
50-41706-1	FLY 650	51-37770-1/2/3	Y 250	56-29231-1/2	26C81	100-0025	Y 16 <sup>3</sup>
50-55033-1	FLY 542	51-37770-1/2/3/4/	Y 236	56-29231-3	26C81	100-0030	Y 10 <sup>3</sup>
50-55042-1	20-1061	-7	Y 236	56-31056-2	22S21	100-0032	Y 46
50-55043-1	19-1001	51-39119-1/3/4/	Y 236	56-31056-4	26S73	100-0033	Y 46
-4	Y 25	51-39911-1/2/		56-33084-1	26C80	100-0034	Y 46 <sup>3</sup>
50-84255-2	FLY 202	-3/4	Y 228	56-70805-2	26C79	100-0035	Y 46 <sup>3</sup>
50-84586-1	FLY 104	51-41174-1/2	Y 248	56-73151-1/D	26C44	100-0038	Y 46 <sup>3</sup>
50-85953-6	19-3125	51-73841-1	Y 23	56-73326-3	26S51 <sup>7</sup>	100-0040	Y 46
50-85953-7	19-4201	51-73946-1	WC 23	56-73854-1	26A03	100-0041	Y 46
50-85953-9	19-2027	51-73947-1	FLY 23	56-73858-1	26S49	100-0042	Y 46
50-85953-10	19-3075	51-73947-2	FLY 23	56-74384-2	26S49	100-0043	Y 46
50-85953-11	19-3500	51-77766-D	FLY 69	56-7647-1	26S72	111-0022	15-1083
50-85957-3	HS 38	51-78776-1	FLY 23	56-79216-1	26C44	112-0014	19-3036
50-88332-1	Y 46	51-78862-1	FLY 91	56-84603-2	26S48	113-0010	HVO 50
50-88519-1	FLY 148	51-79079-2	Y 14	56-89342-9	26C79	118-0003	17-3400
50-88961-1	HS 44	51-83562-1	Y 14	56-89797-6/7	26S29	118-0004	17-3402
50-89422-1	HS 42	51-84220-1/		56-94278-1	26S75	118-0005	17-1066
50-89702-1/		-2/-3/-4/-6	Y 16	56-97301-1	24S82	118-0007	20-1006
-3	FLY 148	51-84220-5	Y 25	56-97301-3	24S82	118-0010	19-1005
50-91237-1	FLY 202	51-88332-1	Y 46	56-97301-4	24S84	118-0011	20-1045
50-91292-1	FLY 148	51-88332-2/3/4	Y 46	56-97301-9/	-11	118-0019	17-3401
50-91626-6	FLY 104	51-88339-4	Y 46	56-99229-2	24S80	118-0020	19-2861
50-92043-1/		51-88424-1	Y 46	57-10243-1	16-6758	118-0022	20-1004
50-93279-1/		51-89556-1/2	Y 46	57-10253-1	16-6758	118-0025	20-1045
-2	FLY 202	51-89564-1/		57-11394-1	17-3406	118-0026	20-1049
50-94292-1/		-2	Y 46	57-11602-1	20-1055	118-0032	19-1000
50-95369	FLY 148	51-91258-1	Y 10	57-11604-1	17-1105	119-0002	17-4503 <sup>1</sup>
50-95934-3	FLY 210	51-91627-3	Y 11	57-11606-1	17-1106	119-0003	17-5002
50-97572-1/		51-91883-1	Y 10	57-11606-2	17-1106	119-0004	17-5003
-3	FLY 210	51-92193-2	Y 27	57-11611-2	17-3414	119-0005	17-5004
50-97794-2/		51-94416	Y 46	57-11612-2	17-3414	119-0006	17-5004
-3	FLY 210	51-94416-1	Y 46	57-11637-1/2	17-5062	119-0007	17-4504 <sup>1</sup>
50-97797-1	WC 14	51-95669-45	Y 46	57-11651-2	26C79	119-0009	17-5004
50-97802-1	HS 43	51-96139-1	Y 46	57-15795-1	17-3405	119-0011	17-4503 <sup>1</sup>
50-97908-1/		51-97811-1/		57-15796-1	17-3405	119-0012	17-5002
-2	FLY 210	-6/-7	Y 46	57-15905-8	17-3419	119-0013	17-5004
51-11643-1/		55-10391-1	26R105 <sup>1</sup>	57-15906-7	17-3414	119-0014	17-5004
-2	Y 46 <sup>3</sup>	55-11817-1	26R122 <sup>1</sup>	57-16185-2	17-6022	119-0019	17-5004
51-11653-2	Y 46 <sup>3</sup>	55-11996-1	26R115 <sup>1</sup>	57-16233-3	17-3418	119-0020	17-4522
51-11818-1	Y 46 <sup>3</sup>	55-15153-1	26R122 <sup>1</sup>	57-16233-7	17-3414	119-0021	17-5067
51-11818-2	Y 46 <sup>3</sup>	55-15153-2	26R115	57-16233-8	17-3419	119-0022	17-5068
51-12506-1	Y 25	55-15470-1	26R105 <sup>1</sup>	57-17112-1	17-3418	119-0023	17-5066
51-15473-1/2	Y 111	55-16015-1/		57-17339-1	17-5063	119-0026	17-4536 <sup>1</sup>
51-15474-1/2/3	Y 111	-2	26R150	57-17842-1	17-5064	119-0027	17-4536
51-15475-1/		55-23040-1	21F09	57-23827-1	17-3409	119-0028	17-4524 <sup>1</sup>

# SYLVANIA

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
119-0029	17-4536	132-0005	WC 22	145-0020	26C79	29576A	17-3400
120-0001	17-3495	132-0007	WC 23 <sup>1</sup>	145-0023	26C43	29661	HS 17
120-0003	17-3495	132-0009	HS 7	145-0024	26C77	29694	17-3477
120-0008	17-3495	132-0011	WC 23 <sup>1</sup>	145-0025	19-1005	29714	17-3400
120-0009	17-3495	132-0012	WC 23 <sup>1</sup>	145-0026	19-6033	29727	17-3411
120-0011	17-5004	132-0016	HS 5	145-0043	26C80	29728	17-3413
120-0017	17-5002	132-0017	HS 38	146-0005	HS 5	29729	17-3414
120-0018	17-4534	132-0018	WC 19	146-0012	19-3093	29730	17-3417
120-0019	17-3495	132-0019	HS 38	146-0016	19-3036	29734	WC 41
120-0021	17-3489	132-0021	WC 19	147-0014	19-1001	29735	WC 42
120-0023	17-3489	132-0022	HS 44	147-0022	19-1001	29737	Y 107
120-0027	20-1044 <sup>1</sup>	132-0023	HS 43	155-0008	26C79	29740	WC 35
121-0010	16-6758	132-0024	HS 42	240-0001	26F65 <sup>1</sup>	29741	HS 7
121-0011	16-3487	132-0027	WC 14	241-0001	26S53 <sup>7</sup>	29744	17-6016
121-0017	16-3487	133-0001	WC 33	241-0003	26F52	29745	17-6018
121-0018	20-1049	133-0002	WC 33	241-0004	26S52	29746	17-6019
122-0010	16-6758	133-0003	WC 33	241-0005	FLY 22	29748	19-6821
122-0011	16-3487	141-0008	26R81	241-0006	FLY 22	29749	WC 17
122-0017	16-3487	141-0009	26R81	241-0007	FLY 23	29749	26S48
122-0019	17-6770	141-0011	26F65	241-0008	26S51 <sup>7</sup>	89S06	26R150
124-0002	20-1005	141-0013	26R72	241-0009	26S72	89S07	FLY 284
124-0003	20-1005	141-0015	26R92	241-0010	FLY 69	89S08	26S95
125-0001	17-1064	141-0016	26R72	241-0011	FLY 91	89S10	26C81
125-0002	17-1066	141-0024	26R20	241-0012	FLY 69	89S54	26R150
126-0002	17-5000	141-0027	26R28U <sup>1</sup>	241-0013	FLY 81	109264	
126-0004	17-5004	141-0030	22R43	241-0016	26S11	903562-507	Y 107
128-0007	17-3487	141-0037	26R101	241-0018	26S73	906152-501	FLY 277
128-0008	17-3497	141-0039	26R101	241-0019	FLY 81	961415-3	26S86
128-0012	17-3499	141-0041	22R43 <sup>1</sup>	241-0024	26S17	1104665-3	26C81
128-0014	17-3497	141-0045	26R108	241-0025	FLY 25 <sup>3</sup>	2440151/H	Y 121
128-0015	17-3429	141-0033	26F65 <sup>1</sup>	241-0033	FLY 104	2440152H	Y 121
129-0001	20-1004	141-0063	21F08	241-0034	26S29	2440262	Y 121
129-0004	WC 22	141-0090	24R02	241-0035	FLY 171	5210491H	23V268
129-0006	HS 8	141-0092	26R119	241-0036	FLY 171	A105065	WC 41
130-0001	17-3402	143-0009	26S50	241-0037	FLY 171	A105066	WC 42
130-0002	20-1004 <sup>2</sup>	143-0010	24S88	241-0038	FLY 171	A105295	20-1057
130-0003	17-3402	143-0013	26S49 <sup>1</sup>	241-0041	FLY 171	A106383	20-1050
130-0004	20-1005	143-0014	26S49	241-0042	FLY 171	A109180	WC 43
131-0001	20-1005	143-0017	24S6				

# SYMPHONIC

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
T-828A	26C77	T-L2005	19-3275	TR-219	22S45	T-S2022	20-1051
T-830	20C59	T-L2006	19-3500	TR-220	22S45	T-S2023	17-1072
T-D41	Y 81	T-L2501	19-7100	TR-226	24S96	TR-001	24S50
T-D41A	Y 81	T-L2504	19-3300	TR-232	24S53	TR-002	26S72
T-D64	Y 121	T-L2506	19-3500	TR-233	24S53	TR-004	26C78
TDR-003	FLY 95	TLF-001	17-1031	TR-234	24S53	T-V108	24S150
TDY-001	Y 52	TLF-003	17-3495	TR-234-1	22S45	T-V111	26S49
T-F76A	FLY 390	TR-109	24S53	TR-235	24S53	T-V120	24S53
T-F76A-33	FLY 390	TR-146	24S53	TR-244	24S51	T-V127	22S48
T-F86A	FLY 5088	TR-170	24S53	TR-248-1	24S51	T-W27	26S08
T-F88A	FLY 5088	TR-174	24S53	TR-251	24S53	T-W40	26S11
T-F89A-33	FLY 390	TR-178	22S45	TR-253	24S51	YSG-35461	24S51
T-F99A-17	FLY 390	TR-184	22S45	T-S81C-UC-25	Y 122	YSG-35631	26S85
T-F103	FLY 443	TR-196	22S45	T-S1038	17-3419	YSG-35784	WC 33
T-F103A	FLY 443	TR-197	22S45	T-S1040	17-3419	YSG-35788	17-3419
T-F104	FLY 380	TR-198	24S53	T-S1052	17-3487	YSG-35821-A	Y 86
T-F123A	FLY 443	TR-199	24S53	T-S1810	17-3418	YSG-35825-A	Y 86
THLF-470	19-3500	TR-201	24S04	T-S1820	17-3410	YSG-36100-B	FLY 5065
T-L162	19-3180	TR-202	24S50	T-S1822A	17-3415	YSG-36531	26S85
T-L163	19-3500	TR-216	24S53	T-S2014	20-1055		

# TOSHIBA

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AZ-195F	WC 22	TSB-280	Y 109 <sup>5,14</sup>	201300	HS 27	299924	17-4534
AZ-399A	WC 34	TSB-286	24S173	201329	Y 105	299927	24S06
AZ-9052A	WC 34	TSB-302	Y 109 <sup>5,14</sup>	201364	Y 123	299937	20-1044
AZ-9122	FLY 647	TSB-303	Y 121	201365	17-1015	23211018	26C77
AZ-9996	WC 22	TSB-324	24S96	201379	26C81	23211019	26C77
D005W	Y 123	TSB-328A	Y 123	201383/85	FLY 5008	23211025	26C81
DO19Z	Y 81	TSN8-3040-A5	26A05	201390	26S85	23211054	26C77
TFD-332B	26S85	46-80211-3	FLY 647	201393	17-5031	23211008	24S96
TFD-333	26S29	46-80497-3	26S72	201430	26S72	23222011	WC 45
TFD-336	26S72	200105	26A05	201433	HS 7	23222012	WC 20
TFD-2003	26S72	200116	WC 34	201442	26A05	23222307	HS 8
TL-983	WC 22	200397	WC 22	201453	WC 35	23222313	HS 27
TPW-104	26C81	200426	19-6033	210136	Y 105	23222528	WC 44
TPW-104A	26C77	200529	17-6019	299754	Y 109 <sup>5,14</sup>	23222540	WC 44
TPW-956A	26C77	200597	17-6016	299756	24S173	23225120	HS 7
TPW-971	26C77	200763	24S96	299766	26C77	23226031	26S85
TPW-988	26C77	201170	19-3125	299773	FC 6	23226074	26S72
TSB-200	Y 105	201172	19-3160	299774	HS 7	23226175	FLY 647
TSB-200A	Y 105	201176	19-3275	299783	26S49	23226229	FLY 647
TSB-200B	Y 105	201177	19-3330	299805	Y 138	23227034	Y 120
TSB-200D	Y 105	201179	19-3500	299813	26R150	23227040	Y 123
TSB-210	24S06	201181	19-3660	299845	WC 22	23227054	Y 121
TSB-217	24S04	201203	24S96	299847	HS 7	23227067	Y 123
TSB-238B	Y 123	201204	Y 105	299850	26S48	23227093	Y 207 <sup>5</sup>
TSB-238D	Y 123	201279	WC 34	299859	17-6018	23252029	17-1015
TSB-238E	Y 123	201288	Y 123	299873	26S67	23260261	17-3404
TSB-242	24S51	201291	26C77	299875	Y 107	23264067	17-5031
TSB-246A	Y 120	201292	24S51	299884	Y 107	23264068	17-5022
TSB-249	26S48	201293	17-5031	299914	19-1011		
TSB-272	26S49	201295	17-5022	299922	17-5004		

# TRUETONE

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
A13D16943	HS 5	A16A16515	19-3660 <sup>2</sup>	A16A19366	19-3250	A201-16329	17-1004
A13D19355	HS 5	A16A16516	19-4400	A16A19367	19-4400	A201-16379	19-3001
A13M18021	17-1003	A16A16637	19-1000	A16A19486	19-4400	A201-16405	19-3001
A13M18026	17-1003	A16A17128	19-1005	A16B16023	19-3001	A201-18695	17-3400
A13M18233	WC 11 <sup>1</sup>	A16A17937	19-1005	A201-15608	19-3001	A201-18746	17-3400
A13M18861	WC 16 <sup>1</sup>	A16A18685	19-3250	A201-15609	19-3001	A201-19363	17-3400
A16A16514	19-3036 <sup>2</sup>	A16A19365	19-4400	A201-16158	19-4250	AT-18	24S54

# TRUETONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
AT-32	24S48	ES61X174	17-6051	L-235	17-6028	TR-50A	26S08
AT-50	24S48	ES64X100	26S58	L-236	17-6032	TR-51/A	FLY 137
AT-52/A	24S53	ES77X12	FLY 623	L-237	17-6022	TR-52A	26R123
AT-62	22S45	ET36X410	19-3125	L-239	WC 41	TR-52B	26S51 <sup>1</sup>
AT-63	24S64	ET36X536	19-1008	L-240	WC 43	TR-53A	FLY 175
AT-75	24S64	ET36X814	20-1051	L-241	WC 44	TR-57	FLY 149 <sup>3</sup>
AT-78	24S48	EU36X536	19-1008	L-242	WC 36	TR-63	26R127
AT-79	24S61	EU61X121	20-1057	L-243	20-1050	TR-73	FLY 137
AT-81A	22S22	ETA28A36A	24S78 <sup>1</sup>	L-244	20-1052	TR-77/A	26S07
AT-83	22S61	ETA35A4/A	22S61	L-245	17-6033	TR-78	26S85
BT-507	HS 5	ETA48E27M	24S115	L-246	Y 107	TR-78B	26S85
B12C1007.4	24S50A	ETA48E27WA	24S06	L-262	Y 208	TR-79	FLY 514
B12C16050	26S53	FC-5/A/B	26C79	L-263	Y 208	TR-84	FLY 277
B12C17303	26S51	FC-9	26C77	L-265	17-5002	TR-85	26R150
B12C18743/-1	24S52	FC-18/A	26C79	L-266	17-5010	TR-86	26S86
B12C19048	26S53 <sup>2</sup>	FC-23/-24	26C81	L-267	19-1010	TVL-197	Y 101
B12C19990	26S49	FC-23A	26C78	L-302	17-1052	TVL-200	Y 64
B12C70761-1	26S54	FT-520	FLY 443	LI-19	16-6758	TVL-209	Y 208
B12M18241	26A03	L-66A	HS 7	S-38A1003	19-3500	TVL-262	Y 208
B12M18241-3	26A03	L-80A	20-1020	SPK-135	24S53	TVL-263	Y 208
B13A16612	16-3487 <sup>1</sup>	L-81A	Y 99	TF-107A	FLY 443	2DC-144	Y 123
B13A166612	16-6678 <sup>1</sup>	L-82	17-4534	TIF372	17-520	2DC-170	Y 123
B13B16000	16-3487 <sup>1</sup>	L-84	17-4514	TIF373	21-5023	2TL-299	19-2026
B13B16302	16-6678 <sup>1</sup>	L-88	19-5100	TIF374	17-3419	2TL-948	WC 41
B13B17273	17-3493	L-89	20-1004	TL-23	HS 16	2TL-985	19-1002
B13B18784	17-1068	L-90	17-3400	TL-77	19-2006	7T-182	22S61
B13A18788	17-1031	L-103	17-5002	TL-227	19-1002	BFT-598	FLY 435
B13D16611	14-1060	L-110/A/B	17-1031 <sup>2</sup>	TL-260	19-1014	BFT-644	FLY 5098
B13E12046	19-3001	L-118D	Y 99	TL-275	19-3125	BFT-650	FLY 436
B13M13590	Y 3	L-119A	HS 9	TL-601	19-1006	BFT-656	FLY 429
B13M16001	17-3488	L-126/A	19-4160	TL-121-153	19-3125 <sup>2</sup>	BT-192	26S30
B13M16335	17-1033	L-127/A	19-3375	TL-301-999	19-3300	BT-204	26S30 <sup>1</sup>
B13M17273	17-3493	L-128/A	19-3125	TL-351-999	19-3330	9A1881	19-3001
B13M18888	Y 5 <sup>1</sup>	L-132A	HS 5	TLF-302D	FLY 430	9A1970	17-3487
B16A16051	26C92	L-133A	19-6022	TLF-3030S	FLY 432	9A1974	FC 2
B16A17959	26C44	L-135A	Y 100	TLF 418	FLY 398	9A1976	WC 11
B18A16440	22S58	L-149B/-192	Y 64	TLF 605	FLY 431	9A1997	19-4122
B201-15612	17-1003	L-150	17-5004	TLF-5004-1	FLY 643	9A1978	19-4122
B201-16412	17-1003	L-151	17-5004	TLF-5004-3	FLY 643 <sup>1</sup>	9A1979	19-3036
C1.458	WC 11	L-152	17-5026	TLH-203-1	HS 8	9A1980	17-1004
C1.459	WC 14	L-154	16-3445	TLH-209	HS 16	9A1981	WC 14
CBG11892	19-4400	L-156	HS 5	TLH-603	WC 23	9A1982	17-1005
C9.209	Y 3	L-160	19-1005	TLH-5301	HS 7	9A1983	17-1013
C9.228-3	26S51	L-162	19-3180	TLI-1154	17-3405	9A1984	HS 2
C9.230-2	26A03	L-163	19-4950	TLI-51251	17-5014 <sup>1</sup>	9A1985	20-1021
C9.234-2	FC 2	L-164	19-1001	TLI-51252	17-5014 <sup>1</sup>	9A1986	17-1012
C9.236	FLY 1	L-165	17-5003	TLI-51253	17-5014 <sup>1</sup>	9A1987	Y 3
C9.237	26C93	L-167	17-3494	TLI-53052	17-4538	9A2029	16-6758
C9.241	26S49	L-170	17-5025	TLM-053-999	19-1008	9A2030	16-3487
C12A17822	26R15	L-171	17-5025	TLM-080-999	19-1009	9A2033	19-3001
C12A18839	26R15	L-177/-174/B	Y 64	TLP-113	26C791	9A2034	16-3487
C12A18839-1	26R15	L-178A	Y 99	TLP-5151	26C81 <sup>1</sup>	9A2048	Y 3
C12M18285	FLY 34	L-179	17-5003	TLQ-100-999	19-1005	9A2049	17-1047
C12M18286	FLY 34	L-188	17-3495	TLQ-120-139	19-2017	9A2053	FC 2
C12M18689-2	FLY 35	L-197	Y 101	TLQ-121-999	19-3125	9A2055	17-1005
C12M19407	FLY 36	L-200	Y 64	TLQ-500-999	17-7047	9A2057	HS 3
C16A15624	26C43	L-202	HS 16	TLQ-700-999	19-7068	9A2059	20-1021
C18A18022	24S52	L-203	17-1093	TLQ-900-999	19-3093	9A2060	16-3487
C18A18588	24S52	L-205	17-1094	TLS-1153	20-1051	9A2061	16-3487
C201-16411	17-1021	L-206A	17-1075	TLS-1160	20-1051	9A2062	16-6758
C201-19250	Y 5 <sup>5</sup>	L-208	17-5004	TLS-1161	20-1051	9A2063	16-6758
C201-21025	FLY 39	L-209	Y 208	TLS-1165	20-1055	9A2064	17-3487
C201-21130	Y 5 <sup>5</sup>	L-210	19-1001	TLS-1512	20-1081	9A2069	Y 3
C201-21138	Y 5 <sup>5</sup>	L-212	19-1008	TLS-2151	17-1008	9A2071	17-1002
C201-21514	Y 5 <sup>5</sup>	L-213	19-1005	TLS-51003	20-1004	9A2073	20-1021
D9.235	26R95	L-214	19-3125	TLS-51201(-1)	17-1026 <sup>1</sup>	9A2074	20-1004
DC184	Y 123	L-215	19-4073	TLS-51202(-2)	17-3495 <sup>1</sup>	9A2075	WC 11
EP36X1	19-1002	L-216	HS 23	TLS-51203(-1)	17-1031<		



MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
9A2166	17-1005	-2B	Y 73	9A2622-001	17-3415	16A18676	19-1002
9A2167	17-1002	9A2487	HS 5	9A2629-002	WC 53	16A19365	19-4400
9A2168	17-1031 <sup>1</sup>	9A2491/-C01	16-6758	9A2630-001	WC 54	16A19366	19-3250
9A2169	20-1021	9A2496-001	14-7002	9A2634-001	WC 38	16A19485	19-3250
9A2170	17-3495	9A2504	20-1004	9A2634-002	WC 38	16A19486	19-4400
9A2171	17-3495	9A2507-001	14-1040	9A2637-001	Y 245	16A19818	19-6022
9A2172	WC 16	9A2508-001	16-6758	9A2650-001	Y 17-5030	16A20020	19-3125
9A2183	WC 15 <sup>1</sup>	9A2509-000/-		9A2654-001(E)	Y 109	16A20021	19-3125
9A2193	Y 75	-001	16-3487	9A2658-002	17-6028	16A20469	19-3001
9A2194	Y 75	9A2510-000/-		9A2660-001	17-6053	16A20470	19-3100
9A2201	17-1031 <sup>1</sup>	-001	16-3487	9A2661-002	17-6027	16A20770	19-3001
9A2225	17-1004	9A25138	HS 5	9A2666-001	17-3404	16A20970	19-3250
9A2226	17-1002	9A2514-2	Y 74	9A2667-002	17-6022	16A21214	26C44 <sup>1</sup>
9A2230	17-1063	9A2515/8	HS 16	9A2676-001	17-5023	16A21391	19-3001
9A2236	Y 75	9A2518-001	19-1003	9A2681-001	20-1079	16A21656	19-1005
9A2257	Y 75	9A2519-000/-		9A2681-002	20-1079	16A21701	19-1005
9A2261	Y 75	9A2522/-1	Y 104	9A2682-001	HS 6 <sup>1</sup>	16A22427	19-1004
9A2262	WC 22	9A2525/-001	17-5021	9A2683-001	17-5020	16A22923	19-6022
9A2269	17-3493	9A2526/-1	20-1069	9A2686-001	Y 1078	16A23899/-1	26C80
9A2274	Y 75	9A2527/-1	17-1075	9A2707-001(B)	Y 1371 <sup>4</sup>	16A24019	19-3500
9A2292	WC 20	9A2528	17-5020	9A2745-001	Y 181	16A24020	19-3160
9A2293	WC 22 <sup>1</sup>	9A2529/-1	20-1070	9A2757-001	Y 172	16A24090	19-1005
9A2294	HS 3	9A2530	17-5019	9A2758-001/B	Y 259	16A24375	19-3660
9A2295	17-1033	9A2536-000/-		9L-222	19-1008	16A24504	20-1004
9A2316	17-5001	-001	16-6823	9L-227	19-2005	16A24998	19-3125
9A2317	17-5003	9A2537-000/-		9T-177	26C81 <sup>1</sup>	16A25441	20-1004
9A2318/19	17-5004	-001	19-6817			16A25688	19-1001
9A2321	20-1045	9A2539/-1	17-5023	12A18839-1	26R15	16A26520	19-1004
9A2323	17-3495	9A2540/-1	17-5022	12A19942/-1	26R94	16A26520	19-1001
9A2327-2	Y 4 <sup>2</sup>	9A2541/-1	17-5015	12C18743	24S52	16A26986	19-1004
9A2332-2	Y 75	9A2542/-1	17-5024	12D19849	26S51	16A26987	19-1005
9A2334-1	Y 4 <sup>2</sup>	9A2543-001	19-1002	12C21215	24S50	16A26991	17-3401 <sup>1</sup>
9A2334-2	Y 4 <sup>2</sup>	9A2544-1	Y 73	12C23704-1	24S49	16A27202	19-3250
9A2342-000	19-1006	9A2544-001/B	Y 73	12C23704-2	26S49	16A27204	19-4400
9A2363	17-4536	9A2545-001	17-5020	12C24170	24S48	16A27466	19-3075
9A2364	17-4535	9A2547-001	17-5019	12C25148-1	24S50	16A27467	19-4400
9A2365	17-4534	9A2553-001	19-2010	12D19250	26F65	16B16023	19-1002
9A2366	20-1004	9A2553-002	19-1008	12D21160	21F11 <sup>1</sup>	16B25146/-3	26C78
9A2367	20-1005	9A2553-004	19-1008	12D23699	26F67	25A12701	19-3001
9A2368	17-3495	9A2554-001	WC 23	12D23699-3	26F67	25A15401	19-3001
9A2369	20-1045	9A2555-001/A	HS 41	12D25563	21F24 <sup>1</sup>	1A1076	19-1020
9A2370	17-4514	9A2555-002	WC 41	12D25564	21F24 <sup>1</sup>	31A078	17-1003
9A2371	HS 7	9A2555-003/A	WC 41	12E19048-2	26S14	31B230	19-1005
9A2372	HS 8	9A2556-001	WC 43	12E23726	26S52	31B239	19-1005
9A2373-1	Y 76	9A2556-002	WC 45	12E23726-1	26S52	31B295	19-3001
9A2375	19-3036	9A2556-003	WC 45	12E23939	FLY 80	31B296	19-3001
9A2380/-1	19-1001	9A2557-001/C	WC 44	12E24440	HS 7	31B-638-1	19-3001
9A2381	WC 22	9A2558-001	WC 36	12E24441	HS 8	34A546	19-3001
9A2382	17-3400	9A2559-000C	20-1050	12E25101-1	26S75	34A575	19-3001
9A2383	17-1026	9A2559-001	20-1050	12E25423	FLY 97	34A576	19-3001
9A2385/-1	Y 76	9A2560-000/B	20-1052	12E25424	FLY 97	34A704	19-3100
9A2387/-1B	Y 71	9A2560-001	20-1052	12E26993	HS 7 <sup>1</sup>	34A732	19-3001
9A2388/-1B	Y 71	9A2561-000	17-1083	12E27097	FLY 99	35A5	19-3036
9A2389	17-4534	9A2561-001	17-1083	12E27149/-1	FLY 98	36A1	19-3100
9A2390	17-5026	9A2562-001	17-3418	12E27156	26S14	36A2	19-3180
9A2400	17-1026	9A2562-002	17-3414	12E27189	26S52	36A4	19-4201 <sup>2</sup>
9A2403	Y 71	9A2562-003	17-3419	12M1841-1	26A03	36A5	19-3660
9A2413	17-3400	9A2562-004	17-3419	13A19514	17-1031 <sup>1</sup>	36A7	19-3180 <sup>2</sup>
9A2414	17-4535	9A2562-005	17-5015	13A24203	17-4503	36A8	19-3180 <sup>2</sup>
9A2415	Y 72	9A2563-000	20-1058	13A24224	17-5001 <sup>1</sup>	36A10	19-4060
9A2416	HS 7	9A2563-001	20-1058	13A24937	17-5003 <sup>1</sup>	36A11	19-3500
9A2423	Y 76	9A2564-001	17-6022	13A25139	17-1064	36A12	19-4160 <sup>2</sup>
9A2425	20-1020	9A2565-000	20-1057	13A25140	17-1064	36A13	19-3180 <sup>2</sup>
9A2426	20-1005	9A2565-001	20-1057	13A26998	17-4500 <sup>1</sup>	36A16	19-3075 <sup>2</sup>
9A2427	17-4534	9A2566-001	17-6028	13B23887	17-1067	36A17	19-3160 <sup>2</sup>
9A2430	HS 5	9A2567-001	17-6032	13D19540	HS 5	36A19	19-3125
9A2432-000	19-1001	9A2568-001	17-6033	13M18026	17-1003	36A21	19-3125
9A2432-001	19-1006	9A2568-002	17-6028	13M18233	WC 11 <sup>1</sup>	36A22	19-3300 <sup>2</sup>
9A2434	17-1026	9A2569-000A	17-3420	13M19521	17-1003	36A23	19-3100 <sup>2</sup>
9A2435	17-4514	9A2569-001	17-3420	13M19643	17-3493	36A25	19-3100 <sup>2</sup>
9A2436	17-4514	9A2569-002	19-1008	13M20780	19-3001	36A27	19-3300
9A2444	17-5016	9A2570-001	17-6031	13M21644	17-3493	36A28	19-3300 <sup>2</sup>
9A2452	Y 71	9A2572-001	FC 6	13M23755	Y 5 <sup>2</sup>	36A33/38	19-4201 <sup>2</sup>
9A2453	Y 72	9A2576-001(C)	Y 107	13M24085	HS 8	36A34	19-3375
9A2458/B	Y 71	9A2577-001	16-6758	13M24086	HS 6	36A35	19-3075 <sup>2</sup>
9A2461	17-4538	9A2578-001	16-6758	13M24441	HS 5	36A36	19-3100
9A2476	Y 72	9A2592-001	20-1054	13M25686	20-1006	36A37	19-3250 <sup>2</sup>
9A2477/-1B/		9A2595-001	20-1054	13M26988	20-1005 <sup>1</sup>	36A38	19-4201 <sup>2</sup>
-1C/-2	Y 72	9A2597-001	17-1019	13M26992	HS 8 <sup>1</sup>	36A40	19-4073 <sup>2</sup>
9A2481	HS 7	9A2599-001	20-1057	13M27404	19-7047	36A41	19-3100 <sup>2</sup>
9A2482/-1A	Y 71	9A2602-001	17-5030	13M27405	19-4215	36A43	19-3160
9A2483	17-4514	9A2604-001(A)	Y 105	16A17128	19-3001	36A44	19-4201
9A2484-1A	Y 72	9A2605-002(A)	Y 105 <sup>2</sup>	16A17937	19-3001	36A45	19-3275
9A2485-1/-1D/		9A2610-001	14-9015	16A17959	26C44	36A49	19-4201

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
36A50	19-3250	51X223-1/-3	26S07	53X320	FLY 169	63T1	19-3001
36A51	19-3375	51X224/-1	26S07	53X324	26R93	63T12	17-3402
36A52	19-3375	51X229-1/A	26S30	53X325	26R92	63T13	19-4121
36A94-1	19-4201	51X0229-002	26S30	53X326	FLY 37	63T14	19-4120
36A0094-001	19-4201	51X0229-005	26S30	53X328	FLY 37	63T15	19-3125
36A94-2	19-3660	51X0229-007	26S30	53X329	FLY 37	63T16	19-3160
36A94-3	19-3330	51X233-1	26S23	53X330	FLY 37	63T18	26C93
36A0094-003	19-3330	51X0233-003	26S30	53X331	26R20	63T20	WC 15
36A0094-005	19-3500 <sup>2</sup>	51X0235-002/		53X332	26R89	63T22	WC 14
36A0094-006	19-3500	-2A	24S53	53X333	26R34	63T23	17-3497
36A94-9	19-3300	51X0235-003	24S53	53X336	26R58	6414	Y 6
36A94-10	19-4201 <sup>2</sup>	51X0235-005	24S53	53X338	FLY 24	66X0060-001	VMT-05
36A0094-010	19-4201 <sup>2</sup>	51X0236-000/		53X339/A	26R56	66X0060-002	VMT-05
36A0094-015	19-3060	-001	22S37	53X340/A	26R89	72C132-42	17-3408
36A0094-017	19-2028	51X0236-003	24S06	53X345	26R11	72C132-61	20-1051
36A0095-001	19-7058	51X0236-004	24S06	53X346	FLY 37	72C132-65	14-3414
36A0095-002	19-1005	51X0237-001/		53X350	FLY 202	72C132-67	17-3110
36A0096-001	19-3036	A/-001	26S86	53X354-A	26R41	72C132-82	20-1051
36A0096-002	19-3660 <sup>2</sup>	51X0238-001/		53X355	FLY 203	72C185-2	17-1072
36A0096-003	19-3125 <sup>2</sup>	B	26S64	53X359/A	FLY 202	72B208-6	17-1073
36A0096-005	19-2028	51X0239-001	26S07	53X362/C/G	FLY 223	72B216-5	20-1057
36A0096-006	19-3075	(A)	26S103	53X366	FLY 201	72B220-2	17-3420
38A3286-000	Y 245	51X0242-001	26S105	53X369A	26R58	72C251-1	20-1058
39-12676-1	19-3001	51X0244-001	26S102	53X372	FLY 146	72C251-2	17-3422
50-688	17-5004 <sup>1</sup>	51X0246-001	26S104	53X381	FLY 224	72C251-3	17-3421
50A372-1	17-1004	51X0247-001/		53X382/A	FLY 226	72C251-8	17-3419
50A431	17-1063	B	26S107	53X383/A	26R106	72B261-2	17-3407
50A432	17-1021	51X0249-001/D	24S05	53X386	FLY 224	72C268-3	17-6029
50B406	17-1033	51X0251-001/A	24S07	53X389	FLY 225	72C269-2	17-6025
50B411	HS 5	52C170	26R15 <sup>1</sup>	53X390	FLY 244	72C269-4	17-6025
50B458	17-1062	52C185	26R64	53X397/A-2	FLY 244	72G284-3	17-6021
51-2100	19-3180 <sup>2</sup>	52C195	26R21	53X398/A/C/F	FLY 146	72B284-4	1

# TRUETONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
79(1)30-2	FLY 331	15-178182	19-1014	033-007802	26583	201-15608	19-6022
79(1)30-3(D)	FLY 331	15-178187	19-2033	033-008400	FLY 277	201-15612	17-1003
79(1)38-2	FLY 334	15-178251	19-2025	033-008600	26586	201-15625	17-1002
79(1)38-11	FLY 422	15-178258	26C78	033-010200	FLY 277	201-19490	Y 5
79(1)38-18	FLY 422	15-178209	19-3660	033-011900	26R152	201-19490-1	Y 5 <sup>5</sup>
80B74-1	19-3001	15-178210	19-6022	033-012700	FLY 277	201-19533	FLY 36
85C079	24552	15-178211	19-3125	033-012800	FLY 488	201-19817	FLY 36
90T4A/C	26R92	15-178212	19-1014	033-013000	FLY 277	201-19817-1	FLY 36
91TC	26553	15-178215	19-1008	36-0004	Y 81 <sup>5</sup>	201-19817-3	FLY 36
91T3	26551	15-178221	19-7047	36-0006	Y 81 <sup>5</sup>	201-19947-1	Y 5 <sup>5</sup>
91T4	24551 <sup>1</sup>	15-178222	19-7068	051-102101	19-4400	201-19999	FLY 37
91T5,A,B	FLY 50 <sup>1</sup>	15-178224	19-3660	051-102184	19-3160 <sup>2</sup>	201-20062	17-3400
91T6	26A03	15-178225	19-3125	051-201857	20-1005 <sup>1</sup>	201-20186	WC 16 <sup>1</sup>
94D17-16	HS 5	15-178234	17-3418	051-202167	17-4534	201-20186-1	WC 16
94D255-1/-2/-3	Y 229	15-178237	17-3420	051-202169	HS 5	201-20265	19-3036
94C268-4	HS 7	15-178243	17-6053	053-300396	Y 60	201-20291	HS 5
94D268-4	HS 7	15-178244	26C81 <sup>1</sup>	055-100303	26585	201-20696	17-3400
94C302-6	Y 229	15-178248	19-1014	055-300301	FLY 146	201-20782	17-1003
94D302-5/-6/-106	Y 229	15-178251	19-2025	055-300303	26585	201-20936	Y 5 <sup>5</sup>
94A304-2	Y 138	15-178258	26C78	109-020200	HS 16	201-21025-1	FLY 39
94D304-6	Y 216	15-178277	19-2034	109-020300	17-1093	201-21398	20-1004
94C305-1	WC 41	15-178287	19-7047	109-020600/601	17-1075	201-23727	20-1005
94D305-1	WC 41	15-178289	19-7068	109-020800	17-5014	201-23729/-1	20-1006
94C305-2	WC 58	15-178299	19-2026	109-021600	HS 23	201-23744	Y 5 <sup>5</sup>
94D305-2	WC 58	15-178300	19-3180	109-022100	17-3418	201-23829	19-1021
94D305-5	WC 60	15-178311	19-1014	109-022200	20-1058	201-23873/-1	16-3445
94D305-6	WC 59	15-178312	19-3125	109-022300	17-3414	201-24043	17-4500
94C305-7	WC 62	15-178313	19-3125	109-022400	17-3419	201-24056	Y 5 <sup>5</sup>
94C305-8	WC 58	15-178334	19-3060	109-023100	17-6031	201-24472-1	HS 7
94C305-9	WC 59	15-178335	19-1008	109-023300	17-3420	201-24473	HS 8
94(1)372-1	Y 149	15-178336	19-2026	109-023400	20-1057	201-24473-2/-3	HS 8
94(1)571-2	Y 187	15-178342	26C78	109-023600	17-6032	201-24563-1/-2	Y 5
105S25237	19-3001	15-178348	19-1008	109-023900	WC 41	201-24748	Y 5 <sup>5</sup>
107S25258	19-3001	15-178349	19-2024	109-024000	WC 43	201-24749	20-1004
700A814-8	Y 229	15-178391	19-3180	109-024100	WC 44	201-25360	Y 16 <sup>4</sup>
700C814-3/-5	Y 229	15-179022	Y 122 <sup>3</sup>	109-024200	WC 40	201-25360-1	Y 16 <sup>4</sup>
700C1089-6	Y 229	15-179030	Y 109 <sup>14</sup>	109-024500	17-6033	201-25566	Y 5 <sup>8</sup>
750C305-24/-26/-29	Y 229	15-179033	Y 91	109-029700	17-1085	201-26019	Y 18
750C647-8	FLY 371	15-179036	Y 123	109-029800	17-1052	201-27120	Y 16 <sup>4</sup>
750C1089-3/-6/-12/-13	Y 229	20-0115	26534 <sup>1</sup>	109-029900	20-1052	241K60016	Y 60
15-094003	26530	21-0114	24553	109-030200	17-1052	251-100003	19-3660
15-094007	HS 16	21-0130	26549	109-033700	17-6045	251-100005	19-3160
15-094012	20-1008	22-0371	17-5015 <sup>1</sup>	109-033800	17-6043	251-100008	20-1020
15-094013	17-5020 <sup>1</sup>	22-0372	17-3418	109-034100	20-1055	251-200006	20-1020
15-094014	17-5023 <sup>1</sup>	22-0423	17-3419	109-034200	17-1083	253-300003	Y 16 <sup>4</sup>
15-094015	17-3419	24-0124	19-2011	109-034300	20-1055	255-100012	24548
15-094021	17-3419	24-0235	19-1006	109-034400	17-5027	255-300005	24548
15-094022	17-3419	24-0236	19-1010	109-034700	20-6044	255-300007	26573 <sup>3</sup>
15-094023	17-3415	24-0238	19-3660	109-035600	17-6046	255-400008	FLY 155 <sup>3</sup>
15-094024	17-5020 <sup>1</sup>	24-0239	19-1014 <sup>2</sup>	109-035700	17-6044	256-200002	26C92
15-094025	17-5021 <sup>1</sup>	24-0240	26C77	109-036000	20-1073	256-200008	26C43
15-094026	20-1051	24-0245	17-4538	110-021600	HS 23	101819	19-3036
15-094028	20-1058	24-0295	19-2015	110-024200	WC 40	103037	19-3036
15-094032	20-1057	24-0297	26C79	111-012601	19-3160 <sup>2</sup>	103037	19-3036
15-094033	20-1008	24-0298	19-2003	111-012701	19-2028 <sup>2</sup>	105295	20-1057
15-094034	17-3418	24-0299	19-2004	111-013301	19-6022	106383	20-1050
15-094035	19-2006	24-0303	19-3375	111-016400	19-1001	109252	17-3418
15-094036	26530	24-0304	17-1015	111-021000	19-1001	109261	20-1052
15-094037	Y 123	24-0306	19-4201	111-021100	19-2008	109457	Y 107
15-094038	24560 <sup>1</sup>	24-0308	20-1081	111-021200	19-1008	112822	245114
15-094039	26571	24-0364	26C81	111-021400	19-3125 <sup>5</sup>	112829	26C81
15-094040	22561	24-0366	20C47	111-021500	19-3075	112866	HS 23
15-094041	17-6045	24-0369	19-7068	111-021700	19-3036	112870	17-1083
15-094042	19-1006	24-0371	19-2034	111-021800	19-2028	112871	17-3420
15-094043	19-1006	24-0372	19-3180	111-021900	19-3660 <sup>2</sup>	112875	17-3420
15-094044	19-1006	24-0373	19-3060	111-022600	19-1005	112875	WC 36
15-094045	19-1006	24-0379	19-2033	111-033700	19-1005	112879	17-3414
15-178006	19-1014	24-0384	20-1057	111-033700	19-1005	113382	FLY 277
15-178007	19-3125	24-0387	19-1006	111-023500	17-6028	113382	26R150
15-178008	19-1006	24-0388	19-3500	111-023700	19-1005	113388	19-3660
15-178013	19-1006	24-0389	19-2024	111-026700	19-1010	113390	26586
15-178015	20-1048	24-0390	19-2014	111-031600	WC 45	113404	19-3660
15-178019	19-1006	24-0391	19-2026	111-031700	WC 38	113547	17-3419
15-178028	19-1007	24-0396	19-7068	111-031800	WC 41	115228	Y 6 <sup>5</sup>
15-178040	26C81 <sup>1</sup>	027-026200	Y 208	111-031900	WC 54	115311	Y 14 <sup>5</sup>
15-178044	19-1002	027-026300	Y 208	111-032200	FC 6	115323	Y 14 <sup>5</sup>
15-178046	19-1002	027-031400	Y 109	111-032300	WC 35	250499-5	19-3180 <sup>2</sup>
15-178047	19-2026	027-032800	Y 109	111-032400	WC 53	320141-1	24553
15-178061	WC 41	027-033000	Y 208	111-034900	19-1015	320142-1	26508 <sup>1</sup>
15-178163	19-4216	031-008300	24548 <sup>1</sup>	111-035000	19-3060 <sup>2</sup>	320143-1	26C77
15-178164	19-3330	031-009400	26550	111-036200	WC 23	320144-1	24560
15-178165	19-4214	032-002301	26C78	111-036400	19-2012	320147-1	26572
15-178176	19-2003	032-002600	26C81	111-036500	19-1008	361047-2	Y 86
15-178178	19-6022	032-002900	26C81	111-036600	19-2028	361050-6	19-1009

# TRUETONE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
361050-7	19-2027	508341	26C93	520518	19-3001	520984	19-3160
361050-8	19-3275	508667	WC 20	520520	19-3001	520985	19-3660
361050-9	19-3500	508967	HS 5	520620	19-3180	520986	19-3660
361050-10	19-1001	509340	19-3660	520689	19-3180	521066	FLY 24 <sup>2</sup>
361050-12	19-6022	509341	520714	520714	19-3001	521156	26R94
361050-13	19-1003	509342	19-4400	520715	19-3036	521343	FLY 16
361050-14	19-3125	509361	WC 23	520734	17-1004	521735	FLY 16
361050-15	19-3250	509373	26553 <sup>7</sup>	520911	WC 22	521835	19-3001
361121-1	Y 81	509376	24551	520942	Y 7 <sup>3</sup>	522020	19-1004
361129-1	HS 16	509378	20-1005	520943	HS 3 <sup>3</sup>	970016	Y 229
507343	17-1004	509603	20-1004	520975	26553 <sup>7</sup>	970116	Y 229
507367	19-3036	509706	17-3497 <sup>1</sup>	520977	17-1062	970800	Y 229
507584	19-3001	520487	26R21	520979	17-1064	48004014	Y 109 <sup>14</sup>
508076	26A03	520489	FLY 5	520980	26A03	48005006	Y 122 <sup>3</sup>

## WESTERN AUTO

(SEE TRUETONE)

## WHITE STORE

(SEE CORONADO & EMERSON)

## WESTINGHOUSE

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
D-9-382C	Y 10	V-6128	17-3498	V-6852	24561	V-9642	16-3487
D-9383-1	FLY 5021	V-6129	16-3487	V-6981-1	26553	V-9685	26550
H-84930	Y 27	V-6130	16-6758	V-6981-2	26553	V-9688	16-3487
TLF3705-2D	FLY 342	V-6130-1	16-6758	V-6981-3	26553	V-9723	26R16 <sup>1</sup>
TLI-33051	20-1062	V-6130-2	16-6758	V-6981-6	26553	V-9778	26C44 <sup>1</sup>
TLY3359-4D	Y 120	V-6142	16-3487	V-6981-7	26553	V-9807	24550 <sup>1</sup>
TLY3361-2D	Y 120	V-6179-2	16-6770	V-6987	26550	V-9814	26548 <sup>1</sup>
V-2851	22R06 <sup>1</sup>	V-6206	WC 16	V-8201	Y 3	V-9828	17-3498
V-4886-1	19-1006	V-6207	WC 11	V-8298	Y 12	V-9829	17-3498
V-4886-2	19-3001	V-6213	FLY 4	V-8621-2	15-1082	V-9858	26R21
V-4886-4	19-3036	V-6455-1/-		V-8621-3	15-1082	V-9879	17-5001
V-4886-6/-7	19-3001	V-6471	26C44	V-8621-5	15-1083	V-9879-1	17-5001
V-4886-10	19-3001	V-6471-2	26C44	V-8621-6	19-1006	V-9879-4	17-5001
V-4937	24551	V-6471-3	26C44	V-9099-2	19-1003	V-9880/-2	17-5004
V-5798	26						

# WESTINGHOUSE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
V-9915-7	19-3160	V-14346-1	FLY 73 <sup>3</sup>	230V010M08	19-7047	230V151C02	20-1067
V-9915-8	19-3300	V-14408-2	14-1073	230V010M09	19-3500	230V159B02	WC 55
V-9958-1	26R94	V-14601-1	WC 18 <sup>1</sup>	230V012H01	19-6817	230V176C01	WC 38
V-9958-2	26R94	V-14602-1	WC 17 <sup>1</sup>	230V012H04	20-1004	230V177C01	WC 45
V-9957-3	26R94	V-14602-2	WC 17 <sup>1</sup>	230V012H06	17-6017	230V178C01	WC 54
V-9958-5	26R94	V-14609-1	26S24	230V012H07	19-6821	230V179C01	WC 41
V-9958-6	26R94	V-14662-1	Y 16 <sup>5</sup>	230V013H02	17-1031	230V181H01	WC 53
V-9960	WC 18	V-14662-2	Y 16 <sup>5</sup>	230V013H02	19-3075	230V183B01/	
V-9982	24S51	V-15068-1	17-4522	230V019H03	19-1041	H01	HS 46
V-9982-2	24S51	V-15271-1	Y 16 <sup>5</sup>	230V019H04	19-1013	230V184B01	WC 38
V-9983	22S47 <sup>1</sup>	V-15271-2	Y 16 <sup>5</sup>	230V019H05	19-1041	230V185B01	WC 45
V-10045-1	Y 6	V-15271-4/-6	Y 16 <sup>5</sup>	230V019H06	19-1000	230V186B01	WC 54
V-10045-3	Y 5	V-15324-1	FLY 76 <sup>3</sup>	230V019H09	19-3500	230V187B01	WC 41
V-10045-4	Y 6	V-15324-2	FLY 76 <sup>3</sup>	230V019H10	19-1006	230V187H02	WC 62
V-10046	Y 5	V-15324-3	FLY 76 <sup>3</sup>	230V019H11	19-3036	230V188B01/	
V-10049-1	Y 5	V-15325-1	26S72	230V019H12	19-3250	H01	17-6091
V-10049-2	Y 5	V-15325-2	26S72	230V019H13	19-1006	230V191B01/	
V-10077-1	17-3495	V-15325-3	26S72	230V019H15	19-1006	H01	WC 100
V-10078-1	17-3495	V-15325-4/-6	26S72	230V019H16	19-3250	230V191B02/	
V-10147-1	WC 26	V-15480-2	19-3125	230V019H24	19-7048	H02	WC 101
V-10204-1	FLY 159	V-15480-3	19-3125	230V019M05	19-1006	230V192B01	17-6022
V-10213-1	FLY 158	V-15480-4	19-3160	230V019M10	19-1006	235V005H01	17-5030
V-10214	FLY 159	V-15580-5	19-3300	230V023H02	17-4538	235V005H02	17-5030
V-10214-1	FLY 159	V-15480-6	19-3300	230V027H01	20-1005	235V005H03	17-5030
V-10288-1	24S50	V-15490-1	17-3400	230V027M02/		235V020H01	17-5031
V-10288-2	24S50	V-15490-2	20-1004	H02	17-1095	235V020H03	17-5031
V-10350-1	16-6770	V-15550-1	FLY 76 <sup>3</sup>	230V030H01	17-4538	235V021H01	17-5033
V-10351-1	16-6770	V-15550-2/-3	FLY 76 <sup>3</sup>	230V030H02	20-1066	235V023H11	16-6786
V-10538-1/2/-3/-4/-5/-6/-7/-8	Y 6	V-15685-1	17-5014	230V030H07	17-1109	235V039H03	16-3487
V-10560	Y 6	V-15790-1	17-1075	230V030H08	17-1110	235V045H04	17-3419
V-10560-3	Y 27	V-15791-1	HS 5	230V030H09	20-1072	235V046H01	17-1090
V-10586-1	17-4538	V-15795-1	20-1005	230V031H01	20-1055	235V048H01/02	17-3419
V-10619	16-6758	V-15795-2	17-1095	230V031C04	17-1095	235V048M02	17-3419
V-10771-1	17-4538	V-15796-1	19-3100	230V031H04	17-1090	235V048H04/05	17-3419
V-10833-1	FLY 5026	V-15796-4	19-3125	230V031C06	20-1055	235V049H01	17-5017
V-10909-1	26S54	V-15796-6	19-3160	230V031H08/		235V049H02/	
V-10909-2	26S54	V-15796-7	19-3300 <sup>1</sup>	GCP	20-1112	03	17-5069
V-10911-1	Y 6	V-15796-7	19-3250	230V032A01	HS 16	235V059H01	16-3490
V-10911-3	Y 6	V-15995-1	Y 16	230V032H01/M	HS 16	235V069H01	17-5018
V-10911-4	Y 6	V-16036-1	Y 16	230V033H01	17-1096	235V069H02	17-5018
V-10911-5	Y 6	V-19024-9	15-1091	230V034H01	19-3330	235V069H04	17-5018
V-10911-6	Y 6	3L594-502	Y 27	230V034H02	19-3100	235V069H05	17-5018
V-10945-1	16-6758	5M164-1/2	Y 27	230V034H03	19-3160	235V069H06	17-5018
V-11045-3	Y 5	6L137-1	FLY 1	230V034H04	19-4500	235V076H01/	20-1067
V-11045-5	Y 5	6M403-1	Y 27	230V034H05	19-4201	235V076H02/	
V-11049-5	Y 5	7L309-1/2	FLY 1	230V034H06	19-4400	04	17-1092
V-11264	22S45 <sup>1</sup>	7L997-1/2	FLY 5026	230V034H09	19-3235	235V084H04	17-3419
V-11264-1	16-3487	8L594-501/		230V034H11	19-3660	235V094H01/02/	
V-11360-1	22S45 <sup>1</sup>	-502	Y 27	230V034H13	19-3250	04/05/06	17-5018
V-11396-1	17-1031 <sup>1</sup>	8L594-503/		230V034H16	19-3125	235V139C01	17-5017
V-11544-1	26R18	-504	Y 10	230V065H04	19-2004	235V139H01	17-5017
V-11544-2	26R18	8L594-505/		230V069H01	20-1071	235V141B01/	
V-11544-3	26R18	-508	Y 27	230V069H02	20-1071	H01	20-1102
V-11544-3N	26R18	9L853-501/		230V076H01	20-1067	235V143C01	17-6023
V-11544-4	26R18	-502	Y 27	230V076H02	20-1068	235V143H02/C	17-6092
V-11545-1	WC 18	12K360-1/2	FLY 5026	230V076H04	17-1092	235V144B01/	
V-11546-2/-3	WC 17	12K373-1	FLY 5022	230V083H01	17-1086	H01	17-6093
V-11548-1	FLY 73	13K95-501	Y 10	230V095H03	19-1050	235V145B01	20-1057
V-11548-2/-3	FLY 73	13M95-501	Y 10	230V117H01	19-4073	235V146H01	17-1090
V-11548-4	FLY 5021	14K51-1	FLY 5022	230V117H02	19-3160	235V148H05	17-3419
V-11566-2	WC 17	14K95-1	FLY 5021	230V130H01	19-1008	410V012H01	26R125
V-11570-1	Y 10	17K936-1/2	FLY 5018	230V130H02	19-1006	410V028H01	26R128
V-1171-1	Y 10	17K937	Y 25	230V130H03	19-2009	410V029H01	26R119
V-11789-1	WC 18 <sup>1</sup>	18L417-502	Y 68	230V130H04	19-1005	410V042H01	26R113
V-11791-1	WC 17 <sup>1</sup>	18L477-501/		230V130H09	19-2011	410V051H01/02	21F21
V-11973-1	20-1049	-502/-503/		230V130H10	19-2013	410V067D01	26R150
V-12072-1	Y 16 <sup>1</sup>	-504	Y 25	230V134H01	HS 16	430V003M01	26S48 <sup>1</sup>
V-12102-1	WC 22 <sup>1</sup>	22K750-1	Y 25	230V137H01	HS 16	430V003M02	26S84
V-12103-1	SC 22 <sup>1</sup>	22K785-1/		230V141H02	19-3600	430V004M01	26S72
V-12170-1	26C44	-2/-3	FLY 5021	230V141H03	19-3125	430V005H04	26W28
V-12218-1	Y 10 <sup>27</sup>	65J709-1	FLY 5029	230V141H04	19-3500	430V005H05	26S28
V-12218-2	Y 10 <sup>27</sup>	65J733-1	FLY 5029	230V141H05	19-2027	430V005H06/	
V-12218-3	Y 10 <sup>27</sup>	719D450-1/		230V141H06	19-2026	07/09	26S28
V-12605-4C	26R88	230V005A01	HS 16	230V141H07	19-4400	430V005M01	26S72
V-12605A-1	26R88	230V007M02	20-1054	230V141H08	19-3300	430V005M02/C	26S28
V-12605-1	26R88	230V007H03	20-1054	230V141H09	19-3330	430V026M01	24S52
V-12605-1	26R88	230V008H01	17-5032	230V141H12	19-7048	430V031H01	26S58 <sup>1</sup>
V-12605D-2	26R33	230V008M01	17-5032	230V141H13	19-3660	430V031M01	26S58 <sup>1</sup>
V-12974-1	WC 19	230V010H02	19-3180	230V141H14	19-1005	430V032H01	26C77
V-12988-1	26C44	230V010H03	19-3250	230V141H15	19-2013	430V032M01	26C77
V-14061-3	20-1049	230V010H04	19-3330	230V141H16	19-2023	430V032H02	26C79
V-14080-2	24S49	230V010H09	19-3500	230V144B01	HS 16	430V032H03	26C77
V-14080-4	24S49	230V010H10	19-1006	230V144H01	HS 16	430V032H04	26C77
V-14080G-4	24S49	230V010H14	19-3100	230V151C01	20-1068	430V033H02	26S84

# WESTINGHOUSE

(CONTINUED)

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
430V033H03	26S84	490L007H03	Y 150	493V007H05/		690V045H46	17-6020
430V033M01	26S84	490L007H04	Y 150	-06/-07	FLY 5043	690V045H47	WC 41
430V038H01	24S52	490L008H01	Y 81	493V010H01	FLY 202	690V045H48	WC 42
430V039H02/03/05/06	26S72	490V008H01	Y 53 <sup>8</sup>	493V011H01	FLY 5049	690V045H49	WC 43
430V039C08	26S72	490L008M01	Y 81	493V012H02	FLY 202	690V045H50	26R150
430V039H08	26S72	490V008H02/		493V015H01	FLY 561	690V045H51	26S86
430V039C11	26S71	-03/-04	Y 53 <sup>3</sup>	493V017H01	FLY 5044	690V045H52	26S50
430V039C11	26S72	490L009D01	Y 216	493V018H01	FLY 560	690V045H54	WC 56
430V041H01	24S52	490L010C01	Y 150	493V019H01	FLY 560	690V045H55	FLY 305
430V045H01	26S48	490V011H01	Y 102	493V019C01	FLY 561	690V045H56	19-3060
430V048H01	24S48	490V011H02	Y 150	493V019H01	FLY 561	690V045H58	19-3300
430V053H01	26S71	490V011H04	Y 150	493V020C01	FLY 562	690V045H59	HS 23
430V063H01	24S53	490V013C02	Y 105	493V020C02	FLY 562	690V050H37	17-3418
430V064H01	26C79	490V013H02	Y 105	493V020H01	FLY 562	690V050H38	17-3419
430V066H01	22S45 <sup>1</sup>	490V013C04	Y 105	493V020H02	FLY 562	690V050H47	19-3100
430V067H01	26S48	490V013H04	Y 105	493V020H03	FLY 562	690V050H48	19-3660
430V083H01	24S07	490V014H01	Y 105	493V020H03	FLY 562	690V050H58	Y 81 <sup>8</sup>
430V088H01	22S61	490V014H02	Y 150	493V021C01/A	FLY 5052	690V050H59	HS 16
430V088H02	22S61	490V016C01	Y 105	493V022D01	FLY 445	690V050H62	26C77
430V099H01	26						

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
S-13970	16-6675	S-18812	19-3250	S-23438	FLY 118	S-45831	20-1005
S-13973	17-3494	S-18857	17-4538	S-23490	17-5070	S-46564	FLY 217
S-15015	FLY 53	S-18859	19-3001	S-23632	17-1083	S-46592	FLY 182
S-15048	20-1021	S-18990	FLY 82	S-23940	17-5070	S-46868	17-5070
S-15051	17-1003	S-19001	20-1005	S-23984	FLY 114 <sup>d</sup>	S-47071	FLY 182
S-15052	17-1003	S-19002	17-4538	S-23989	FLY 114 <sup>d</sup>	S-47149	FLY 182
S-15055	17-1004	S-19006	17-3412	S-23992	17-4522	S-47150	HS 6
S-15057	20-1004	S-19020	20-1005	S-23993	17-4523	S-47624	17-4523
S-15060	19-3001	S-19032	FLY 83	S-23995	FLY 118	S-47660	WC 14
S-15065	19-3001	S-19079	FLY 83	S-23998	FLY 118	S-47662	FLY 219
S-15128	19-1005	S-19342	WC 23 <sup>1</sup>	S-23999	17-5070	S-47702	20-1005 <sup>10</sup>
S-15242	17-1004	S-19408	FLY 110	S-24080	17-4538	S-47729	WC 51
S-15709	FLY 53	S-19409	WC 24	S-24095	FLY 118	S-47905	19-3250 <sup>2</sup>
S-15711	FLY 104	S-19411	WC 23	S-24432	FLY 181	S-47906	19-4400
S-15911	FLY 53	S-19486	WC 18 <sup>1</sup>	S-24644	15-1083	S-47967	17-5070
S-15912	FLY 104	S-19712	17-3412	S-24645	17-1083	S-47968	17-5070
S-16009	17-1003	S-19728	FLY 82	S-24736	20-1020	S-48045	20-1044
S-16011	19-3250	S-19735	WC 12	S-24978	FLY 128	S-48046	20-1049
S-16012	17-3412	S-19736	17-5004	S-40019	FLY 114 <sup>d</sup>	S-48195	20-1020
S-16013	20-1005	S-19743	HS 6	S-40124	FLY 118	S-48197	FLY 217
S-16015	19-3300	S-19854	FLY 82	S-40125	FLY 118	S-49892	20-1020
S-16016	19-3300	S-19952	17-5004	S-40235	17-4538	S-49918	FLY 218
S-16024	FLY 53	S-19953	19-3160 <sup>2</sup>	S-40276	17-1018	S-50095	FLY 218
S-16186	HS 6	S-19954	19-3160	S-40279	17-4522	S-50341	20-1020
S-16275	17-5001	S-19958	20-1049	S-40280	17-4522	S-50485	17-3402
S-16276	17-5001	S-19959	20-1020	S-40284	FLY 181 <sup>10</sup>	S-50487	17-1018
S-16501	20-1044	S-19962	16-3445	S-40294	17-5070	S-50488	20-1020
S-16556	WC 17	S-19969	19-3036	S-40486	15-1082	S-50489	20-1020
S-16566	FLY 52	S-20021	19-4201 <sup>2</sup>	S-40818	20-1020	S-50536	16-112
S-16604/05	17-5001	S-20099	FLY 132	S-40820	17-4538	S-50604	19-1053
S-16624	20-1004	S-20216	14-1074	S-40821	17-4538	S-50985	20-1020
S-16652	20-1020	S-20219	16-3445	S-40823	17-4523	S-51445	17-1018
S-16656	17-3402	S-20290	20-1045	S-40824	17-4538	S-51508	17-1021
S-16738	17-3402	S-20367	19-3180	S-40836	17-4538	S-51583	FLY 250
S-16751	WC 15 <sup>1</sup>	S-20607	19-4180 <sup>2</sup>	S-41196	FLY 118 <sup>10</sup>	S-51643	FLY 118 <sup>10</sup>
S-16855	20-1020	S-20622	20-1044	S-41198	FLY 183 <sup>10</sup>	S-51746	17-4538
S-16984	19-3001	S-20629	19-1000	S-41676	19-3375	S-51747	17-4538
S-17104	17-4538	S-20880	19-3125 <sup>2</sup>	S-41681	20-1004	S-51748	19-3100
S-17112	WC 17	S-20902	17-4538	S-41684	19-3036	S-51749	17-4500
S-17114	HS 6	S-20908	FLY 52	S-41690	19-1051	S-51750/52	17-4500
S-17116	17-3401	S-20993	FLY 84	S-41710	17-6011	S-51753	17-4535
S-17130	FLY 53	S-21012	19-3125 <sup>2</sup>	S-41717	20-1005	S-52322	FLY 271
S-17140	FLY 52	S-21019	17-5002	S-41874	19-3093	S-52410	20-1044
S-17175	WC 17	S-21078	FLY 84	S-41879	19-3075	S-52645	19-3180
S-17176	WC 23 <sup>1</sup>	S-21085	19-3093	S-41880	19-3160	S-52679	19-4400
S-17233	FLY 52	S-21219	FLY 117	S-41883	20-1049	S-52687	17-5070
S-17265	FLY 53	S-21261	FLY 117	S-41887	20-1044	S-52688	17-5070
S-17343	19-3093	S-21264	FLY 116	S-41890	19-4524	S-53047	17-4538
S-17434	FLY 52	S-21317	FLY 111	S-41891	17-4523	S-53053	17-4538
S-17435	FLY 52	S-21345	FLY 111	S-41899	17-1018	S-53066	19-3660
S-17472	17-5001	S-21492	20-1020	S-41906	FLY 181	S-53067	19-4201
S-17907	17-5004	S-21561	19-1006	S-41974	FLY 181 <sup>10</sup>	S-53071	20-1044
S-17908	17-5001	S-21562	19-3160 <sup>2</sup>	S-41986	17-1018	S-53072	20-1020
S-17911	19-3160	S-21563	19-3125 <sup>2</sup>	S-41988	FLY 183	S-53082	20-1020
S-17912	19-3160	S-21623	17-4524	S-41990	20-1020	S-53097	FLY 218
S-17927	FLY 52	S-21718	20-1049	S-42042	20-1020	S-53098	17-4538
S-17939	FLY 52	S-21719	17-4538	S-42054	17-1018	S-53099	17-4500
S-17940	WC 15 <sup>1</sup>	S-21752	19-1005	S-42153	20-1020	S-53354	FLY 271
S-17949	WC 15 <sup>1</sup>	S-21888	19-1004	S-42214	17-5070	S-53617	19-3275
S-17954	17-3412	S-22130	FLY 114	S-42624	19-3100 <sup>2</sup>	S-53706	FLY 271
S-17955	20-1005	S-22154	FLY 116	S-42795	20-1049	S-53754	WC 35
S-17956	17-3401	S-22169	FLY 114	S-42872	20-1020	S-53840	FLY 250
S-17958	19-3500	S-22321	17-4511	S-42874	17-4522	S-54083	19-3060
S-17970	17-4538	S-22331	17-4511	S-42875	20-1020	S-54785/87	20-1020
S-18020	19-3001	S-22344	17-5001	S-42878	FLY 184	S-54824	FLY 182
S-18125	FLY 52	S-22345	17-5001	S-43125	20-1020	S-54829	FLY 218 <sup>10</sup>
S-18209	20-1049	S-22347	17-1018	S-43126	20-1020	S-54840	FLY 250
S-18210	20-1049	S-22348	16-3445	S-43219	19-4201 <sup>2</sup>	S-54860	FLY 271
S-18211	20-1045	S-22350	20-1020 <sup>2</sup>	S-43443	17-4536	S-55139	17-4502
S-18420	WC 17	S-22352	HS 5	S-43615	19-3125	S-55140	17-5070
S-18421	WC 16 <sup>1</sup>	S-22353	HS 5	S-43616	19-3125	S-55299	20-1005
S-18537	FLY 52	S-22444	19-6022	S-43618	19-3180 <sup>2</sup>	S-55294	17-6112
S-18566	FLY 82	S-22448	FLY 118	S-43619	19-3180	S-55307	17-5070
S-18567	FLY 82	S-22451	FLY 118	S-43624	17-4536	S-55308	20-1020
S-18568	20-1020	S-22475	19-3500	S-43717	17-1018	S-55842	FLY 218 <sup>10</sup>
S-18570	WC 25 <sup>1</sup>	S-22678	15-1083	S-43891	20-1044	S-56502	17-1018
S-18589	17-4534	S-22720	FLY 139	S-43892	20-1049	S-56503	20-1020
S-18727	19-3100	S-22777	19-1005	S-44279	HS 7	S-56508	17-1021
S-18730	17-5004	S-22996	FLY 114	S-45229	20-1005	S-56538	FLY 274
S-18744	20-1045	S-23016	17-5070	S-45510	FLY 184	S-56686	20-1020
S-18748	WC 24	S-23017	17-5070	S-45543	HS 7	S-56689	20-1020
S-18749	19-1006	S-23049	FLY 133	S-45678	HS 7	S-56752	FLY 271
S-18750	19-3180	S-23348	16-3445	S-45679	HS 7	S-56761	20-1020
S-18751	19-3160 <sup>2</sup>	S-23424	19-3660	S-45680	FLY 220	S-56875	HS 7

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
S-56876	HS 6	S-66305	17-6122	S-76970	FLY 323	S-87813	FLY 490
S-56877	HS 24	S-66308	17-6121	S-77202	17-6131	S-87921	Y 175
S-56887	HS 24	S-66316/18	17-4538	S-77338	17-1111	S-88066	FLY 482 <sup>10</sup>
S-57271	20-1004	S-66328	17-6122	S-77358	20-1005	S-88562/X	FLY 489
S-57621	17-4502	S-66427	20-1005	S-77405	20-1005	S-88567/X	FLY 363
S-57622	17-4502	S-66590	20-1044	S-77411	17-6132	S-88581	FLY 478
S-57623	17-4524	S-66627	19-6821	S-77435	20-1005	S-88582/X	FLY 626
S-57624	17-4524	S-66699	20-1005	S-77490	FLY 321	S-89112	FLY 660
S-57628	20-1020	S-66705	17-1111	S-77581	17-1111	S-89482	FLY 477
S-57630	FLY 271	S-66715	20-1020	S-77652	20-1005	S-89633	Y 167
S-58035	20-1020	S-66717	FLY 162	S-77669	20-1114	S-89730	Y 130
S-58038	WC 52	S-66739	FLY 275	S-77905	17-6133	S-89750	Y 162
S-58041	WC 51	S-66788	20-1005	S-77975	WC 52	S-89877	FLY 479
S-58047	17-4538	S-66845	FLY 316	S-78218	20-1005	S-89889	FLY 404
S-58110	17-1018	S-66849	20-1020	S-78276	17-4524	S-89958	FLY 403
S-58187	17-6117	S-66851	17-4502	S-78277	WC 22	S-90526	FLY 408
S-58348	20-1020	S-66854	17-5070	S-78313	17-5070	S-90534	FLY 491
S-58349	20-1020	S-67025	FLY 347	S-78327	FLY 347	S-90/34-/01	FLY 531 <sup>10</sup>
S-58350	FLY 314	S-67031/33	17-1111	S-78761	17-4538	S-92032	FLY 662
S-58355	17-1018	S-67633	17-1111	S-78762	20-1044	S-92263	Y 132
S-58357	20-1005	S-67716/801	17-1018	S-78988	FLY 532	S-92510	FLY 531
S-58377	20-1005	S-67915	FLY 309	S-78997	FLY 363	S-92510-01	FLY 531
S-58515	17-6118	S-67950	FLY 323	S-79039	FLY 250	S-93172	FLY 480 <sup>10</sup>
S-58516	17-6118	S-67965	20-1020	S-79153	FLY 532	S-93187-/01-	
S-58518	FLY 275	S-68007	17-6123	S-79154	FLY 363	-02	FLY 539
S-58565	FLY 404	S-68004	WC 53	S-79340	20-1005	S-93188/89	FLY 539
S-58572	17-4536	S-68155	17-6123	S-79435	HS 16	S-93256	Y 173
S-58614	17-5070	S-68204	17-6817	S-79638	FLY 532	S-93296-02	FLY 481
S-58675	HS 7	S-68273	HS 7	S-79640	FLY 363	S-93297	FLY 481
S-58725	17-4500	S-68398	FLY 317	S-79692	WC 106	S-93755	FLY 477
S-58737	17-4500	S-68613	17-4523	S-80212	FLY 327 <sup>10</sup>	S-93995	FLY 660
S-58738	17-4500	S-68765	17-1111	S-80253	17-4524	S-94147-/01	Y 176
S-58776	19-6823	S-69249	17-1111	S-80322	17-6134	S-94248	FLY 482 <sup>10</sup>
S-58777	19-6823	S-69428	17-1111	S-80327	FLY 489	S-94289	FLY 541
S-58821	17-4500	S-69562	17-6126	S-80411	20-1005	S-94397	FLY 535 <sup>10</sup>
S-58822	17-4500	S-69563	20-1114	S-80480	20-1005	S-94415/B	FLY 535 <sup>10</sup>
S-58824	17-5070	S-69564	17-6127	S-80558	20-1020	S-94740	Y 176
S-58826	FLY 250	S-69566/A	20-1020	S-80590	17-6135	S-96453-/01-	
S-59102	WC 39	S-69570	17-1111	S-80629	WC 107	-02/03	FLY 533 <sup>10</sup>
S-59194	WC 39	S-69599	FLY 322	S-80791	17-6136	S-96471-/01-	
S-59300	17-1018	S-69760	FLY 318	S-80820	FLY 347	-	

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
20-2003	19-3660	95-1189	26S50	95-1435	Y 39 <sup>8</sup>	95-1805	26C78
20-2004	19-1004	95-1198	Y 7	95-1436	26S11	95-1816	26R115 <sup>1</sup>
20-2005	19-1005	95-1200	16-6758 <sup>1</sup>	95-1437	Y 39	95-1823/A/B	26S30
20-2006	19-6022	95-1201	16-3474	95-1438	16-6790	95-1824	26R115
20-2007	19-6033	95-1217	Y 3	95-1440	26R53	95-1825/L	Y 98
20-2008	19-3036	95-1218	26C93	95-1441	26S22	95-1838	26C78
20-2012	19-3250	95-1219	24S86 <sup>1</sup>	95-1443	Y 39	95-1839/C	Y 39
20-2013	19-3093	95-1227	26S48	95-1446	Y 39	95-1840	26R53 <sup>1</sup>
20-2014	19-3180	95-1233	26S48 <sup>1</sup>	95-1448	Y 39	95-1841/C	26S22
20-2015	19-3093	95-1238	24S06	95-1452	Y 39	95-1842	26C76
20-2017	19-3660	95-1239	26S53	95-1454	26S22	95-1847	16-3476
20-2020	19-7068	95-1240	26S53	95-1466	Y 39	95-1852	22S58
20-2021	19-3100	95-1241	Y 7	95-1469	26R51	95-1866	16-3477
20-2022	19-4201	95-1246	Y 7	95-1471	26R52	95-1892	22S58
20-2024	19-4500	95-1247	24S06	95-1473	26R53	95-1894	26R53 <sup>1</sup>
20-2026	19-4950	95-1248	16-6682	95-1475	26S06	95-1895	26R115 <sup>1</sup>
20-2028	19-3330	95-1249	16-6683	95-1476	Y 39	95-1896	26R109 <sup>1</sup>
20-2033	19-1005	95-1250	16-6684	95-1479	26S06	95-1897	26R115 <sup>1</sup>
20-2040	19-1005	95-1251	16-6685	95-1480	26S23	95-1900	16-3478
20-2041	19-6022	95-1252	22S56	95-1483	24S98	95-1904/A	22S88
20-2052	19-1002	95-1253	24R05U <sup>1</sup>	95-1484	16-6791	95-1905/D	26S87
20-2061	19-3660	95-1254	16-6686	95-1497	26R511	95-1913	24S42
20-2062	19-3060	95-1263	Y 7	95-1497	26R51 <sup>1</sup>	95-1915	16-6788
20-2063	19-1005	95-1267	Y 7	95-1504	16-6792	95-1917	16-6789
20-2067	19-7047	95-1271	26C41	95-1505	16-6793	95-1918	16-3480
20-2070	19-2015	95-1272	26S50	95-1509	Y 39	95-1919	16-3480
20-2071	19-7047	95-1274	26S48	95-1523	26C43	95-1920	17-3480
20-2072	19-2018	95-1275	26S53	95-1527	Y 39	95-1922	16-6780
20-2301	19-7047	95-1277	26R45	95-1534	24S83	95-1924	16-6796
20-2501	19-4160	95-1280	26C44	95-1535	26S06	95-1941	24S52
20-2502	19-3330	95-1292	Y 7	95-1536	26C76	95-1942	Y 55
20-2504	19-3125	95-1294	26S48	95-1543	26C77	95-1943	26R115 <sup>1</sup>
20-2505	19-3180	95-1297	Y 7	95-1544	26R41 <sup>1</sup>	95-1944	Y 39
20-2512	19-4201	95-1297E	Y 7	95-1546	Y 39	95-1945	26R53 <sup>1</sup>
20-2514	19-3250	95-1298	26R43 <sup>1</sup>	95-1552	26S22	95-1970	26S30
20-2515	19-4251	95-1300	26S50	95-1553	26C44	95-1971	20C21
20-2516	19-3093	95-1306	Y 7	95-1554	Y 39	95-1972	26R149
20-2517	19-4201	95-1307	Y 7	95-1555	26R51 <sup>1</sup>	95-1973	22S35
20-2518	19-3025	95-1309	26S11	95-1557	22S58	95-1974	Y 107
20-2520	19-3375	95-1310	26C93	95-1558	26S23	95-1975/B	Y 39 <sup>8</sup>
20-2521	19-3093	95-1311	26R59	95-1559	26C44	95-1976	26R115 <sup>1</sup>
20-2522	19-3230	95-1312	16-6680	95-1560	Y 39	95-1983	17-3481
20-2523	19-4160	95-1313	16-6688	95-1561	26R127 <sup>1</sup>	95-1984	Y 55
20-2524	19-4201	95-1324	22S56	95-1569/W	24S98	95-1986	26C78
20-2526	19-3660	95-1326	26S11 <sup>1</sup>	95-1579	Y 39 <sup>8</sup>	95-1987	26R115
20-2528	19-2023	95-1328	16-3475	95-1581	26C41	95-1988	24S60 <sup>1</sup>
20-2534	19-1001	95-1334	26C43	95-1593	26S22	95-1990	26S23
20-2536	19-4160	95-1335	Y 7	95-1603	24R04U	95-1991	26S79
20-2541	19-4201 <sup>2</sup>	95-1337	Y 7	95-1610	Y 39	95-2010	17-3431
20-2702	19-1053	95-1339	26S48	95-1613	24S96	95-2018/B/F	26S30
20-2707	19-6033	95-1340	24S51	95-1636	16-6794	95-2023	Y 55 <sup>8</sup>
20-2712	19-6033	95-1346	26C93	95-1644	20C21	95-2024	26R127 <sup>1</sup>
20-3219	19-6816	95-1348	26C93	95-1646	26S23	95-2025/B	26S30
20-3238	19-4534	95-1349	16-6687	95-1647	24S42	95-2026	26S30
20-3547	WC 52	95-1350	16-6688	95-1648	Y 39 <sup>8</sup>	95-2038/A	26S23
20-3559	WC 11	95-1352	26S11	95-1650	24S07	95-2038D	26S30
95-115	26R27U <sup>1</sup>	95-1353	26R54	95-1651	24R40U <sup>1</sup>	95-2039	26C78
95-956	22R34 <sup>1</sup>	95-1355	26S56	95-1654	Y 98	95-2040	Y 55 <sup>8</sup>
95-957	26C41	95-1357	Y 7	95-1655	26S23	95-2042	22S28
95-1062	24R05U <sup>1</sup>	95-1358	Y 7	95-1656/A/G/	26S23	95-2050	26S88
95-1063	24S51	95-1359	Y 39	J	26S30	95-2051	26R149
95-1101	16-6680	95-1361	26S11	95-1663	26C44	95-2052/AR/	
95-1102	16-6681	95-1367	22S35	95-1665	24S50A <sup>1</sup>	AS	22S35
95-1108	26S49	95-1375	26R43 <sup>1</sup>	95-1666	Y 55	95-2054	26R127
95-1109	26C43	95-1376	26C44	95-1681	26C78	95-2059	26R128 <sup>10</sup>
95-1110	Y 3	95-1377	26S22	95-1682	26C78	95-2061	26R105 <sup>1</sup>
95-1112	26S53	95-1378	Y 7	95-1694	26C78	95-2062	26R113
95-1113	24A88	95-1379	24S52	95-1695	Y 55	95-2067	Y 107
95-1114	26S49	95-1383	26S48 <sup>1</sup>	95-1696	26S29	95-2084	24R105
95-1115	26R27U	95-1384	26S17 <sup>1</sup>	95-1700	26S73	95-2085	26S22
95-1124	26R27U	95-1386	26R54	95-1703/D	22S90	95-2091	Y 55 <sup>8</sup>
95-1132	16-6680	95-1389	26C41	95-1718	16-6788	95-2092/A	26S22
95-1133	16-6688	95-1397	26S11	95-1719	16-6795	95-2093/C	Y 98
95-1147	FC 3	95-1398	22S56	95-1721	Y 55 <sup>8</sup>	95-2094	26R105
95-1148	16-6680	95-1399	26C95	95-1743	24R40U <sup>1</sup>	95-2095	26S23
95-1149	16-6688	95-1400	26R52	95-1748	Y 39	95-2096/AG	24S98
95-1150	16-3473	95-1406	Y 7	95-1768/N/M	Y 98	95-2098	24S60 <sup>1</sup>
95-1153	17-3479	95-1413	Y 7	95-1771	Y 98	95-2104/A	26S23
95-1154	26C43	95-1421	26S22	95-1782	Y 55 <sup>8</sup>	95-2105	26R105 <sup>1</sup>
95-1165	Y 3	95-1427	Y 39	95-1791	24R01U <sup>1</sup>	95-2109/C	26S89
95-1166	24S86	95-1428	24S83	95-1793	Y 107	95-2110	26R105 <sup>1</sup>
95-1167	26S48	95-1431	26S30	95-1795	Y 55 <sup>8</sup>	95-2114	26R148
95-1168	26R27U <sup>1</sup>	95-1432	Y 39	95-1802	26R115 <sup>1</sup>	95-2116	26R105 <sup>1</sup>
95-1170	26C88	95-1434	26R43 <sup>1</sup>	95-1803	26S23	95-2118	20C21

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
95-2120	16-3481	95-2383	Y 98	95-2688	24S48	95-3242-02/-03	FLY 653
95-2121	26S22	95-2384/B	26S23	95-2690	26C91	95-3242-03	FLY 669
95-2139/C	26S61	95-2385(A5)	24S51	95-2696	Y 132	95-3243-03	FLY 670
95-2141	26R105 <sup>1</sup>	95-2387	16-9054	95-2702	26C81	95-3249	23V257
95-2142	24S48	95-2389	26S22	95-2706/C	22S61	95-3264-01	FLY 671
95-2144	22S24	95-2391/C	Y 130	95-2713	17-1052	95-3287-01	FLY 672
95-2146	26S23	95-2392	26C81	95-2730/B	26S60	95-3288-01	FLY 664
95-2157	Y 55 <sup>8</sup>	95-2395	26S22	95-2732	WC 51	95-3352-01	FLY 665
95-2158/AT	24S06	95-2396	24S51	95-2733	20C187	95-3355-01	20C191
95-2159/AT	24S06	95-2402	26C81	95-2739	22S22 <sup>1</sup>	206-600	22S48
95-2169	17-5071	95-2405/AE	22S22	95-2745/AR	22S20	212-102	VMT-04
95-2175	17-3426	95-2406	26S48	95-2746	Y 130	212-103	VMT-04
95-2179	26R148	95-2408	Y 105 <sup>8</sup>	95-2747	Y 238 <sup>8</sup>	212-104	VMT-04
95-2181/C	20C21	95-2413	26R105 <sup>1</sup>	95-2749	20C126	212-105	VMT-04
95-2185/R	22S24	95-2421	17-6034	95-2779	Y 257	212-106	VMT-04
95-2186/A	26S23	95-2436	16-9042	95-2780	Y 137	212-108	VMT-04
95-2187	26C78	95-2437	16-9055	95-2781	Y 132	212-109	VMT-04
95-2188	Y 55 <sup>8</sup>	95-2438	16-9056	95-2796	24S52	212-110	VMT-04
95-2189	26C78	95-2440	20C21	95-2797	24S08	212-128	VMT-04
95-2190/X	26S48	95-2444	22S33	95-2851	26C81	212-129	VMT-04
95-2200	26R106 <sup>1</sup>	95-2450	Y 119	95-2854	22S36	212-130	VMT-04
95-2201	24S51	95-2453	16-9057	95-2869-A	23V440 <sup>1</sup>	212-130X	VMT-04
95-2207	Y 55 <sup>8</sup>	95-2455	26C81	95-2869-01	23V440 <sup>1</sup>	212-131	VMT-04
95-2211	Y 55 <sup>8</sup>	95-2456	24S53	95-2874	Y 130	212-132	VMT-04
95-2212	26S22	95-2457	Y 130 <sup>8</sup>	95-2875/BX	Y 118	212-133	VMT-04
95-2216	23V257 <sup>8</sup>	95-2459	23V440 <sup>1</sup>	95-2880	Y 174	212-134	VMT-04
95-2222/A	26S37	95-2469	16-9032	95-2885	26C81	212-135	VMT-04
95-2223	Y 108	95-2470/E	26S60	95-2887	Y 167	212-136	VMT-04
95-2224AZ	26S48	95-2471	26S85	95-2891	Y 150	212-137	VMT-04
95-2233	16-9036	95-2479	Y 132	95-2893	24S48	212-138	VMT-04
95-2234	16-9037	95-2490	26C81	95-2896	Y 167	212-139	VMT-03-02
95-2235	16-9037	95-2491/F	26S106	95-2899	Y 130	212-139-01	VMT-03-02
95-2236	16-3495	95-2499/B	22S61	95-2905	22S61 <sup>1</sup>	212-139-02	VMT-03-02
95-2237	16-9050	95-2500	Y 108	95-2911	23V440 <sup>1</sup>	212-139-03	VMT-05-02
95-2238	16-9051	95-2501	Y 108	95-2917	26C81	212-140	VMT-04
95-2239	20C21	95-2510	22S31	95-2919	Y 167	212-140-01	VMT-04
95-2242	Y 105 <sup>8</sup>	95-2520	19-3375	95-2974	26S60		

# MISCELLANEOUS

MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT	MFR'S PART	REPLACEMENT
<b>AMC</b>				<b>SETCHELL-CARLSON</b>			
9A2654-001/E	Y 109	A 29056-A	FLY 625	033-013000	FLY 277	HF-155	FLY 252
53X0446-001/B	FLY 337	A 29062-B	Y 109	033-014500	FLY 345	PF-155	FLY 252
708476	Y 116	A 29072-B	Y 109	033-015500	FLY 338	T-103	FLY 252
708479	Y 116	A 29158-AS	Y 109	906186-501	Y 245	T-108	FLY 252
<b>ANDREA</b>				<b>MUNTZ</b>			
A 52-3162	FLY 281	A 2912-A/-B	Y 109	LC-0115/-2	Y 88 <sup>9</sup>	T-111	FLY 252
A 52-3209	Y 3000	A 30105-A-26	Y 47	LC-0131	Y 88	T-123	FLY 253
A 95-5314 <sup>16</sup>	VMT-03-02	A 30305-B/-C	FLY 434	LC-0141	Y 88 <sup>9</sup>	T-124	FLY 253
ST-3095/-1/-2	FLY 201	A 30786-D	Y 113	LC-9127	Y 107	T-132	FLY 254
<b>ARVIN</b>				<b>HOFFMAN</b>			
TLF-418/-T	FLY 398	L-209	Y 208	LC-9151	Y 245	T-133	FLY 254
TLF-5002/U	FLY 620	L-262	Y 208	LC-9159	Y 245	TF-10	FLY 252
TLF-5004-1	FLY 643	L-263	Y 208	TO-0054	FLY 198	TF-1025	FLY 277
TLY-3359-3D/-4D	Y 120	TVL-209	Y 208	TO-0055	FLY 198	TF-1116	FLY 656
YSG-T85-4-1	FLY 520	TVL-262	Y 208	TO-0060	FLY 240	TWF-90	FLY 251
YSG-T85-4-3	FLY 520	TVL-263	Y 208	TO-0070	FLY 240	TWF-110	FLY 251
YSG-T86-5-2	Y 211	5158A/-2	FLY 204	TO-9104	FLY 277	WF-9	FLY 251
2004007-27	FLY 398	5165	FLY 206	TO-9106/-1	FLY 295	WF-14	FLY 253
2006582-29	FLY 520	5168	FLY 206	Y-502	Y 91 <sup>3</sup>	WF-30	FLY 254
2006582-35	Y 211	5191A	FLY 501 <sup>4</sup>	TO-9106/-1	FLY 295	WF-70	FLY 253
<b>BROADMOOR</b>				<b>NIPPON ELECTRIC CO</b>			
24D68531A01	Y 120	782002	FLY 204	YSG-36100-B	FLY 5065	WF-71	FLY 254
VZ12017	FLY 677	782006	FLY 201	47004101	FLY 520	WF-80	FLY 254
<b>CLOVIS</b>				<b>SINGER</b>			
A 29056-A	FLY 625	782009	FLY 201	TLF-5005	FLY 621	WF-90	FLY 251
<b>DELMONICO,NIVICO, JVC</b>				<b>SPARTON</b>			
A 20098-F-22	Y 105	782010	FLY 201	218R28	FLY 5011	WF-110	FLY 251
A 20098-H-25	Y 105	782013	Y 146	218R60	FLY 5019	701045-00	FLY 656
A 20262-A	Y 91	027-026200	Y 208	218R62-1	FLY 5019	906152-501	FLY 277
A 20538-B	Y 91	027-026300	Y 208	218R121	FLY 5085		
		027-033000	Y 208				
		027-031400	Y 109				
		027-032000	Y 109				
		027-032800	Y 109				
		033-010200	FLY 277				
		033-012700	FLY 277				
		033-012800	FLY 488				

## SERVICE NOTES

- Mounting difference.
- Peaking coils require use of original value resistor in parallel.
- Terminal number differences.
- Reverse yellow and black leads.
- May require removal or addition of some ringing components.
- Jumper terminals 1 and 3.
- Connect windings in series and use as autoformer.
- Lead difference exists. Connect as in original circuit.
- Cut off plug and connect same as original.
- Use original mounting bracket.
- Splice leads if necessary.
- Use original plug.
- Lead colors not same as original.
- Change lead connections to terminals or plug per original.
- Remove or add jumper per original as required.
- Use original anode cap.
- Cut "G" lead at surface of failed multiplier. Strip and connect to "G" terminal of replacement.

## Sales Representatives

### ALABAMA

See Georgia

### ALASKA

See Oregon

### ARIZONA

J.R. Morgan Agency  
3411A E. Corma Ave.  
Phoenix, AZ 85040  
Ph. 602/268-3464

### ARKANSAS

See Tennessee, Memphis

### CALIFORNIA

Moulthrop Sales, Inc.  
7080 Commerce Dr.  
Pleasanton, CA 94566  
Ph. 415/846-0550

Mike Roth Sales, Inc.  
16117 Wyandotte St.  
Van Nuys, CA 91406  
Ph. 213/989-3738

### COLORADO

Bill Newman Co.  
3805 Marshall St.  
Wheatridge, CO 80033  
Ph. 303/425-9503

Elcom, Inc.  
8755 E. Orchard Rd.  
Englewood, CO 80111  
Ph. 303/770-4400

### CONNECTICUT

See Massachusetts

### DELAWARE

See New Jersey

### DISTRICT OF COLUMBIA

See New Jersey

### FLORIDA

Cartwright & Bean  
200 E. Marks St.  
Orlando, FL 32803  
Ph. 305/422-4531

4000 No. State Rd. 7  
Ft. Lauderdale, FL 33319  
Ph. 305/735-4900

### GEORGIA

Cartwright & Bean  
3198 Cains Hill Place NW  
Atlanta, GA 30305  
Ph. 404/233-2939

### HAWAII

See California, Mike Roth Sales, Inc.

### IDAHO

See Colorado & Oregon

### ILLINOIS

Bob Burns & Associates  
1020 Busse Hwy.  
Park Ridge, IL 60068  
Ph. 312/775-1233

### INDIANA

Electronic Representatives, Inc.  
11900 E. Washington St.  
Indianapolis, IN 46229  
Ph. 317/894-1414

18838 Wellsworth Ave.  
South Bend, IN 46637  
Ph. 219/277-4565

### IOWA

See Missouri

### KANSAS

Lowell-Kangas & Associates  
12302 Johnson Dr.  
Shawnee Mission, KS 66216  
Ph. 913/631-3515

### KENTUCKY

See Indiana

### LOUISIANA

Cartwright & Bean  
2121 N. Causeway Blvd.  
Metairie, LA 70001  
Ph. 504/835-6220

### MAINE

See Massachusetts

### MARYLAND

See New Jersey

### MASSACHUSETTS

Rudolph & MacInnis Associates  
850 Providence Hwy.  
Dedham, MA 02026  
Ph. 617/329-4795

### MICHIGAN

See Ohio

### MINNESOTA

HMR, Inc.  
9001 E. Bloomington Frwy.  
Minneapolis, MN 55420  
Ph. 612/888-2100

Nortec Sales, Inc.  
4530 W. 77th St.  
Minneapolis, MN 55435  
Ph. 612/835-7414

### MISSISSIPPI

Cartwright & Bean  
5166 Keele St.  
Jackson, MS 39206  
Ph. 601/981-1170

### MISSOURI

Lowell-Kangas & Associates  
12015 Manchester

St. Louis, MO 63131  
Ph. 314/821-4050

### MONTANA

See Colorado and Oregon

### NEBRASKA

See Missouri

### NEVADA

See California

## Sales Representatives

(CONTINUED)

### NEW HAMPSHIRE

See Massachusetts

### NEW JERSEY

Trinkle Sales, Inc.  
1010 Haddonfield—Berlin Rd.  
Cherry Hill, NJ 08034  
Ph. 609/795-4200

### NEW MEXICO

See Arizona

### NEW YORK

Jack Brown Electronic Sales Reps.  
30 Broadway  
Massapequa, NY 11758  
Ph. 516/795-3903

Warren Kauffman & Associates  
157 Rawlinson Rd.  
Rochester, NY 14617  
Ph. 716/266-2728

### NORTH CAROLINA

Cartwright & Bean  
1165 Commercial Ave.  
Charlotte, NC 28205  
Ph. 704/377-5673  
3948 Browning Place  
Raleigh, NC 27619  
Ph. 919/781-6560

### NORTH DAKOTA

See Minnesota

### OHIO

Electronic Salesmasters, Inc.  
24100 Chagrin Blvd.  
Beachwood, OH 44122  
Ph. 216/831-9555

### OKLAHOMA

McKinney Sales Co.  
7302 S. Canton  
Tulsa, OK 74136  
Ph. 918/492-8882

# Sales Representatives

(CONTINUED)

Notes

## OREGON

Weber & Schwab  
1226 SE 7th Ave.  
Portland, OR 97214  
Ph. 206/623-5990

## PENNSYLVANIA

Covert & Newman Co.  
300 Mt. Lebanon Blvd.  
Pittsburgh, PA 15234  
Ph. 412/531-2002

Also See New Jersey

## RHODE ISLAND

See Massachusetts

## SOUTH CAROLINA

See North Carolina, Charlotte

## SOUTH DAKOTA

See Minnesota

## TENNESSEE

Cartwright & Bean  
560 S. Cooper St.  
Memphis, TN 38104  
Ph. 901/276-4442

8507 Unicorn Dr.  
Knoxville, TN 37919  
Ph. 615/693-7450

## TEXAS

McKinney Sales, Co.  
1303 Chemical St.  
Dallas, TX 75207  
Ph. 214/631-9450

P.O. Box 1026  
Bellaire, TX 77401  
Ph. 713/444-3817

## UTAH

See Colorado

## VERMONT

See Massachusetts

## VIRGINIA

See New Jersey

## WASHINGTON

See Oregon

## WEST VIRGINIA

See Pennsylvania

## WISCONSIN

See Illinois

## WYOMING

See Colorado

## EXPORT ONLY

Roburn Agencies, Inc.  
111 8th Ave.  
New York, NY 10011  
Ph. 212/989-5939

Electronica International  
2323 NW 17th Ave.  
Miami, FL 33142  
Ph. 305/635-8670